

ESTIMATE TO REPAIR

VEHICLE NO. : SJN 8996 G
 MAKE : HONDA
 MODEL : CIVIC 2.0L 5AT
 YEAR : 2009
 CHASSIS NO : JHMFD26409S200871

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

DATE : 4-Aug-18
 DATE OF ACCIDENT : 3-Aug-18
 THIRD PARTY REF : SKL 5258 Y / AXA

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ 638.00
2 pcs	Rear Bumper Bracket		\$ 13.90		\$ 27.80
2 pcs	Rear Bumper Retainer		\$ 18.90		\$ 37.80
1 pc	Rear End Panel				\$ 300.50
1 pc	Rear End Panel Garnish				\$ 56.10
2 pcs	Taillamps		\$ 308.70		\$ 617.40
1 pc	Rear Boot Lid				\$ 610.70
2 pcs	Rear Boot Inner Lamp		\$ 202.20		\$ 404.40
1 pc	Rear Boot Lock				\$ 194.50
1 pc	Rear Boot Rubber				\$ 97.60
1 pc	Rear Boot Centre Emblem				\$ 25.70
1 pc	Rear Boot CIVIC Emblem				\$ 29.10
1 pc	Rear Boot 2.0 I-VTEC Emblem				\$ 29.10
					\$ 3,068.70
	Less 20%				\$ 613.74
					\$ 2,454.96
1 set	Rear Bumper Sensor	S.Nett			\$ 200.00
	To putty & spray painting.				\$ 800.00
	To check rear wiring and water leakage.				\$ 30.00
	To anti-rust.				\$ 80.00
	Labour Charges.				\$ 600.00
TG-RA/-	TOTAL				\$ 4,164.96

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
 Tel:65-64520893 Fax:65-64589127 Website : www.LTM.sg
 Co.Reg No.199307277D GST Reg No.M2-0019086-0