

ASS. REC. BY:

REF: CS/FCI 18014378/Ard322

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

CWS

From (Person):

Maychua

of

FCI

Date/Time: 6/8/18 @ 5:36pm

Estimated Cost:

Bill to:

OB / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHJ 4564T

Insured:

SHD 4980D

at Workshop m/s

Kah Motor

Tel:

81006306

of

15 Ubi Rd #

Policy No:

Claim No:

D18005818MPST

Sum Insured:

Excess:

D.O.A. 31/07/2018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

11:29am @ 7/8/18

Person Contacted:

Any

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SHJ 4564T - X
	SHD 4980D - X
8/8/18 -	called wesp vehicle not in (Any)
10/8/18 -	called vehicle not in (Any)
15/8/18 -	called Any vehicle still not in yet.

(08/11/13) wel

ASS. REC. BY:

REF: FCI

ASSIGNMENT

From Date: 4/9/18

Estimated Cost:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLJ 4564T

at Workshop m/s Kah Motor

of 15 ubi Rd 4

Insured

Policy No.

Claims No.

Sum Insured

Excess:

(Client's Record)


After 3pm

Make of Veh:

Any

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLJ4564T. Yr Regn: 2016, Dec.

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic c.c. 1597.

Colour: Red. A/C: Insured / Std / NI / NA

Sp. Reading: 21635. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MRHFC56506T000716.

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R16.

R: 215/55R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook.

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 04/09/18.

Survey held at Kah motor.

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 1st Cap.

25/9/18 Revert thru email

Confirm \$1699.79 @ 3 days
 Red \$2947.31, 63%.

RECEIVED 26 SEP 2018

Date/Time, Fee Pass to?



Preli. Report

Days Of Repair: 3

Resurvey No. of Trip: 1

1) ^{typist}

Final Report

Date/Time, Fee Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

TP

Lump Sum / I.B.I. (\$) 1699.79

135
50
50
18
253

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18014378/Ard3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 07-08-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4980D	Veh. Inspected	SLJ 4564T
Policy No.		Coverage (\$)	0.00
Claim No.	D18005818MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	07/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	31/07/2018	Inspection Date	04/09/2018
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	01-08-2018	Our Ref No. D18005818MFSH
Accident Date	31-07-2018	Claim Type. Third Party
Insured Vehicle	SHD4980D	Third Party Vehicle. SLJ4564T
Survey Location	15 UBI ROAD 4	
Contact Person.	ARY CHUA WAI NGEE	
Contact No.	68465673/ 81006306	Fax No. 67480770
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO SDN BHD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Your Ref: D18005818MFSH

Our Ref: CS/FCI18014378/Ard3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLJ 4564T .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 04.09.2018 at the premises of M/s KAH MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>4,647.10</u> .
Revised Estimate Amount	: S\$ <u>1,876.40</u> .
"Check" Items Amount	: S\$ _____ .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:
The vehicle sustained damages
at rear portion.



Yours faithfully

ADRIAN LING
Automotive Assessor

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Tuesday, September 25, 2018 11:48 AM
To: 'Claim Workflow System'
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005818MFSH/1
Attachments: SLJ 4564T.pdf

Dear Sir/ Madam,

Enclosed preliminary advice for SLJ 4564T.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, August 07, 2018 11:34 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005818MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 6 August 2018 5:35 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005818MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/07/2018 18:54
Date Of Accident	31/07/2018 08:15
Exact Location Of Accident	WHAMPOA SOUTH JUNCTION TOWARDS BENDEMEER RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ4564T
Insured/Policyholder	
Name Of Registered Owner	TAN JOKE SAN
NRIC No	S1168885C
Email Address	JUSTINTANYZ@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96826637
Alternative Phone No	OFFICE-96826637

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.6 L (A)
Exact Purpose for which vehicle was being used at time of accident	P/USED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	16-MV012091-R00
Cover Note Number	

Driver

Name of Driver	TAN YANZHI, JUSTIN (CHEN YANGZHI)
NRIC No	S8945927C
Date Of Birth	18/12/1989
Occupation	INDOOR
Date Of Driving Pass	18/11/2008
Driving Experience	9 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82180809
Fax Number	
Contact Number	OFFICE-82180809
Email Address	JUSTINTANYZ@GMAIL.COM

Vehicle No

SLJ 4564 T

SKETCH PLAN

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Justin T

16:16pm

31 JUL 2018


Any

ARY CHUA

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Please continue to Annex E

Receipt

> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 31 Jul 2018 / 15:59:43

Receipt Date/Time : 31 Jul 2018 / 15:59:43

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180731-001490

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - SHD4980D As at 31 Jul 2018/08:15:15 Insurance Co: MS FIRST CAPITAL INSURANCE LIMITED			
1	Insurance Enquiry - SHD4980D Enquiry Fee 20180731155826494287	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	xxxxxxxxxxxx9280 Credit Card: Visa/MasterCard			7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

04 SEP 2018 @ 15:00pm
Survey & Repair
68411972 Larita
appointment confirmed
by Owner

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLJ4564T
Chassis No : MRHFC5650GT000716
Model : CIVIC 1.6 VTI YM2016
Owner's Name : TAN JOKE SAN
Ins Policy No : 16-MV012091-200
Date of Accident : 31/7/2018

Document No. : SQT18003191 Page 1
Date : 31. Jul 2018
Customer No. : WZF002
Svc Advisor : ARY CHUA WAI NGEE
Engine No : R16B21600954
Date | Time : 31. Jul 2018 3:42:11 PM
Surveyor Name : DID : +65 6845 5673
Survey Date : HP : +65 8100 6305
Authorisation Date : Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TAN JOKE SAN OWNER INSURER: TOKIO MARINE INSURANCE LTD ACC DATE: 31/07/2018@ SURVEYED BY: DATE: REF NO: D18005818MFSH TP INSURER: First Capital Insurance Ltd TP VEH: SHD4980D (HYUNDAI I40/BLUE TAXI)						
91505-TM8-003	CLIPBUMPER <i>new</i>	14	2.00	21.80 ✓	28.00	1.96	29.96
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER <i>deland</i>	1	617.20	462.90 ✓	617.20	43.20	660.40
71508-TEA-T00	GARNISHL.RR.BUMPER SIDE <i>new</i>	1	7.60	x 7.60	7.60	0.53	8.13
71593-TEA-T01	SPACERR.RR.BUMPER SIDE <i>new</i>	1	11.50	8.62 ✓	11.50	0.81	12.31
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	8.62 ✓	11.50	0.81	12.31
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER <i>cut</i>	1	38.20	28.65 ✓	38.20	2.67	40.87
71506-TEX-Y00	COVERRR.TOWING HOOK <i>new</i>	1	8.70	x 8.70	8.70	0.61	9.31
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER <i>not new</i>	1	173.00	x 173.00	173.00	12.11	185.11
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE <i>new</i>	1	2.20	x 2.20	2.20	0.15	2.35
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	1	2.20	x 2.20	2.20	0.15	2.35
33555-TEA-T01	REFLECTOR ASSYL.RR. <i>new new</i>	1	7.00	x 7.00	7.00	0.49	7.49
	Sum Item				907.10	63.49	970.59
BOSUN	SUNDRIES	1	100.00 <i>20</i>		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	160.00 <i>x</i>		160.00	11.20	171.20
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	180.00 <i>140</i>		180.00	12.60	192.60
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (1P)	1	1500.00 <i>450</i>		1500.00	105.00	1605.00
BKRP21S	STRAIGHTEN ALIGN RR PANEL RR L FENDER & RENEW	1	1800.00 <i>560</i>		1800.00	126.00	1926.00
	Sum Labor				3740.00	261.80	4,001.80

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLJ4564T
Chassis No : MRHFC5650GT000716
Model : CIVIC 1.6 VTI YM2016
Owner's Name : TAN JOKE SAN
Ins Policy No. : 16-MVD12091-R00
Date of Accident : 31/7/2018

Document No. : SQT18003191 Page 2
Date : 31. Jul 2018
Customer No. : WZF002
Svc Advisor : ARY CHUA WAI NGEE
Engine No : R16B21600954
Date | Time : 31. Jul 2018 3:42:11 PM
Surveyor Name :
Survey Date : DID : +65 6646 5673
Authorisation Date : HP : +65 8100 6306
Email : arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Survey By	Adrian King						
Date & Time	04/09/18						
Excess							
Status	Not Authorised						
Signature	[Signature]						
					Total Amount	4,647.10	325.29
					Total (Inclusive of GST)		4,972.39

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 6/8/2018 8:43:46 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZF002 / MS FIRST CAPITAL
Chassis No: MRHFC5650GT000716
License No: SLJ4564T
Mileage: 21636
Engine No: R16B21600954

Document No: SVO18050963
Printed By: ARYCHUA
Order Date: 31. August 2018
Order Time: 9:37:51 AM
Service Advisor: ARY CHUA WAI NGE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 71150) OWNER: TAN JOKE SAN OWNER INSURER: TOKIO MARINE INSURANCE LTD ACC DATE: 31/07/2018@08.15am SURVEYED BY: ADRIAN LING(LKKAUTO)04/09/2018@16.16PM REF NO: D18005818MFSH TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED TP VEH: SHD4980D (HYUNDAI I40/BLUE TAXI)						
91505-TM8-003	CLIPBUMPER	14	2.00	25	21.00	1.47	22.47
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	38.20	25	28.65	2.01	30.66
	SUM PARTS:				529.79	37.08	566.87
BOSUN	0672 SUNDRIES	1	20.00		20.00	1.40	21.40
BA02R	EXT-YJ REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	140.00		140.00	9.80	149.80
BP01R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(1P)	1	450.00		450.00	31.50	481.50
BKRP21S	EXT-YJ STRAIGHTEN ALIGN RR PANEL RR L FENDER & RENEW DAMAGE PARTS.	1	560.00		560.00	39.20	599.20
	SUM LABOUR:				1,170.00	81.90	1,251.90
	TOTAL SGD				1,699.79	118.98	1,818.77
	Total Payable (SGD)						1,818.77

GST Amount is calculated from individual line(s)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18014378/Ard3s2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 02-10-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 4980D	Veh. Inspected	SLJ 4564T
Policy No.		Coverage (\$)	0.00
Claim No.	D18005818MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	06/08/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MRHFC5650GT000716	Colour	RED
Odometer	21635	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55R16	HANKOOK	6 mm
L/H Front Tyre	215/55R16	HANKOOK	6 mm
R/H Rear Tyre	215/55R16	HANKOOK	6 mm
L/H Rear Tyre	215/55R16	HANKOOK	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	31/07/2018	Inspection Date	04/09/2018
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 4564T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
14	CLIPBUMPER (SN)	NECESSARY	28.00	21.00
1	FACE ASSY,RR BUMPER (SN)	DEFORMED	617.20	462.90
1	GARNISHL RR BUMPER SIDE (SN)	NOT NECESSARY	7.60	-
1	SPACERR RR BUMPER SIDE (SN)	NECESSARY	11.50	8.62
1	SPACERL RR BUMPER SIDE (SN)	NECESSARY	11.50	8.62
1	GARNISH RR BUMPER LOWER (SN)	CUT	38.20	28.65
1	COVERRR TOWING HOOK (SN)	NOT NECESSARY	8.70	-
1	BEAM COMPRR BUMPER (SN)	NOT NECESSARY	173.00	-
1	BRACKETR RR BUMPER SIDE (SN)	NOT NECESSARY	2.20	-
1	BRACKETL RR BUMPER SIDE (SN)	NOT NECESSARY	2.20	-
1	REFLECTOR ASSYL RR (SN)	NOT NECESSARY	7.00	-
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			1,007.10	549.79
LABOUR				
	INSPECT RR LIGHTING MECHANISMS PERFORM WATER.	NOT NECESSARY	160.00	-
	REMOVE & INSTALL REVERSE SENSORS-4 PCS.		180.00	140.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		1,500.00	450.00
	STRAIGHTEN ALIGN RR PANEL RR L FENDER & RENEW.		1,800.00	560.00
			3,640.00	1,150.00
GRAND TOTAL			4,647.10	1,699.79
RECOMMENDED COST OF REPAIRS				1,699.79

Report Ref No. CS/FCI18014378/Ard3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.