



方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Road Builders Singapore Pte Ltd
37 Kranji Link
Singapore 728643

Dear sir

Estimate cost of repair to vehicle no. SLT 1846Y

To supply

1. Rear knuckle arm right	1,070.89	?
2. Wheel bearing right	978.34	?
3. Rear upper arm	927.34	?
4. Rear trailing arm	980.34	?
5. Rear track rod	982.45	?
6. Rear lower arm	850.67	?
7. Rear cross member	2,890.11	X
8. Rear linkage	280.93	?
9. Rear anti lower bar	490.23	X
10. Wheel sport rim	550.00	X?
11. Tyres	350.00	?
12. Tail lamp	1,025.23	?
13. Rear bumper	2,134.25	✓
14. Rear bumper retainer	96.80	✓
15. Rear bumper lower spoiler	725.70	X
16. Rear bumper reflector	190.34	✓
17. Rear fender	2,880.32	X
18. Rear fender air inlet garish	214.56	?
19. Rear fender outer inner garish	280.90	✓

Labour charges

Panel beating

Spray painting

Rust proofing

Towing 4wheel, king trolley

Undercarriages and wheel alignment

Total

	1,500.00	500
	880.00	440
	100.00	X
(Bill)	200.00	120
	350.00	220
	20,929.17	

Your faithfully

ALBERT POON

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: