

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 660D**

AAD1807-254

*Not Authorized  
11 Sep @ 3100h*

Vehicle No.:	<b>SHD 660D</b>
Chassis No.:	VF1ABL15AUC283410
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	26.7.2018
Third Party Insurer :	<i>Axa</i>

PART	LIST
1 DOOR PANEL FRT RH	\$ <i>N</i> 2,844.66
1 DOOR HINGE UPPER RH	\$ <i>N</i> 261.28
1 DOOR HINGE LOWER RH	\$ <i>N</i> 300.55
1 DOOR CHECK FRT RH	\$ <i>Sn</i> 194.77
1 DOOR LOCK FRT RH	\$ <i>N</i> 908.75
1 DOOR CATCH FRT RH	\$ <i>Sn</i> 131.23
1 DOOR HANDLE OUTER FRT RH	\$ <i>Sn</i> 477.76
1 DOOR HANDLE COVER FRT RH	\$ <i>Sn</i> 13.22
1 DOOR HANDLE MODULE FRT RH	\$ <i>Sn</i> 133.60
1 DOOR REGULATOR FRT RH	\$ <i>N</i> 505.19
1 DOOR REGUALTOR MOTOR FRT RH	\$ <i>N</i> 796.46
1 DOOR REGULATOR GUIDE FRT RH	\$ <i>Sn</i> 120.97
1 DOOR PANEL REAR RH	\$ <i>N</i> 2,844.66
1 DOOR GUIDE REAR RH	\$ <i>Sn</i> 176.82
1 DOOR HINGE UPPER RH	\$ <i>N</i> 274.50
1 DOOR HINGE LOWER RH	\$ <i>N</i> 300.55
1 DOOR CHECK REAR LH/RH L70Y	\$ <i>Sn</i> 203.06
1 DOOR LOCK REAR RH	\$ <i>N</i> 908.75
1 DOOR HANDLE OUTER REAR RH	\$ <i>Sn</i> 126.49
1 DOOR HANDLE CAP REAR RH	\$ <i>Sn</i> 35.52
1 DOOR HANDLE SEAL REAR RH	\$ <i>Sn</i> 7.89
1 DOOR HANDLE COVER REAR RH	\$ <i>Sn</i> 13.22
1 DOOR HANDLE MODULE REAR RH	\$ <i>N</i> 133.60
1 DOOR REGULATOR REAR RH	\$ <i>N</i> 1,135.10
1 DOOR REGUALTOR MOTOR REAR RH	\$ <i>Sn</i> 893.75
1 DOOR REGULATOR NUT REAR L70Y	\$ <i>Sn</i> 12.43
1 DOOR REGUALTOR MOTOR SCREW REAR L70Y	\$ <i>Sn</i> 6.31
1 DOOR FINISHER REAR RH	\$ <i>Sn</i> 423.10
1 DOOR MOULDING REAR RH	\$ <i>Sn</i> 176.82
1 DOOR MOULDING CLIP L70Y	\$ <i>N</i> 5.92

**Trans-cab Auto Services Pte Ltd**

**AAD1807-254**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 660D**

1	DOOR MOULDING SCREW L70Y	\$	<i>na</i> 6.91	}
1	DOOR CASING REAR RH	\$	<i>su</i> 1,509.06	
1	DOOR WATER SHIELD REAR RH	\$	<i>su</i> 30.39	
1	DOOR CASING CLIP	\$	<i>na</i> 12.63	
1	DOOR CASING LIGHT L70Y	\$	<i>su</i> 48.74	
1	DOOR FINISHER INNER REAR RH	\$	<i>su</i> 323.44	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>n</i> 46.97	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>n</i> 20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>n</i> 20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>n</i> 20.33	
1	DOOR GRAB HANDLE REAR RH	\$	<i>su</i> 210.96	
1	DOOR BLIND REAR RH	\$	<i>su</i> 741.80	
1	DOOR WHEATHESTRIP REAR RH	\$	<i>su</i> 410.66	
1	DOOR SEAL REAR RH	\$	<i>su</i> 162.02	
1	DOOR GLASS RUNNER SEAL REAR RH	\$	<i>su</i> 229.31	
1	DOOR WAIST SEAL OUTER REAR RH	\$	<i>su</i> 334.69	
1	DOOR WAIST SEAL INNER REAR RH	\$	<i>su</i> 115.64	
		\$	<b>18,611.14</b>	
		10% \$	<b>1,861.11</b>	
		\$	<b>16,750.02</b>	

**Special Nett**

1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>na</i> 70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>na</i> 20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>na</i> 30.00	X
1SET	WHEELARCH CLIP FRT LH	\$	<i>na</i> 30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	<i>na</i> 80.00	<i>60na</i>
1	FRONT DOOR STICKER 'Chassis'	\$	<i>na</i> 50.00	<i>15na</i>
1	REAR DOOR STICKER '6555-3333'	\$	<i>na</i> 80.00	<i>60na</i>
1	DOOR CHECK BOLT	\$	<i>su</i> 22.69	}
1	DOOR GUIDE SCREW	\$	<i>su</i> 10.85	
1	DOOR HINGE BOLT	\$	<i>su</i> 10.85	
1	DOOR HINGE NUT RH	\$	<i>su</i> 14.60	
1	DOOR CHECK BOLT	\$	<i>su</i> 22.69	
1	DOOR CHECK NUT	\$	<i>su</i> 3.75	
1	DOOR LOCK SCREW L70Y	\$	<i>su</i> 6.12	
1	DOOR CATCH SCREW L70Y	\$	<i>su</i> 10.06	

**Trans-cab Auto Services Pte Ltd**

AAD1807-254

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 660D**

<b>TOTAL</b>	<b>\$</b>	<b>462.13</b>
<b>TOTAL PARTS</b>	<b>\$</b>	<b>17,212.15</b>

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	4401
Putty and spray painting of the affected portion.	\$	4,200.00	6601
To rust-proofing of the affected areas.	\$	170.00	301
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	~ 380.00 X
To check steering geometry and computer wheel alignment	\$	220.00	~ 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00	~ 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	~ 380.00 X
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	601
Towing Fees.	\$	120.00	~ 120.00 X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	~ 380.00 X

**Trans-cab Auto Services Pte Ltd**

**AAD1807-254**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 660D**

Labour charge to mount and dismount vehicle on jig  
bench, to facilitate repair.

\$ *nn* 380.00 X

**TOTAL** \$ 11,450.00

**Over All Total** \$ 28,662.15

**PART-BY-PART (REPAIR DAY)**

~~15~~ DAYS

3 days

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: