



SLU9671B

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6904 4596 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 04-08-18

Vehicle Reg. No. : SLU9671B
Vehicle Reg. Date: 19-12-17
Make / Model : SIENTA HYBRID 1.5X CVT
Engine No. : 1NZR463046
Chassis No. : NSP170706836

COST OF CLAIMS

Parts Cost / List Items : \$ 14,218.72
Plus/Less 25% \$ 3,554.68
Total Cost / List : \$ 10,664.04
Special Nett Items : \$ 805.00
Total Parts Amount : \$ 11,469.04
Total Labour Amount : \$ 4,670.00
Gross Total : \$ 16,139.04
GST % : 7% \$ 1,129.73
Nett Amount : \$ 17,268.77

Surveyor Name and Company :

Taufik 97495749

Date of survey : 8/8/18 @ 1120

Part by Part / Lump Sum : 5 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : suv@lkkauto.com

Fax No :

HP No :

This claim is handled by : MINOKO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SLU9671B**

Vehicle Reg. Date: **19-12-17**

Make / Model : **SIENTA HYBRID 1.5X CVT**

Engine No. : **1NZR463046**

Chassis No. : **NSP170706836**

Estimates on Parts

PAGE 1

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear windscreen glass	X			
2	1	Rear windscreen glass moulding	rel ✓	\$ 1,922.40		
3	2	Rear number plate lamp	X	\$ 168.00		
4	1	Rear bumper	cut ✓	\$ 158.00		
5	1	Rear bumper cover center	cut ✓	\$ 838.80		
6	1	Rear bumper cover LH	X	\$ 182.40		
7	1	Rear bumper cover RH	X	\$ 195.50		
8	1set	Rear bumper clips	X	\$ 195.50		
9	2	Rear bumper side retainer LH/RH	rel ✓	\$ 50.00		
10	2	Rear bumper bracket LH/RH	X	\$ 164.00		
11	1	Rear bumper sponge	X	\$ 164.00		
12	2	Rear bumper reflector LH/RH	X	\$ 98.00		
13	2	Rear bumper splash shield LH/RH	X	\$ 108.00		
14	1	Tail gate	X	\$ 170.00		
15	1	Tail gate lock	bt ✓	\$ 1,360.00		
16	1	Tail gate striker	del ✓	\$ 246.60		
17	1	Tail gate stay LH	X	\$ 48.00		
18	1	Tail gate stay RH	X	\$ 160.00		
19	1	Tail gate logo	X	\$ 160.00		
20	1	Tail gate emblem RH	del ✓	\$ 50.00		
21	1	Tail gate outer garnish	wh ✓	\$ 59.40		
22	1	Tail gate weatherstrip	X	\$ 84.50		
23	1	Tail gate lamp LH	X	\$ 145.00		
24	1	Tail gate lamp RH	X	\$ 194.00		
25	1	Tail door trim	X	\$ 194.00		
26	1	Rear wiper motor	X	\$ 280.00		
27	1	Rear wiper motor link	X	\$ 400.00		
28	1	Rear wiper arm	X	\$ 240.00		
29	1	Rear wiper blade	X	\$ 200.00		
30	1	Rear end panel outer <i>\$ photo</i>	X	\$ 87.80		
31	1	Rear end panel inner	Rp	\$ 498.20		
32	1	Rear end panel garnish	X	\$ 498.02		
33	1	Tail gate inner side trim LH	X	\$ 195.20		
34	1	Tail gate inner side trim RH	X	\$ 750.00		
35	1	Tail lamp LH	X	\$ 750.00		
36	1	Tail lamp RH	X	\$ 389.90		
37	2	Tail lamp panel	X	\$ 389.90		
38	1	Spare tyre well panel	X	\$ 170.00		
39	1	Spare tyre board	X	\$ 822.60		
40	1	Spare tyre bracket	X	\$ 256.00		
				\$ 60.00		



SLU9671B

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6904 4596 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 04-08-18

Vehicle Reg. No. : SLU9671B
Vehicle Reg. Date: 19-12-17
Make / Model : SIENTA HYBRID 1.5X CVT
Engine No. : 1NZR463046
Chassis No. : NSP170706836

COST OF CLAIMS

Parts Cost / List Items :	\$ 14,218.72
Plus/Less 25%	\$ 3,554.68
Total Cost / List :	\$ 10,664.04
Special Nett Items :	\$ 805.00
Total Parts Amount :	\$ 11,469.04
Total Labour Amount :	\$ 4,670.00
Gross Total :	\$ 16,139.04
GST % : 7%	\$ 1,129.73
Nett Amount :	\$ 17,268.77

Surveyor Name and Company :

Taufik 97445749

Date of survey : 8/8/18 @ 120

Part by Part / Lump Sum : 5 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : sur@khanto.com

Fax No :

HP No :

This claim is handled by : MINOKO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SLU9671B**

Vehicle Reg. Date: **19-12-17**

Make / Model : **SIENTA HYBRID 1.5X CVT**

Engine No. : **1NZR463046**

Chassis No. : **NSP170706836**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear windscreen glass	X	\$ 1,922.40		
2	1	Rear windscreen glass moulding	net	\$ 168.00		
3	2	Rear number plate lamp	X	\$ 158.00		
4	1	Rear bumper	cut	\$ 838.80		
5	1	Rear bumper cover center	cut	\$ 182.40		
6	1	Rear bumper cover LH	X	\$ 195.50		
7	1	Rear bumper cover RH	X	\$ 195.50		
8	1set	Rear bumper clips	net	\$ 50.00		
9	2	Rear bumper side retainer LH/RH	X	\$ 164.00		
10	2	Rear bumper bracket LH/RH	X	\$ 164.00		
11	1	Rear bumper sponge	?	\$ 98.00		
12	2	Rear bumper reflector LH/RH	X	\$ 108.00		
13	2	Rear bumper splash shield LH/RH	X	\$ 170.00		
14	1	Tail gate	ba	\$ 1,360.00		
15	1	Tail gate lock	dt	\$ 246.60		
16	1	Tail gate striker	X	\$ 48.00		
17	1	Tail gate stay LH	X	\$ 160.00		
18	1	Tail gate stay RH	X	\$ 160.00		
19	1	Tail gate logo	wh	\$ 50.00		
20	1	Tail gate emblem RH	wh	\$ 59.40		
21	1	Tail gate outer garnish	?	\$ 84.50		
22	1	Tail gate weatherstrip	?	\$ 145.00		
23	1	Tail gate lamp LH	?	\$ 194.00		
24	1	Tail gate lamp RH	X	\$ 194.00		
25	1	Tail door trim	X	\$ 280.00		
26	1	Rear wiper motor	X	\$ 400.00		
27	1	Rear wiper motor link	X	\$ 240.00		
28	1	Rear wiper arm	X	\$ 200.00		
29	1	Rear wiper blade	X	\$ 87.80		
30	1	Rear end panel outer <i># photo</i>	Rp	\$ 498.20		
31	1	Rear end panel inner	X	\$ 498.02		
32	1	Rear end panel garnish	X	\$ 195.20		
33	1	Tail gate inner side trim LH	X	\$ 750.00		
34	1	Tail gate inner side trim RH	X	\$ 750.00		
35	1	Tail lamp LH	X	\$ 389.90		
36	1	Tail lamp RH	X	\$ 389.90		
37	2	Tail lamp panel	X	\$ 170.00		
38	1	Spare tyre well panel	X	\$ 822.60		
39	1	Spare tyre board	X	\$ 256.00		
40	1	Spare tyre bracket	X	\$ 60.00		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SLU9671B**

Vehicle Reg. Date: **19-12-17**

Make / Model : **SIENTA HYBRID 1.5X CVT**

Engine No. : **1NZR463046**

Chassis No. : **NSP170706836**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	SPARETYRE TOOL TRAY	X	\$ 700.00		
42	1	SPARETYRE TRIANGLE PLATE & COVER	X	\$ 70.00		
43	1set	Tail door trim clips	new 30	\$ 50.00		
44	1set	Tail gate inner side trim LH clips	X	\$ 50.00		
45	1set	Tail gate inner side trim RH clips	X	\$ 50.00		
46	1	Tail lamp seal	X		\$ 100.00	
47	1	Rear end panel sealant	?	40	\$ 80.00	
48	1	Tail gate seal	new	40	\$ 80.00	
49	1	Rear windscreen sealant	new		\$ 80.00	
50	1	Rear windscreen inner seal tape	new		\$ 40.00	
51	1	Spare tyre panel sealant	X		\$ 80.00	
52	1	Reverse sensor	new	200	\$ 300.00	
53	1	Rear number plate	X		\$ 45.00	
54	1	Tailgate antenna	?	\$ 195.00		
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

Tel : 6904 4596 | Fax No : 6694 4929

PAGE 1

[illegible]