

100 G/LPC 130 14398; A203n2

LKK:
TRAC

Surveyor:

LWP

DOI:

ASSIGNMENT

6/8/2018

Date / Time:

6/8/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

G8B 5597C

Name of Insured:

FIRST OCEAN POOLS P/L

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A: 3/8/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

LIN YAN

Driver Tel No.:

9119 6653 (V/L)

(NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SGF 1677B



INSRS:

WSP:

Tel:

Liability:

RMKS:

SM



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

14/8

Actual

SGF 1677B - CC4/AXA 120 14705 / Apb392:00A: 25/1/17

G8B 5597C - X

14/8

Please verify O/D's PL.

CHECK WITH IRL -

20.9.18.

IPC Inform D/L NO ISSUE.

21.9.18

FILE PASS TO TYPIST TO PREPARE REPORT.

RECEIVED 21 SEP 2018

RECEIVED 03 DEC 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time: 21.09.18

Sent By: ASH.

FINALIZATION

Date/Time:

Confirm with:

Confirm by: LWP

Repair Cost:

45

SS 4,200

(

5

days) Reduction:

77

%

Email

Call

FINAL SETTLEMENT

Date/Time: 21.11.18

Confirm with:

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

23

If NO or B 28, Ass. Lia:

Repair Cost:

SS 4,200.00

O/D REVERSED INTO PARKING LOT HIT TP.

Loss of Rental (LOR):

SS 700.00

(

7

days) x 100

Loss of Use (LOU):

SS -

(\$

x

days)

Loss of Income (LOI):

SS -

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

SS 7.45

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 4,901.45

Global Sum SS:

FINAL PAYMENT

Date/Time: 21.11.18

Confirm with:

Email

Call

Payee 1:

SS 4,901.45

Name 1:

SM AUTOMOTIVE

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

+450

COPY SENT
21/11/18

REF:

ASS. REC. BY: Adrian King

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGF16773 Yr Regn: 2006 AprilType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Lauer c.c. 1584Colour: Black A/C: Insured / Std / NI / NASp. Reading: 217924 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JmySTCS3A6u007389Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/55R15R: 195/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 06/08/18Survey held at SM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Lon Pac.COE Expiry: 02/04/21H/S: 4,200 (RED: 13,933 77%)

MV: 18K
PV: 12.21K
Nett: 5.8K

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others:

TOTAL

Report Format:

Lump Sum / I.B.E. (\$)

Mei Kwan (LKKAUTO)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 10 August, 2018 9:19 AM
To: Mei Kwan (LKKAUTO); MT_Claim_SG
Cc: Asher Sng (LKKAUTO); Hsiao Tong (LKKAUTO); Joy Irene (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving GBB5597C (OI : LPC - 18/18/18/VC05/020814) and SGF1677B (TP : LKK REF - CC6/LPC18014398/Aea3) on 03/08/2018
Attachments: GBB5597C 030818.PDF
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Hi Mei Kwan

Attached is our Insured's GIA report for your handling.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Friday, 10 August, 2018 9:01 AM
To: MT_Claim_SG
Cc: GERALD POH WEE BIN; ericwoo; ONG LI LI; Asher Sng (LKKAUTO); Hsiao Tong (LKKAUTO); Joy Irene (LKKAUTO); Admin A
Subject: Direct Settlement - Accident Involving GBB5597C (OI : LPC - TBA) and SGF1677B (TP : LKK REF - CC6/LPC18014398/Aea3) on 03/08/2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

We have inspected TP vehicle SGF 1677B at M/s SM Automotive - Kaki Bukit.

Enclosed for your perusal is:

- TP's GIA report

Please be informed that the estimated cost of repair and preliminary advice is not ready yet.

We will revert to you on preliminary advice in due course.

Kindly assist to verify validity of our insured's policy, and let us have a copy of insured's accident report for our necessary action.

SEARCH

Lancer

Price Range

Depreciation

> 10 year(s)

Vehicle Type

Search

View All

Advanced Search

Used Car Comparison

--- Comparing 4 Vehicles ---

Mitsubishi Lancer 1.6A GLX (COE till 05/2021)



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Mitsubishi Lancer 1.6M GLX (COE till 05/2021)



Add to Shortlist

Mitsubishi Lancer 1.6A GLX Sports (COE till 05/2021)



Add to Shortlist

Mitsubishi Lancer 1.6A GLX (COE till 11/2021)



Add to Shortlist

CAR DETAILS

Price	\$22,500	\$18,800	\$22,800	\$26,000
Instalment	N.A.	N.A.	N.A.	N.A.
Registration Date	30-May-2006	13-Jun-2006	21-Jul-2006	15-Nov-2006
Manufactured	2006	2006	2006	2006
Mileage	-	-	160,000 km	-
Transmission	Auto	Manual	Auto	Auto
Engine Cap	1,584 cc	1,584 cc	1,584 cc	1,584 cc
Road Tax	\$881 /yr	\$881 /yr	\$881 /yr	\$881 /yr
Power	79.0 kW (105 bhp)	79.0 kW (105 bhp)	79.0 kW (105 bhp)	79.0 kW (105 bhp)
Curb Weight	1,162 kg	1,162 kg	1,162 kg	1,162 kg
Features	Powerful And Fuel Efficient 1.6L Engine, 5 Speed CVT Auto Transmission, ABS, Dual Airbag.	1.6L 4G18 SOHC Producing 105Bhp With Responsive 5 Speed Manual Transmission, SRS Airbags, ABS.	A SOHC Engine Powering 105Bhp On A Front Wheel Drive Setup Mated To A 5 Speed Automatic Gearbox With Safety ABS/6SRS Airbags.	Black Color.
Accessories	Sports Edition With Full BodyKit And Rear Spoiler, Leather Seat, Upgraded CD Player And Speakers, Parking Sensors, Knockdown Rearseat, 15" Sports Rims.	Solar Film, Reverse Sensors, Audio System.	Engine Gasket Change, 15 Inch Advan RGD Sports Rims, Brand New 4 Tyres 195/55/15, New Radiator Hose, Water Pump, Crank Pulley, Spark Plugs And More.	As Per Factory Fitti
Description	\$5K White Head Light, Blue Speedometer Light, Subwoofer, STI Side Skirt, Front Lip, Upgraded Sparks Plug Cable, Front Summit Strut Bar, New Front Both Suspension, Things That Just Replaced Less Than A Month, New Front Driveshaft, Full Timing Belts Replaced, Timing Seal, Timing Bearing, Fan Belt, Water Pump, Oil Pump, Front Lower Arm, All Comes With Receipts. Call/Sms Us To Arrange For A Viewing.	Sporty Looking Mitsubishi Lancer In Full Black Out And In Excellent Condition! Ideal Manual Daily Driving 4 Door Saloon For The Road! 6 Months Warranty And 1 Free Major Servicing! Witness First Hand For Yourself How We Perform Major Servicing At Our In House Workshop! Full Loan Available! Buy With Trust And Assurance! Come Down And Have A Look Today!	Fully Stocked, Tune By Well Known Tuner For Cs3 For Performance With Backfire. On Tomei Coil For Low Stance. Will Throw In Momo Steering With Evo 9 Boss Kit & Spare Head Lights, Pole Lights, Dome Lights. Sound System Upgrade For Better Bass And Voice. All Trade Ins Accepted. High Loan Up To 90% Available. 6 Owners Due To Transfer For Car Plates. 3 Owners Originally. Call/Whatsapp Now For Viewing.	Look No Further, B Money. Direct Own Lancer 1.6 A With Upholstery. Selling New Car. Original i Genuine Mileage A In And Up To 80% Miss, Must Call To Viewing This Unit 1
COE	\$22,789	\$22,789	\$22,789	\$25,821
OMV	\$13,430	\$11,958	\$12,397	\$12,706
ARF	\$14,773	\$13,154	\$13,637	\$13,977
Depreciation	\$8,000 /yr	\$6,670 /yr	\$8,090 /yr	\$7,930 /yr
No. of Owners	6	5	6	4
Type of Vehicle	Sedan	Sedan	Sedan	Sedan
Category	COE Car	COE Car	COE Car, Premium Ad Car	COE Car
Availability	Available	Available	Available	Available

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0017J
Vehicle Details	
Vehicle No.:	SGF1677B
Vehicle to be Exported:	Yes
Intended De-registration Date:	06 Aug 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 A
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	4G18HC5092
Chassis No.:	JMYSTCS3A6U007389
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$13,295.00
Original Registration Date:	03 Apr 2006
First Registration Date:	03 Apr 2006
Transfer Count:	1
Actual ARF Paid:	\$14,625.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	02 Apr 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$23,039.00
COE Rebate Amount:	\$12,238.00
Total Rebate Amount:	\$12,238.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 06 Aug 2018

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 0017J

Vehicle Details

Vehicle No.: SGF1677B
Vehicle to be Exported: No
Intended De-registration Date: 03 Aug 2018
Vehicle Make: MITSUBISHI
Vehicle Model: LANCER 1.6 A
Primary Colour: Black
Manufacturing Year: 2006
Engine No.: 4G18HC5092
Chassis No.: JMYSTCS3A6U007389
Maximum Power Output: 79.0 kW (105 bhp)
Open Market Value: \$13,295.00
Original Registration Date: 03 Apr 2006
First Registration Date: 03 Apr 2006
Transfer Count: 1
Actual ARF Paid: \$14,625.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 02 Apr 2021
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$23,039.00
COE Rebate Amount: \$12,275.00
Total Rebate Amount: \$12,275.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 03 Aug 2018.

OK

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

04/08/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Lon Pac
Ashes

Accident date: 03/07/2018

Estimated repair cost for vehicle no: SGF1677B MITSUBISHI LANCER 1.6 A '06

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Front R/H Door <i>Dented</i>		\$964.00 ✓
2	1	Front R/H Door Side Mirror Assy <i>Bent</i>		\$431.00 ✓
3	1	Front R/H Fender <i>Dented</i>		\$573.00 ✓
4	1	Front R/H Fender Signal Lamp <i>New</i>		\$79.00 ✓
5	1	Front R/H Fender Cowling <i>torn</i>		\$128.00 ✓
6	10	Front R/H Fender Cowling Clip <i>n</i>	\$6.50	\$65.00 30
7	1	Front R/H Head Lamp <i>Cracked</i>		\$652.00 ✓
8	1	Front Grille		\$146.00 +
9	2	Front Grille Cover	\$91.00	\$182.00 +
10	1	Front Grille Emblem Logo		\$38.00 +
11	8	Front Grille Clip	\$6.50	\$52.00 +
12	1	Front Bumper <i>Dented</i>		\$638.00 ✓
13	10	Front Bumper Clip <i>n</i>	\$6.50	\$65.00 30
14	2	Front Bumper Side Retainer <i>RH bent</i>	\$38.00	\$76.00 38
15	14	Front Bumper Side Retainer Rivet <i>n</i>	\$3.50	\$49.00 30
16	1	Front Bumper Lower Spoiler <i>New n</i>		\$680.00 +
17	2	Front Bumper Fog Lamp <i>New n</i>	\$377.00	\$754.00 +
18	2	Front Bumper Fog Lamp Cover <i>Cracked RH</i>	\$65.00	\$130.00 65
19	1	Front Bumper Number Plate		\$50.00 +
20	1	Front Bumper Number Plate Garnish		\$58.00 +
21	1	Front Bumper Centre Inner Cover		\$132.00 +
22	1	Front Bumper Reinforcement <i>Bent</i>		\$186.00 ✓
23	1	Front Support Panel <i>Reis</i>		\$893.00 +
24	1	Front Air-Con Condenser		\$937.00 +
25	1	Front Radiator		\$1,161.00 +
26	1	Front Wiper Tank		\$104.00 +
27	1	Front R/H Rim		\$650.00 +
28	1	Front R/H Tyre		\$350.00 +

29	1	Front R/H Lower Arm	2	\$292.00	+
30	1	Front R/H Shock Absorber		\$387.00	+
31	1	Front R/H Knuckle Arm	Ac u	\$358.00	+
32	1	Front R/H Knuckle Arm Bearing		\$259.00	+
33	1	Front Steering Rack		\$1,833.00	+

3165

Subtotal:- \$13,352.00

3388.50

Labour charges

To remove & refit front R/H door, lock, gear motor, glass trim board \$180.00 80

To remove & refit front R/H undercarriage & steering rack \$550.00 +

To remove & refit air-con condenser, radiator, fan motor & top up gas \$450.00 120

To check wheel alignment \$150.00 +

Tuff kote \$150.00 +

To check wiring \$100.00 30

Panel beating \$1,600.00 700

Spray painting \$1,600.00 900

Towing

60 ✓

Subtotal:- \$4,780.00

Total:- \$18,132.00

Adrian Lij

h/s 08/08/18

OS Amp

total 5278.50

h/s 42K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC6/LPC18014398/Aea3n2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 04-12-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 5597C	Veh. Inspected	SGF 1677B
Policy No.	Z18VC05000137	Coverage (\$)	0.00
Claim No.	18/18/18/VC05/020814	Excess (\$)	0.00
Assign From		Assign Date	06/08/2018

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI LANCER	c.c	1584
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JMYSTCS3A6U007389	Colour	BLACK
Odometer	217924	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	KUMHO	6 mm
L/H Front Tyre	195/55 R15	KUMHO	6 mm
R/H Rear Tyre	195/55 R15	KUMHO	6 mm
L/H Rear Tyre	195/55 R15	KUMHO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/08/2018	Inspection Date	06/08/2018
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGF 1677B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT R/H DOOR	DENTED	964.00	964.00
1	FRONT R/H DOOR SIDE MIRROR ASSY	DAMAGED	431.00	431.00
1	FRONT R/H FENDER	DENTED	573.00	573.00
1	FRONT R/H FENDER SIGNAL LAMP	NOT NECESSARY	79.00	-
1	FRONT R/H FENDER COWLING	TORN	128.00	128.00
10	FRONT R/H FENDER COWLING CLIP @\$6.50	NECESSARY	65.00	30.00
1	FRONT R/H HEAD LAMP	CRACKED	652.00	652.00
1	FRONT GRILLE	NOT NECESSARY	146.00	-
2	FRONT GRILLE COVER @\$91.00	NOT NECESSARY	182.00	-
1	FRONT GRILLE EMBLEM LOGO	NOT NECESSARY	38.00	-
8	FRONT GRILLE CLIP @\$6.50	NOT NECESSARY	52.00	-
1	FRONT BUMPER	DEFORMED	638.00	638.00
10	FRONT BUMPER CLIP @\$6.50	NECESSARY	65.00	30.00
2	FRONT BUMPER SIDE RETAINER @\$38.00	O/S BENT	76.00	38.00
14	FRONT BUMPER SIDE RETAINER RIVET @\$3.50	NECESSARY	49.00	30.00
1	FRONT BUMPER LOWER SPOILER	NOT NECESSARY	680.00	-
2	FRONT BUMPER FOG LAMP @\$377.00	NOT NECESSARY	754.00	-
2	FRONT BUMPER FOG LAMP COVER @\$65.00	O/S CRACKED	130.00	65.00
1	FRONT BUMPER NUMBER PLATE	NOT NECESSARY	50.00	-
1	FRONT BUMPER NUMBER PLATE GARNISH	NOT NECESSARY	58.00	-
1	FRONT BUMPER CENTRE INNER COVER	NOT NECESSARY	132.00	-
1	FRONT BUMPER REINFORCEMENT	BENT	186.00	186.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	893.00	-
1	FRONT AIR-CON CONDENSER	NOT NECESSARY	937.00	-
1	FRONT RADIATOR	NOT NECESSARY	1,161.00	-
1	FRONT WIPER TANK	NOT NECESSARY	104.00	-
1	FRONT R/H RIM	NOT NECESSARY	650.00	-
1	FRONT R/H TYRE	NOT NECESSARY	350.00	-
1	FRONT R/H LOWER ARM	NOT NECESSARY	292.00	-
1	FRONT R/H SHOCK ABSORBER	NOT NECESSARY	387.00	-

Report Ref No. CC6/LPC18014398/Aea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT R/H KNUCKLE ARM	NOT NECESSARY	358.00	-
1	FRONT R/H KNUCKLE ARM BEARING	NOT NECESSARY	259.00	-
1	FRONT STEERING RACK	NOT NECESSARY	1,833.00	-
	LESS 10% DISCOUNT		-	-376.50
			13,352.00	3,388.50
	LABOUR			
	TO REMOVE & REFIT FRONT R/H DOOR, LOCK, GEAR MOTOR, GLASS TRIM BOARD.		180.00	80.00
	TO REMOVE & REFIT FRONT R/H UNDERCARRIAGE & STEERING RACK.	NOT NECESSARY	550.00	-
	TO REMOVE & REFIT AIR-CON CONDENSER, RADIATOR, FAN MOTOR & TOP UP GAS.		450.00	120.00
	TO CHECK WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
	TUFF KOTE.	NOT NECESSARY	150.00	-
	TO CHECK WIRING.		100.00	30.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		1,600.00	700.00
	SPRAY PAINTING.		1,600.00	900.00
	TOWING.		60.00	60.00
			4,840.00	1,890.00
	GRAND TOTAL		18,192.00	5,278.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,200.00

Report Ref No. CC6/LPC18014398/Aea3n2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.