

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

13 AUG 2018 @ 09:30am
Lavita: 68411972
Guo Qiang: 82880282
13 AUG 2018 @ 9:30am
08 AUG 2018 @ 15:25pm

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SKV9141X
Chassis No : MRHGM6660GP000300
Model : CITY 1.5SV CVT 2016
Owner's Name : LEE SIAU PENG
Ins Policy No. : SI17V15087/VPC/R02
Date of Accident : 2/8/2018

Document No. : SQT18003226
Date : 2. Aug 2018
Customer No. : WZI007
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15Z12714576
Date | Time : 2. Aug 2018 2:36:55 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: LEE SIAU PENG OWNER INSURER: LIBERTY INSURANCE PTE LTD ACCIDENT DATE: 02/08/2018@12.05PM SURVEYED BY: Marcus Chua @ 1ktauto.com REF NO: TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD TP VEH: SHC1204L (HYUNDAI/SONATA/BLEU/TAXI)						
91505-TM8-003	CLIPBUMPER <i>neu</i>	10	2.00	25	15.00	1.05	16.05
71593-T9A-J00	SPACER R.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-T9A-J00	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71501-T9A-T00ZZ	FACERR.BUMPER <i>TD</i>	1	463.70	25	347.77	24.34	372.11
					Sum Item	380.01	26.59
							406.60
BOSUN	SUNDRIES <i>neu</i>	1	60.00	20	60.00	4.20	64.20
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	80	180.00	12.60	192.60
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	240.00	130	240.00	16.80	256.80
BKBU02R	REMOVE & RENEW RR BUMPER & STRAIGHTEN RR PANEL	1	1120.00	560	1120.00	78.40	1198.40
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1350.00	900	1350.00	94.50	1444.50
					Sum Labor	2950.00	206.50
							3,156.50

Survey By

Date & Time

Excess

Status

Signature

*marcus chua**13/8/18**not authorized**take photo before painting.
3 day.*

Total Amount	3,330.01	233.09	3,563.10
LKK Auto Consultants hence notify the Repairer the following:			
Total (Inclusive of GST) 3,563.10			
• To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
Acknowledged by Repairer			
Signature:			
Date:			



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SKV9141X
Chassis No : MRHGM6660GP000300
Model : CITY 1.5SV CVT 2016
Owner's Name : LEE SIAU PENG
Ins Policy No. : SI17V15087/VPC/R02
Date of Accident : 2/8/2018

Document No. : SQT18003226 Page 2
Date : 2. Aug 2018
Customer No. : WZI007
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15Z12714576
Date | Time : 2. Aug 2018 2:36:55 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
------	-------------	-----	------------	--------	--------	---------------	------------------

Printed on 4/8/2018 8:45:14 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)