

CS3/LPC18011723/G103-1

GR
Ong Li Li

ASSIGNMENT (OFFICE)

LPC

07/08/2018

OD (IP) WS/CPRES/ODRES/EVA/ESA/MSV/CS

Technology Vehicle Inc

SKR 48202

SJL 3088X

Work Log no

LSM Lynston Motor

9438 9828

4

25 Kaki Bukit Rd 4 #05-66 /68

Policy no

Claim No: 1711818/vpos/020704

Condition of

Make of Veh

to Rent's Record

CA / REV / REP / REV 24 HRS

lup

25/06/2018
In after 12pm

Date/Time 8:55am @ 27/6/18

Person Contacted

Daphne

to CD Endorsement

IN (initial)

Date/Time

Assignment (X) Estimate

SKR 48202

SJL 3088X-LSM 11/11/2015/17/CPB

DVA 13/2/2013

Submit PRS Report

\$2850, 5 Days. Cred: 1954.80 (40%)



DVA File pass to typist.

RECEIVED 27 SEP 2018

ASS. REC. BY: PRS
XKL

REF: LPC

ASSIGNMENT

From: Date: 27/6/18

Estimated Cost:

OP: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKR 4820Z
at Workshop m/s LSM Lynston Motor
of 25 Kaki Bukit Rd 4 #05-66/68 Synergy

Insured:

Policy No.

Claims No.

Sum Insured

Excess:

(Client's Record)

Make of Veh:

Daphne @ 9438 9828
after 12pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1 up}

Date:

Person Contacted

Vehicle: IN / OUT

Veh No: SKR4820Z Yr Regn: - /

Type: ☒ M.Cas / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Golf c.c. -

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 113294

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WUWZZZ AU 8FW 171382

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205 / 55 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

27-06-18

Survey held at

w/s

2:30 pm

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$ 4000 - \$ 5000

RECEIVED 17 JUL 2018

Date/Time: File Pass to?

☐

: Preli. Report

1) AA Typist

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair: ☒

Resurvey No. of Trip: ☒

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

TP-PRS

Lump Sum / I.B.I. (\$

Survey Fee:

490

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

490

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 7 August 2018 5:31 PM
To: Nivitha (LKK Auto); ASSIGNMENTS@LKKAUTO.COM
Cc: MT_Claim_SG; sur@lkkauto.com
Subject: ACCIDENT ON 25 JUNE 2018 INVOLVING MOTOR VEHICLES NO(S). SKR4820Z AND SJL3088X AT ALONG AYE TOWARDS CTE FROM PORTSDOWN AVENUE [Our ref: AP/2018/000054] Lonpac Ref:17/18/18/VP05/020704
Attachments: 20704 TP survey report.pdf

Dear Nivitha

Attached is the TP survey report.

Please let us have your surveyor's review and report.

Thanks,
Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 27 June, 2018 9:38 AM
To: ERIC WOO JUN KIAT; ASSIGNMENTS@LKKAUTO.COM
Cc: MT_Claim_SG; ONG LI LI; sur@lkkauto.com
Subject: RE: PROPERTY DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 25 JUNE 2018 AT ABOUT 10:30HRS INVOLVING MOTOR VEHICLES NO(S). SKR4820Z AND SJL3088X AT ALONG AYE TOWARDS CTE FROM PORTSDOWN AVENUE [Our ref: AP/2018/000054] Lonpac Ref:17/18/18/VP05/020704

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ERIC WOO JUN KIAT [mailto:ericwoo@lonpac.com]
Sent: Tuesday, 26 June 2018 12:58 PM
To: Charles Hoon <charles@apl.com.sg>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; assignments@lkkauto.com
Subject: RE: PROPERTY DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 25 JUNE 2018 AT ABOUT 10:30HRS INVOLVING MOTOR VEHICLES NO(S). SKR4820Z AND SJL3088X AT ALONG AYE TOWARDS CTE FROM PORTSDOWN AVENUE [Our ref: AP/2018/000054] Lonpac Ref:17/18/18/VP05/020704

Dear Charles,

Thank you for your list of surveyors.

We regret we are not agreeable to your panel of surveyor as listed.

We shall be assigning to LKK Auto Consultants Pte Ltd to conduct the survey on your client's vehicle No: SKR 4820Z.

Kindly advise the workshop to conduct survey.

Dear Catherine / Nivitha,

FYA.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

From: Charles Hoon [mailto:charles@aplp.com.sg]

Sent: Tuesday, 26 June, 2018 12:04 PM

To: ERIC WOO JUN KIAT

Cc: MT_Claim_SG

Subject: RE: PROPERTY DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 25 JUNE 2018 AT ABOUT 10:30HRS INVOLVING MOTOR VEHICLES NO(S). SKR4820Z AND SJL3088X AT ALONG AYE TOWARDS CTE FROM PORTSDOWN AVENUE [Our ref: AP/2018/000054] Lonpac Ref:17/18/18/VP05/020704

Dear Eric,

Please find attached, our letter of even date.

Regards,

Charles Hoon

AP Law Practice

9 Temasek Boulevard #09-01 Suntec Tower 2 Singapore 038989

T: 64071429 F: 64071427 E: charles@aplp.com.sg

Singapore UEN No.: 53380739E

This email transmission is confidential and intended only for the addresses(s). It may contain information which is privileged as between solicitor and client or protected by litigation privilege. If you are not the intended recipient, please delete this message and all attachments and inform us by return email. No part of this message should be disclosed to any party, copied or used for any purpose. Thank you for your co-operation.

From: ERIC WOO JUN KIAT <ericwoo@lonpac.com>

Sent: Tuesday, 26 June 2018 11:54 AM

To: Charles Hoon <charles@aplp.com.sg>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: RE: PROPERTY DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 25 JUNE 2018 AT ABOUT 10:30HRS INVOLVING MOTOR VEHICLES NO(S). SKR4820Z AND SJL3088X AT ALONG AYE TOWARDS CTE FROM PORTSDOWN AVENUE [Our ref: AP/2018/000054] Lonpac Ref:17/18/18/VP05/020704

Dear Charles,

We will proceed to conduct a pre-repair survey of the damage to your client's vehicle jointly with your workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert. (Please see attached).

Please let us know within 2 working days whether you are agreeable to the appointment of any of the motor surveyors provided to you as a single joint expert. You may select one of the listed motor surveyors.

Kindly advise the workshop to conduct survey.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767

From: CHEW BENG KEE

Sent: Tuesday, 26 June, 2018 9:50 AM

To: MT_Claim_SG; 'charles@aplp.com.sg'

Subject: FW: PROPERTY DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 25 JUNE 2018 AT ABOUT 10:30HRS INVOLVING MOTOR VEHICLES NO(S). SKR4820Z AND SJL3088X AT ALONG AYE TOWARDS CTE FROM PORTSDOWN AVENUE [Our ref: AP/2018/000054] [your ref: to be advised]

Dear Charles

One of our officers will revert to you in due course. Eric, pls assist on the PRI.
Thank you.

Best Regards

Chew Beng Kee

Head of Claims | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext. 246 | Fax: (65) 6296 2706

From: Charles Hoon [<mailto:charles@aplp.com.sg>]

Sent: Monday, June 25, 2018 7:00 PM

To: CHEW BENG KEE

Subject: PROPERTY DAMAGE CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 25 JUNE 2018 AT ABOUT 10:30HRS INVOLVING MOTOR VEHICLES NO(S). SKR4820Z AND SJL3088X AT ALONG AYE TOWARDS CTE FROM PORTSDOWN AVENUE [Our ref: AP/2018/000054] [your ref: to be advised]

Attn: Motor Claim Department

Dear Sirs,

We refer to the above matter.

Please find attached, our letter of even date.

Regards,

Charles Hoon

AP Law Practice

9 Temasek Boulevard #09-01 Suntec Tower 2 Singapore 038989

T: 64071429 F: 64071427 E: charles@aplp.com.sg
Singapore UEN No.: 53380739E

This email transmission is confidential and intended only for the addressee(s). It may contain information which is privileged as between solicitor and client or protected by litigation privilege. If you are not the intended recipient, please delete this message and all attachments and inform us by return email. No part of this message should be disclosed to any party, copied or used for any purpose. Thank you for your co-operation.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0720618

Date of Report : 07/07/2018

To : Mr Tan Bao An, Kelvin
C/o. 50 Playfair Road
#05-04
Singapore 367995

Date of Assignment : 27/06/2018
Report requested by : Mr Tan Bao An, Kelvin
Date of Accident : 25/06/2018
Date of Inspection : 27/06/2018
Claim No. : Third Party Claim
Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SKR4820Z
Make & Model : Volkswagen Golf (A)
Date of Registration : 11/02/2015
Colour : Met. Blue

Engine Capacity (cc) : 1197cc
Mileage (km) : 113294km
Chassis / Frame No. : WVVZZZAUZFW171382
Engine No. : CJZ580292

TYRE CONDITION

Front LH : 7 mm
Make : Pirelli

Front RH : 7 mm
Make : Pirelli

Rear LH : 7 mm
Make : Pirelli

Rear RH : 7 mm
Make : Pirelli

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Isafe Garage
50, Playfair Road, Noel Building, #05-04, Singapore 367995

ASSESSMENT

Repairer's Estimate : \$ 5,446.30
Revised Amount : \$ 4,804.80
Less Excess : \$ -
Recommended Reserve : \$ 3,850.00 (Lump Sum)

Estimated Normal Period of Repairs : 6 Working Days

Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St 3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg 201404434D

Vehicle No : SKR4820Z

Report No. : PAS/TP/0720618

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Isafe Garage, 25, Kaki Bukit Road 4, Synergy@KB, #05-66/67/68, Singapore 417800.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the rear LH portion.

DAMAGES

The tailgate, rear bumper, rear end panel, rear floor panel, LHR chassis member, LHR fender, rear exhaust silencer, LH taillamp, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$4,804.80.

CONCLUSION


The repairer has agreed to undertake the repairs at a lump sum of SGD \$3,850.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,
Prominent Appraiser Services Pte Ltd


Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

Vehicle No. : SKR4820Z

Report No. : PAS/TP/0720618

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	1 pc	Taillamp LH	Cracked/Loop Broken	\$ 387.00	\$ 387.00
2	1 pc	Rr bumper	Dented	\$ 942.00	\$ 942.00
3	1 pc	Rr bumper reflector LH	Cracked/Broken	\$ 82.00	\$ 82.00
4	1 pc	Rr bumper lower cover	Dented/Cracked	\$ 289.00	\$ 289.00
5	6 pcs	Rr bumper clip	Necessary	\$ 12.00	\$ 12.00
6	2 pcs	Rr bumper retainer R/L	Cracked/Necessary	\$ 92.00	\$ 92.00
7	1 pc	Rr bumper center guide	Dented/Cracked	\$ 81.00	\$ 81.00
8	1 pc	Rr bumper reinforcement	Dented	\$ 483.00	\$ 483.00
9	1 pc	Rr end panel	Dented/Distorted	\$ 604.00	\$ X 604.00 <i>Repair</i>
10	1 pc	Rr end panel garnish	Refit	\$ 135.00	\$ -
11	1 pc	Tailgate	Dented/Repair		(Refer labour no. 5 & 6)
12	1 pc	Rr fender LH	Dented/Repair		(Refer labour no. 2, 5 & 6)
13	1 pc	Exhaust silencer	Dented/Repair		(Refer labour no. 4)
				\$ 3,107.00	\$ 2,972.00 <i>2368</i>
Less Discount : 10%				\$ 310.70	10% \$ 297.20
List Parts Sub-Total :				\$ 2,796.30	\$ 2,674.80 <i>231.</i>
1	1 pc	Rr reverse sensor	Dented/Damaged	\$ 220.00	\$ 220.00
2	1 pc	Rr end panel sealant	Necessary	\$ 40.00	\$ X 40.00 <i>nn</i>
Special Nett Sub-Total :				\$ 260.00	\$ 260.00
Parts Total :				\$ 3,056.30	\$ 2,934.80

2351.2



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simel St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SKR4820Z

Report No. : PAS/TP/0720618

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To check rear electrical wiring system.	\$ 50.00	\$ 30.00 ✓
2	To remove and reinstall rear interior trims, garnishes, etc. for necessary repairs.	\$ 120.00	\$ 100.00 60
3	To remove, replace and reinstall rear reverse sensors & control unit.	\$ 60.00	\$ 50.00 40
4	To straighten, repair and realign rear exhaust silencer.	\$ 80.00	\$ X 60.00 nn
5	To straighten, repair, realign on affected area and replace damaged parts.	\$ 1,000.00	\$ 770.00 500
6	To spray painting, blending on affected and adjacent area.	\$ 1,000.00	\$ 800.00 600
7	To spray anti-rust coating on new and affected panels.	\$ 80.00	\$ X 60.00 nn
Labour Total :		\$ 2,390.00	\$ 1,870.00
Total (Parts & Labour) :		\$ 5,446.30	\$ 4,804.80

1230

3581.2

24%: 2850

5 Days.

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 3,850.00

Under normal circumstances, the repairs should be completed within a reasonable period of 6 Working Days. (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

64 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS3/LPC18011723/Gtd3e2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 28-09-2018	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJL 3088X	Veh. Inspected	SKR 4820Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	17/18/18/VP05/020704	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	07/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN GOLF	c.c	1197	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WWZZZAUZFW171382	Colour	BLUE	
Odometer	113294	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	PIRELLI	6 mm	
L/H Front Tyre	205/55 R16	PIRELLI	6 mm	
R/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
L/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/06/2018	Inspection Date	27/06/2018	
Survey held at	LYNSTON MOTORWORKS 25 KAKI BUKIT ROAD 4 #08-43 SYNERGY @KB 417800 SINGAPORE			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 4820Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILLAMP LH	CRACKED / LOOP BROKEN	387.00	387.00
1	RR BUMPER	DENTED	942.00	942.00
1	RR BUMPER REFLECTOR LH	CRACKED / BROKEN	82.00	82.00
1	RR BUMPER LOWER COVER	DENTED / CRACKED	289.00	289.00
6	RR BUMPER CLIP @\$2.00	NECESSARY	12.00	12.00
2	RR BUMPER RETAINER R/L @\$46.00	CRACKED / NECESSARY	92.00	92.00
1	RR BUMPER CENTER GUIDE	DENTED / CRACKED	81.00	81.00
1	RR BUMPER REINFORCEMENT	DENTED	483.00	483.00
1	RR END PANEL	TO REPAIR SEE LABOUR	604.00	-
1	RR END PANEL GARNISH	REFIT	135.00	-
1	TAILGATE (NPA)	TO REPAIR SEE LABOUR	-	-
1	RR FENDER LH (NPA)	TO REPAIR SEE LABOUR	-	-
1	EXHAUST SILENCER(NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 10% DISCOUNT		-310.70	-236.80
			2,796.30	2,131.20
<u>SPECIAL NETT ITEMS</u>				
1	RR REVERSE SENSOR (SN)	DENTED / DAMAGED	220.00	220.00
1	RR END PANEL SEALANT (SN)	NOT NECESSARY	40.00	-
			260.00	220.00
<u>LABOUR</u>				
	TO CHECK REAR ELECTRICAL WIRING SYSTEM.		50.00	30.00
	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, ETC, FOR NECESSARY REPAIRS.		120.00	60.00

Report Ref No. CS3/LPC18011723/Gtd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REPLACE AND REINSTALL REAR REVERSE SENSORS & CONTROL UNIT.		60.00	40.00
	TO STRAIGHTEN, REPAIR AND REALIGN REAR EXHAUST SILENCER.	NOT NECESSARY	80.00	-
	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF RR END PANEL, TAILGATE, RR FENDER LH AND EXHAUST SILENCER.		1,000.00	500.00
	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA.		1,000.00	600.00
	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.	NOT NECESSARY	80.00	-
			2,390.00	1,230.00
GRAND TOTAL			5,446.30	3,581.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,850.00

Report Ref No. CS3/LPC18011723/Gtd3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.