



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA

Our ref: CC6/EQI18014406/Uha3

Date: 10.08.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

FBM 4745R

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 08.08.2018 at the premises of M/s Ban Hock Hin Co. Pte Ltd - Defu Lane and have the following to report:-

Workshop Estimate Amount	: S\$	<u>2,153.00</u>
Revised Estimate Amount	: S\$	<u>1,191.00</u>
"Check" Items Amount	: S\$	<u>-</u>
Total (Including Check Items)	: S\$	<u>1,191.00</u>
Market Value	: S\$	<u>-</u>
LTA Reimbursement Value	: S\$	<u>-</u>
Nett Value	: S\$	<u>-</u>

Description of Damage:

The vehicle sustained damages at the Rear and N/S Body



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4.0 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser



QUOTATION

NO. : 32852

Customer:

EQ INSURANCE COMPANY LIMITED
22 GEMMILL LANE
SINGAPORE 069257

MOTOR CLAIMS DEPT

VEHICLE NO : FBM4745R
MAKE/MODEL : YAM / YBR125

*not about
2 car
taken into other
report
H.H.
8/8/18*

DATE : 06/08/2018
CLAIM NO : 11169
POLICY NO : AVFMSB0000591803
FROM : RAYMOND

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price		Amount
1	ALIGNMENT BODY P/N 29561	REPLACE	1.00	\$350.00	nt	350.00 X
2	COVER TAIL LH (BLACK) P/N 50952	REPLACE	1.00	\$85.00	2	85.00 X
3	CRASH BAR P/N 35878	REPLACE	1.00	\$195.00	100	195.00
4	FOOT REST 1 P/N 50005	REPLACE	1.00	\$55.00	7.00	55.00
5	HEADLIGHT ASSY P/N 50950	REPLACE	1.00	\$490.00	scr	490.00
6	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING PARTS QUOTED	Supply/Install	3.00	\$35.00	100	105.00
7	LAMP SIGNAL REAR LH P/N 44858	REPLACE	1.00	\$63.00	3.00	63.00
8	LEVER CLUTCH P/N 52644	REPLACE	1.00	\$15.00	scr	15.00 X
9	MIRROR LH P/N 49947	REPLACE	1.00	\$80.00	scr	80.00 X
10	PROTECTOR EXHAUST CAP P/N: 50006	REPLACE	1.00	\$56.00	one	56.00
11	REPAIR FUEL TANK P/N: 34839	Repair	1.00	\$154.00	work	154.00 X
12	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	2.00	\$14.00	7.00	28.00
13	SPRAY PAINT FRONT COWLING	Spray	1.00	\$63.00	scr	63.00

L Respy 45



S/N	Description	Action	Qty	Unit Price	Amount
14	SPRAY PAINT FRONT MUDGUARD	Spray	1.00	\$45.00	45.00
15	SPRAY PAINT LH SIDE COVER	Spray	1.00	\$40.00	40.00
16	SPRAY PAINTING FUEL TANK	Spray	1.00	\$154.00	154.00
17	STICKER (MCDONALDS) ACCIDENTAL P/N: 57420	REPLACE	1.00	\$28.00	28.00
18	STICKER (MCDONALDS) SIDE COVER V2 P/N: 56222	REPLACE	1.00	\$16.00	16.00
19	STICKER (MCDONALDS) WINDSHIELD V2 P/N: 56223	REPLACE	1.00	\$16.00	16.00
20	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$12.00	12.00
21	TRANSPORT CHARGES-DELIVERY / COLLECTION P/N: 41525		1.00	\$35.00	35.00
22	VISOR P/N: 42004	REPLACE	1.00	\$68.00	68.00

SUB TOTAL \$2,153.00
 GST @ 7% \$150.71
GRAND TOTAL \$2,303.71

Validity 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

P-887
 7983

1102.30

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal indemnity is allowed
- Supplementary claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer
 Signature:
 Date:





QUOTATION

Customer :

NO. : 32852 - Rev. 1

EQ INSURANCE COMPANY LIMITED
22 GEMMILL LANE
SINGAPORE 069257

DATE : 06/08/2018
CLAIM NO. : 11169
POLICY NO. : AVFMSB0000591803

MOTOR CLAIMS DEPT

FROM : RAYMOND

VEHICLE NO. : FBM4745R
MAKE/MODEL : YAM / YBR125

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	CRASH BAR P/N: 35878	REPLACE	1.00	\$195.00 Disc %: 10.00	175.50
2	FOOT REST 1 P/N: 50005	REPLACE	1.00	\$55.00 Disc %: 10.00	49.50
3	HEADLIGHT ASSY P/N: 50950	REPLACE	1.00	\$490.00 Disc %: 10.00	441.00
4	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING PARTS QUOTED.	Supply/Install	1.00	\$100.00	100.00
5	LAMP SIGNAL REAR LH P/N: 44858	REPLACE	1.00	\$63.00 Disc %: 10.00	56.70
6	PROTECTOR EXHAUST CAP P/N: 50006	REPLACE	1.00	\$56.00 Disc %: 10.00	50.40
7	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	2.00	\$14.00 Disc %: 10.00	25.20
8	SPRAY PAINT FRONT COWLING	Spray	1.00	\$45.00	45.00
9	SPRAY PAINT FRONT MUDGUARD	Spray	1.00	\$40.00	40.00
10	SPRAY PAINT LH SIDE COVER	Spray	1.00	\$40.00	40.00
11	STICKER (MCDONALDS) ACCIDENTAL P/N: 57420	REPLACE	1.00	\$28.00	28.00
12	STICKER (MCDONALDS) SIDE COVER V2 P/N: 56222	REPLACE	1.00	\$16.00	16.00
13	TRANSPORT CHARGES-DELIVERY / COLLECTION P/N: 41525		1.00	\$35.00	35.00



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
		SUB TOTAL			\$1,102.30
		GST @ 7 %			\$77.16
		GRAND TOTAL			\$1,179.46

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.





QUOTATION

Customer :

EQ INSURANCE COMPANY LIMITED
22 GEMMILL LANE
SINGAPORE 069257

MOTOR CLAIMS DEPT

VEHICLE NO. : FBM4745R
MAKE/MODEL : YAM / YBR125

*not about
2 hrs
take photo after
repair
H.H.
8/8/18*

NO. : 32852

DATE : 06/08/2018
CLAIM NO. : 11169
POLICY NO. : AVFMSB0000591803
FROM : RAYMOND

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price		Amount
1	ALIGNMENT BODY P/N: 29561	REPLACE	1.00	\$350.00	1.00	350.00 X
2	COVER TAIL LH (BLACK) P/N: 50952	REPLACE	1.00	\$85.00	1.00	85.00 X
3	CRASH BAR P/N: 35878	REPLACE	1.00	\$195.00	1.00	195.00
4	FOOT REST 1 P/N: 50005	REPLACE	1.00	\$55.00	1.00	55.00
5	HEADLIGHT ASSY P/N: 50950	REPLACE	1.00	\$490.00	1.00	490.00
6	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING PARTS QUOTED.	Supply/Install	3.00	\$35.00	100	105.00
7	LAMP SIGNAL REAR LH P/N: 44858	REPLACE	1.00	\$63.00	3.00	63.00
8	LEVER CLUTCH P/N: 52644	REPLACE	1.00	\$15.00	5.00	15.00 X
9	MIRROR LH P/N: 49947	REPLACE	1.00	\$80.00	5.00	80.00 X
10	PROTECTOR EXHAUST CAP P/N: 50006	REPLACE	1.00	\$56.00	1.00	56.00
11	REPAIR FUEL TANK P/N: 34839	Repair	1.00	\$154.00	1.00	154.00 X
12	RUBBER FOOTREST FRONT P/N: 28136	REPLACE	2.00	\$14.00	2.00	28.00
13	SPRAY PAINT FRONT COWLING	Spray	1.00	\$63.00	1.00	63.00

L Respy 45



S/N	Description	Action	Qty	Unit Price	Amount
14	SPRAY PAINT FRONT MUDGUARD	Spray	1.00	\$45.00	45.00 <i>SCN</i>
15	SPRAY PAINT LH SIDE COVER	Spray	1.00	\$40.00	40.00 <i>SCN</i>
16	SPRAY PAINTING FUEL TANK	Spray	1.00	\$154.00	154.00 <i>SCN</i> <i>Local respray 40</i> <i>L spray</i> <i>17</i> <i>X</i>
17	STICKER (MCDONALDS) ACCIDENTAL P/N: 57420	REPLACE	1.00	\$28.00	28.00 <i>SCN</i>
18	STICKER (MCDONALDS) SIDE COVER V2 P/N: 56222	REPLACE	1.00	\$16.00	16.00 <i>SCN</i>
19	STICKER (MCDONALDS) WINDSHIELD V2 P/N: 56223	REPLACE	1.00	\$16.00	16.00 <i>17</i> <i>X</i>
20	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$12.00	12.00 <i>17</i> <i>X</i>
21	TRANSPORT CHARGES-DELIVERY / COLLECTION P/N: 41525		1.00	\$35.00	35.00
22	VISOR P/N: 42004	REPLACE	1.00	\$68.00	68.00 <i>17</i> <i>X</i>
SUB TOTAL					\$2,153.00
GST @ 7 %					\$150.71
GRAND TOTAL					\$2,303.71

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



CERTIFICATE OF INSURANCE

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP 189) OF THE REPUBLIC OF SINGAPORE
THE ROAD TRANSPORT ACT 1967 OF MALAYSIA

THE AGREEMENT BETWEEN THE MINISTER FOR FINANCE (SINGAPORE) AND THE MOTOR INSURERS' BUREAU OF SINGAPORE DATED 21 FEBRUARY 1975
THE AGREEMENT BETWEEN THE MINISTER OF TRANSPORT (MALAYSIA) AND THE MOTOR INSURERS' BUREAU OF WEST MALAYSIA DATED 15 JANUARY 1968
ANY SUBSEQUENT REVISIONS TO THE ABOVE ACTS AND AGREEMENTS

CERTIFICATE No. AVFMSB0000592702 CheNo: LBPRE101000059306

1. Index Mark and Registration Number of Vehicle FEM 4745 R
2. Name of Policyholder BAN HOCK HIN CO PTK LTD
3. Effective Date of Commencement of Insurance for the purposes of the Ordinance 21 November 2017
4. Date of Expiry of Insurance 20 November 2019

5. Persons or Classes of Persons entitled to drive* (For certificate references MX1 and MX4, see overleaf)

ANY PERSON WHO IS UNDER THE POLICYHOLDER &/OR HIRER'S EMPLOYMENT AND IS DRIVING ON THEIR ORDER OR WITH THEIR PERMISSION.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

6. Limitations as to Use* (For certificate reference MX1, see overleaf)

USE ONLY FOR THE POLICYHOLDER &/OR HIRER'S BUSINESS OR PROFESSION.

THE POLICY DOES NOT COVER:

1. USE FOR RACING, FACE-MAKING, RELIABILITY TRIAL OR SPEED-TESTING.
2. USE WHILST DRAWING A TRAILER EXCEPT THE TOWING (OTHER THAN FOR REWARD) OF ANY ONE DISABLED MECHANICALLY PROPELLED VEHICLE.
3. USE FOR THE CARRIAGE OF PASSENGERS FOR HIRE OR REWARD BY ANY PERSON TO WHOM THE VEHICLE IS HIRED.

Type of Cover : Third Party

* Limitations rendered inoperative by Section 79 of the Road Traffic Ordinance 1958 (Malaysia) or Section 7 of the Motor Vehicle (Third-Party Risks and Compensation) Ordinance 1960 (Republic of Singapore) are not to be included under the headings.

I/WE HEREBY CERTIFY that the policy to which this certificate relates is issued in accordance with the provisions of Part IV of the Road Transport Act 1967 (Malaysia) and The Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) (Republic of Singapore)

RT



Approved Insurers

Examined By

Handwritten signature

[> Back to OneMotoring](#)**Enquire Transfer Fee**

Vehicle Details			
Vehicle No. :	FBM4745R		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	YAMAHA		
Vehicle Model :	YBR125		
Chassis No. :	LBPRES101000059306		
Propellant :	Petrol		
Engine No. :	E3F5E044260		
Engine Capacity :	124 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	320 kg		
Unladen Weight :	114 kg		
Year Of Manufacture :	2017		
Original Registration Date :	14 Nov 2017		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$4,903.00		
COE Expiry Date :	13 Nov 2027		
Road Tax Expiry Date :	13 May 2019		
Inspection Due Date :	13 Nov 2020		
Intended Transfer Date :	08 Aug 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0288K
Vehicle Details	
Vehicle No.:	FBM4745R
Vehicle to be Exported:	No
Intended De-registration Date:	10 Aug 2018
Vehicle Make:	YAMAHA
Vehicle Model:	YBR125
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	E3F5E044260
Chassis No.:	LBPRES101000059306
Maximum Power Output:	-
Open Market Value:	\$1,859.00
Original Registration Date:	14 Nov 2017
First Registration Date:	14 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$279.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Nov 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$4,903.00
COE Rebate Amount:	\$4,539.00
Total Rebate Amount:	\$4,539.00

The information contained herein is correct as at 10 Aug 2018

OK

Mei Kwan (LKKAuto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Friday, 22 February, 2019 3:48 PM
To: Mei Kwan (LKKAuto)
Cc: Vic (LKKAuto); Hsiao Tong (LKKAuto); Admin A
Subject: RE: Direct Settlement - Accident Involving SLW8992X (OI : EQI - DM18HO02110/JT) AND FBM4745R (TP : LKK REF - CC6/EQI18014406/Uha3) on 30/07/2018
Attachments: 11169_LOD.PDF; SAS2478909.PDF
Categories: HMK

Dear Mei Kwan,

OI report and LOD as attached.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

A Member of Ciystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Tuesday, September 11, 2018 1:59 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Vic (LKKAuto) <vicalpeh@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving SLW8992X (OI : EQI - TBA) AND FBM4745R (TP : LKK REF - CC6/EQI18014406/Uha3) on 30/07/2018

Dear Janet,

We refer to the above matter.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Thank you.
Best Regards,
Mei Kwan | Admin

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report
- Photographs of TP vehicle in its damaged condition

Kindly let us have a copy of your insured's GIA report for our necessary action.

Please take note that the case handler in-charge Vic and he can be contacted at DID: 6841 2096.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 19700288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

17 AUG 2018

Your Ref :
Our Ref : TP/11169/FBM4745R/SLW8992X

BY EMAIL & HAND

EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110

ATTN: Motor Claims Dept

Dear Sir / Madam,

Accident Involving FBM4745R & SLW8992X on 30/07/2018

We refer to the above-mentioned matter.

As instructed by our client, we proceed to quantify our claim as itemized below:

1. Cost of Repair (Inc 7% GST)	\$1,179.46
2. Loss of Use (4 days x \$20)	\$ 80.00
3. LTA Vehicle Insurance Search Fee	\$ 7.45
TOTAL	<u>\$1,266.91</u>

We attached our Tax Invoice and LTA search for your perusal.

Please acknowledge receipt.

If you require any further clarification, please do not hesitate to contact Mr Raymond at 6281 6520 ext. 220.

Thank you.

BAN HOCK HIN CO PTE LTD

Raymond Tan
Manager/Insurance Dept



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
		SUB TOTAL			\$1,102.30
		GST @ 7 %			\$77.16
		GRAND TOTAL			\$1,179.46

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

 

Printed by : RAYMOND



> Back to OneMotoring

Land Transport Authority

Land Transport Authority
 10 Sin Ming Drive
 Singapore 575701
 GST Registration No. : M4-0006529-2

Print Date/Time : 07 Aug 2018 / 16:24:57

Receipt Date/Time : 07 Aug 2018 / 16:24:57

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180807-001629

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLW8992X As at 30 Jul 2018/21:00:00 Insurance Co: EQ INSURANCE COMPANY LTD				
1	Insurance Enquiry - SLW8992X Enquiry Fee 20180807162317728073	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20180807162346901	Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

[> Back to OneMotoring](#)

Land Transport Authority

Land Transport Authority
 10 Sin Ming Drive
 Singapore 575701
 GST Registration No. : M4-0006529-2

Print Date/Time : 07 Aug 2018 / 16:24:57

Receipt Date/Time : 07 Aug 2018 / 16:24:57

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180807-001629

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLW8992X As at 30 Jul 2018/21:00:00 Insurance Co: EQ INSURANCE COMPANY LTD				
1	Insurance Enquiry - SLW8992X Enquiry Fee 20180807162317728073	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20180807162346901	Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



h

17 AUG 2018

Your Ref :
Our Ref : TP/11169/FBM4745R/SLW8992X

BY EMAIL & HAND

EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110

ATTN: Motor Claims Dept

Dear Sir / Madam,

Accident Involving FBM4745R & SLW8992X on 30/07/2018

We refer to the above-mentioned matter.

As instructed by our client, we proceed to quantify our claim as itemized below:

1. Cost of Repair (Inc 7% GST)	\$1,179.46
2. Loss of Use (4 days x \$20)	\$ 80.00
3. LTA Vehicle Insurance Search Fee	\$ 7.45
TOTAL	<u>\$1,266.91</u>

We attached our Tax Invoice and LTA search for your perusal.

Please acknowledge receipt.

If you require any further clarification, please do not hesitate to contact Mr Raymond at 6281 6520 ext. 220.

Thank you.

BAN HOCK HIN CO PTE LTD

Raymond Tan
Manager/Insurance Dept





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/EQI18014406/Uha3

04 April 2019

ROSET LIMOUSINE SERVICES PTE LTD

53 UBI AVENUE 1, #03-47
PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934
Attn: The Management

Dear Sir/Madam,

ACCIDENT INVOLVING SLW8992X AND FBM 4745R ON 30/07/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from FBM 4745R against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHAN JIA LE
Case Handler
DID: 6749 5792
FAX: 6741 4108
EMAIL: vicalpeh@lkkauto.com

c.c. *EQ INSURANCE COMPANY LIMITED*
(Motor Claims Dept)



TAX INVOICE

Customer :
EQ INSURANCE COMPANY LIMITED
22 GEMMILL LANE
SINGAPORE 069257

GST Reg No. : M2-0010542-7

Invoice No. : **LECR20035927-I11169**
Invoice Date : 15/08/2018
Payment Due Date : 14/09/2018

MOTOR CLAIMS DEPT

CLAIM NO. : 11169
POLICY NO. : AVFMSB0000591803
VEHICLE NO. : FBM4745R
MAKE/MODEL : YAM / YBR125

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	TRANSPORT CHARGES-DELIVERY / COLLECTION		1	\$35.00	\$35.00
2	PROTECTOR EXHAUST CAP	REPLACE	1	\$56.00	\$50.40
				Disc %: 10%	
3	RUBBER FOOTREST FRONT	REPLACE	2	\$14.00	\$25.20
				Disc %: 10%	
4	STICKER (MCDONALDS) ACCIDENTAL	REPLACE	1	\$28.00	\$28.00
5	STICKER (MCDONALDS) SIDE COVER V2	REPLACE	1	\$16.00	\$16.00
6	SPRAY PAINT FRONT COWLING	Spray	1	\$45.00	\$45.00
7	SPRAY PAINT LH SIDE COVER	Spray	1	\$40.00	\$40.00
8	LABOUR	Supply/Install	1	\$100.00	\$100.00
9	SPRAY PAINT FRONT MUDGUARD	Spray	1	\$40.00	\$40.00
10	CRASH BAR	REPLACE	1	\$195.00	\$175.50
				Disc %: 10%	
11	FOOT REST 1	REPLACE	1	\$55.00	\$49.50
				Disc %: 10%	
12	HEADLIGHT ASSY	REPLACE	1	\$490.00	\$441.00
				Disc %: 10%	
13	LAMP SIGNAL REAR LH	REPLACE	1	\$63.00	\$56.70
				Disc %: 10%	

 



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
		SUB TOTAL			\$1,102.30
		GST @ 7 %			\$77.16
		GRAND TOTAL			\$1,179.46

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

 

Printed by : RAYMOND



[Back to OneMotoring](#)

Land Transport Authority

Land Transport Authority
 10 Sin Ming Drive
 Singapore 575701
 GST Registration No. : M4-0006529-2

Print Date/Time : 07 Aug 2018 / 16:24:57

Receipt Date/Time : 07 Aug 2018 / 16:24:57

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180807-001629

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLW8992X As at 30 Jul 2018/21:00:00 Insurance Co: EQ INSURANCE COMPANY LTD				
1	Insurance Enquiry - SLW8992X Enquiry Fee 20180807162317728073	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20180807162346901	Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



To : M/s EQ INSURANCE COMPANY LTD

Date: 18/04/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SLW 8992X (Insd Veh)	Your Ref. No. : DM18HO02110/JT
	FBM 4745R (TP Veh)	Our Ref. No. : CC6/EQ118014406/Uha3q2
Date of Accident	30/7/2018	

Liability	100%	
Final Repair Cost	: \$ 1,179.46	
Loss of Use	: \$ 80.00	4 days
Rental (If any)	: \$	days
Others:	: \$ 7.45	
	: \$	
	1,266.91	
Final Settlement Sum	: \$ 1,266.91	
Remarks	:	

<u>Payment Instruction: Payee's Breakdown</u>		
1)	BAN HOCK HIN CO. PTE LTD	: \$ 1,266.91
		: \$

JOANNE LEE
LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQ118014406/Uha3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 18-04-2019



Code : EQ1

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLW 8992X	Veh. Inspected	FBM 4745R
Policy No.	DMCFHQ17-000185	Coverage (\$)	0.00
Claim No.	DM18HO02110/JT	Excess (\$)	0.00
Assign From		Assign Date	08/08/2018

2. Vehicle Particulars & Condition

Make & Model	YAMAHA YBR125	c.c	124
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	LBPRES101000059308	Colour	BLACK
Odometer	24877	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	2.75-18	MICHELIN	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	2.75-18	MICHELIN	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY. DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/07/2018	Inspection Date	08/08/2018
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 4745R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	ALIGNMENT BODY	NOT NECESSARY	350.00	-
1	COVER TAIL LH (BLACK)	TO REPAIR SEE LABOUR	85.00	-
1	CRASH BAR	DENTED	195.00	195.00
1	FOOT REST 1	TORN	55.00	55.00
1	HEADLIGHT ASSY	SCRATCHED	490.00	490.00
1	LAMP SIGNAL REAR LH	BROKEN	63.00	63.00
1	LEVER CLUTCH	SERVICEABLE	15.00	-
1	MIRROR LH	SERVICEABLE	80.00	-
1	PROTECTOR EXHAUST CAP	CRACKED	56.00	56.00
1	REPAIR FUEL TANK (DENTED)	NOT CONSISTENT WITH THE IMPACT	154.00	-
2	RUBBER FOOTREST FRONT @\$14.00	TORN	28.00	28.00
1	STICKER (MCDONALDS) WINDSHIELD V2	NOT NECESSARY	16.00	-
1	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT	NOT NECESSARY	12.00	-
1	VISOR	NOT NECESSARY	68.00	-
	LESS 10% DISCOUNT		-	-88.70
			1,667.00	798.30
SPECIAL NETT ITEMS				
1	FRONT MUDGUARD (LOCAL RESPRAY) (SN)	SCRATCHED	45.00	40.00
1	LH SIDE COVER (LOCAL RESPRAY) (SN)	SCRATCHED	40.00	40.00
1	STICKER (MCDONALDS) ACCIDENTAL (SN)	NECESSARY	28.00	28.00
1	STICKER (MCDONALDS) SIDE COVER V2 (SN)	NECESSARY	16.00	16.00
1	FRONT COWLING (LOCAL RESPRAY) (SN)	SCRATCHED	63.00	45.00
			192.00	169.00
LABOUR				
	LABOUR -FOR DISMANTLE AND ASSEMBLING PARTS QUOTED.INCLUSIVE OF THE REPAIR OF COVER TAIL LH (BLACK).		105.00	100.00
	SPRAY PAINTING FUEL TANK .	NOT NECESSARY	154.00	-

Report Ref No. CC6/EQ118014406/Uha3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TRANSPORT CHARGES-DELIVERY /COLLECTION.		35.00	35.00
			294.00	135.00
GRAND TOTAL			2,153.00	1,102.30
RECOMMENDED COST OF REPAIRS				1,102.30

Report Ref No. CC6/EQ118014406/Uha3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Joanne Lee (LKK Auto)

From: Joanne Lee (LKK Auto) <report@lkkauto.com>
Sent: Thursday, 18 April 2019 3:42 PM
To: 'janet.tan@eqinsurance.com.sg'
Subject: TP Direct Settlement - Accident Involving SLW 8992X (OI) and FBM 4745R (TP) on 30/07/2018
Attachments: LKK REPORT & PHOTO.pdf; TP DS SUPPORTING DOCUMENT.pdf

Dear Sir/Madam,

Please be informed that the above-mentioned case had been settled.

Enclose herewith final report & relevant documents for your necessary action please.

Thank you.

Best Regards,

JOANNE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933