

REPAIR ESTIMATE\*

VEHICLE NO : SHA 1663E

DATE 7/8/2018 16:03

*AMT*

MAKE :

*Chang*

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door (LH) <i>x repair</i>			} To be Advise
	Front Door Mirror (LH) <i>-</i>			
	Front Wheel Rim (LH) <i>-</i>			
	Front bumper <i>x repair</i>			
	LH Rocker Panel <i>x repair</i>			
	Rear LH Door <i>x repair</i>			
	SUB TOTAL			
	LESS 20%			
	DISCOUNTED TOTAL			
	Front Door Comfort Logo (LH) <i>-</i>			\$ 75.00
	Rear Door Tel No. Sticker (LH) <i>-</i>			\$ 10.00
				<b>\$ 85.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>350.00</del> <sup>200</sup>
	Spray Painting Charge			\$ <del>1,150.00</del> <sup>1050</sup>
	Wiring Charge			\$ <del>50.00</del> <sup>20</sup>
	Tuff Kote			\$ <del>50.00</del> <sup>x</sup>
	Transfer of Door			\$ <del>120.00</del> <sup>x</sup>
	<b>TOTAL LABOUR</b>			<b>\$ 1,720.00</b>
	<b>ESTIMATE TOTAL</b>			

*Kahin 1000*  
*M 8/8/18 1015h*  
*2 hrs.*  
*PIR*  
*Return Pirt. P.L.H.*

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.