

ASS. REP. BY: Reisu REF: CS/MSG18012646/R1rd3-1  
 Surveyor: Meimen Monica Chung of MSIG Date/Time: 07/08/2018  
 Estimated Cost: Bill to:  
 OD: ☒ TP/WS / TP RES / OD RES / EVA / INV / MV / CS  
 To Inspect Vehicle No: FBD1487C Insured: SLW 12082  
 at Workshop m/s: Hua chin (2000) Tel: 68966619  
 of: 50 Bkt Batok st. 23 #02-02  
 Policy No: 29070671AVW Claim No:  
 Sum Insured: Excess:  
 Make of Veh: D.O.A. 08/07/2018  
 (Client's Record):

CA / REV / REP. / REV 24 HRS (up) 12/07/2018  
 Date/Time: 4:47pm 11/7/18 Person Contacted: Mr. Lim H.O.D. Endorsement:  
 Vehicle: ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	<u>FBD1487C - X</u>
	<u>SLW 12082 - X</u>
	Range 3,500 - 4,000/-
	TG Lim Repair days 4
	<u>lim</u>
	<u>12/18</u>

Submit L/s \$2200 @ 4 days  
 (Red: \$1350, 38%.)

L/s 2,200/2  
 Repair days 4

TG Lim  
 lim  
10/8/18

  
14/8/2018

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost:

OD ☒ TP ☒ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MVTo Inspect Vehicle No: FBD 1487Cat Workshop m/s Hua CHINof 50, BUKIT BARU ST 23 # 0202Insured: MSIG

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: FBD 1487 Yr Regn: NOV / 2008Type: M.Car / ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: \_\_\_\_\_ c.c. 135Colour: MULTI A/C: Insured / Std / NI / NASp. Reading: 658182 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ Order / Jammed / Leaked / Burnt orBrake: ☒ Order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim orTyre Size: F: 90/80-17  
R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or MAXXI

Front

Rear

R/Bal. 3 mm R/Bal. 3 mm

L/Bal. \_\_\_\_\_ mm L/Bal. \_\_\_\_\_ mm

D.O.A. \_\_\_\_\_ D.O.I. 12/07/08Survey held at HUA CHINDes. of Damages: ☒ Fnt / ☒ Rear / ☒ O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>7/8</u>	<u>Submit PRE report.</u>

7/8/2008

Date/Time: File Pass to?

☐ : Preli. ReportDays Of Repair: 4.

1)

☐ : Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time: File Return to?

Transportation:

2)

Add Fee: ☐ : Site Insp. (\$

) \$ + RS. \$

☐ : Interview (\$

) Photos

☐ : Tech Invs (\$

) Others

☐ : Weekend (\$

)

Report Format: PRE

Lump Sum / I.B.I: (\$

TOTAL

## Nivitha (LKK Auto)

---

**From:** Monica Chung <Monica\_Chung@sg.msig-asia.com>  
**Sent:** Tuesday, 7 August 2018 5:37 PM  
**To:** ASSIGNMENTS@LKKAUTO.COM  
**Subject:** TP FBD1487C DOA-08/07/18      Our Ref: 564047

Dear Catherine,

We have shared the documents for paper adjustment in Merimen.

Thanks.

Regards,

Monica Chung  
Executive, Claims Services (Motor)  
D: +65 6594 2552 | F: +65 6225 7402 | [monica\\_chung@sg.msig-asia.com](mailto:monica_chung@sg.msig-asia.com)



**MSIG**



Insurer Claims  
Team of the Year  
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6225 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

### CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to a person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

REG / CS / PAY / FA  
30 JUL 2018  
564047

# MAHADI ABU BAKAR & PARTNERS

ADVOCATES & SOLICITORS

(UEN No. 53179837B)

#14-01, TONG ENG BUILDING, 101 CECIL STREET SINGAPORE 069533

TEL: 62252355 FAX: 62279913

YOUR REF: SLW 1208 Z

19 July 2018

OUR REF: MAB/10687/18/zila

**LUKE ALEXANDER ROBERTSON**

Blk 45 Mandalay Road

#10-03 Singapore 308225

**WITHOUT PREJUDICE**

Certificate of Posting

**URGENT**

Dear Sir

**PROPERTY DAMAGE CLAIM BY MR SAIRAN BIN OTHMAN OF BLK 664B JURONG WEST STREET 64 #04-228 SINGAPORE 642664**

We are instructed by the abovenamed as the owner of motorcycle no. FBD 1487 C to claim damages and consequential loss against your company in connection with accident involving SLW 1208 Z & FBD 1487 C along Jalan Jurong Kechil towards Jalan Anak Bukit on 08/07/2018 at 5.10 pm.

We are instructed that the accident was caused by your negligent driving and/or management of your motorvehicle no. SLW 1208 Z.

As a result of the accident, our client's motorcycle was damaged and our client has been put to great loss and expenses, particulars of which are as follows:-

1) Lump sum Repair Cost on motorcycle no. FBD 1487 C (as per Survey Report by M/s L H Teo Appraisal Services)	\$3,550.00
2) Loss of Use (6 days x \$30.00 per day)	\$ 180.00
3) Towing fee	\$ 40.00
4) Legal costs (at this stage)	\$ 700.00
5) Disbursements:-	
a) LTA search fee	\$ 7.49
b) GIA search/report fee	\$ 43.00
c) Survey Report fee	\$ 420.00
d) Miscellaneous	\$ 100.00
	<u><b>\$5,040.49</b></u>

Copies of the following documents supporting the claim have been forwarded to your insurers, **M/s MSIG Insurance (Singapore) Pte. Ltd.**, with a copy of this letter. You may obtain the same from them if you wish so.

1. Traffic Police Accident Report & Singapore Accident Statement lodged by the rider of motorcycle no. FBD 1487 C
2. Singapore Accident Statement lodged by the driver of motorvehicle no. SLW 1208 Z
3. Survey Report by M/s L H Teo Appraisal Services enclosing colour photographs of the damaged motorcycle no. FBD 1487 C
4. Towing fee Official Receipt
5. Certificate of Insurance on motorcycle no. FBD 1487 C
6. LTA Search on motorvehicle no. SLW 1208 Z and all other official receipts

We have on 10/07/2018 notified your insurer **MSIG Insurance (Singapore) Pte. Ltd.** of the accident and a pre-repair survey of our client's motorcycle was carried out.


Please note that if you are insured and wish to claim under the insurance policy, you should immediately pass this letter to the insurer. Please note that you or your insurer should send to us an acknowledgement of receipt of this letter **within 14 days of your receipt of this letter.**

Should you fail to acknowledge receipt of this letter **within 14 days**, our client can commence court proceedings against you without further notice to you or your insurer.


Please also note that if you have a counterclaim against our client arising out of the accident, you are required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents **within 8 weeks of your receipt of this letter.**

Yours faithfully

enc  
cc



Claims Department  
MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way #21-01  
SGX Centre 2  
Singapore 068807  
Your insured motorvehicle no. SLW 1208 Z



**WITHOUT PREJUDICE**  
**BY HAND**

**URGENT**



**SINGAPORE  
POLICE FORCE**



T/20180709/2103

1 of 3

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

Report No. T/20180709/2103

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 09/07/2018 15:30		Vide Report No.:		Station Diary No.: 88	
<b>Informant's Particulars</b>					
Name of Informant: MUSTAKIM BIN SAIRAN			Address: APT BLK 664B JURONG WEST STREET 64 #04-228 SINGAPORE 642664		
ID Type / ID No.: NRIC NO / S9240909J			Contact No.: Home/Office: Mobile: 98365745		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 25	Date of Birth: 11/11/1992	Type of Informant: Rider		
Race: Indonesian			Language: English		Institution / School Name:
Occupation: DELIVERY DRIVER			Driving Licence Information: Class: 2B,2A,2 Date of Expiry:		

<b>General Information of the Accident</b>				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 08/07/2018 17:10	Type of Location: X-Junction
Location: Along Road 1 JALAN JURONG KECHIL  TOWARDS JLN ANAK BUKIT				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
FBD1487C	Motorcycle	YAMAHA	T135	Blue		0
SLW1208Z	Car	VOLKSWAGO N	GOLF TSI TL	Grey		2

<b>Details of Person Involved</b>	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20180709/2103

2 of 3

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

Report No. T/20180709/2103

**CONTINUATION OF REPORT**

<b>Rider</b>			
Name	MUSTAKIM BIN SAIRAN	ID No.	S9240909J
Related Vehicle	NIL	Contact No.	98365745
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	01	Degree of Injury	NIL
<b>Driver</b>			
Name	LUKE ALEXANDER ROBERTSON	ID No.	S7489894G
Related Vehicle	NIL	Contact No.	90914450
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On the 08/07/2018 at about 1710hrs, I was riding on my motorcycle (FBD1487C) along Jln Jurong Kechill and came to a stop as the traffic light was red. Subsequently, the traffic light turns green and I started to move off as the vehicles of the opposite junction has stopped. When I was at the middle of the junction, I saw that there was a vehicle (SLW1208Z) driving towards my direction and I do not have time to avoid it so collision happened. Therefore, it caused me to lose balance and fell off from my bike. I was shocked at that point of time and was unsure what exactly happened. I am unsure of the damages of vehicles but I have some abrasions right elbow and knee.

Traffic police and Ambulance attended. There was a in-cam for the car. I have seen a doctor at NUH and was given a day of MC.





**SINGAPORE  
POLICE FORCE**



T/20180709/2103

3 of 3

Police Station Of Origin:  
Jurong West N.P.C  
700 Corporation Road SINGAPORE 649818  
Tel No: 1800-2689999

Report No. T/20180709/2103

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 1 LIM JUNJIE

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt LEE GUANG HUI

Contact No.: 65476138

SN 126

Authentication Stamp

NP168

Signature:

Singapore Police Force

Signature Of Informant:

Date/Time:

09/07/2018 15:30

Classification Of Case:







# BIKEBULANCE

Reg. No. 52886984A

9D Yuan Ching Rd, #03-38 Singapore (618646)

Tel: 6425 5333

Email: bikebulance@yahoo.com

PIAGGIO, HARLEY, ISOS Appointed Motorcycle Haulage Company

## CASH SALE

NO: 17730

RE:

DATE:

8/7/18

M/s

ITEM	QTY	DESCRIPTION	UNIT PRICE	AMOUNT
1		Towing FBD 1487C		to
2		3LN ANAK BUKIT		
3		- HUA CHIN		
Total \$				80

Bikebulance is The Solution To Your Motorcycle / Scooter  
Conveying Needs (Local & West Malaysia)

E. &amp; O. E.

Truck No: YM 2E ☐ YM3C ☐ GY 2E ☐ GBB 2K ☐ GZ 2320T ☐ Other ☐

Issued By

Customer Signature &amp; Chop

注意:本公司對所拖的電單車,在拖運中如有任何損壞,一概由車主自行負責  
NOTE: Vehicle is hauled at owner's risk, The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

3 Gambas Crescent, #07-14 Nordcom 1, Singapore 757088 Tel: 63966319 Fax: 63966320 Email: lhtas@singnet.com.sg

**Loss Adjuster, Consulting Automotive Engineer, Accident Reconstruction & Analyst.**

Mr Sairan Bin Othman  
C/o Mahadi Abu Bakar & Partners  
101 Cecil Street  
#14-01 Tong Eng Building  
Singapore- 069533

Bill No : AL180704  
OurRef : TP/1807/FBD1487/HC  
Date : 18 July 2018


To our Services rendered in connection with the below matters: -

<u>Description</u>	<u>Amount</u>
Survey fees	\$ 320.00
Transportation and	60.00
Photographs ( 40 ) Copies	40.00
<b>Total</b>	<b>\$ 420.00</b>

Dollars: Four hundred and twenty only

Please quote our bill No, or return a copy of our bill with your remittance. Cheque should be made payable to **L H Teo Appraisal Services**.

**L H TEO APPRAISAL SERVICES**

  
Teo Liak Hoo  
Advance Automotive Engineer (UK)  
Dip. Mech. Engr. M Prof BTM(Dip.BTM)  
MIIE, MIMI, AMSIM

**Loss Adjuster, Consulting Automotive Engineer, Accident Reconstruction & Analyst.****VEHICLE APPRAISAL REPORT**

Mr Sairan Bin Othman  
C/o Mahadi Abu Bakar & Partners  
101 Cecil Street  
#14-01 Tong Eng Building  
Singapore- 069533

Our Ref : TP/1807/FBD1487/HC  
Date : 18 July 2018

**REFERENCE PARTICULARS**

Your Reference No : Not Advised  
Date of Accident : 08 July 2018

Date of Assignment : 10 July 2018  
Date of Inspection : 11 July 2018  
Date of Re-inspn. : N/A

**PARTICULARS OF VEHICLE**

Regn. No : FBD 1487C  
Make : YAMAHA  
Model : T135  
Year : 2008 (COE.Exp : Nov 2018)

Odometer : 65818km  
Color : Blue  
Chassis No. : 5YP300312  
Engine No : 5YP300312

**TYRE / CONDITION**

<u>Location</u>	<u>Make</u>	<u>Size</u>	<u>Thread Balance</u>
Front	Maxxis	80 / 90 R 17	5 mm
Rear	Maxxis	80 / 90 R 17	5 mm

**DAMAGE PROFILE**

The motor cycle sustained damage on all sides.

Please refer to photographs and assessment of repairs for details.

**ASSESSMENT SUMMARY**

Repair cost to the vehicle is assessed as \$ **3,550.00 lump sum**

Survey conducted at: Hua Chin (2000) Trading Motor Service Centre.

Enclosed (40) photographs depicting damage to the vehicle.

Estimated time required for repairs: (6) days.

The survey was conducted on a **WITHOUT PREJUDICE BASIS**.

**ASSESSMENT FOR REPAIR : FBD 1487 C**

Qty	Description	Condition	Repairer's Estimate	Our Assessment
1 pc	Handle bar	Bent	80.00	✓ 80.00 BT ✓
1 set	Handle bar grip	Cut	40.00	✓ 40.00 CUT ✓
1 pc	Clutch lever	Cut	24.00	✓ 24.00 SCR ✓
1 pc	Brake lever	Broken	26.00	✓ 26.00 BR ✓
2 pcs	Mirror @45.00	Broken / Cut	90.00	✓ 90.00 BR ✓
1 pc	Head light	Cut	115.00	115.00 NCX
1 pc	Head light cover	Cut	85.00	85.00 NCX
1 pc	Meter cover	Usable	65.00	~
1 pc	Front cowling	Torn	135.00	98.00 135.00 BR ✓
1 pc	Front cowling stay	Bent	45.00	✓ 45.00 BT ✓
		RH Hldr		
2 pcs	Front pilot lamps @82.00	Broken	164.00	82.00 NCX
2 pcs	Front forks @275.00	Bent	550.00	550.00 R X
1 pc	Steering stem	Distorted	145.00	✓ 145.00 NEC ✓
1 pc	Front fender	Cut	76.00	76.00 R X
1 pc	Radiator assy	Dented	375.00	✓ 375.00 DD ✓
2 pcs	Front leg shield outer @106.00 56.00	Torn / Cut	212.00	112.00 212.00 BR ✓
1 pc	Front leg shield inner	Cracked	165.00	✓ 165.00 CRA ✓
1 pc	Chassis cover top	Deformed	54.00	✓ 54.00 CUT ✓
2 pcs	Chassis cover side @42.00	Cut	84.00	✓ 84.00 CUT ✓
2 pcs	Tail board @95.00	Cut	190.00	✓ 190.00 CUT ✓
1 pc	Tail board center cover	Usable	28.00	~
1 pc	Front footrest bar	Bent	58.00	✓ 58.00 BT ✓
1 set	Footrest rubber	Cut	25.00	✓ 25.00 CUT ✓
1 pc	Gear pedal	Usable	45.00	~
1 pc	Brake pedal	Bent	52.00	✓ 52.00 BT ✓
2 pcs	Pillion footrest @35.00	Missing / Cut	70.00	✓ 70.00 MIS ✓
2 pcs	Pillion footrest bracket @70.00	Broken / Bent	140.00	70.00 140.00 BR ✓
1 pc	Tail light	Hldr Broken	95.00	60.00 95.00 BR ✓
1 pc	Rear fender	Cut	126.00	126.00 NN X
1 pc	Rear swingarm	Cut - Repair	385.00	S.N. 120.00 R X
			3,744.00	3,139.00 1864.00
		Less 10%	374.40	313.90 186.40
			3,369.60	2,825.10 1677.60
	<u>Special Nett Items</u>			
	Add special nett items from above			120.00 NN X
1 pc	Steering cone & bearing	Necessary	80.00	✓ 60.00 NEC ✓
1 pc	IU Unit	Cut	156.00	✓ 156.00 CUT ✓
1 pc	Front number plate	Cut	15.00	12.00 NN X
1 pc	Rear number plate	Deformed	18.00	✓ 15.00 BT ✓
1 pc	Muffler, Yoshimura	Cut / Dented	1,250.00	1,250.00 R X
1 pc	Front box	Broken	100.00	✓ 80.00 BR ✓
1 pc	Rear top box	Broken	350.00	180.00 300.00 BR ✓
1 pc	Rear box bracket	Bent	150.00	100.00 120.00 CUT ✓
			2,119.00	2,113.00 591.00


Our Ref.: TP/1807/FBD1487/HC

<u>Labour</u>				
1	Towing	80.00	50.00	NNX
2	Repair and align body frame	350.00	300.00	
3	Workmanship to repair, remove, renew damaged areas	400.00	350.00	300.00
		830.00	700.00	600.00
Total Parts & Labours		6,318.60	<del>5,638.10</del>	2868.60
Lump Sum Repair Adjustment			<del>4,500.00</del>	2200.00


#### ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle. We have listed the breakdown of our findings and our recommendation as per assessment above.

Inspected by

  
Dylan Lee

Faithfully Yours  
L H TEO Appraisal Services

  
Teo Liak Hoo  
Advance Automotive Engineer (UK)  
Dip. Mech. Engr. M Prof BTM(Dip.BTM)  
MIE, MIM1, AMSIM

4/5 2,200/2  
Repair days 4

**Certificate of Insurance**

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5065494925-03 Cover : Third Party

- |                                                     |                     |
|-----------------------------------------------------|---------------------|
| 1. Index mark and Registration Number of Vehicle    | : FBD1487C          |
| Chassis Number                                      | : SYP300312         |
| 2. Name of Policyholder                             | : SAIRAN BIN OTHMAN |
| 3. Effective Date of Insurance                      | : 06 May 2017       |
| 4. Expiry Date of Insurance                         | : 05 Nov 2018       |
| 5. Persons or Classes of Persons entitled to drive# |                     |

(a) Named Driver(s) Only.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

(a) Use for hire or reward.

(b) Use for racing, pace-making, reliability trial or speed-testing.

(c) Use for the carriage of goods (other than samples) in connection with any trade or business.

(d) Use for any purpose in connection with the Motor Trade.

# Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: N/A
INSURE WITH COE	: N/A
NAMED DRIVER (1)	: SAIRAN BIN OTHMAN
NAMED DRIVER (2)	: MUSTAKIM BIN SAIRAN
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : DIRECT BUSINESS DEPT (00000600280)  
Date of Issue : 02 May 2017 13:52 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED



Countersigned By:

Authorised Officer



Chief Executive



**Enquire Vehicle & Owner Information ( Vehicle No. SLW1208Z As At 08 Jul 2018 / 17:10:00 )****Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident  
Law Firm Case No.: MAB/10686/18/ANA

**Current Owner Details**

Owner ID Type: Singapore NRIC  
Owner ID: S7489894G  
Owner Name: LUKE ALEXANDER ROBERTSON  
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes  
Registered Block/House No.: 45  
Registered Street Name: MANDALAY ROAD  
Registered Unit No.: # 10 - 03  
Registered Building Name: -  
Registered Postal Code: 308225

**Current Vehicle Details**

Vehicle No.: SLW1208Z  
Make Description/Model: VOLKSWAGEN / GOLF TSI TL  
Insurance Company Name: MSIG INSURANCE (SINGAPORE) PTE LTD

7/10/2018

Invoice



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE**  
**RECORDS MANAGEMENT CENTRE**  
6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

## TAX INVOICE

Our Ref No: GR-18-105517  
Date of Request: 10/07/2018

Your Ref No: MAB/10687/18/ANA

MAHADI ABU BAKAR & PARTNERS  
101 Cecil Street #14-01  
Tong Eng Building  
Singapore 069533

Dear Sir/Madam,

**Your Search Criteria:**

Date of Accident: 08/07/2018  
Place of Accident: JLN JURONG KECHIL-JLN ANAK BT  
Passenger/Pedestrian Name: MUSTAKIM BIN SAIRAN

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

## TAX INVOICE

Our Ref No: GR-18-105650  
Date of Request: 11/07/2018

Your Ref No: MAB/10687/18/ANA

MAHADI ABU BAKAR & PARTNERS  
101 Cecil Street #14-01  
Tong Eng Building  
Singapore 069533

Dear Sir/Madam,

Date of Accident: 08/07/2018  
Vehicle No: FBD1487C  
Place of Accident: JLN JURONG KECHIL  
Involving Vehicle No: SLW1208Z

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SLW1208Z	JLN JURONG KECHIL	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

7/11/2018

Invoice



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735**TAX INVOICE**Our Ref No: GR-18-105651  
Date of Request: 11/07/2018

Your Ref No: MAB/10687/18/ANA

MAHADI ABU BAKAR & PARTNERS  
101 Cecil Street #14-01  
Tong Eng Building  
Singapore 069533

Dear Sir/Madam,

Date of Accident: 08/07/2018  
Vehicle No: FBD1487C  
Place of Accident: JLN JURONG KECHIL

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
FBD1487C	JLN JURONG KECHIL	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jul 2018		11 Jul 2018 16:14 <a href="#">Edit Adj Rpt</a>	<b>S\$2,200.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,200.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	LUKE ALEXANDER ROBERTSON, ID: S7489894G, Tel: +6590914450, Email: LUKE.JYD@GMAIL.COM								
Main Claimant:	SAIRAN BIN OTHMAN, ID: S1835682A								
Vehicle Reg. No.:	FBD1487C	Date of Loss:	08/07/2018 17:00 - :59 [116 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 564047	Policy/Cover Note No.:	A29070671AVW (Comprehensive) Coverage: 30/01/2018 - 29/01/2019						
Vehicle Reg. No. (Insured):	SLW1208Z	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	Hua Chin (2000) Trading Motor Service Centre (HQ) 50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING, 659578 Bukit Batok - Tel: 68966619								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 24/08/2018]								
Driver/Custodian (Insured):	LUKE ALEXANDER ROBERTSON (43 / Male), NRIC: S7489894G, Tel: +6590914450								
Adj Asg. Remarks:	on WP. LIABILITY NOT CLEAR TP DISAGREE SJE -APPOINT LKK CONSULTANCY PTE LTD ACCODING TO CHART PLS CONTACT MR LIM W.KOON FOR SURVEY @68966619								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
<ul style="list-style-type: none"> <li>MSIG_SG (21/08/2018): Report Send Back Alerts - FBD1487C (TP)</li> </ul>									
<b>ALL ASSOCIATED TASKS</b>			<a href="#">View All</a>	<a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FBD1487C (564047)  
[SLW1208Z]

TP  
SAIRAN BIN OTHMAN

Jul 8 2018 5:00PM

[LUKE ALEXANDER ROBERTSON]

Hua Chin (2000) Trading Motor Service Centre

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View** View in Browser

1 per page ▼ ☒

Thumbnail ▼ ☒

Print ☒

Video				
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		
1	12/07/18 08:50	Video - AccidentOI		Load MOV


















3 per page ▼ ☒









Thumbnail ▼ ☒

Print ☒

Photos/Images				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
2	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
3	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
4	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
5	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
6	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
7	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
8	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
9	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
10	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
11	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
12	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
13	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
14	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
15	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
16	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
17	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
18	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
19	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
20	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
21	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
22	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
23	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
24	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
25	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
26	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
27	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
28	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
29	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
30	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
31	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
32	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
33	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>
34	13/07/18 11:54	General View		Load JPG <input checked="" type="checkbox"/>



Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
36	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
37	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
38	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
39	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
40	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
41	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
42	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
43	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
44	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
45	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
46	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
47	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
48	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
49	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
50	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
51	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
52	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
53	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
54	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
55	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
56	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
57	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
58	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
59	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
60	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
61	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
62	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
63	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
64	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
65	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
66	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
67	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
68	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
69	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
70	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
71	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
72	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
73	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
74	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
75	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
76	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
77	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
78	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
79	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
80	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
81	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
82	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/07/18 13:50	OI SLW1208Z GIA REPORT		Load PDF
2	10/07/18 13:50	TPD FBD1487C GIA REPORT		Load PDF
3	10/07/18 14:07	FAX TO MAHADI ABU BAKAR & PARTNERS WITH 10 SURVEY NAME - FBD1487C		Load PDF
4	10/07/18 15:50	TPD FBD1487C - SURVEY LISTING		Load PDF
5	10/07/18 15:50	Reject email to TP Lawyer & appoint LKK AUTO - FBD1487C		Load PDF
6	11/07/18 11:00	WORKSHOP DETAILS -FBD1487C.pdf		Load PDF
7	06/08/18 17:17	LOD, POLICE RPEORT, REPAIR BILL, SURVERY REPORT, COI & GIA SEARCH		Load PDF
8	06/08/18 17:17	COLOURED IMAGES		Load PDF

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18012646/R1RD3E2-1

Date: 21/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29070671AVW

Claimant Vehicle No : FBD1487C

Insured Vehicle No : SLW1208Z

Date of Loss: 08/07/2018

Nature of Claim: TP

Claim No: 564047

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBD1487C

Make &amp; Model: YAMAHA T135, 135cc (A)

Engine No: 5YP300312

Reg. Date: 06/11/2008 (Man. Year: 2008)

Chassis No: 5YP300312

Colour: Multi-colour

Odometer: 658182 km

Engine Capacity: 135 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 90/80-17

Rear Tyre Size:

90/80-17

Front Left Side: Maxxis 3 mm

Rear Left Side:

Maxxis 3 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,488.60	2,267.70	3,220.90	58.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	830.00	600.00	230.00	27.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,318.60</b>	<b>2,867.70</b>	<b>3,450.90</b>	<b>54.61</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,200.00</b>		
<b>(S\$)</b>	6,318.60	2,200.00	4,118.60	65.18
<b>+ GST 7.00/7.00% (S\$)</b>	442.30	154.00	288.30	65.18
<b>Nett Amount (S\$)</b>	<b>6,760.90</b>	<b>2,354.00</b>	<b>4,406.90</b>	<b>65.18</b>

INSPECTION

Date of Assignment: 11/07/2018

Date Inspected: 12/07/2018 Inspected At:

Hua Chin (2000) Trading Motor Service  
Centre (HQ)  
50 BUKIT BATOK STREET 23, #02-02  
MIDVIEW BUILDING  
Singapore 659578

Estimated Period of Repair: 4.0 days

---

**Adjuster:** XING GUO QIANG**Manager:** Ho Zhao Tian

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

Part Source:	(Last Synchronised: 21 Aug 2018)	
Parts:	N/A	YAMAHA T135 135cc (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBD1487C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	80.00 FL	*80.00 FL
2	1		*SET HANDLE BAR GRIP	Cut	40.00 FL	*40.00 FL
3	1		*CLUTCH LEVER	Scratched	24.00 FL	*24.00 FL
4	1		*BRAKE LEVER	Broken	26.00 FL	*26.00 FL
5	2		*MIRROR	Broken	90.00 FL	*90.00 FL
6	1		*HEAD LIGHT (CUT)	Not Consistent With The Impact	115.00 FL	*- FL
7	1		*HEAD LIGHT COVER (CUT)	Not Consistent With The Impact	85.00 FL	*- FL
8	1		*METER COVER	Usable	65.00 FL	*- FL
9	1		*FRONT COWLING	Broken	135.00 FL	*98.00 FL
10	1		*FRONT COWLING STAY	Bent	45.00 FL	*45.00 FL
11	2		*FRONT PILOT LAMPS (BROKEN)	Not Consistent With The Impact	164.00 FL	*- FL
12	2		*FRONT FORKS	Repair	550.00 FL	*- FL
13	1		*STEERING STEM	Necessary	145.00 FL	*145.00 FL
14	1		*FRONT FENDER	Repair	76.00 FL	*- FL
15	1		*RADIATOR ASSY	Dented	375.00 FL	*375.00 FL
16	2		*FRONT LEG SHIELD OUTER	Broken	212.00 FL	*112.00 FL
17	1		*FRONT LEG SHIELD INNER	Cracked	165.00 FL	*165.00 FL
18	1		*CHASSIS COVER TOP	Cut	54.00 FL	*54.00 FL
19	2		*CHASSIS COVER SIDE	Cut	84.00 FL	*84.00 FL
20	2		*TAIL BOARD	Cut	190.00 FL	*190.00 FL
21	1		*TAIL BOARD CENTER COVER	Usable	28.00 FL	*- FL
22	1		*FRONT FOOTREST BAR	Bent	58.00 FL	*58.00 FL
23	1		*SET FOOTREST RUBBER	Cut	25.00 FL	*25.00 FL
24	1		*GEAR PEDAL	Usable	45.00 FL	*- FL
25	1		*BRAKE PEDAL	Bent	52.00 FL	*52.00 FL
26	2		*PILLION FOOTREST	Missing	70.00 FL	*70.00 FL
27	1		*PILLION FOOTREST BRACKET (2PCS)	Broken-1PC ONLY	140.00 FL	*70.00 FL
28	1		*TAIL LIGHT	Broken	95.00 FL	*60.00 FL
29	1		*REAR FENDER	Not Necessary	126.00 FL	*- FL
30	1		*REAR SWINGARM	Repair	385.00 FL	*- FL
31	1		*STEERING CONE & BEARING	Necessary	80.00 FS	*60.00 FS
32	1		*IU UNIT	Cut	156.00 FS	*156.00 FS
33	1		*FRONT NUMBER PLATE	Not Necessary	15.00 FS	*- FS
34	1		*REAR NUMBER PLATE	Bent	18.00 FS	*15.00 FS
35	1		*MUFFLER, YOSHIMURA	Repair	1,250.00 FS	*- FS
36	1		*FRONT BOX	Broken	100.00 FS	*80.00 FS
37	1		*REAR TOP BOX	Broken	350.00 FS	*180.00 FS
38	1		*REAR BOX BRACKET	Cut	150.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Sub Total (S\$)	2,454.00
					5,863.00	
					- List Item Discount on L Items 10.00/10.00% (S\$)	186.30
					374.40	
					Total Parts (S\$)	2,267.70
					5,488.60	

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	80.00	0.00
2	REPAIR AND ALIGN BODY FRAME	New	350.00	300.00
3	WORKMANSHIP TO REPAIR, REMOVE, RENEW DAMAGED AREA	New	400.00	300.00
Gross Labour Cost (S\$)			830.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >