

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05829

Vehicle Insured : SLZ1570K
Accident Date : 05-Aug-2018

Date : 07-Aug-2018

Our Ref : 218134 (ECICS) / CHAN

PAGE : 1

LEE SIEW WENG
96 HILLVIEW CRESCENT
Singapore 669489

*Not Authorized
L.B.I
Resurvey B4 paint*

ESTIMATED COST OF REPAIR FOR M/BENZ A180 SCZ8083K

1 pc	Tail gate		1,944.00	—
1 pc	Tail gate "A180" emblem		82.00	—
1 pc	Tail gate "C&C" plate		56.00	—
1 pc	Tail gate logo		51.00	—
2 pcs	Taillamp	@ S\$457.00	914.00	?
1 pc	Rear bumper fascia		1,404.00	?
1 pc	Rear bumper reinforcement		499.00	?
1 pc	Rear bumper inner parts		134.00	?
2 pcs	Rear bumper side retainer	@ S\$ 30.00	60.00	X
4 pcs	Rear bumper lower clip	@ S\$ 8.00	32.00	✓
2 pcs	Rear bumper parking sensor	@ S\$306.00	612.00	?
1 pc	Rear bumper tow cover		65.00	✓
1 pc	Rear exhaust silencer box		1,240.00	X
1 pc	Rear exhaust heat seal		188.00	X
1 pc	Front bumper fascia		1,261.00	—
1 pc	Front bumper sponge		152.00	?
1 pc	Front bumper reinforcement		361.00	?
1 pc	Front bumper logo		57.00	✓
1 pc	Front bumper lower grille		173.00	✓
1 pc	Front bumper tow cover		61.00	X
2 pcs	Front bumper parking sensor	@ S\$306.00	612.00	?
1 pc	Radiator grille		720.00	✓
1 pc	Radiator grill logo base		446.00	?
2 pcs	Headlamp	@ S\$934.00	1,868.00	?
			12,992.00	
			Less 10% :	1,299.20

11,692.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLZ1570K

Page : 2

1 pc Rear w/s glass sealant
1 pc Rear no. plate with box
1 pc Front no.plate with box

na *40sn* 60.00 sn
CRS 50.00 sn *45sn*
na 50.00 sn *45sn*

To rewire damaged parts and refocus
headlamp beam.

120.00 *40%*

To remove & refix rear windscreen
glass and conduct water leak test.

150.00 *120%*

To remove roof lining, front and
rear seats, trim board and carpet

120.00 *7*

To remove and renew exhaust
silencer box

na 80.00 *X*

To putty and spray replaced parts

1,200.00 *1000%*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1,400.00 *700%*

Total : S\$14,922.80
=====

Singapore Dollars Fourteen Thousand Nine Hundred
and Twenty Two and Cents Eighty Only