



Your Ref : SHD4325X

Our Ref : PC238B/Kumar Limousine/1808

15 Aug 2018

To : M/S India International Insurance Pte Ltd
64 Cecil Street,
#04/#05/#06-02, IOB Building
Singapore 049711
Attn : Motor Claims Dept

Via Email : motorclaim@iii.com.sg

Dear Sir/Mdm,

RE : Request To Conduct Pre-Repair Inspection For Non-Injury Motor Accident Claims

Accident Involving PC238B & SHD4325X On 25.03.2018 At Along Balestier Road Towards Serangoon Road

We are instructed by **Kumar Limousine And Coach Services Pte Ltd** to notify your client of a road traffic accident involving our client's vehicle no PC238B and vehicle no SHD4325X driven by your client at the material time. A copy of the Singapore Accident Statement is enclosed.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within **2 working days** of your receipt of this notice whether you/ your clients would like to conduct a pre-repair survey of the motor vehicle.

If you want to conduct a pre-repair inspection, please let us have your list of appointed surveyors.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Venue : Lexbuild Auto & Trading Pte Ltd
74, Sungei Kadut St 1
Singapore 729374

Contact : Hui Wen @ 6362-3393 Email : huiwen.lim@sungee.com.sg

Your Faithfully



HuiWen Lim