

CC 3, TP 100 14423, Kea39

Surveyor:

Kenneth

DOI:

9/8/18

Date / Time:

7/9/18

Registered in Meritum:

Pre-assign / CCU / FTE



Insured Vehicle No. :

Claim No. :

Name of Insured :

Policy No. :

Insured Tel No. : HP:

Make / Model :

Excess Sec II :SS D.O.A: 30/3/18

Place of Accident :

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

S4C 5035 G



INSRS: WSP: Tel: Liability: RMKS:

Trans-Tab



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting Itr (1st)	
	Non-Reporting Itr (2nd)	
	Non-Reporting Itr (Final)	
	Notification Itr (if non-pickup):	
	Call OI:	
	After call Itr to OI:	
	Documentation Check List: Handler Typist	
	Notification Itr (if non-pickup)	<input type="checkbox"/>
	After call Itr to OI:	<input type="checkbox"/>
	Authorisation To Act:	<input type="checkbox"/>
	Release Voucher:	<input type="checkbox"/>
	Final Repair Bill:	<input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD	<input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

RECEIVED 14 SEP 2018

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: S\$ _____ (_____ days) Reduction: _____ % Email Call

FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email Call

Final Liability: % _____ (Agreed / Assessed) BOLA S/N No. : _____ If NO or B 28, Ass. Lia : _____

Repair Cost: S\$ _____

Loss of Rental (LOR): S\$ _____ (_____ days)

Loss of Use (LOU): S\$ _____ (\$ x _____ days)

Loss of Income (LOI): S\$ _____ (\$ x _____ days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search: S\$ _____

Medical: S\$ _____

Disbursement: S\$ _____ (e.g Tow/ Independent)

Legal Cost: S\$ _____

Total: S\$ _____ **Global Sum S\$:** _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: S\$ _____ Name 1: _____

Payee 2: (Strike if N.A.) S\$ _____ Name 2: _____

Payee 3: (Strike if N.A.) S\$ _____ Name 3: _____

COMPLIMENT 14/9/18

ASS. REC. BY:

REF: TP/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s Trans Cob

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 01 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S14C 50356 Yr Regn: 12, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or A)

Make: Renault Latitude c.c. 1985

Colour: m. white/red A/C: Insured / Std / NI / NA

Sp. Reading: 653932 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VFI ABL 15 AUC 276025

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Braks: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Giti 215/60R16

ling R: lag

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 30/7/18

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 7/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

8/8 File pass to Catherine
1 Day @ 850

(REQ. → 65,391.53 99%)

Date/Time, File Pass to?

: Prell. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:

Transportation:

S - RS - SI

Fixing

Others

TOTAL

50x15=840
170+840=1010
50
11
80
1151

Report Format :

Lump Sum / I.B.I. (\$ _____)

26/2/18

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/07/2018 11:50
Date Of Accident	30/07/2018 22:20
Exact Location Of Accident	BUANGKOK DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5035G
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
Vehicle Particulars	
Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	
Driver	
Name of Driver	LIM FONG CHAI
NRIC No	S1143329D
Date Of Birth	06/06/1955
Occupation	OUTDOOR
Date Of Driving Pass	05/01/1976
Driving Experience	42 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84885035
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 667B JURONG WEST STREET 65
#04-159
Postcode 642667
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1 NAME: : UNKNOWN
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

On 30.7.2018 at about 2220 hours, I was travelling straight on the third lane along Buangkok Drive when I make a stop due to traffic light turns red. Moment later while stationary, I felt an impact. Vehicle B (SHB360E) hit onto my taxi rear portion.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHB360E
Vehicle Make/Model/Colour
Details Of Properties SMRT TAXI
Vehicle Category TAXI
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorized Driver.**
3. Information provided must be **truthful and accurate as possible.** Any willful misrepresentation or withholding of material facts may alter the insurer's conclusions to **reputate policy liability.**
4. The signing and acceptance of this form by insureds constitutes an admission of policy liability on the part of the insureds involved.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurer to the Claims Records Management Centre established by the General Insurance Association of Singapore (GIAS) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurer, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available at the Centre.

5. Consent under the Personal Data Protection Act (PDPA)

I understand and knowingly agree and consent that:

- (a) My insurer, my advisor(s) and the General Insurance Association of Singapore ("GIAS") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or processed by my insurer (collectively the "Personal Information") and it shall not transfer such Personal Information to all insurers who have insured vehicles involved in this accident (all insurers) who have insured vehicles involved in this accident (all insurers collectively referred to as the "Insurers"), the Insurers' (lawyer) law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out estate dealing with my motor cars or responding to any enquiries by me;
 - (iv) administering my claims including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes (mail packages) and/or;
 - (v) entering into or administering law, administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurers who have insured vehicles involved in this accident and the Insurers' (lawyer) law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may also be disclosed by any of the Insurers and/or GIAS to their third party service providers or agents (including their lawyer law firms) which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information or context under (a) above may be shared / disclosed:
 - (i) to all insurers, agents or other third parties that assist in evaluating, investigating, controlling or managing fraud;
 - (ii) regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (iii) for complying with requirements under any regulatory laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(Approved by the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
MFC/PA No.:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5035G

AAD1807-289

*Not Authorized
L/Sing @ 950.*

Vehicle No.:	SHC 5035G
Chassis No.:	VF1ABL15AUC276025
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	30.7.2018
Third Party Insurer :	<i>SMF</i>

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>R</i> 1,108.46 <i>X</i>
2	1 BUMPER LOWER REAR	\$	<i>add/less</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sm</i> 113.47
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>Sm</i> 135.97
5	1 BUMPER RETAINER RH REAR	\$	<i>Sm</i> 44.99
6	1 BUMPER REFLECTOR RH	\$	<i>Sm</i> 43.61
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>Sm</i> 135.97
8	1 BUMPER RETAINER LH REAR	\$	<i>Sm</i> 44.99
9	1 BUMPER REFLECTOR LH	\$	<i>Sm</i> 43.61
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95
13	1 BOOT REAR	\$	<i>R</i> 2,872.68
14	1 BOOT FINISHER	\$	<i>Sm</i> 470.06
15	1 BOOT WHEATERSTRIP	\$	<i>Sm</i> 323.05
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sm</i> 493.35
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sm</i> 493.35
18	1 BOOT BADGE 'RENAULT'	\$	<i>un</i> 225.36
19	1 BOOT BADGE	\$	<i>un</i> 225.36
20	1 BOOT STRUT LH	\$	<i>Sm</i> 276.08
21	1 BOOT STRUT RH	\$	<i>Sm</i> 276.08
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84
24	1 BOOT INNER TRIM	\$	<i>Sm</i> 586.45
25	1 BOOT SWITCH	\$	<i>Sm</i> 168.13
26	1 BOOT LOCK	\$	<i>R</i> 202.67
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40
28	2 LICENCE PLATE LAMP	\$	<i>Sm</i> 50.52
29	2 BOOT RUBBER PLUG	\$	<i>Sm</i> 221.81

Trans-cab Auto Services Pte Ltd

AAD1807-289

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5035G

30	1 FENDER PANEL REAR LH	\$	R	3,299.13	}
31	1 WHEELARCH REAR LH	\$	Sm	543.47	
32	1 FENDER PANEL INNER TRIM REAR RH	\$	Sm	671.45	
33	1 FENDER PANEL REAR RH	\$	R	3,299.13	
34	1 WHEELARCH REAR RH	\$	Sm	543.47	
35	1 TAILLAMP RH	\$	Sm	552.55	
36	1 TAILLAMP PANEL RH	\$	R	986.70	
37	1 TAILLAMP LH	\$	Sm	552.55	
38	1 TAILLAMP PANEL LH	\$	R	986.70	
39	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77	
40	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sm	404.56	
41	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	
42	1 SPARE WHEEL PANEL TRIM	\$	Sm	612.21	
43	1 EXHAUST REAR	\$	R	7,489.05	
44	1 EXHAUST CAP REAR	\$	R	230.49	
45	1 CHASSIS PANEL REAR RH	\$	R	3,766.43	
46	1 KUCKLE ARM REAR RH L70Y	\$	Sm	736.67	
47	1 BRAKE DISC REAR L70Y	\$	Sm	525.91	
48	1 WHEEL HUB NUT L70Y	\$	Sm	51.11	
49	1 WHEEL HUB CAP L70Y	\$	Sm	57.82	
50	1 ABS SENSOR REAR RH L70Y	\$	Sm	255.75	
51	1 REAR AXLE L70Y	\$	Sm	4,167.03	
52	1 AXLE ARM RH L70Y	\$	Sm	117.22	
53	1 LOWER ARM REAR RH L70Y	\$	Sm	905.99	
54	1 ABSORBER REAR	\$	Sm	389.75	
55	1 STABILIZER BAR REAR RH	\$	Sm	604.65	
56	1 BRAKE CALIPER REAR RH	\$	Sm	1,300.67	
57	1 WHEEL HOUSING PANEL REAR RH	\$	R	4,682.09	
58	1 CHASSIS PANEL REAR RH	\$	R	3,766.43	
TOTAL		\$		56,525.01	}
10%		\$		5,652.50	
		\$		50,872.51	

Special Nett

1	1SET PARKING AID	\$	Sm	700.00	X
2	1SET REAR BUMPER CLIP	\$	na	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	X
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X

Trans-cab Auto Services Pte Ltd

AAD1807-289

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5035G

5	1SET BUMPR RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	sm	17.82	}
11	1SET BOOT FINISHER CLIP	\$	na	24.20	
12	1 BOOT STICKER "Trans-cab"	\$	na	30.00	
13	1 BOOT STICKER "6555-3333"	\$	na	30.00	
14	1 BOOT INNER TRIM CLIP	\$	na	45.00	
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
17	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
18	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
19	1 TAILLAMP CLIP RH	\$	na	5.00	
20	1 TAILLAMP CLIP LH	\$	na	5.00	
21	2 REAR WINDSCREEN SELANT	\$	na	80.00	
22	1 WINDSCREEN MOULDING	\$	na	100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sm	385.00	
25	1 SPARE TYRE	\$	sm	330.00	
26	1 RIGHT REAR TYRE	\$	sm	330.00	
27	1 RIGHT REAR TYRE RIM	\$	sm	380.00	

TOTAL \$ 2,935.02**TOTAL PARTS \$ 53,807.53****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	2001
To Rust-Proofing Of The Affected Areas.	\$	na	170.00 X

Trans-cab Auto Services Pte Ltd

AAD1807-289

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5035G

To reinstall rear bumper parking sensor.	\$	<i>na</i> 170.00 X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00 X
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i> 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>na</i> 380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>na</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00 X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 X

TOTAL \$ 12,540.00**Over All Total \$ 66,347.53****(LUMP SUM)****Repair Days****20 DAYS***1 day*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spraying painting
- To display damaged part(s) during resurvey
- Parts prices are subject to our quotation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
TRANS-CAB AUTO SERVICES PTE LTD		Ref : CC3/TP18014423/Kea3q2	
NO.2 ANG MO KIO STREET 63SINGAPORE 569111		Date : 26-10-2018	
		Code : TP378	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.		Veh. Inspected	SHC 5035G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	07/08/2018
2. Vehicle Particulars & Condition			
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	VF1ABL15AUC276025	Colour	METALLIC WHITE / RED
Odometer	653932	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	9 mm
L/H Front Tyre	215/60 R16	GITI	9 mm
R/H Rear Tyre	215/60 R16	LING LONG	7 mm
L/H Rear Tyre	215/60 R16	LING LONG	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	30/07/2018	Inspection Date	07/08/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5035G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	TO REPAIR SEE LABOUR	1,108.46	-
1	BUMPER LOWER REAR	DENTED / CUT	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BOOT REAR	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE 'RENAULT'	NOT NECESSARY	225.36	-
1	BOOT BADGE	NOT NECESSARY	225.36	-
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-

Report Ref No. CC3/TP18014423/Kea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHWELARCH REAR RH	SERVICEABLE	543.47	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
1	CHASSIS PANEL REAR RH	TO REPAIR SEE LABOUR	3,766.43	-
1	KNUCKLE ARM REAR RH L70Y	SERVICEABLE	736.67	-
1	BRAKE DISC REAR L70Y	SERVICEABLE	525.91	-
1	WHEEL HUB NUT L70Y	SERVICEABLE	51.11	-
1	WHEEL HUB CAP L70Y	SERVICEABLE	57.82	-
1	ABS SENSOR REAR RH L70Y	SERVICEABLE	255.75	-
1	REAR AXLE L70Y	SERVICEABLE	4,167.03	-
1	AXLE ARM RH L70Y	SERVICEABLE	117.22	-
1	LOWER ARM REAR RH L70Y	SERVICEABLE	905.99	-
1	ABSORBER REAR	SERVICEABLE	389.75	-
1	STABILIZER BAR REAR LH	SERVICEABLE	604.65	-
1	BRAKE CALIPER REAR RH	SERVICEABLE	1,300.67	-
1	WHEEL HOUSING PANEL REAR RH	TO REPAIR SEE LABOUR	4,682.09	-

Report Ref No. CC3/TP18014423/Kea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CHASSIS PANEL REAR RH	TO REPAIR SEE LABOUR	3,766.43	-
	LESS 10% DISCOUNT		-5,652.50	-76.88
			50,872.49	691.96
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	66.00	-
1	SET BUMPER BRACKET CTR CLIP (SN)	NOT NECESSARY	33.00	-
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER 'TRANS-CAB' (SN)	NOT NECESSARY	30.00	-
1	BOOT STICKER '6555-3333' (SN)	NOT NECESSARY	30.00	-
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
1	RIGHT REAR TYRE (SN)	SERVICEABLE	330.00	-
1	RIGHT REAR TYRE RIM (SN)	SERVICEABLE	380.00	-
			2,935.02	66.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION		6,000.00	220.00

Report Ref No. CC3/TP18014423/Kea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME INCLUSIVE OF THE REPAIR OF BUMPER COVER REAR,BUMPER BEAM REAR,BUMPER BEAM BRACKET LH REAR,BUMPER BEAM BRACKET RH REAR,BOOT REAR,BOOT HINGE LH,BOOT HINGE RH ,BOOT LOCK,BOOT LOCK CATCH,FENDER PANEL REAR LH,FENDER PANEL REAR RH,TAILLAMP PANEL RH,TAILLAMP PANEL LH,OUTER PANEL REAR (END PANEL),SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL),EXHAUST REAR,EXHAUST CAP REAR,CHASSIS PANEL REAR		4,200.00	200.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR .	NOT NECESSARY	170.00	-
	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			-	-
			-	-
			-	-
			12,920.00	420.00
	GRAND TOTAL		66,727.51	1,177.96

Report Ref No. CC3/TP18014423/Kea3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			950.00
---	--	--	---------------

Report Ref No. CC3/TP18014423/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.