

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5035G

Kew-h

AAD1807-289

*Not Authorized
L/Rep @ 950/.*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHC 5035G
VF1ABL15AUC276025
RENAULT
LATITUDE
30.7.2018
Smt

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>R</i> 1,108.46 <i>X</i>
2	1 BUMPER LOWER REAR	\$	<i>nd/cor</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sm</i> 113.47
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>Sm</i> 135.97
5	1 BUMPER RETAINER RH REAR	\$	<i>Sm</i> 44.99
6	1 BUMPER REFLECTOR RH	\$	<i>Sm</i> 43.61
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>Sm</i> 135.97
8	1 BUMPER RETAINER LH REAR	\$	<i>Sm</i> 44.99
9	1 BUMPER REFLECTOR LH	\$	<i>Sm</i> 43.61
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95
13	1 BOOT REAR	\$	<i>R</i> 2,872.68
14	1 BOOT FINISHER	\$	<i>Sm</i> 470.06 <i>X</i>
15	1 BOOT WHEATERSTRIP	\$	<i>Sm</i> 323.05
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sm</i> 493.35
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sm</i> 493.35
18	1 BOOT BADGE 'RENAULT'	\$	<i>un</i> 225.36
19	1 BOOT BADGE	\$	<i>un</i> 225.36
20	1 BOOT STRUT LH	\$	<i>Sm</i> 276.08
21	1 BOOT STRUT RH	\$	<i>Sm</i> 276.08
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84
24	1 BOOT INNER TRIM	\$	<i>Sm</i> 586.45
25	1 BOOT SWITCH	\$	<i>Sm</i> 168.13
26	1 BOOT LOCK	\$	<i>R</i> 202.67
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40
28	2 LICENCE PLATE LAMP	\$	<i>Sm</i> 50.52
29	2 BOOT RUBBER PLUG	\$	<i>Sm</i> 221.81

Trans-cab Auto Services Pte Ltd

AAD1807-289

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5035G

30	1 FENDER PANEL REAR LH	\$	R	3,299.13	}	
31	1 WHEELARCH REAR LH	\$	Sm	543.47		
32	1 FENDER PANEL INNER TRIM REAR RH	\$	Sm	671.45		
33	1 FENDER PANEL REAR RH	\$	R	3,299.13		
34	1 WHEELARCH REAR RH	\$	Sm	543.47		
35	1 TAILLAMP RH	\$	Sm	552.55		
36	1 TAILLAMP PANEL RH	\$	R	986.70		
37	1 TAILLAMP LH	\$	Sm	552.55		
38	1 TAILLAMP PANEL LH	\$	R	986.70		
39	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77		
40	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sm	404.56		
41	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88		
42	1 SPARE WHEEL PANEL TRIM	\$	Sm	612.21		
43	1 EXHAUST REAR	\$	R	7,489.05		
44	1 EXHAUST CAP REAR	\$	R	230.49		
45	1 CHASSIS PANEL REAR RH	\$	R	3,766.43		
46	1 KUCKLE ARM REAR RH L70Y	\$	Sm	736.67		}
47	1 BRAKE DISC REAR L70Y	\$	Sm	525.91		
48	1 WHEEL HUB NUT L70Y	\$	Sm	51.11		
49	1 WHEEL HUB CAP L70Y	\$	Sm	57.82		
50	1 ABS SENSOR REAR RH L70Y	\$	Sm	255.75		
51	1 REAR AXLE L70Y	\$	Sm	4,167.03		
52	1 AXLE ARM RH L70Y	\$	Sm	117.22		
53	1 LOWER ARM REAR RH L70Y	\$	Sm	905.99		
54	1 ABSORBER REAR	\$	Sm	389.75		
55	1 STABILIZER BAR REAR RH	\$	Sm	604.65		
56	1 BRAKE CALIPER REAR RH	\$	Sm	1,300.67		
57	1 WHEEL HOUSING PANEL REAR RH	\$	R	4,682.09		
58	1 CHASSIS PANEL REAR RH	\$	R	3,766.43		
TOTAL		\$		56,525.01		
10%		\$		5,652.50		
		\$		50,872.51		

Special Nett

1	1SET PARKING AID	\$	Sm	700.00	X
2	1SET REAR BUMPER CLIP	\$	na	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	X
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X

Trans-cab Auto Services Pte Ltd

AAD1807-289

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5035G

5	1SET BUMPR RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	sm	17.82	} X
11	1SET BOOT FINISHER CLIP	\$	na	24.20	
12	1 BOOT STICKER "Trans-cab"	\$	na	30.00	
13	1 BOOT STICKER "6555-3333"	\$	na	30.00	
14	1 BOOT INNER TRIM CLIP	\$	na	45.00	
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
17	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
18	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
19	1 TAILLAMP CLIP RH	\$	na	5.00	
20	1 TAILLAMP CLIP LH	\$	na	5.00	
21	2 REAR WINDSCREEN SELANT	\$	na	80.00	
22	1 WINDSCREEN MOULDING	\$	na	100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sm	385.00	
25	1 SPARE TYRE	\$	sm	330.00	
26	1 RIGHT REAR TYRE	\$	sm	330.00	
27	1 RIGHT REAR TYRE RIM	\$	sm	380.00	

TOTAL \$ 2,935.02

TOTAL PARTS \$ 53,807.53

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	2001
To Rust-Proofing Of The Affected Areas.	\$	na	170.00 X

Trans-cab Auto Services Pte Ltd

AAD1807-289

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5035G

To reinstall rear bumper parking sensor.	\$	<i>na</i> 170.00 X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00 X
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i> 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>na</i> 380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>na</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00 X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 X

TOTAL \$ 12,540.00

Over All Total \$ 66,347.53

(LUMP SUM)

Repair Days

20 DAYS

1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: