

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5107H**AAD1808-024***Not Authorized
L/Lng @ 4200L*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5107H

VF1ABL15AUC276178

RENAULT

LATITUDE

2.8.2018

AIG**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42	✓
2	1	BUMPER SPOILER FRT	\$	<i>Sm</i> 181.75	} ^
3	1	BUMPER ABSORBER FRT	\$	<i>Sm</i> 394.68	
4	1	BUMPER RETAINER FRT LH	\$	<i>Sm</i> 151.41	
5	1	BUMPER SUPPORT FRT	\$	<i>Sm</i> 123.88	
6	1	BUMPER RETAINER FRT RH	\$	<i>Sm</i> 150.77	
7	1	BUMPER SUPPORT FRT	\$	<i>Sm</i> 123.88	
8	1	BUMPER UNDERTRAY FRT	\$	<i>Sm</i> 472.83	
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Sm</i> 266.80	
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sm</i> 207.21	
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sm</i> 207.21	
12	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08	} X
13	1	TOW COVER FRT	\$	<i>Sm</i> 28.61	
14	1	RADIATOR GRILLE	\$	<i>CM</i> 1,707.78	
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>R</i> 225.36	
16	1	RADIATOR GRILLE FRAME	\$	<i>CM</i> 1,353.75	
17	1	FRAME FULL SUPPORT PANEL	\$	<i>CM</i> 615.90	
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79	
19	1	HEADLAMP LH	\$	<i>Sm</i> 1,184.43	
20	1	HEADLAMP RH	\$	<i>Sm</i> 1,184.43	
21	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15	
22	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15	
23	1	BONNET	\$	<i>R</i> 1,941.63	} X
24	1	BONNET INSULATOR	\$	<i>Sm</i> 405.73	
25	1	BONNET STRUT LH	\$	<i>Sm</i> 88.61	
26	1	BONNET STRUT RH	\$	<i>Sm</i> 88.61	
27	1	BONNET HINGE LH	\$	<i>R</i> 348.31	
28	1	BONNET HINGE RH	\$	<i>R</i> 348.31	

Trans-cab Auto Services Pte Ltd**AAD1808-024**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5107H

29	1	BONNET CABLE COVER	\$	SL 161.03 X
30	1	BONNET SEAL OUTER	\$	SL 92.36 X
31	1	BONNET SEAL INNER	\$	SL 157.28 X
32	1	FENDER PANEL FRT LH	\$	R 783.83 X
33	1	FENDER PANEL FRT RH	\$	R 783.83 X

TOTAL	\$	16,347.81
10%	\$	1,634.78
	\$	14,713.03

Specical Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	nn 52.00 ✓
2	1SET	BUMPER CLIP FRT	\$	nn 66.00 ✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	nn 12.00
4	1	BUMPER SUPPORT CLIP FRT LH	\$	nn 10.50
5	1	BUMPER BRACKET CLIP FRT RH	\$	nn 12.00
6	1	BUMPER SUPPORT CLIP FRT RH	\$	nn 10.50
7	1	TOW COVER FRT	\$	nn 14.50
8	1SET	RADAIOR GRILLE SCREW	\$	nn 16.00
9	1SET	BUMPER GRILLE LOWER CLIP	\$	nn 69.00
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn 70.00
11	2	FRAME FULL SUPPORT PANEL NUT	\$	nn 20.00
12	2	FRAME FULL SUPPORT PANEL STUD	\$	nn 30.00
21	1	Windscreen moulding	\$	nn 100.00
22	1SET	Front licence plate with holder	\$	BP 80.00 45.00

TOTAL	\$	562.50
TOTAL PARTS	\$	15,275.53

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts,
adjust and realign the same

\$ 2,450.00 2001

To apply paint protection system (PPS) maintain
and enhancement

\$ 380.00 X

Trans-cab Auto Services Pte Ltd**AAD1808-024**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5107H

Putty and spray painting of the affected portion.	\$	2201 2,200.00
To rust-proofing of the affected areas.	\$	na 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na 380.00 X
To check steering geometry and computer wheel alignment	\$	na 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	na 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 101
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	na 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	na 380.00 X
To replace, refix and top up coolant for radiator	\$	na 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	na 170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	na 170.00 X

TOTAL \$ 7,790.00**Over All Total \$ 23,065.53****(LUMP SUM) Repair Days****7 DAYS***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: