

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AXA INSURANCE SINGAPORE PTE LTD

8, Shenton Way #27-01

AXA TOWER S,pore 068811

Accident date:03/08/18

Date:08/08/18

4 Days.
Unpsum repair
After repair photos.
QuoQing - 82880282
10/8/18.

Estimate cost to repair vel: SJP 6310M (Hyundai Avante) claims under vel: FBM 4420C.

1pce left tail lamp	✓	OK	\$ 282.60
1pce rear bumper	✓	re.	446.00
1set rear bumper reverse sensors	X	NN	450.00
2pcs rear bumper side holders@\$28	✓	OK/NN	56.00
10pcs rear bumper inner clips@\$4	✓	OK	40.00
1pce rear left fender	X	Repair.	1,806.70
1pce rear left fender petrol cover	X		69.00
1pce rear windscreen outer rubber	X		68.00
1set rear windscreen tape from	X		45.00
1pce rear windscreen inner sealant	X		140.00
1pce rear fender top side glass sealant	X	NN	80.00
1pce boot lid	X		985.00
1pce boot lid avante plate	X		26.00
1pce boot lid emblem	X		24.00
1pce boot lid s plate	X		35.00
1pce boot lid reflector	X		155.70
1pce rear panel	X		559.50
			\$ 5,268.50
Less 20%			1,053.70
			4,214.80
Lobour			
To rustproof		X NN	200.00
To check wiring		30	50.00
To remove/refit rear windscreen & side glass		X NN	140.00
To remove/refit petrol tank		X	100.00
To remove/refit rear interior to effect repair		60	100.00
To dismantle/renew reverse sensors		40	100.00
To dismantle/renew accident portion		400	1,800.00

To spray paint

1,500.00
TOTAL \$ 8,204.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: