

INS. CASE OWNER:

100

CC 4, ASM 180

14438, 71 has 302

LKK:

6.2105

IDAC:

Surveyor:

MTH

DOF:

ASSIGNMENT


20/8/2018

Date / Time

21/8/2018

Registered in Meritana:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKH 8919A

Claim No.:

S8m 05 RA3

Name of insured:

Sarame Lim Yen Cheun

Policy No.:

GA309786

Insured Tel No.:

HP:

98807571

Make / Model:

V. Shavan

Excess Sec II :SS

D.O.A.:

4/8/2018

Place of Accident:

Telok Ayer St / Boon Tat St.

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(VL: YES / NO)

Insured Liability: %

Final ? Yes / No

SFC 9554



INSRS: WSP: Tel: Liability: RMKS:

AC



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/ Time	STAGE	DATE / PIC
2/8	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
08/10/18 @ 5:40PM	Call OI: 08/10/18 - vic	
	After call ltr to OI: 09/10/18 - vic	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>
PRELIMINARY ADVICE	Date/Time: [Signature]	Sent By: 21/8
FINALIZATION	Date/Time:	Confirm with:
Repair Cost: P/P	SS 12,565.81 (8 days)	Reduction: 22 %
FINAL SETTLEMENT	Date/Time: 10/08/19	Confirm with: ALAN
Final Liability:	% 100 (Agreed / Assessed)	BOLA S/N No.: 2A
Repair Cost: CW/GRO	SS 13,415.42	
Loss of Rental (LOR):	SS 1,100.00 (11 days) X \$100.00	
Loss of Use (LOU):	SS - (\$ x days)	
Loss of Income (LOI):	SS - (\$ x days)	
LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]
GIA/LTA Search	SS 2.00	
Medical:	SS -	
Disbursement:	SS - (e.g. Tow/Independent)	
Legal Cost	SS -	
Total:	SS 14,547.42	Global Sum SS:
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	SS 14,547.42	Name 1: CYCLE & CARRIAGE INDUSTRIES PTE LTD
Payee 2: (Strike if N.A.)	SS -	Name 2: -
Payee 3: (Strike if N.A.)	SS -	Name 3: -

COPY SENT 14/8/19

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format:
- 3) Survey fee: \$350.00

Tanpin

REG:

AXIA

AXIA 3311.87

Insured: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle At: _____

at Workshop on: _____

at: _____

Insured: _____

Policy No: _____

Claim No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$100K.

IDAC Accident Report Consistent? : Yes or No

GLA / FR Seven Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lump Sum: % 3 Val Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Vehicle No: SFC95554 at Resp: 246 Feb.

Type: M / Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mercedes Benz B180 1595

Colour: Black. MS: Insured / Std / NI / NA

Sp. Reading: 45157 EB: Insured / Std / NI / NA

Eng No: _____

Ch No: WDD24624225371650

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD A/Rim or

Tyre Size: F: 205 / 55 R14
R: - -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or TURANZA

Front		Rear	
R/Bal. 6 mm		R/Bal. 6 mm	
L/Bal. 6 mm		L/Bal. 6 mm	

D.O.A: _____ D.O.L: 20/8/801620

Survey held at: CBL Pander Loop

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

P/R \$12,565.81
 (RBD: \$3,587.34 / 22%)

Time/Time (To/From) _____

: Preli. Report

: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Time/Time (To/Return to) _____

Add Fee: Gate Trip \$5
 Inter-city \$8
 Local \$10
 Night \$15

Report Format: _____

Lump Sum / L.B.T. _____



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SFC9555U

Wang Kim Meng @ Tan Kim Meng

21 Jalan Peradun
Singapore 808666

Vehicle & Document Information

WIP No 25878
Reg No/Reg Date SFC9555U / 11/02/2016
Date In/Mileage / 0
Chassis No WDD2462422J371650
Engine No 27091030826995
Make/Model MB/B 180 SEDAN (W246) "STYLE
Colour/Trim 021 191 Cosmos Blac/ 041 118 Alpaca grey

Table with 5 columns: Account No, Terms, Date/Time Printed, CSE, Operator. Row 1: WCV23741, CRDVCH, 07/08/2018/ 10:15, AQ, 305 / Alan Quek Ai Lun

Main table with 5 columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Includes items like POLICY NO/ACC DATE, BPILAB USE XENTRY, SUPPLY & TRANSFER 1PC REAR RIGHT RIM, etc.

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SFC9555U

Wang Kim Meng @ Tan Kim Meng
21 Jalan Peradun
Singapore 808666

Vehicle & Document Information
WIP No 25878
Reg No/Reg Date SFC9555U / 11/02/2016
Date In/Mileage / 0
Chassis No WDD2462422J371650
Engine No 27091030826995
Make/Model MB/B 180 SEDAN (W246) "STYLE
Colour/Trim 021 191 Cosmos Blac/ 041 118 Alpaca grey

Account No WCV23741, Terms CRDVCH, Date/Time Printed 07/08/2018/ 10:15, CSE AQ, Operator 305 / Alan Quek Ai Lun

Table with 5 columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Includes items like RH/R DOOR ORNAMENTAL, RH/R DOOR INSULATION, etc.

ESTIMATE (large watermark)

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarrriage.com.sg

Tan Kim 97425749
-wp'
20/8/18 @ 1620
sure @ kkan...
Resurvey before part
8 days

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification allowed
• Supplemental survey must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

Confirmed & accepted by

Authorized signatory and company stamp

Nett 16,102.77
7% GST on 16102.77 1127.19
Total Payable 17,229.96
16,153.15

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorized Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SFC9555U

Finalization

Mr Wang Kim Meng @ Tan Kim Meng

C/O AXA INSURANCE PTE LTD
MOTOR CLAIM DEPARTMENT
8 SHENTON WAY #24-01
SINGAPORE 068811
63387288

Tanfikh

Vehicle & Document Information

WIP No 25878
Reg No/Reg Date SFC9555U / 11/02/2016
Date in/Mileage 20/08/2018 / 45157
Chassis No SWDD2462422J371650
Engine No 27091030826995
Make/Model MB/B 180 SEDAN (W246) "STYLE
Colour/Trim 021 191 Cosmos Blac/ 041 118 Alpaca grey

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	26/12/2018/ 12:21	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
OFFICIAL TAX INVOICE				
M BPNSUN POLICY NO/ACC DATE : 2100447911 // 04-08-2018 DRIVE IN-06-08-2018 // TP CAR NO: SKH8919A (AXA INSURANCE) DATE IN/DATE SURVEY: 20-08-2018 // LKK TAUFIKH BY/AUTHORIZED ON : LKK VIC ALPEH // 16-08-2018				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
A BPILAB TRANSFER MECHANICAL & ELECTRICAL COMPONENTS TO NEW DOOR.NETT				960.00
S BPN SUB LABOUR TO REMOVE AND INSTALL TYRE FROM RIM (RUN FLAT) WHEEL BALANCE AND INSTALL NEW VALVE HEAD				60.00
A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT				540.00
A BPILAB REMOVE & REPLACE FRONT RIGHT DOOR, REAR RIGHT DOOR & REPAIR REAR RIGHT FENDER AND REAR BUMPER				2880.00
A BPIRES RESPRAY FRONT RIGHT DOOR, REAR RIGHT DOOR, REAR RIGHT FENDER, REAR BUMPER, REAR RIGHT DOOR HANDLE & RIGHT RUNNING BOARD				2700.00
X RH/R DISC WHEEL	1.00	503.18	00.00	503.18
X RH/F DOOR SHELL	1.00	1568.90	00.00	1568.90
X RH/F DOOR WEATHERSTRIP	1.00	280.72	00.00	280.72
X RH/F DOOR INSULATION	1.00	62.05	00.00	62.05
X RH/F DOOR ORNAMENTAL	1.00	112.66	00.00	112.66
X RH/F DOOR WINDOW GUIDE RAIL	1.00	73.78	00.00	73.78
X RH/R DOOR SHELL	1.00	1682.48	00.00	1682.48
X RH/R DOOR WEATHERSTRIP	1.00	280.72	00.00	280.72
X RHF/R DOOR ORNAMENTAL	1.00	126.99	00.00	126.99
X RHR/R DOOR ORNAMENTAL	1.00	126.99	00.00	126.99
X RH/R DOOR INSULATION	1.00	62.05	00.00	62.05

ESTIMATE 8 Days

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SFC9555U

Finalization

Mr Wang Kim Meng @ Tan Kim Meng

C/O AXA INSURANCE PTE LTD
MOTOR CLAIM DEPARTMENT
8 SHENTON WAY #24-01
SINGAPORE 068811
63387288

Vehicle & Document information

WIP No 25878
Reg No/Reg Date SFC9555U / 11/02/2016
Date in/Mileage 20/08/2018/45157
Chassis No SWDD2462422J371650
Engine No 27091030826995
Make/Model MB/B 180 SEDAN (W246) *STYLE
Colour/Trim 021 191 Cosmos Blac/ 041 118 Alpaca grey

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	26/12/2018/ 12:21	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X RH/R DOOR WINDOW GUIDE RAIL	1.00	114.91	00.00	114.91
X BLIND RIVET WITH PAN HEAD	22.00	2.29	00.00	50.38

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 12,565.81
7% GST on 12565.81 879.61
Total Payable 13,445.42

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SFC9555U

SUPPLEMENTARY

Mr Wang Kim Meng @ Tan Kim Meng

C/O AXA INSURANCE PTE LTD
MOTOR CLAIM DEPARTMENT
8 SHENTON WAY #24-01
SINGAPORE 068811
63387288

Vehicle & Document Information
WIP No 25878
Reg No/Reg Date SFC9555U / 11/02/2016
Date In/Mileage 20/08/2018 / 45157
Chassis No **S**WDB2462422J371650
Engine No 27091030826995
Make/Model MB/B 180 SEDAN (W246) *STYLE
Colour/Trim 021 191 Cosmos Blac/ 041 118 Alpaca grey

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	26/12/2018/ 12:20	AQ	305 / Alan Quek At Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M. BPNSUN POLICY NO/ACC DATE : 2100447911 // 04-08-2018 DRIVE IN=06-08-2018 // TP CAR NO: SKH8919A (AXA INSURANCE) DATE IN/DATE SURVEY: 20-08-2018 // LKK TAUFIKH BY/AUTHORIZED ON : LKK VIC ALPEH // 16-08-2018 X BLIND RIVET WITH PAN HEAD	22.00	2.29	00.00	50.38 ✓

OFFICIAL TAX INVOICE

ESTIMATE

SUPPLEMENTARY

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

	Nett	50.38
7% GST on	50.38	3.53
	Total Payable	53.91

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Tuesday, 7 August 2018 12:53 PM
To: assignments
Subject: FW: SFC9555U / SKH8919A Date of accident:04-08-2018
Attachments: img-807101617-0001.pdf; SFC9555U.PDF

2. 12pm @ 7/8/2018
vehicle not in
person @ Alan

Hi Nivitha,

Kindly assist.

TP AXA – Smart.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Alan Quek Ai Lun <alan.quek@cyclecarriage.com.sg>
Sent: Tuesday, 7 August, 2018 10:57 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Subject: SFC9555U / SKH8919A Date of accident:04-08-2018

AXA INSURANCE SINGAPORE PTE LTD

Attn: Motor Claims Dept

RE: Accident involving motor vehicle nos. **SFC 9555 U & SKH 8919 A.**
Along **TELOK AYER STREET.**

We have instructs by our client's of motor vehicle no:**SFC 9555 U**, which was involved in the above accident. Our client's vehicle was damaged and. We now claiming against you for costs of repair and other consequential loss.

In order that you are the insurer of vehicle no:**SKH 8919 A** are willing to DIRECT SETTLEMENT and other incidental claims. We shall be grateful if you could kindly settle the cost of repair directly with us. On this note we will be much appreciated and looking forward to your Confirmation of settlement.

Your Sincerely

Alan Quek
Service Advisor

Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Tel: 6771 4377 | DID: 9186 5112 | Fax: 6872 1272
Website: www.mercedes-benz.com.sg



Exceptional Journeys



 Please consider the environment before printing this e-mail.

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.



Re:<REVISED MANDATE> S8M00R83

Type

🔗 Question

Message

PLS PROCEED AS RECOMMENDED.

Reply

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKH 8919A (Insd veh)	Model:	MERCEDES BENZ B180
	SFC 9555U (TP veh)		
Date of Accident:	04/08/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$		17,283.87
Final Repair Cost	: \$		13,445.42
Loss of Use	: \$		days at \$0.00 per day
Rental (if any)	: \$		1,100.00 11 days
LTA / GIA Search Fee	: \$		2.00

Others: : \$

: \$

Final Settlement Sum : \$ 14,547.42

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: 24

BOLA Liability: 100 (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown		
1)	CYCLE & CARRIAGE INDUSTRIES PTE LTD	: \$ 14,547.42

NUR SHAQILAH BTE ABDOL
WAHAB

24/05/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18014438/T1ha3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 24-05-2019



ATTN: KIAN CHUAN

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKH 8919A	Veh. Inspected	SFC 9555U
Policy No.	GA309776	Coverage (\$)	0.00
Claim No.	S8M00R83	Excess (\$)	0.00
Assign From	KIAN CHUAN	Assign Date	07/08/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ B180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDD2462422J371650	Colour	BLACK
Odometer	45157	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55R16	TURANZA	6 mm
L/H Front Tyre	205/55R16	TURANZA	6 mm
R/H Rear Tyre	205/55R16	TURANZA	6 mm
L/H Rear Tyre	205/55R16	TURANZA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/08/2018	Inspection Date	20/08/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFC 9555U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RH / R DISC WHEEL (SN) (CONSISTENT)	CUT	503.18	503.18
1	RH / R BUMPER SIDE BRACKET (SN) (CONSISTENT)	NOT NECESSARY	8.93	-
1	RH / F DOOR SHELL (SN) (CONSISTENT)	BENT	1,568.90	1,568.90
1	RH / F DOOR WEATHERSTRIP (SN) (CONSISTENT)	NECESSARY	280.72	280.72
1	RH / F INSULATION (SN) (CONSISTENT)	NECESSARY	62.05	62.05
1	RH / F DOOR ORNAMENTAL (SN) (CONSISTENT)	NECESSARY	112.66	112.66
1	RH / F DOOR LOCK (SN) (CONSISTENT)	NOT NECESSARY	289.91	-
1	RH / F DOOR WINDOW LIFTER (SN) (CONSISTENT)	NOT NECESSARY	540.81	-
1	RH / F DOOR WINDOW GUIDE RAIL (SN) (CONSISTENT)	NECESSARY	73.78	73.78
1	RH / R DOOR SHELL (SN) (CONSISTENT)	BENT	1,682.48	1,682.48
1	RH / R DOOR WEATHERSTRIP (SN) (CONSISTENT)	NECESSARY	280.72	280.72
1	RHF / R DOOR ORNAMENTAL (SN) (CONSISTENT)	NECESSARY	126.99	126.99
1	RHR / R DOOR ORNAMENTAL (SN) (CONSISTENT)	NECESSARY	126.99	126.99
1	RH / R DOOR INSULATION (SN) (CONSISTENT)	NECESSARY	62.05	62.05
1	RH / R DOOR TOP HINGE (SN) (CONSISTENT)	NOT NECESSARY	97.30	-
1	RH / R DOOR BOTTOM HINGE (SN) (CONSISTENT)	NOT NECESSARY	121.72	-
1	RH / R DOOR LOCK (SN) (CONSISTENT)	NOT NECESSARY	285.84	-
1	RH / R DOOR WINDOW LIFTER (SN) (CONSISTENT)	NOT NECESSARY	582.83	-
1	RH / R DOOR WINDOW GUIDE RAIL (SN) (CONSISTENT)	NECESSARY	114.91	114.91
1	REAR RIGHT RIM (SN) (CONSISTENT)	NECESSARY	60.00	60.00
22	BLIND RIVET WITH PAN HEAD (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	50.38	50.38
			7,033.15	5,105.81
LABOUR				
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.			380.00	380.00
TRANSFER MECHANICAL & ELECTRICAL COMPONENTS TO NEW DOOR.			960.00	960.00
INSPECT & CONDUCT WHEEL ALIGNMENT.			540.00	540.00
REMOVE & REPLACE FRONT RIGHT DOOR, REAR RIGHT DOOR & REPAIR REAR RIGHT FENDER AND REAR BUMPER.			3,840.00	2,880.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RESPRAY FRONT RIGHT DOOR, REAR RIGHT DOOR, REAR RIGHT FENDER, REAR BUMPER & RIGHT RUNNING BOARD.		3,400.00	2,700.00
			9,120.00	7,460.00
GRAND TOTAL			16,153.15	12,565.81
RECOMMENDED COST OF REPAIRS				12,565.81

Report Ref No. CC4/ASM18014438/T1ha3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.