



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SFC9555U

Wang Kim Meng @ Tan Kim Meng
21 Jalan Peradun
Singapore 808666

Vehicle & Document Information

WIP No 25878
Reg No/Reg Date SFC9555U / 11/02/2016
Date In/Mileage / 0
Chassis No WDD246242J371650
Engine No 27091030826995
Make/Model MB/B 180 SEDAN (W246) "STYLE
Colour/Trim 021 191 Cosmos Blac/ 041 118 Alpaca grey

Account No	Terms	Date/Time Printed	CSE	Operator
WCV23741	CRDVCH	07/08/2018/ 10:15	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : 2100447911 // 04-08-2018 DRIVE IN: 06-08-2018 // TP CAR NO: SKH8919A (AXA INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
A BPILAB TRANSFER MECHANICAL & ELECTRICAL COMPONENTS TO NEW DOOR.NETT				960.00
S BPNSUB SUPPLY & TRANSFER 1PC REAR RIGHT RIM PURCHASE ORDER NO:				60.00
A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT				540.00
A BPILAB REMOVE & REPLACE FRONT RIGHT DOOR, REAR RIGHT DOOR & REPAIR REAR RIGHT FENDER AND REAR BUMPER				3840.00
A BPIRES RESPRAY FRONT RIGHT DOOR, REAR RIGHT DOOR, REAR RIGHT FENDER, REAR BUMPER & RIGHT RUNNING BOARD			0.02	3400.00
M RH/R DISC WHEEL	1.00	503.18	00.00	503.18
M RH/R BUMPER SIDE BRACKET	1.00	8.93	00.00	8.93
M RH/F DOOR SHELL	1.00	1568.90	00.00	1568.90
M RH/F DOOR WEATHERSTRIP	1.00	280.72	00.00	280.72
M RH/F DOOR INSULATION	1.00	62.05	00.00	62.05
M RH/F DOOR ORNAMENTAL	1.00	112.66	00.00	112.66
M RH/F DOOR LOCK	1.00	289.91	00.00	289.91
M RH/F DOOR WINDOW LIFTER	1.00	540.81	00.00	540.81
M RH/F DOOR WINDOW GUIDE RAIL	1.00	73.78	00.00	73.78
M RH/R DOOR SHELL	1.00	1682.48	00.00	1682.48
M RH/R DOOR WEATHERSTRIP	1.00	280.72	00.00	280.72

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SFC9555U

Wang Kim Meng @ Tan Kim Meng

21 Jalan Peradun
Singapore 808666

Vehicle & Document Information

WIP No **25878**
Reg No/Reg Date **SFC9555U / 11/02/2016**
Date In/Mileage **SFC9555U / 0**
Chassis No **WDD2462422J371650**
Engine No **27091030826995**
Make/Model **MB/B 180 SEDAN (W246) "STYLE**
Colour/Trim **021 191 Cosmos Blac/ 041 118 Alpaca grey**

Account No	Terms	Date/Time Printed	CSE	Operator
WCV23741	CRDVCH	07/08/2018/ 10:15	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RH/R DOOR ORNAMENTAL	1.00	126.99	00.00	126.99
M RHR/R DOOR ORNAMENTAL	1.00	126.99	00.00	126.99
M RH/R DOOR INSULATION	1.00	62.05	00.00	62.05
M RH/R DOOR TOP HINGE	1.00	97.30	00.00	97.30
M RH/R DOOR BOTTOM HINGE	1.00	121.72	00.00	121.72
M RH/R DOOR LOCK	1.00	285.84	00.00	285.84
M RH/R DOOR WINDOW LIFTER	1.00	582.83	00.00	582.83
M RH/R DOOR WINDOW GUIDE RAIL	1.00	114.91	00.00	114.91

THIS IS NOT AN OFFICIAL TAX INVOICE
ESTIMATE

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 16,102.77
7% GST on 16102.77 1127.19

Authorized signatory and company stamp

Total Payable 17,229.96

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg