

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

6-Aug-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1404 X

1 pc	Front n/s head lamp X	\$	1,531.57
1 pc	Front bumper /	\$	811.11
1 pc	Front bumper emblem X	\$	27.80
2 pcs	Front bumper o/s & n/s side bracket @\$32.51 X	\$	65.02
1 pc	Front n/s fender /	\$	514.02
1 pc	Front n/s rim /	\$	246.00
1 pc	Front n/s fender signal lamp /	\$	32.10
		\$	3,227.62
Less 20%		\$	645.52
		\$	2,582.10

S/NETT

1 set	Front bumper clips /	\$	48.00
1 pc	Front n/s fender sticker /	\$	30.00
Sundry		\$	50.00 ²⁰
To check wheel alignment		\$	80.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc		\$	750.00 ⁴⁰⁰
To putty and spray painting on front bumper, front n/s fender		\$	500.00 ³⁶⁰
To apply rustproofing on the repaired and replaced panels.		\$	150.00 ⁵⁰
		\$	4,190.10

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahar ICCK,
8/8/18 09 45h
3 1/2
PIP
Before Pull P

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____