

22/03/2002

ASS. REC. BY:

REF: CS/CTI18014444/Arb3<sup>n2</sup>

Special Instruction:

Survivor  
Manner

Adrian

ASSIGNMENT (Office)

From (Person):

Janyu Ty

of

CTI

Date/Time: 7/8/18 @ 3:06pm

Estimated Cost:

Bill to:

OD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

EY 3287D

Insured:

SCL 5833G

at Workshop m/s

Trans Euro Cars

Tel:

63457577

of

5 ubi close

Policy No:

DMPCSN 3009681804

Claim No:

SNM18D 0383802

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 6/8/2018

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

3:18pm @ 8/8/18

Person Contacted:

Vion

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	EY 3287D-X
	SCL 5833G-CB/AIG 09016155/wz1
	DOA: 9/4/2007

(08/11/13) wef

REF: CFI

ASS. REC. BY:

## ASSIGNMENT

From: Date: 8/8/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

lup

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

EY3287D

Yr Regn: 2018 / June

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda MX5

c.c. 1998

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

585

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6ND2ETAJ0200057

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

205/45R17

R:

205/45R17

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

08/08/18

Survey held at

TransEuropa

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP China

Final fig 23,085.65 (Red. 10, 206.20, 76%)

RECEIVED 15 OCT 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

220

Report Format:

TP

Lump Sum / I.B.I: (\$ 3,085.65)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18014444/Ard3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 08-08-2018



Code : CTI

## Policy Particulars :- THIRD PARTY CLAIM

1.

Insured Veh.	SCL 5833G	Veh. Inspected	EY 3287D
Policy No.	DMPCSN3009681804	Coverage (\$)	0.00
Claim No.	SNM18D03838C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	08/08/2018

## Vehicle Particulars & Condition

2.

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## Conditions of Tyres

3.

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## Description of Damages

4.

--

## General Information

5.

Accident Date	06/08/2018	Inspection Date	08/08/2018
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605		

## Remarks

5a.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Aug 2018		07 Aug 2018 15:06 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:			
Main Claimant:	LEE JET TONG		
Vehicle Reg. No.:	EY3287D	Date of Loss:	06/08/2018 00:00 - :59
Claim Type:	TP / SNM18D03838C02	Policy/Cover Note No.:	DMPCSN3009681804
Vehicle Reg. No. (Insured):	SCL5833G	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Trans Eurokars Pte Ltd (HQ) 5 Ubi Close, 408605 Ubi - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... <b>[Final Rpt due 17/08/2018]</b>		
Adj Asg. Remarks:	EST \$13,291.85, CASE WITH SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	5252Z
<b>Vehicle Details</b>	
Vehicle No.:	EY3287D
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Oct 2018
Vehicle Make:	MAZDA
Vehicle Model:	MX-5 HARDTOP 2.0 AT 2WD
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	PE31183695
Chassis No.:	JM6ND2E7AJ0200057
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$37,733.00
Original Registration Date:	28 Jun 2018
First Registration Date:	28 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$44,827.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2028
PARF Rebate Amount:	\$33,620.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	27 Jun 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,989.00
COE Rebate Amount:	\$36,849.00
<b>Total Rebate Amount:</b>	<b>\$70,469.00</b>

The information contained herein is correct as at 15 Oct 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	06/08/2018 20:00
Date Of Accident	06/08/2018 07:50
Exact Location Of Accident	BUKIT TIMAH ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	EY3287D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LEE JET TONG
NRIC No	S6915252Z
Email Address	WHYPAYLESS@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-91999991
Alternative Phone No	OFFICE-NOPHONE

### Vehicle Particulars

Manufacturer	MAZDA
Model	MX-5-2.0 6AT
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

### Driver

Name of Driver	LEE JET TONG
NRIC No	S6915252Z
Date Of Birth	06/05/1969
Occupation	INDOOR
Date Of Driving Pass	01/01/1998
Driving Experience	20 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91999991
Fax Number	
Contact Number	OFFICE-NOPHONE
EEmail Address	WHYPAYLESS@YAHOO.COM.SG

Address	24 CANBERRA DRIVE #15-10
Postcode	768427
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SCL5833G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NG BEE LENG
NRIC/Passport Number	S7011990J
Contact Number	91058501
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 6/8/2018  
11:00 AM

Driver's Signature

(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature

Name:  
NRIC/FIN No.:

GUARANTEE Sketch Plan form\_V3




# Sketch Plan Pg. 2

## SKETCH PLAN

Bt. Timah Road  
(City-bound)

Turn  
city  
(slip road)



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- I was on Bt. Timah road, in direction of City, near Turf City slip road, on 6 Aug 2018, 7:50am
- My car came to a stop due to the traffic in front, and the Jaguar XJ6 (SCL5833G) also came to a stop right behind me.
- When the cars in front started to move off, I was also preparing to move off when SCL5833G rangged me from behind.
- The lady driver Ms Ng Bee Leng (S70119903) apologised to me.
  - She claimed that the car is in her husband's name
  - She also claimed to have no insurance particular with her in the car
- We took pictures of each other NRIC & Driving Licence, and also pictures of both cars, before driving off.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 6/8/2018  
11:00AM

Driver's Signature

(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature

Name:  
NRIC/FIN No.:

Trans Eurokars Pte Ltd  
Singapore 408605  
Tel: 6474 0003 / 6749 4333  
Fax: 6746 0660



**TRANS EUROKARS PTE LTD**  
**NO:5 UBI CLOSE, SINGAPORE 408605**  
**ESTIMATE COST OF REPAIRS**



CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Lee Jet Tong ADDRESS : 24 Canberra Drive #15-10 Singapore 768427 TEL :		WIP : 21190 EXCESS : DATE: 7-Aug-18	
VEH NO :	EY3287D	DATE IN :		CONTACT PERSON :	Vion 63957877
CHASSIS NO :	JM6ND2E7AJ0200057	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MX5	DATE REG.:	28-Jun-18	POLICY NO. :	
<b>NATURE OF WORKS</b>					
<b>Parts Description</b>					
NO	QTY	REVISED	PRICES		
1	REAR BUMPER <i>behind</i>	1	MNAY5-50-22X BB	\$ 1,021.00	✓
2	RETAINER CENTER LHS, REAR BUMPER <i>3 not</i>	1	MN243-50-2R2	\$ 10.80	+
3	RETAINER CENTER RHS, REAR BUMPER <i>2 not</i>	1	MN243-50-2R1	\$ 10.80	+
4	BRACKET CENTER, REAR BUMPER <i>new</i>	1	MKD53-50-251	\$ 5.10	✓
5	BRACKET LHS, REAR BUMPER <i>3 not</i>	1	MN243-50-161A	\$ 24.80	+
6	BRACKET RHS, REAR BUMPER <i>2 not</i>	1	MN243-50-151A	\$ 24.80	+
7	BRACKET LOWER LHS, REAR BUMPER <i>3 not behind</i>	1	MN243-50-331B	\$ 25.90	✓
8	BRACKET LOWER RHS, REAR BUMPER	1	MN243-50-321B	\$ 25.90	✓
9	REAR REINFORCEMENT <i>new</i>	1	MNA1J-50-260	\$ 634.40	+
10	SENSOR, ULTRASONIC <i>3 not</i>	4	MDA6T-67-UC1 64	\$ 517.20	+
11	CORD SHORT, SENSOR <i>2 not</i>	1	MN80D-67-290	\$ 317.70	+
12	FASTENER, REAR BUMPER <i>3 not</i>	4	MB45A-56-146A	\$ 11.20	✓
13	GROMMET, REAR BUMPER	2	MBHN1-50-021A	\$ 5.00	✓
14	RIVET, REAR BUMPER <i>new</i>	4	MBN8F-50-355	\$ 21.60	✓
15	LAMP LHS, TAILLAMP <i>2 not</i>	1	MN243-51-160F	\$ 784.00	+
16	GROMMET, TAILLAMP <i>2 not</i>	1	MBHN1-50-021A	\$ 2.50	+
17	FASTENER, TAILLAMP	1	MKD53-51-146B	\$ 3.90	+
18	FASTENER, TAILLAMP	1	MGJ6A-51-14Y	\$ 14.90	+
19	REFLECTOR LAMP LHS <i>not new</i>	1	MN244-51-250B	\$ 163.60	+
20	CLIP, LAMP <i>not new</i>	1	MC274-50-133	\$ 3.50	+
21	SEAL RUBBER, REAR BUMPER <i>3 not</i>	2	MN243-50-2G2	\$ 17.80	+
22	SEAL RUBBER, REAR BUMPER <i>2 not</i>	4	MNC10-50-2G2	\$ 8.40	+
23	TAPE PROTECTOR, REAR BUMPER <i>new</i>	2	MG043-62-864A	\$ 6.60	✓
24	BOOTLID <i>not new</i>	1	MN2Y8-52-61XA	\$ 1,550.50	+
25	BOOTLID LOCK <i>not new</i>	1	MN243-56-820	\$ 228.40	+
26	LAMP, LICENSE PLATE <i>combined</i>	2	MD09H-51-270A	\$ 106.20	✓
TOTAL PARTS				\$ 5,546.50	
LESS 10%				\$ 554.65	
TOTAL PARTS COST				\$ 4,991.85	

Labour Description			
1	MZ-BR-REAR03	TO REPLACE REAR BUMPER, REAR REINFORCEMENT AND BOOT LID. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 2,640.00 <i>660</i>
2	MZ-SP-SREAR3	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT AND BOOT LID.	\$ 2,520.00 <i>630</i>
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	\$ 660.00 <i>300</i>
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	\$ 660.00 <i>x</i>
5	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE. <i>crushed</i>	NETT \$ 70.00 <i>-</i>
6	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 250.00 <i>x</i>
7	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 250.00 <i>120</i>
8	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 350.00 <i>180</i>
9		TO SUPPLY BRILA PREMIUM COATING.	NETT \$ 800.00 <i>x</i>
10	MZ-BR-SUNDRI	SUNDRIES. <i>rec</i>	NETT \$ 100.00 <i>20</i>
TOTAL LABOUR			\$ - \$ 8,300.00
TOTAL PARTS			\$ - \$ 4,991.85
TOTAL			\$ - \$ 13,291.85
LESS EXCESS			\$ - \$ -
TOTAL AFTER EXCESS			\$ -
GST 7%			\$ - \$ -
GRAND TOTAL			\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

Adrian Ling. 96893735  
P/P 08/08/18  
030mgs



**TRANS EUROKARS PTE LTD**  
**NO:5 UBI CLOSE, SINGAPORE 408605**  
**FINALISED COST OF REPAIRS**



<b>CHINA TAIPING INSURANCE P/L</b> 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 ATTN : MOTOR CLAIMS FAX :		<b>NAME :</b> Mr Lee Jet Tong <b>ADDRESS :</b> 24 Canberra Drive #15-10 Singapore 768427 <b>TEL :</b>		<b>WIP :</b> 21190 <b>EXCESS :</b> <b>DATE:</b> 7-Aug-18	
<b>VEH NO :</b>	<b>EY3287D</b>	<b>DATE IN :</b>		<b>CONTACT PERSON :</b>	Vion 63957877
<b>CHASSIS NO :</b>	JM6ND2E7AJ0200057	<b>MILEAGE :</b>		<b>TYPE OF CLAIM :</b>	THIRD PARTY CLAIM
<b>MODEL :</b>	MX5	<b>DATE REG.:</b>	28-Jun-18	<b>POLICY NO. :</b>	

**NATURE OF WORKS**

**Parts Description**

NO	QTY		REVISED	PRICES
1	1	MNAY5-50-22X BB	\$ 1,021.00	\$ 1,021.00
2	1	MN243-50-2R2		\$ 10.80
3	1	MN243-50-2R1		\$ 10.80
4	1	MKD53-50-251	\$ 5.10	\$ 5.10
5	1	MN243-50-161A		\$ 24.80
6	1	MN243-50-151A		\$ 24.80
7	1	MN243-50-331B	\$ 25.90	\$ 25.90
8	1	MN243-50-321B	\$ 25.90	\$ 25.90
9	1	MNA1J-50-260		\$ 634.40
10	4	MDA6T-67-UC1 64		\$ 517.20
11	1	MNB0D-67-290		\$ 317.70
12	4	MB45A-56-146A	\$ 11.20	\$ 11.20
13	2	MBHN1-50-0Z1A	\$ 5.00	\$ 5.00
14	4	MBN8F-50-355	\$ 21.60	\$ 21.60
15	1	MN243-51-160F		\$ 784.00
16	1	MBHN1-50-0Z1A		\$ 2.50
17	1	MKD53-51-146B		\$ 3.90
18	1	MGJ6A-51-14Y		\$ 14.90
19	1	MN244-51-250B		\$ 163.60
20	1	MC274-50-133		\$ 3.50
21	2	MN243-50-2G2		\$ 17.80
22	4	MNC10-50-2G2		\$ 8.40
23	2	MG043-62-864A	\$ 6.60	\$ 6.60
24	1	MN2Y8-52-61XA		\$ 1,550.50
25	1	MN243-56-820		\$ 228.40
26	2	MD09H-51-270A	\$ 106.20	\$ 106.20
<b>TOTAL PARTS</b>			<b>\$ 1,228.50</b>	<b>\$ 5,546.50</b>
<b>LESS 10%</b>			<b>\$ 122.85</b>	<b>\$ 554.65</b>
<b>TOTAL PARTS COST</b>			<b>\$ 1,105.65</b>	<b>\$ 4,991.85</b>

Labour Description				
1	MZ-BR-REAR01	TO REPLACE REAR BUMPER. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 660.00	\$ 2,640.00
2	MZ-SP-SREAR1	TO RESPRAY REAR BUMPER.	\$ 630.00	\$ 2,520.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	\$ 300.00	\$ 660.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.		\$ 660.00
5	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	\$ 70.00	\$ 70.00
6	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
7	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00
8	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
9		TO SUPPLY BRILA PREMIUM COATING.		\$ 800.00
10	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
TOTAL LABOUR			\$ 1,980.00	\$ 8,300.00
TOTAL PARTS			\$ 1,105.65	\$ 4,991.85
TOTAL			\$ 3,085.65	\$ 13,291.85
LESS EXCESS			\$ -	\$ -
TOTAL AFTER EXCESS			\$ 3,085.65	
GST 7%			\$ 216.00	\$ -
GRAND TOTAL			\$ 3,301.65	\$ -

REMARKS:

3 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

## LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18014444/ARD3N2

Date: 16/10/2018

## REFERENCE

<b>Handling Insurer:</b>	China Taiping Insurance (Singapore) Pte. Ltd.	<b>Policy No:</b>	DMPCSN3009681804
<b>Claimant Vehicle No :</b>	EY3287D	<b>Insured Vehicle No :</b>	SCL5833G
<b>Date of Loss:</b>	06/08/2018	<b>Nature of Claim:</b>	TP
		<b>Claim No:</b>	SNM18D03838C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

<b>Reg No:</b>	EY3287D	<b>Engine No:</b>	PE31183695
<b>Make &amp; Model:</b>	MAZDA MX-5, 2.0 6AT	<b>Chassis No:</b>	JM6ND2E7AJ0200057
<b>Reg. Date:</b>	28/06/2018 (Man. Year: 2018)	<b>Odometer:</b>	585 km
<b>Colour:</b>	White		
<b>Engine Capacity:</b>	1998 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (S\$):</b>	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

<b>General Condition:</b>	<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	Yes	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>

## CONDITION OF TYRES

<b>Front Tyre Size:</b>	205/45R17	<b>Rear Tyre Size:</b>	205/45R17
<b>Front Left Side:</b>	Bridgestone 6 mm	<b>Rear Left Side:</b>	Bridgestone 6 mm
<b>Front Right Side:</b>	Bridgestone 6 mm	<b>Rear Right Side:</b>	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,161.85	1,195.65	3,966.20	76.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,130.00	1,890.00	6,240.00	76.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>13,291.85</b>	<b>3,085.65</b>	<b>10,206.20</b>	<b>76.79</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>930.43</b>	<b>216.00</b>	<b>714.43</b>	<b>76.78</b>
<b>Nett Amount (S\$)</b>	<b>14,222.28</b>	<b>3,301.65</b>	<b>10,920.63</b>	<b>76.79</b>

## INSPECTION

<b>Date of Assignment:</b>	07/08/2018	<b>Inspected At:</b>	Trans Eurokars Pte Ltd (HQ)
<b>Date Inspected:</b>	08/08/2018		5 Ubi Close
			Singapore 408605
<b>Estimated Period of Repair:</b>	3.0 days		

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 16 Oct 2018)	
<b>Parts:</b>	N/A	MAZDA MX-5 2.0 6AT (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for EY3287D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,021.00 FL	*1,021.00 FL
2	1		*RETAINER CENTER LHS,REAR BUMPER	Not Necessary	10.80 FL	*- FL
3	1		*RETAINER CENTER RHS,REAR BUMPER	Not Necessary	10.80 FL	*- FL
4	1		*BRACKET CENTER,REAR BUMPER	Necessary	5.10 FL	*5.10 FL
5	1		*BRACKET LHS,REAR BUMPER	Not Necessary	24.80 FL	*- FL
6	1		*BRACKET RHS,REAR BUMPER	Not Necessary	24.80 FL	*- FL
7	1		*BRACKET LOWER LHS,REAR BUMPER	Deformed	25.90 FL	*25.90 FL
8	1		*BRACKET LOWER RHS,REAR BUMPER	Deformed	25.90 FL	*25.90 FL
9	1		*REAR REINFORCEMENT	Not Necessary	634.40 FL	*- FL
10	4		*SENSOR,ULTRASONIC	Not Necessary	517.20 FL	*- FL
11	1		*CORD SHORT,SENSOR	Not Necessary	317.70 FL	*- FL
12	4		*FASTENER,REAR BUMPER	Necessary	11.20 FL	*11.20 FL
13	2		*GROMMET,REAR BUMPER	Necessary	5.00 FL	*5.00 FL
14	4		*RIVET,REAR BUMPER	Necessary	21.60 FL	*21.60 FL
15	1		*LAMP LHS,TAILLAMP	Not Necessary	784.00 FL	*- FL
16	1		*GROMMET,TAILLAMP	Not Necessary	2.50 FL	*- FL
17	1		*FASTENER,TAILLAMP	Not Necessary	3.90 FL	*- FL
18	1		*FASTENER,TAILLAMP	Not Necessary	14.90 FL	*- FL
19	1		*REFLECTOR LAMP LHS	Not Necessary	163.60 FL	*- FL
20	1		*CLIP,LAMP	Not Necessary	3.50 FL	*- FL
21	2		*SEAL RUBBER,REAR BUMPER	Not Necessary	17.80 FL	*- FL
22	4		*SEAL RUBBER,REAR BUMPER	Not Necessary	8.40 FL	*- FL
23	2		*TAPE PROTECTOR,REAR BUMPER	Necessary	6.60 FL	*6.60 FL
24	1		*BOOTLID	Not Necessary	1,550.50 FL	*- FL
25	1		*BOOTLID LOCK	Not Necessary	228.40 FL	*- FL
26	2		*LAMP,LICENSE PLATE	Cracked	106.20 FL	*106.20 FL
27	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
28	1		*NUMBER PLATE	Cracked	70.00 FS	*70.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,716.50</b>	<b>1,318.50</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>554.65</b>	<b>122.85</b>
<b>Total Parts (\$\$)</b>	<b>5,161.85</b>	<b>1,195.65</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER,REAR REINFORCEMENT AND BOOT LID .REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	2,640.00	660.00
2	TO RESPRAY REAR BUMPER,REAR REINFORCEMENT AND BOOT LID	New	2,520.00	630.00
3	TO TRANSFER REVERSE SENSORS	New	660.00	300.00
4	TO TRANSFER REVERSE CAMERA	New	660.00	-
5	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	-
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	120.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
8	TO SUPPLY BRILA PREMIUM COATING	New	800.00	-
<b>Gross Labour Cost (S\$)</b>			<b>8,130.00</b>	<b>1,890.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >