

2/3/2008

ASS. REC. BY:

REF:

CS/CT#18014445/Tlsd3

Special Instruction:

SUBJECT:
men men

Teuchleh

ASSIGNMENT (Office)

From (Person):

Gleane cheong

of

CTI

Date/Time:

7/8/18 @ 9:49am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKU 5573P

Insured:

SJW 1058M

at Workshop no/s

Ding Auto

Tel:

9239 4128

of

249 Julien Boon Lay

Policy No:

DMPCSN 1430761703

Claim No:

8NM18D 03818C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

3/8/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

3:33pm @ 8/8/18

Person Contacted:

Michelle

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKU 5573P-X

SJW 1058M-X

(\$ 10,170.26 Red - 94%)

(08/11/13) wef

ASS. REC. BY: *Tan Jue*

REF: CTI

ASSIGNMENT

From: _____ Date: **8/8/18**

Estimated Cost: _____

OD / (P) / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: **SKU 5573P**at Workshop m/s **Ding Auto**of **249 Julien Boun lay**

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS **up**

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SKU 5573P** Yr Regn: **2015 July**Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Toyota A1A5** c.c. **1528**Colour: **Silver** A/C: Insured / Std / NI / NASp. Reading: **237114** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **MR052REH104535831**Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: **205/51R16**R: **2 -**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **triangle**Front **6**Rear **6**

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. **6** mm L/Bal. _____ mmD.O.A. _____ D.O.I. **8/8/18 0145**Survey held at **Ding Auto**Des. of Damages: Rear / Frt / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 20 AUG 2018

Date/Time, File Pass to?

1) **20/02/18**

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: **2**Resurvey No. of Trip: **1**

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) \$ + RS. _____☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$ **650/- L/s**)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Aug 2018		07 Aug 2018 09:49 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:			
Main Claimant:	LCRF PTE LTD		
Vehicle Reg. No.:	SKU5573P	Date of Loss:	03/08/2018 00:00 - :59
Claim Type:	TP / SNM18D03818C02	Policy/Cover Note No.:	DMPCSN1430761703
Vehicle Reg. No. (Insured):	SJW1058M	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Ding Auto Pte Ltd - Boon Lay (HQ) 249 JALAN BOON LAY SINGAPORE 619523, 619523 Boon Lay - Tel: ✓		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/08/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN ADRIAN LING AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18014445/T1sd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 08-08-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJW 1058M	Veh. Inspected	SKU 5573P	
Policy No.	DMPCSN1430761703	Coverage (\$)	0.00	
Claim No.	SNM18D03818C02	Excess (\$)	0.00	
Assign From	MERIMEN (ELAINE CHEONG)	Assign Date	08/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/08/2018	Inspection Date	08/08/2018	
Survey held at	249 JALAN BOON LAY			
Repairer	DING AUTO PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

• **Shirley Hiew (LKK Auto)**

From: Michelle <accounts@dingauto.sg>
Sent: Monday, 20 August 2018 2:41 PM
To: Shirley Hiew (LKK Auto)
Cc: 'Duan Hongbo'; 'Kenneth Ding'; 'You jingfeng'; 'Dd hashim'; 'SUR'; 'Olivia Lau (LKKAuto)'; 'Taufikh (LKKAuto)'
Subject: Re: FW: [CTI]: 1 of 197 85008496/SKU5573P - FINALIZE AMOUNT AND AFTER PAINT PHOTO // LKK Ref: CS/CTI18014445/T1sd3

Dear Shirley,

We confirm the finalize amount.

Thank you so much

Yours sincerely
Michelle Fang
92394128
Ding Auto Pte Ltd

On 20/8/2018 2:19 PM, Shirley Hiew (LKK Auto) wrote:

Dear Hong bo,

As spoken, please re-confirmed final fig of \$650.00 under lump sum repair before GST .

Final invoice and all supporting documents sent over to **China Taiping Insurance (Singapore) Pte. Ltd.**

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Olivia Lau (LKKAuto) [<mailto:olivialau@lkkauto.com>]

Sent: Monday, 13 August 2018 1:10 PM

To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: Kenneth Ding <kenneth.ding@dingauto.sg>; You jingfeng <JINGFENG@dingauto.sg>; Dd hashim <dd.hashim@dingauto.sg>; Accounts Ding Auto <accounts@dingauto.sg>; Duan Hongbo <duan.hongbo@dingauto.sg>; SUR <sur@lkkauto.com>

Subject: [CTI]: 1 of 197 85008496/SKU5573P - FINALIZE AMOUNT AND AFTER PAINT PHOTO // LKK Ref: CS/CTI18014445/T1sd3

LKK Ref: CS/CTI18014445/T1sd3

Taufikh / Shirley,

Please handle.

Best Regards,
Olivia Lau | Admin Manager
LKK Auto Consultants
phone: 6256-3561 | email: olivialau@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Make
good
use of
Today

From: Duan Hongbo [<mailto:duan.hongbo@dingauto.sg>]
Sent: Saturday, 11 August, 2018 2:31 PM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Kenneth Ding <kenneth.ding@dingauto.sg>; You jingfeng <JINGFENG@dingauto.sg>; Dd hashim <dd.hashim@dingauto.sg>; Accounts Ding Auto <accounts@dingauto.sg>
Subject: 1 of 197 85008496/SKU5573P - FINALIZE AMOUNT AND AFTER PAINT PHOTO

Dear Mr Taufikh,

Please see attach file for the finalize according to our conversion to finalize for SKU5573P.

Total Repair - 02 Days
L/S

Labour - \$430.00
Special Netts - \$-35.00
Parts after 25% Discount - \$364.91
Total (Labour + S.N + Part) :\$829.91

Final Amount After -20% : \$663.92

Thanks You And Please Help To Close The File

Best Regards
Ding Auto Pte Ltd
Duan hong bo
Hp : 9050 7859

BEST REGARDS

DING AUTO PTE LTD

DUAN HONG BO
TEL Office : 92394128
FAX :62652690

ALL MAILL LETTER AND CHEQUE PAYMENT IS TO BE MAILED TO OUR MAIN OFFICE AS BELOW

- BLOCK 10 #01-20 SIN MING INDUSTRIAL EST.SEC C SINGAPORE 5756

--
Yours Sincerely,
Michelle Fang
92394128

NOTE !!!

All mailed letter & cheque payment is to be mailed to our main office address :
BLOCK 10 #01-20
SIN MING INDUSTRIAL EST. SEC C
SINGAPORE 575645



Virus-free. www.avast.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/08/2018 10:31
Date Of Accident	03/08/2018 21:30
Exact Location Of Accident	ALONG WOODLAND AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU5573P
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-31584255

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 CLASSIC CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995145
Cover Note Number	

Driver

Name of Driver	SIA KONG TING, IVAN
NRIC No	S8629063D
Date Of Birth	14/10/1986
Occupation	OUTDOOR
Date Of Driving Pass	03/03/2006
Driving Experience	12 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92394128
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	249 JALAN BOON LAY
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	UNKNOWN
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW1058M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/PIN No.:

Accident Sketch Plan Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

TURNING OUT FROM WOODLANDS AVE 3. STOPPING AT TRAFFIC LIGHT AND THE CAR CAME FROM BEHIND TO KNOCK MY BACK OF CAR. HAPPEND AT 03RD AUGUST 2130 HRS

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre/Inspector's Signature
Name:
NRIC/PIN No.:



TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

06/08/2018 11:15

JOB-NO: 85008496

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD

CONTACT: 0

Page 1 of 2

ADDRESS: 50 UBI AVENUE 3

0

#01-12

NIL

SINGAPORE 408866

VEHICLE DETAILS

LICENSE NO: SKU5573P

TRANS: AUTO

CHASSIS: MR053REH104535831

MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A)

ENGINE: 1ZR521289

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SURDISP	REV PRICE
<u>LABOUR</u>							
1 TO REMOVE & REPLACED DAMAGED BODY PARTS,REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS	1.00	1,200.00	0.00	1,200.00	Y		200
2 TO SPRAY REAR BUMPER	1.00	250.00	0.00	250.00	Y		200
3 TO SPRAY REAR BUMPER REINFORCEMENT	1.00	250.00	0.00	250.00	Y		X
4 TO SPRAY REAR END PANEL	1.00	250.00	0.00	250.00	Y		X
5 TO SPRAY REAR SPARE TYRE PANEL	1.00	250.00	0.00	250.00	Y		X
6 TO SPRAY REAR BOOTLID	1.00	250.00	0.00	250.00	Y		X
7 RUST PROOFING	1.00	180.00	0.00	180.00	Y		X
8 TO ADJUST TAIL LAMP & CHECK WIRING	1.00	150.00	0.00	150.00	Y		X
9 REMOVE & REFIT REAR SPARE TYRE PANEL,REAR FENDER TRIM LHS & RHS REAR SPARE TYRE BOARD,CUSHION,AND ETC	1.00	150.00	0.00	150.00	Y		X
10 TO REMOVE & REFIT REAR REVERSE SENSOR & SPRAY	1.00	160.00	0.00	160.00	Y		30
11 R & R BOOTLID COMPONENTS	1.00	150.00	0.00	150.00	Y		X n
12 REMOVE & REFIT EXHAUST PIPE & MUFFLER	1.00	150.00	0.00	150.00	Y		X n n
TOTAL:		3,390.00	0.00	3,390.00			

MATERIALS

1 REAR BUMPER	1.00	486.55	121.64	364.91	L	Y	22
2 REAR BUMPER SIDE RETAINER LONG LHS	1.00	105.00	26.25	78.75	L	Y	X
3 REAR BUMPER SIDE RETAINER LONG RHS	1.00	105.00	26.25	78.75	L	Y	? X
4 REAR BUMPER SIDE RETAINER SHORT LHS	1.00	80.00	20.00	60.00	L	Y	X
5 REAR BUMPER SIDE RETAINER SHORT RHS	1.00	80.00	20.00	60.00	L	Y	? X
6 REAR BUMPER BEAM ARM LHS	1.00	102.00	25.50	76.50	L	Y	? X
7 REAR BUMPER BEAM ARM RHS	1.00	102.00	25.50	76.50	L	Y	? X
8 REAR BUMPER REINFORCEMENT	1.00	380.00	95.00	285.00	L	Y	? X
9 REAR BUMPER REFLECTOR LHS	1.00	62.00	15.50	46.50	L	Y	X
10 REAR BUMPER REFLECTOR RHS	1.00	62.00	15.50	46.50	L	Y	X
11 BOOTLID	1.00	880.00	220.00	660.00	L	Y	X
12 BOOTLID ""TOYOTA"" EMBLEM	1.00	66.50	16.63	49.87	L	Y	X
13 BOOTLID ""COROLLA"" BADGE	1.00	66.50	16.63	49.87	L	Y	X
14 BOOTLID ""ALTIS"" BADGE	1.00	66.50	16.63	49.87	L	Y	X
15 BOOTLID HINGE LHS	1.00	115.00	28.75	86.25	L	Y	X
16 BOOTLID HINGE RHS	1.00	115.00	28.75	86.25	L	Y	X
17 BOOTLID LOCK	1.00	350.00	87.50	262.50	L	Y	X

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
18 BOOTLID INNER BOARD	1.00	475.00	118.75	356.25	L	Y	X
19 BOOTLID OUTER CHROME GARNISH	1.00	212.00	53.00	159.00	L	Y	X
20 BOOTLID LICENSE PLATE LAMP LHS	1.00	120.00	30.00	90.00	L	Y	X
21 BOOTLID LICENSE PLATE LAMP RHS	1.00	120.00	30.00	90.00	L	Y	X
22 TAIL LAMP OUTER LHS	1.00	377.50	94.38	283.12	L	Y	X
23 TAIL LAMP OUTER RHS	1.00	377.50	94.38	283.12	L	Y	X
24 TAIL LAMP INNER LHS	1.00	295.00	73.75	221.25	L	Y	X
25 TAIL LAMP INNER RHS	1.00	295.00	73.75	221.25	L	Y	X
26 REAR END PANEL	1.00	705.00	176.25	528.75	L	Y	X
27 REAR END PANEL TOP GARNISH	1.00	345.00	86.25	258.75	L	Y	X
28 REAR SPARE TYRE PANEL	1.00	785.00	196.25	588.75	L	Y	X
29 REAR SPARE TYRE PANEL FLOOR BOARD	1.00	412.00	103.00	309.00	L	Y	X
30 REAR END PANEL WEATHERSTRIP	1.00	185.00	46.25	138.75	L	Y	X
31 REAR FENDER INNER PANEL TRIM RHS	1.00	359.00	89.75	269.25	L	Y	X
32 REAR FENDER INNER PANEL TRIM LHS	1.00	389.00	97.25	291.75	L	Y	X
33 EXHAUST PIPE	1.00	571.00	142.75	428.25	L	Y	X
34 REAR BUMPER CLIP	1.00	35.00	0.00	35.00	S	Y	X
35 REAR REVERSE SENSOR	1.00	260.00	0.00	260.00	S	Y	200 X na
36 REAR NUMBER PLATE & CASING	1.00	60.00	0.00	60.00	S	Y	X
37 BOOTLID INNER BOARD CLIP	1.00	35.00	0.00	35.00	S	Y	X
38 REAR END PANEL TOP GARNISH CLIP	1.00	35.00	0.00	35.00	S	Y	X
39 REAR FENDER INNER PANEL TRIM LHS CLIP	1.00	35.00	0.00	35.00	S	Y	X
40 REAR FENDER INNER PANEL TRIM RHS CLIP	1.00	35.00	0.00	35.00	S	Y	X
TOTAL:		9,742.05	311.79	7,430.26			

TOTAL PARTS & LABOUR:

13,132.05

2,311.79

10,820.26

EXCESS/LOADING:\$5 0.00

No. Of Day:

02 days

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$5

DATE OF SURVEY:

8 / 8 / 18

SURVEYED BY:

Taufik

sure1kauto.com

CONTACT NO:

97495749

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TO :

ESTIMATE REPORT 1ST Quotation

FAX NO:

06/08/2018 11:15

JOB-NO: 85008496

Page 1 of 2

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD

CONTACT: 0

ADDRESS: 50 UBI AVENUE 3

0

#01-12

NIL

SINGAPORE 408866

VEHICLE DETAILS

LICENSE NO: SKU5573P

TRANS: AUTO

CHASSIS: MR053REH104535831

MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A)

ENGINE: 1ZR521289

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO REMOVE & REPLACED DAMAGED BODY PARTS,REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS	1.00	1,200.00	0.00	1,200.00		Y	200
2 TO SPRAY REAR BUMPER	1.00	250.00	0.00	250.00		Y	200
3 TO SPRAY REAR BUMPER REINFORCEMENT	1.00	250.00	0.00	250.00		Y	X
4 TO SPRAY REAR END PANEL	1.00	250.00	0.00	250.00		Y	X
5 TO SPRAY REAR SPARE TYRE PANEL	1.00	250.00	0.00	250.00		Y	X
6 TO SPRAY REAR BOOTLID	1.00	250.00	0.00	250.00		Y	X
7 RUST PROOFING	1.00	180.00	0.00	180.00		Y	X
8 TO ADJUST TAIL LAMP & CHECK WIRING	1.00	150.00	0.00	150.00		Y	X
9 REMOVE & REFIT REAR SPARE TYRE PANEL,REAR FENDER TRIM LHS & RHS,REAR SPARE TYRE BOARD,CUSHION,AND ETC	1.00	150.00	0.00	150.00		Y	X
10 TO REMOVE & REFIT REAR REVERSE SENSOR & SPRAY	1.00	160.00	0.00	160.00		Y	30
11 R & R BOOTLID COMPONENTS	1.00	150.00	0.00	150.00		Y	X
12 REMOVE & REFIT EXHAUST PIPE & MUFFLER	1.00	150.00	0.00	150.00		Y	X
TOTAL:		3,390.00	0.00	3,390.00			
MATERIALS							
1 REAR BUMPER	1.00	486.55	121.64	364.91	L	Y	de
2 REAR BUMPER SIDE RETAINER LONG LHS	1.00	105.00	26.25	78.75	L	Y	X
3 REAR BUMPER SIDE RETAINER LONG RHS	1.00	105.00	26.25	78.75	L	Y	X
4 REAR BUMPER SIDE RETAINER SHORT LHS	1.00	80.00	20.00	60.00	L	Y	X
5 REAR BUMPER SIDE RETAINER SHORT RHS	1.00	80.00	20.00	60.00	L	Y	X
6 REAR BUMPER BEAM ARM LHS	1.00	102.00	25.50	76.50	L	Y	X
7 REAR BUMPER BEAM ARM RHS	1.00	102.00	25.50	76.50	L	Y	X
8 REAR BUMPER REINFORCEMENT	1.00	380.00	95.00	285.00	L	Y	X
9 REAR BUMPER REFLECTOR LHS	1.00	62.00	15.50	46.50	L	Y	X
10 REAR BUMPER REFLECTOR RHS	1.00	62.00	15.50	46.50	L	Y	X
11 BOOTLID	1.00	880.00	220.00	660.00	L	Y	X
12 BOOTLID "TOYOTA" EMBLEM	1.00	66.50	16.63	49.87	L	Y	X
13 BOOTLID "COROLLA" BADGE	1.00	66.50	16.63	49.87	L	Y	X
14 BOOTLID "ALTIS" BADGE	1.00	66.50	16.63	49.87	L	Y	X
15 BOOTLID HINGE LHS	1.00	115.00	28.75	86.25	L	Y	X
16 BOOTLID HINGE RHS	1.00	115.00	28.75	86.25	L	Y	X
17 BOOTLID LOCK	1.00	350.00	87.50	262.50	L	Y	X

Total: \$ 829.91
 4/5: \$ 663.92

G-STAR-WI-ET-001-02-Rev00

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
18 BOOTLID INNER BOARD	1.00	475.00	118.75	356.25	L	Y	X
19 BOOTLID OUTER CHROME GARNISH	1.00	212.00	53.00	159.00	L	Y	X
20 BOOTLID LICENSE PLATE LAMP LHS	1.00	120.00	30.00	90.00	L	Y	X
21 BOOTLID LICENSE PLATE LAMP RHS	1.00	120.00	30.00	90.00	L	Y	X
22 TAIL LAMP OUTER LHS	1.00	377.50	94.38	283.12	L	Y	X
23 TAIL LAMP OUTER RHS	1.00	377.50	94.38	283.12	L	Y	X
24 TAIL LAMP INNER LHS	1.00	295.00	73.75	221.25	L	Y	X
25 TAIL LAMP INNER RHS	1.00	295.00	73.75	221.25	L	Y	X
26 REAR END PANEL	1.00	705.00	176.25	528.75	L	Y	X
27 REAR END PANEL TOP GARNISH	1.00	345.00	86.25	258.75	L	Y	X
28 REAR SPARE TYRE PANEL	1.00	785.00	196.25	588.75	L	Y	X
29 REAR SPARE TYRE PANEL FLOOR BOARD	1.00	412.00	103.00	309.00	L	Y	X
30 REAR END PANEL WEATHERSTRIP	1.00	185.00	46.25	138.75	L	Y	X
31 REAR FENDER INNER PANEL TRIM RHS	1.00	359.00	89.75	269.25	L	Y	X
32 REAR FENDER INNER PANEL TRIM LHS	1.00	389.00	97.25	291.75	L	Y	X
33 EXHAUST PIPE	1.00	571.00	142.75	428.25	L	Y	X
34 REAR BUMPER CLIP	1.00	35.00	0.00	35.00	S	Y	201
35 REAR REVERSE SENSOR	1.00	260.00	0.00	260.00	S	Y	200
36 REAR NUMBER PLATE & CASING	1.00	60.00	0.00	60.00	S	Y	X
37 BOOTLID INNER BOARD CLIP	1.00	35.00	0.00	35.00	S	Y	X
38 REAR END PANEL TOP GARNISH CLIP	1.00	35.00	0.00	35.00	S	Y	X
39 REAR FENDER INNER PANEL TRIM LHS CLIP	1.00	35.00	0.00	35.00	S	Y	X
40 REAR FENDER INNER PANEL TRIM RHS CLIP	1.00	35.00	0.00	35.00	S	Y	X

TOTAL:	9,742.05	311.79	7,430.26
China To			
TOTAL PARTS & LABOUR:	13,132.05	2,311.79	10,820.26

EXCESS/LOADING:SS	0.00
-------------------	------

No. Of Day: 02 days

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: SS

DATE OF SURVEY: 8 / 8 / 18

SURVEYED BY: _____

CONTACT NO: 97495777 FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL: FAX:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Aug 2018		07 Aug 2018 09:49 Edit Adj Rpt	\$650.00 Edit Estimates	\$650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	- ID: -		
Main Claimant:	LCRF PTE LTD		
Vehicle Reg. No.:	SKU5573P	Date of Loss:	03/08/2018 00:00 - :59 [38 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D03818C02	Policy/Cover Note No.:	DMPCSN1430761703
Vehicle Reg. No. (Insured):	SJW1058M	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Ding Auto Pte Ltd - Boon Lay (HQ) 249 JALAN BOON LAY SINGAPORE 619523, 619523 Boon Lay - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 17/08/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN ADRIAN LING AS SJE.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKU5573P (SNM18D03818C02)
[SJW1058M]
TP
LCRF PTE LTD
Aug 3 2018 12:00AM
[-]
Ding Auto Pte Ltd - Boon Lay

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Photos/Images									3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	20/08/18 15:42	Odometer Reading								Load JPG	☒
2	20/08/18 15:42	Chassis Number								Load JPG	☒
3	20/08/18 15:42	General View								Load JPG	☒
4	20/08/18 15:42	General View								Load JPG	☒
5	20/08/18 15:42	General View								Load JPG	☒
6	20/08/18 15:42	General View								Load JPG	☒
7	20/08/18 15:42	General View								Load JPG	☒
8	20/08/18 15:42	General View								Load JPG	☒
9	20/08/18 15:42	General View								Load JPG	☒
10	20/08/18 15:42	General View								Load JPG	☒
11	20/08/18 15:42	General View								Load JPG	☒
12	20/08/18 15:42	General View								Load JPG	☒
13	20/08/18 15:42	General View								Load JPG	☒
14	20/08/18 15:42	General View								Load JPG	☒
15	20/08/18 15:42	General View								Load JPG	☒
16	20/08/18 15:42	General View								Load JPG	☒
17	20/08/18 15:42	General View								Load JPG	☒
18	20/08/18 15:42	General View								Load JPG	☒
19	20/08/18 15:42	General View								Load JPG	☒
20	20/08/18 15:42	General View								Load JPG	☒
21	20/08/18 15:42	General View								Load JPG	☒
22	20/08/18 15:42	Reinspection Photo								Load JPG	☒
23	20/08/18 15:42	Reinspection Photo								Load JPG	☒
24	20/08/18 15:42	Reinspection Photo								Load JPG	☒
25	20/08/18 15:42	Reinspection Photo								Load JPG	☒
26	20/08/18 15:42	Reinspection Photo								Load JPG	☒
27	20/08/18 15:42	Reinspection Photo								Load JPG	☒
Documentation									1 per page		☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)								Thumbnail	Print
1	07/08/18 09:49	PRS								Load PDF	
2	07/08/18 09:49	TP GIA								Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118014445/T1SD3Q2

Date: 06/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN1430761703

Claimant Vehicle
No : SKU5573PInsured Vehicle
No : SJW1058M

Date of Loss: 03/08/2018

Nature of Claim: TP

Claim
No: SNM18D03818C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKU5573P**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)

Engine No: 1ZRX521289

Reg. Date: 31/05/2015 (Man. Year: 2015)

Chassis No: MR053REH104535831

Colour: Silver

Odometer: 237114 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: Triangle 6 mm

Rear Left Side:

Triangle 6 mm

Front Right Side: Triangle 6 mm

Rear Right Side:

Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,430.29	399.91	7,030.38	94.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,390.00	430.00	2,960.00	87.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,820.29	829.91	9,990.38	92.33
Approved Total (Overridden) (S\$)		650.00		
(S\$)	10,820.29	650.00	10,170.29	93.99
+ GST 7.00/7.00% (S\$)	757.42	45.50	711.92	93.99
Nett Amount (S\$)	11,577.71	695.50	10,882.21	93.99

INSPECTION

Date of Assignment: 07/08/2018

Date Inspected: 08/08/2018 Inspected At:

 Ding Auto Pte Ltd - Boon Lay (HQ)
 249 JALAN BOON LAY SINGAPORE
 619523
 Singapore 619523

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Sep 2018)	
Parts: 143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SKU5573P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	486.55 FL	*486.55 FL
2	1		*REAR BUMPER SIDE RETAINER LONG LHS	Not Necessary	105.00 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER LONG RHS	Not Necessary	105.00 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER SHORT LHS	Not Necessary	80.00 FL	*- FL
5	1		*REAR BUMPER SIDE RETAINER SHORT RHS	Not Necessary	80.00 FL	*- FL
6	1		*REAR BUMPER BEAM ARM LHS	Not Necessary	102.00 FL	*- FL
7	1		*REAR BUMPER BEAM ARM RHS	Not Necessary	102.00 FL	*- FL
8	1		*REAR BUMPER REINFORCEMENT	Not Necessary	380.00 FL	*- FL
9	1		*REAR BUMPER REFLECTOR LHS	Not Necessary	62.00 FL	*- FL
10	1		*REAR BUMPER REFLECTOR RHS	Not Necessary	62.00 FL	*- FL
11	1		*BOOTLID	Not Necessary	880.00 FL	*- FL
12	1		*BOOTLID TOYOTA EMBLEM	Not Necessary	66.50 FL	*- FL
13	1		*BOOTLID COROLLA BADGE	Not Necessary	66.50 FL	*- FL
14	1		*BOOTLID ALTIS BADGE	Not Necessary	66.50 FL	*- FL
15	1		*BOOTLID HINGE LHS	Not Necessary	115.00 FL	*- FL
16	1		*BOOTLID HINGE RHS	Not Necessary	115.00 FL	*- FL
17	1		*BOOTLID LOCK	Not Necessary	350.00 FL	*- FL
18	1		*BOOTLID INNER BOARD	Not Necessary	475.00 FL	*- FL
19	1		*BOOTLID OUTER CHROME GARNISH	Not Necessary	212.00 FL	*- FL
20	1		*BOOTLID LICENSE PLATE LAMP LHS	Not Necessary	120.00 FL	*- FL
21	1		*BOOTLID LICENSE PLATE LAMP RHS	Not Necessary	120.00 FL	*- FL
22	1		*TAIL LAMP OUTER LHS	Not Necessary	377.50 FL	*- FL
23	1		*TAIL LAMP OUTER RHS	Not Necessary	377.50 FL	*- FL
24	1		*TAIL LAMP INNER LHS	Not Necessary	295.00 FL	*- FL
25	1		*TAIL LAMP INNER RHS	Not Necessary	295.00 FL	*- FL
26	1		*REAR END PANEL	Not Necessary	705.00 FL	*- FL
27	1		*REAR END PANEL TOP GARNISH	Not Necessary	345.00 FL	*- FL
28	1		*REAR SPARE TYRE PANEL	Not Necessary	785.00 FL	*- FL
29	1		*REAR SPARE TYRE PANEL FLOOR BOARD	Not Necessary	412.00 FL	*- FL
30	1		*REAR END PANEL WEATHERSTRIP	Not Necessary	185.00 FL	*- FL
31	1		*REAR FENDER INNER PANEL TRIM RHS	Not Necessary	359.00 FL	*- FL
32	1		*REAR FENDER INNER PANEL TRIM LHS	Not Necessary	389.00 FL	*- FL
33	1		*EXHAUST PIPE	Not Necessary	571.00 FL	*- FL
34	1		*REAR BUMPER CLIP	Necessary	35.00 FS	*35.00 FS
35	1		*REAR REVERSE SENSOR	Not Necessary	260.00 FS	*- FS
36	1		*REAR NUMBER PLATE & CASING	Not Necessary	60.00 FS	*- FS
37	1		*BOOTLID INNER BOARD CLIP	Not Necessary	35.00 FS	*- FS
38	1		*REAR END PANEL TOP GARNISH CLIP	Not Necessary	35.00 FS	*- FS
39	1		*REAR FENDER INNER PANEL TRIM LHS CLIP	Not Necessary	35.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR FENDER INNER PANEL TRIM RHS CLIP	Not Necessary	35.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (S\$)	9,742.05 521.55
					- List Item Discount on L Items 25.00/25.00% (S\$)	2,311.76 121.64
					Total Parts (S\$)	7,430.29 399.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACED DAMAGED BODY PARTS ,REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS	New	1,200.00	200.00
2	TO SPRAY REAR BUMPER	New	250.00	200.00
3	TO SPRAY REAR BUMPER REINFORCEMENT	New	250.00	0.00
4	TO SPRAY REAR END PANEL	New	250.00	0.00
5	TO SPRAY REAR SPARE TYRE PANEL	New	250.00	0.00
6	TO SPRAY REAR BOOTLID	New	250.00	0.00
7	RUST PROOFING	New	180.00	0.00
8	TO ADJUST TAIL LAMP & CHECK WIRING	New	150.00	0.00
9	REMOVE & REFIT REAR SPARE TYRE PANEL ,REAR FENDER TRIM LHS & RHS ,REAR SPARE TYRE BOARD ,CUSHION AND ETC	New	150.00	0.00
10	TO REMOVE & REFIT REAR REVERSE SENSOR & SPRAY	New	160.00	30.00
11	R&R BOOTLID COMPONENTS	New	150.00	0.00
12	REMOVE & REFIT EXHAUST PIPE & MUFFLER	New	150.00	0.00
Gross Labour Cost (S\$)			3,390.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >