

22/03/2002

ASS. REC. BY:

REF: CS/CTI18014450/T1rd321 Special Instruction:

Surveyor:
menhen

Tau Fieh

ASSIGNMENT (Office)

From (Person):

Ehang Baan Sen

of

CTI

Date/Time: 7/8/18 @ 4:31pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 6857Y

Insured:

SL87554E

at Workshop m/s

Vermogen Ace

Tel:

6368 3031

of

G Behoi Seefor

Policy No:

DMPCS N308757100

Claim No:

SNM/8DO3833C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 05/08/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

11-Bum 08/8/18

Person Contacted:

Ezel

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLC 6857Y-X
	SL87554E-X
	Condrn L/s \$1750.00 @ 4 days
	Red: \$12,588.24, 88%

Taufkin

RET

CT1

ASST. NAIL ST

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s: _____
of: _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

N/S	O/S

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res: Yes or No
Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLC68579 Yr Regn: 2016 May
Type: ☒ M / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Honda Vezel 1496
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 176710 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: R411109782
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 715/60KLL
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Roads four
Front: 6 Rear: 6
R/Bal: mm R/Bal: mm
L/Bal: mm L/Bal: mm
D.O.A: 8/8/18 @ 630
Survey held at: Vennayen
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Frt o/s.
The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

RECEIVED 24 OCT 2018

Date/Time File Pass to?

typist

Date/Time File Return to?

21

Report Format

Lump Sum / TP

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Party to (\$)
☐ Witness (\$)

Survey Time

Transportation

1. 11.00 AM

1. 12.00 PM

1. 1.00 PM

1. 2.00 PM

220
220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18014450/T1rd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 08-08-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLS 7554E	Veh. Inspected	SLC 6857Y	
Policy No.	DMPCSN3087571700	Coverage (\$)	0.00	
Claim No.	SNM18D03833C02	Excess (\$)	0.00	
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	08/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	05/08/2018	Inspection Date	08/08/2018	
Survey held at	6 BENOI SECTOR			
Repairer	VERMOGEN ACE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Aug 2018		07 Aug 2018 16:31 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	JARED WONG FONG TUCK , ID: S11871251		
Main Claimant:	LCRF PTE LTD , Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLC6857Y	Date of Loss:	05/08/2018 11:00 - :59
Claim Type:	TP / SNM18D03833C02	Policy/Cover Note No.:	DMPCSN3087571700 (Comprehensive)
Vehicle Reg. No. (Insured):	SLS7554E	Policy No. (Claimant):	999995075
		Excess:	S\$0.00
Repairer:	Vermogen Ace Pte Ltd (HQ) Blk B, 44 Benoi Rd, 629904 Pioneer - Tel: 65155230		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/08/2018]		
Driver/Custodian (Insured):	JARED WONG FONG TUCK (61 / Male), NRIC: S11871251		
Adj Asg. Remarks:	NO EST, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: ezel.t@vermogen-group.com
Sent: Monday, 6 August, 2018 5:29 PM
To: Claims Dept of CTI
Cc: 'Baldoz Juan Paulo Bongon'; 'Edmond Lim'; 'Minoko Chan'; ace@vermogen-group.com; 'Luis Tan'; 'Glorioso Eric Paul Patambang'; 'Yira Rahman'; 'Pili'; 'Vmg admin'; desmond@vermogen-group.com
Subject: Accident involving SLC6857Y & SLS7554E (Your Insured) on 05/08/2018 - PLEASE ARRANGE TP SURVEY
Attachments: SLC6857Y 05AUG2018 TP.PDF

Dear officer in-charge,

Refer to above attachment, kindly arrange our client's vehicle for pre-repair survey at **Vermogen Ace Pte Ltd** Block B Singapore(629904)

VEHICLE IN WORKSHOP

Beside, we would like to check for the liability on this matter.

Kindly check & revert to us as soon as possible.

Thank you.

Best regards,

Ezel Tejano

Vermogen Ace Pte Ltd

1 Bukit Batok Crescent

#05-23 Wcega Plaza

Singapore 658064

Tel: 6358 3031

Fax: 6694 4929

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/08/2018 10:31
Date Of Accident	05/08/2018 11:30
Exact Location Of Accident	JUNCTION OF CLEMENCEAU AVE AND RIVER VALLEY RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC6857Y
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66944919

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	HIRER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995075
Cover Note Number	

Driver

Name of Driver	MOHAMED SANI BIN JANTAN
NRIC No	S1538742D
Date Of Birth	15/04/1962
Occupation	OUTDOOR
Date Of Driving Pass	21/02/2018
Driving Experience	0 YEAR AND 5 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90106639
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	44 BENOI ROAD BLOCK B, SINGAPORE 629904
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO PHOTOS AS ATTACHED, THANK YOU.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS7554E
Vehicle Make/Model/Colour	
Details Of Properties	VEH. B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA (Record Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

YIRA RAHMAN

Accident Sketch Plan Pg. 2

SKETCH PLAN

Ⓐ 8UC68574
Ⓑ 9LS7554E



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Clemencean Ave of the most extreme left lane heading straight. when suddenly vehicle B from the 3rd lane filtered into my lane and collided into my front right portion and cause the damage. I realised vehicle B filtered from a lane that is heading straight lane.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Deploying Centre Personnel's Signature
Name:
NRIC/FIN No.:

YIP RAHMAN

Identification Card, Driving Licence and Vocational Licence

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: S1538742D

Name: MOHAMED SANI BIN JANTAN

Birth Date: 15 Apr 1962

Issue Date: 27 Feb 2004

9011341517

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1538742D

Name: MOHAMED SANI BIN JANTAN

نام محمد ساني بن جانتان

Race: MALAY

Date of Birth: 15-04-1962

Country/Place of Birth: SINGAPORE

Sex: M

S1538742D

Land Transport Authority

VOCATIONAL LICENCE

Licence No: S1538742D

Name: MOHAMED SANI BIN JANTAN

Issue Date: 13/7/2012

Please visit www.lta.gov.sg to check the status of this vocational licence

PERMITTED TO DRIVE VEHICLES IN THE FOLLOWING

Class 2B	Motorcycles <= 250 CC	22 May 1992
Class 2A	Motorcycles between 251 CC and 600 CC	22 May 1992
Class 3	Motor cars <= 3500 kg with <= 7 passengers, exclusive of the delivery and passenger vehicles <= 2500 kg	22 Feb 2011

S / No. 9000145163

Licence No: S1538742D

5853216

Barcode

NRIC No: S1538742D

Date of Issue: 18-01-2018

APT BLK 31 CHAI CHEE AVENUE #03-184
SINGAPORE 481031

NRIC No: S1538742D Date: 18/03/2018 (R)

This card is not transferable and is the property of the Land Transport Authority (LTA). It must be surrendered to the LTA on request. If found, please return to LTA, 10 Sin Ming Drive, Singapore 575701.

Type	Description	Issue Date
02	TAXI VL	13/07/2012



ACCIDENT LOCATION

8/6/2018

83 Clemenceau Ave - Google Maps

Google Maps 83 Clemenceau Ave



Image capture: Nov 2017 © 2018 Google

Singapore

Google, Inc.

Street View - Nov 2017



<https://www.google.com.sg/maps/@1.2927371,103.8435318,3a,75y,20.17h,76.04t/data=!3m6!1e1!3m4!1sgBTqzU4gen0c7flcwrV5w!2e0!7!13312!> 1/1



SLC6875Y

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA TAIPING
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 05-08-18

Vehicle Reg. No. : SLC6875Y
Vehicle Reg. Date: 23-May-2016
Make / Model : H. VEZEL 1.5X CVT
Engine No. : L15B4029785
Chassis No. : RU11109782

COST OF CLAIMS

Parts Cost / List Items : \$ 12,385.30
Plus/Less 20% \$ 2,477.06
Total Cost / List : \$ 9,908.24
Special Nett Items : \$ 400.00
Total Parts Amount : \$ 10,308.24
Total Labour Amount : \$ 4,030.00
Gross Total : \$ 14,338.24
GST % : 7% \$ 1,003.68
Nett Amount : \$ 15,341.92

Surveyor Name and Company :

Tan Jie 97445749
Date of survey : 8/8/18 @ 1630
Part by Part / Lump Sum : 4 days
Resurvey Before Paint / After Paint After
Authorize/Not Authorize/Without Prejudice Without
Email : sure@kanto.com
Fax No : _____
HP No : _____

This claim is handled by : MINOKO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC6875Y**

Vehicle Reg. Date: **23-05-16**

Make / Model : **H. VEZEL 1.5X CVT**

Engine No. : **L15B4029785**

Chassis No. : **RU11109782**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Washer tank	nn x	\$ 115.00		
2	1	Washer tank motor	nn x	\$ 70.00		
3	1	Headlamp RH	nn y	\$ 2,540.00		
4	1	Headlamp lower bracket RH	nn x	\$ 110.00		
5	1	Front bumper	de	\$ 1,085.00	450	
6	1set	Front bumper clips	nn	\$ 50.00		
7	1	Front bumper retainer RH	nn	\$ 72.00		
8	1set	Front bumper fog lamp RH	nn x	\$ 387.70		
9	1	Front bumper fog lamp garnish RH	nn x	\$ 62.00		
10	1	Front fender RH	Ry	\$ 660.00		
11	1	Front fender inner shield RH	de	\$ 165.00		
12	1	Front fender arch garnish RH	nn	\$ 192.00		
13	1set	Front fender arch garnish clips	nn 30	\$ 50.00	30	
14	1	Front grille base	x	\$ 1,150.00		
15	1	Front grille garnish	x	\$ 251.20		
16	1	Front grille chrome	x	\$ 242.00		
17	1	Front grille side bracket	x	\$ 279.00		
18	1	Front grille centre bracket	x	\$ 139.50		
19	1set	Front grille clips	x	\$ 35.00		
20	1	Front grille logo	x	\$ 52.00		
21	1	Bonnet	x x	\$ 1,130.00		
22	1	Bonnet hinge LH/RH	nn x	\$ 124.00		
23	1	Bonnet insulator	x	\$ 160.50		
24	1set	Bonnet insulator clips	x	\$ 50.00		
25	2	Bonnet rubber side	x	\$ 66.80		
26	1	Bonnet rubber centre	x	\$ 35.20		
27	1	Front rim RH	Ry	\$ 950.00		
28	1	Front shock absorber RH	x	\$ 625.00		
29	1	Front shock absorber mounting RH	x	\$ 40.00		
30	1	Front shock mounting bearing RH	x	\$ 40.00		
31	1	Front shock absorber dust cover RH	x	\$ 50.00		
32	1	Front shock stopper RH	x	\$ 40.00		
33	1	Front lower arm RH	x x	\$ 437.00		
34	1	Front lower arm ball joint RH	nn x	\$ 113.00		
35	1	Front Tyres 215/60R16 RH	x		\$ 400.00	
36	1	Front knuckle arm RH	x	\$ 390.00		
37	1	Front wheel bearing RH	x	\$ 181.40		
38	1	Front wheel hub RH	x	\$ 245.00		
39	0	0				
40	0	0				

Tel : 6358 3031 | Fax No : 6694 4929

SLC6875Y

23-05-16

H. VEZEL 1.5X CVT

L15B4029785

RU11109782

Estimates on Labour

[illegible]

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

FINALIZATION FORM

ATTN TO: LKK-TAUFIK
Surveyor Name and Company

Date of Accident : 5/8/2018

BILL TO: CHINA TAIPING
TP Insurer

VEHICLE REG. NO.

TYPE OF CLAIM: TP

SLC6875Y

Make / Model : H. VEZEL 1.5X CVT

COST OF CLAIMS

Parts Cost / List : \$ 1,594.00

Supp. Parts : \$ -

Special Nett : \$ -

Total Parts : \$ 1,275.20

Total Labour : \$ 1,030.00

TOTAL REPAIR COST : \$ 2,305.20

Total Parts Cost/List :	\$	1,594.00
Plus / Less : 20%	\$	318.80
Total :	\$	1,275.20

Lump Sum Discount : 20%	\$	461.04
Lump Sum Amount:	\$	1,844.16

Final Lump Sum Amount : \$ 1,850.00

Submitted by / Date : MINOKO

No. of Repair Days: 4

Confirmed by / Date : _____

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC6875Y**
 Vehicle Reg. Date: **23/5/2016**
 Make / Model : **H. VEZEL 1.5X CVT**
 Engine No. : **L15B4029785**
 Chassis No. : **RU11109782**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Washer tank		\$ 115.00		
2	1	Washer tank motor		\$ 70.00		
3	1	Headlamp RH		\$ 2,540.00		
4	1	Headlamp lower bracket RH		\$ 110.00		
5	1	Front bumper		\$ 1,085.00		\$ 1,085.00
6	1set	Front bumper clips		\$ 50.00		\$ 50.00
7	1	Front bumper retainer RH		\$ 72.00		\$ 72.00
8	1set	Front bumper fog lamp RH		\$ 387.70		
9	1	Front bumper fog lamp garnish RH		\$ 62.00		
10	1	Front fender RH		\$ 660.00		
11	1	Front fender inner shield RH		\$ 165.00		\$ 165.00
12	1	Front fender arch garnish RH		\$ 192.00		\$ 192.00
13	1set	Front fender arch garnish clips		\$ 50.00		\$ 30.00
14	1	Front grille base		\$ 1,150.00		
15	1	Front grille garnish		\$ 251.20		
16	1	Front grille chrome		\$ 242.00		
17	1	Front grille side bracket		\$ 279.00		
18	1	Front grille centre bracket		\$ 139.50		
19	1set	Front grille clips		\$ 35.00		
20	1	Front grille logo		\$ 52.00		
21	1	Bonnet		\$ 1,130.00		
22	1	Bonnet hinge LH/RH		\$ 124.00		
23	1	Bonnet insulator		\$ 160.50		
24	1set	Bonnet insulator clips		\$ 50.00		
25	2	Bonnet rubber side		\$ 66.80		
26	1	Bonnet rubber centre		\$ 35.20		
27	1	Front rim RH		\$ 950.00		
28	1	Front shock absorber RH		\$ 625.00		
29	1	Front shock absorber mounting RH		\$ 40.00		
30	1	Front shock mounting bearing RH		\$ 40.00		
31	1	Front shock absorber dust cover RH		\$ 50.00		
32	1	Front shock stopper RH		\$ 40.00		
33	1	Front lower arm RH		\$ 437.00		
34	1	Front lower arm ball joint RH		\$ 113.00		
35	1	Front Tyres 215/60R16 RH				
36	1	Front knuckle arm RH		\$ 390.00		
37	1	Front wheel bearing RH		\$ 181.40		
38	1	Front wheel hub RH		\$ 245.00		
39	0	0				
40	0	0				

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]

Janice Lee (LKKAUTO)

From: minoko@vermogen-group.com
Sent: Thursday, October 18, 2018 2:14 PM
To: Taufikh (LKKAUTO)
Cc: SUR; 'Pila Ng'; 'Tejano Exequiel Dawal'; 'Juan paulo baldoz'; 'Desmond Kor'; vmg@vermogen-group.com; 'Vermogen Ace'
Subject: SLC6857Y FINALISE
Attachments: SLC6875Y ESTIMATE.pdf; a0584a4d-9853-48e4-94ef-6ead0e9eaae4.jpg; b7f8bbca-1741-41e0-b7f6-fdc242d9af4d.jpg; b88aa02b-fd29-46f8-a7da-66301af3f665.jpg; d2bb18fe-503e-4574-bbad-3516c216131c.jpg; 28fcfd82-017f-42a2-b9fc-175b1617ec3d.jpg; 57f127f8-8495-4a9f-8dca-43c824dd8e48.jpg; 5097a5dc-504c-4688-a95b-710a0b170148.jpg

Dear Taufik,

Kindly take note: Above vehicle should be **SLC6857Y Non SLC6875Y**.

Refer to attachment, kindly confirm & acceptance finalise @ COR \$1,850.00 & 4 repair days (excluding PRS/RS/Weekend & PH).

please revert.ASAP

Thank you

Best Regards,

Minoko
Vermogen Ace Pte Ltd
1 Bukit Batok Crescent
#05-23 Wcega Plaza
Singapore 658064
Tel: 6904 4596
Fax: 6694 4929

Janice Lee (LKKAUTO)

From: minoko@vermogen-group.com
Sent: Tuesday, October 23, 2018 3:39 PM
To: Janice Lee (LKKAUTO); Taufikh (LKKAUTO)
Cc: 'Pila Ng'; 'Tejano Exequiel Dawal'; 'juan paulo baldoz'; 'Desmond Kor'; vmg@vermogen-group.com; 'Vermogen Ace'
Subject: RE: SLC6857Y FINALISE

Dear Janice,

We agreed to accept your finalise @ \$1,750.00 & 4DAYS (Excluding PRS/RS/Weekend &PH).

Thank you

Best Regards,

Minoko
Vermogen Ace Pte Ltd
1 Bukit Batok Crescent
#05-23 Wcega Plaza
Singapore 658064
Tel: 6904 4596
Fax: 6694 4929

From: Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>
Sent: Tuesday, 23 October 2018 2:53 PM
To: minoko@vermogen-group.com; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: 'Pila Ng' <pila@vermogen-group.com>; 'Tejano Exequiel Dawal' <ezel.t@vermogen-group.com>; 'juan paulo baldoz' <paulovermogenace@gmail.com>; 'Desmond Kor' <desmond@vermogen-group.com>; vmg@vermogen-group.com; 'Vermogen Ace' <ACE@VERMOGEN-GROUP.COM>
Subject: RE: SLC6857Y FINALISE

Dear Minoko,

Kindly confirm L/S \$ 1,750.00 @ 4 DAYS

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: minoko@vermogen-group.com [mailto:minoko@vermogen-group.com]

Sent: Thursday, October 18, 2018 2:14 PM

To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>

Cc: SUR <sur@lkkauto.com>; 'Pila Ng' <pila@vermogen-group.com>; 'Tejano Exequiel Dawal' <ezel.t@vermogen-group.com>; 'juan paulo baldoz' <paulovermogenace@gmail.com>; 'Desmond Kor' <desmond@vermogen-group.com>; vmg@vermogen-group.com; 'Vermogen Ace' <ACE@VERMOGEN-GROUP.COM>

Subject: SLC6857Y FINALISE

Dear Taufik,

Kindly take note: Above vehicle should be SLC6857Y Non SLC6875Y.

Refer to attachment, kindly confirm & acceptance finalise @ COR \$1,850.00 & 4 repair days (excluding PRS/RS/Weekend & PH).

please revert.ASAP

Thank you

Best Regards,

Minoko

Vermogen Ace Pte Ltd

1 Bukit Batok Crescent

#05-23 Wcega Plaza

Singapore 658064

Tel: 6904 4596

Fax: 6694 4929

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Aug 2018		07 Aug 2018 16:31 Edit Adj Rpt	S\$1,750.00 Edit Estimates	S\$1,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	JARED WONG FONG TUCK , ID: S1187125I								
Main Claimant:	LCRF PTE LTD , Co. Reg. No.: 201624597K								
Vehicle Reg. No.:	SLC6857Y	Date of Loss:	05/08/2018 11:00 - :59 [26 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03833C02	Policy/Cover Note No.:	DMPCSN3087571700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLS7554E	Policy No. (Claimant):	999995075						
		Excess:	S\$0.00						
Repairer:	Vermogen Ace Pte Ltd (HQ) Blk B, 44 Benoi Rd, 629904 Pioneer - Tel: 65155230								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 17/08/2018]								
Driver/Custodian (Insured):	JARED WONG FONG TUCK (61 / Male), NRIC: S1187125I								
Adj Asg. Remarks:	NO EST, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLC6857Y (SNM18D03833C02)
[SLS7554E]
TP
LCRF PTE LTD
Aug 5 2018 11:00AM
[JARED WONG FONG TUCK]
Vermogen Ace Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Video									1 per page		☒			
No	Finalized On	Vermogen Ace Pte Ltd (HQ)							Thumbnail		Print			
1	06/08/18 13:21	Video - Accident [Linked Accident Report Documents]									Load MP4			
Assessment Reports									1 per page		☒			
No	Finalized On	Vermogen Ace Pte Ltd (HQ)							Thumbnail		Print			
1	06/08/18 13:27	Accident Statement									Load HTM			
Photos/Images									3 per page		☒			
No	Finalized On	Vermogen Ace Pte Ltd (HQ)							Thumbnail		Print			
1	06/08/18 13:22	Accident Photo [Linked Accident Report Documents]									Load JPG ☒			
2	06/08/18 13:22	Accident Photo [Linked Accident Report Documents]									Load JPG ☒			
3	06/08/18 13:22	Accident Photo [Linked Accident Report Documents]									Load JPG ☒			
4	06/08/18 13:22	Accident Photo [Linked Accident Report Documents]									Load JPG ☒			
5	06/08/18 13:22	Accident Photo [Linked Accident Report Documents]									Load JPG ☒			
6	06/08/18 13:22	Accident Photo [Linked Accident Report Documents]									Load JPG ☒			
7	06/08/18 13:22	Accident Photo [Linked Accident Report Documents]									Load JPG ☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print			
1	23/10/18 13:46	General View									Load JPG ☒			
2	23/10/18 13:46	General View									Load JPG ☒			
3	23/10/18 13:46	General View									Load JPG ☒			
4	23/10/18 13:46	General View									Load JPG ☒			
5	23/10/18 13:46	General View									Load JPG ☒			
6	23/10/18 13:46	General View									Load JPG ☒			
7	23/10/18 13:46	General View									Load JPG ☒			
8	23/10/18 13:46	General View									Load JPG ☒			
9	23/10/18 13:46	General View									Load JPG ☒			
10	23/10/18 13:46	General View									Load JPG ☒			
11	23/10/18 13:46	General View									Load JPG ☒			
12	23/10/18 13:46	General View									Load JPG ☒			
13	23/10/18 13:46	General View									Load JPG ☒			
14	23/10/18 13:46	General View									Load JPG ☒			
15	23/10/18 13:46	General View									Load JPG ☒			
16	23/10/18 13:46	General View									Load JPG ☒			
17	23/10/18 13:46	General View									Load JPG ☒			
18	23/10/18 13:46	General View									Load JPG ☒			
19	23/10/18 13:46	General View									Load JPG ☒			
20	23/10/18 13:46	General View									Load JPG ☒			

Video			1 per page	☒
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
				☒
21	23/10/18 13:46	General View	 Load JPG	☒
22	23/10/18 13:46	General View	 Load JPG	☒
23	23/10/18 13:46	General View	 Load JPG	☒
24	23/10/18 13:46	General View	 Load JPG	☒
25	23/10/18 13:46	General View	 Load JPG	☒
26	23/10/18 13:46	General View	 Load JPG	☒
27	23/10/18 13:46	General View	 Load JPG	☒
28	23/10/18 13:46	General View	 Load JPG	☒
29	23/10/18 13:46	General View	 Load JPG	☒
30	23/10/18 13:47	Reinspection Photo	 Load JPG	☒
31	23/10/18 13:47	Reinspection Photo	 Load JPG	☒
32	23/10/18 13:47	Reinspection Photo	 Load JPG	☒
33	23/10/18 13:47	Reinspection Photo	 Load JPG	☒
34	23/10/18 13:47	Reinspection Photo	 Load JPG	☒
35	23/10/18 13:47	Reinspection Photo	 Load JPG	☒
36	23/10/18 13:47	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/08/18 16:30	PRS	 Load PDF	
2	07/08/18 16:30	TP GIA	 Load PDF	
3	07/08/18 16:30	OI GIA	 Load PDF	
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
1	06/08/18 13:22	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	06/08/18 13:22	Identification Card, Driving Licence and Vocational Licence [Linked Accident Report Documents]	 Load JPG	☒
3	06/08/18 13:22	ACCIDENT LOCATION [Linked Accident Report Documents]	 Load JPG	☒

Linked Accident Report Documents

Video			View	View in Browser	☒
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print	
1	06/08/18 13:21	Video - Accident	 Load MP4		
Assessment Reports			1 per page	☒	
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print	
1	06/08/18 13:27	Accident Statement	 Load HTM		
2	29/08/18 13:11	Addendum Sheet	 Load JPG	☒	
3	29/08/18 13:12	Accident Statement Addm. #1	 Load HTM		
Photos/Images			3 per page	☒	
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print	
1	06/08/18 13:22	Accident Photo	 Load JPG	☒	
2	06/08/18 13:22	Accident Photo	 Load JPG	☒	
3	06/08/18 13:22	Accident Photo	 Load JPG	☒	
4	06/08/18 13:22	Accident Photo	 Load JPG	☒	
5	06/08/18 13:22	Accident Photo	 Load JPG	☒	
6	06/08/18 13:22	Accident Photo	 Load JPG	☒	
7	06/08/18 13:22	Accident Photo	 Load JPG	☒	
Documentation			1 per page	☒	

Video			1 per page	☒
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
No	Finalized On	Vermogen Ace Pte Ltd (HQ)	Thumbnail	Print
1	06/08/18 13:22	Identification Card, Driving Licence and Vocational Licence	 Load JPG	☒
2	06/08/18 13:22	ACCIDENT LOCATION	 Load JPG	☒
3	29/08/18 13:11	Accident Sketch Plan	 Load TIF	
4	29/08/18 13:11	Accident Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: ☐ Handling Insurer	
Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118014450/T1RD3E2

Date: 29/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3087571700
Claimant Vehicle No :	SLC6857Y	Insured Vehicle No :	SLS7554E
Date of Loss:	05/08/2018	Nature of Claim:	TP
		Claim No:	SNM18D03833C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC6857Y	Engine No:	L15B4029785
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11109782
Reg. Date:	23/05/2016 (Man. Year: 2015)	Odometer:	176718 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Roadstone 6 mm	Rear Left Side:	Roadstone 6 mm
Front Right Side:	Roadstone 6 mm	Rear Right Side:	Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,308.24	1,167.20	9,141.04	88.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,030.00	1,030.00	3,000.00	74.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,338.24	2,197.20	12,141.04	84.68
Approved Total (Overridden) (S\$)		1,750.00		
(S\$)	14,338.24	1,750.00	12,588.24	87.79
+ GST 7.00/7.00% (S\$)	1,003.68	122.50	881.18	87.79
Nett Amount (S\$)	15,341.92	1,872.50	13,469.42	87.79

INSPECTION

Date of Assignment:	07/08/2018		
Date Inspected:	08/08/2018	Inspected At:	Vermogen Ace Pte Ltd (HQ) Blk B, 44 Benoi Rd Singapore 629904
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Oct 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC6857Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WASHER TANK	Not Necessary	115.00 FL	*- FL
2	1		*WASHER TANK MOTOR	Not Necessary	70.00 FL	*- FL
3	1		*HEADLAMP RH	Not Necessary	2,540.00 FL	*- FL
4	1		*HEADLAMP LOWER BRACKET RH	Not Necessary	110.00 FL	*- FL
5	1		*FRONT BUMPER	Deformed	1,085.00 FL	*950.00 FL
6	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
7	1		*FRONT BUMPER RETAINER RH	Necessary	72.00 FL	*72.00 FL
8	1		*SET FRONT BUMPER FOG LAMP RH	Not Necessary	387.70 FL	*- FL
9	1		*FRONT BUMPER FOG LAMP GARNISH RH	Not Necessary	62.00 FL	*- FL
10	1		*FRONT FENDER RH	Repair	660.00 FL	*- FL
11	1		*FRONT FENDER INNER SHIELD RH	Deformed	165.00 FL	*165.00 FL
12	1		*FRONT FENDER ARCH GARNISH RH	Cut	192.00 FL	*192.00 FL
13	1		*SET FRONT FENDER ARCH GARNISH CLIPS	Necessary	50.00 FL	*30.00 FL
14	1		*FRONT GRILLE BASE	Not Necessary	1,150.00 FL	*- FL
15	1		*FRONT GRILLE GARNISH	Not Necessary	251.20 FL	*- FL
16	1		*FRONT GRILLE CHROME	Not Necessary	242.00 FL	*- FL
17	1		*FRONT GRILLE SIDE BRACKET	Not Necessary	279.00 FL	*- FL
18	1		*FRONT GRILLE CENTRE BRACKET	Not Necessary	139.50 FL	*- FL
19	1		*SET FRONT GRILLE CLIPS	Not Necessary	35.00 FL	*- FL
20	1		*BONNET	Not Necessary	1,130.00 FL	*- FL
21	1		*BONNET HINGE LH / RH	Not Necessary	124.00 FL	*- FL
22	1		*BONNET INSULATOR	Not Necessary	160.50 FL	*- FL
23	1		*SET BONNET INSULATOR CLIPS	Not Necessary	50.00 FL	*- FL
24	2		*BONNET RUBBER SIDE	Not Necessary	66.80 FL	*- FL
25	1		*BONNET RUBBER CENTRE	Not Necessary	35.20 FL	*- FL
26	1		*FRONT RIM RH	Repair	950.00 FL	*- FL
27	1		*FRONT SHOCK ABSORBER RH	Not Necessary	625.00 FL	*- FL
28	1		*FRONT SHOCK ABSORBER MOUNTING RH	Not Necessary	40.00 FL	*- FL
29	1		*FRONT SHOCK MOUNTING BEARING RH	Not Necessary	40.00 FL	*- FL
30	1		*FRONT SHOCK ABSORBER DUST COVER RH	Not Necessary	50.00 FL	*- FL
31	1		*FRONT SHOCK STOPPER RH	Not Necessary	40.00 FL	*- FL
32	1		*FRONT LOWER ARM RH	Not Necessary	437.00 FL	*- FL
33	1		*FRONT LOWER ARM BALL JOINT RH	Not Necessary	113.00 FL	*- FL
34	1		*FRONT TYRES 215/60R16 RH	Not Necessary	400.00 FS	*- FS
35	1		*FRONT KNUCKLE ARM RH	Not Necessary	390.00 FL	*- FL
36	1		*FRONT WHEEL BEARING RH	Not Necessary	181.40 FL	*- FL
37	1		*FRONT WHEEL HUB RH	Not Necessary	245.00 FL	*- FL
38	1		*FRONT GRILLE LOGO	Not Necessary	52.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	12,785.30	1,459.00
				- List Item Discount on L Items 20.00/20.00% (S\$)	2,477.06	291.80
				Total Parts (S\$)	10,308.24	1,167.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN AND PANEL BEATING ACCIDENT AREA	New	1,500.00	400.00
2	TO PUTTY, RESPRAY PAINTING AND POLISH ACCIDENT AREA	New	1,800.00	400.00
3	TO RUST PROOF AFFECTED AREAS	New	150.00	30.00
4	TO REMOVE AND REFIT INTERNAL PARTS TO ASSIST REPAIR	New	250.00	60.00
5	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT	New	100.00	30.00
6	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
7	TO REPLACE TYRE & RIM, TYRE BALANCE	New	80.00	30.00
Gross Labour Cost (S\$)			4,030.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

