

ASS. REC. BY:

REF: CS/FCI/8014457/Ksdant

Special Instruction:

Surveyor:

Kennedy

ASSIGNMENT (Office)

From (Person):

May chun

of

FCI

Date/Time: 8/8/18 @ 8:31am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGG 9505G

Insured:

SHA 4210J

at Workshop m/s

Cheng Hwe Motor

Tel:

67556142

of

Blk 1019 Yishun Ind. Park A # 01-374

Policy No:

Claim No:

D18005456MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 07/08/2018

CA / REV / REP. / REV 24 HRS

10s

H.O.D. Endorsement:

Date/Time:

0:37 @ 8/8/18

Person Contacted:

june

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate	
	SGG 9505G - NA/INC 68023571/s1	DOA: 24/8/2008
	SHA 4210J - NA/HP 12001513/e1	DOA: 24/01/2012
10/8/18	Email preli. revised to FCI	
12/11	L1 Sup @ 20501 Confirm Tune	

ASS. REC. BY:

REF:

P621

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

18K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGG 95056

Yr Regn:

05 06

Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Altis

c.c.

1598

Colour:

M. Gold

A/C:

Insured / Std / NI / NA

Sp. Reading

185112

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NR0538EC107121294

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / R/Rim or

Tyre Size:

F:

185/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

7/8/18

D.O.I.

8/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

MN \$ 18K - LIA \$ 12,742 = Net value : 5,258

Date / Time

Action / Instruction

10/8 File pass to Catherine

12/11/18 Confirmed L/S \$ 2,050/- @ 5 days with Kenneth.
(\$ 830.11 Red - 29%)

RECEIVED 12 NOV 2018

Date/Time, File Pass to?

12/11/18



: Prell. Report

1)

Type



: Final Report

Date/Time, File Return to?

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

110

50

50+50

21

281

Report Format :

Lump Sum / I.B.I. (\$) 2,050/- L/S



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18014457/Ksd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 08-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4210J	Veh. Inspected	SGG 9505G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005956MFSH	Excess (\$)	0.00	
Assign From	CWS (MAY CHUA)	Assign Date	08/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/08/2018	Inspection Date	08/08/2018	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18005956MFSH

Our ref: CS/FCI18014457/Ksd3

Date : 10/8/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SGG 9505G


We thank for your instruction on 8/8/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 8/8/2018 at the premises of M/s CHENG HOE MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$1,961.88
Revised Estimate Amount	: S\$1,511.88
"Check" Items Amount	: S\$200.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	07-08-2018	Our Ref No. D18005956MFSH
Accident Date	07-08-2018	Claim Type. Third Party
Insured Vehicle	SHA4210J	Third Party Vehicle. SGG9505G
Survey Location	BLK 1019 YISHUN IND. PARK A #01-374	
Contact Person.	JUNE	
Contact No.	67556142/ 0	Fax No. 67557719
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHENG HOE MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 10 August 2018 1:13 PM
To: 'Claim Workflow System'
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005956MFSH/1, SGG 9505G
Attachments: SGG 9505G PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SGG 9505G
Date of survey: 8/8/2018
Number of days : 4 days

Best Regards,

Veron Chen | Case Handler **on behalf of Shirley**

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 8 August 2018 10:47 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005956MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 8 August 2018 8:30 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005956MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4154I
Vehicle Details	
Vehicle No.:	SGG9505G
Vehicle to be Exported:	No
Intended De-registration Date:	07 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Gold
Manufacturing Year:	2006
Engine No.:	3ZZ4574387
Chassis No.:	MR053ZEC107121294
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,950.00
Original Registration Date:	25 May 2006
First Registration Date:	25 May 2006
Transfer Count:	2
Actual ARF Paid:	\$17,545.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 May 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$22,789.00
COE Rebate Amount:	\$12,742.00
Total Rebate Amount:	\$12,742.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 07 Aug 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SGG 9505G
TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP/FC/YS

Claim Type: Third Party

Accident Date: 07/08/2018

TP Veh Reg No: SHA4210J

Estimate No: ES1890912/YISHUN

Date: 08 Aug 2018

Policy No: 10845804

Veh Reg No: SGG9505G

Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Chassis No: MR053ZEC107121294

Engine No: 3ZZ4574387

Reg. Date: 25/05/2006

Estimate Repair Cost to Vehicle No :SGG9505G

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	385.90	1 PC	385.90	—
2 REAR BUMPER CLIPS	3.89	6 PCS	23.34	—
3 REAR BOOT INNER LOCK	39.50	1 PC	39.50	—
4 REAR BOOT EMBLEM (COROLLA)	28.90	1 PC	28.90	—
5 REAR BOOT EMBLEM (ALTIS)	29.40	1 PC	29.40	—
6 REAR BOOT EMBLEM (1.6)	32.90	1 PC	32.90	—
7 REAR BOOT EMBLEM (E)	38.10	1 PC	38.10	—
8 REAR BOOT EMBLEM (VVTI)	37.80	1 PC	37.80	—
			615.84	
		Less 25%	153.96	461.88
Special Net				
9 REVERSE SENSOR	200.00	1 SET	200.00	200.00
Labour				
10 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMP, KNOCK & REPAIR REAR PANEL, TAILLAMP PANELS, BOOT & REALIGN THE SAME	600.00	1 LA	600.00	450
11 PUTTY & RESPRAY ON REAR PANEL, REAR BOOT, REAR BUMPER & REAR AFFECTED AREAS	700.00	1 LA	700.00	600
			1,300.00	1,300.00
			Total	S\$ 1,961.88
			Add GST @ 7%	137.33
			Total Amount Payable	S\$ 2,099.21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SGG9505G
TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP/FC/YS

Claim Type: Third Party

Accident Date: 07/08/2018

TP Veh Reg No: SHA4210J

Estimate No: ES1890912/YISHUN

Date: 08 Aug 2018

Policy No: 10845804

Veh Reg No: SGG9505G

Make/Model: TOYOTA COROLLA
ALTIS 1.6 AUTO

Chassis No: MR053ZEC107121294

Engine No: 3ZZ4574387

Reg. Date: 25/05/2006

Estimate Repair Cost to Vehicle No :SGG9505G

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	385.90	1 PC	Bu 385.90	—
2 REAR BUMPER CLIPS	3.89	6 PCS	M 23.34	—
3 REAR BOOT INNER LOCK	39.50	1 PC	M 39.50	—
4 REAR BOOT EMBLEM (COROLLA)	28.90	1 PC	M 28.90	—
5 REAR BOOT EMBLEM (ALTIS)	29.40	1 PC	M 29.40	—
6 REAR BOOT EMBLEM (1.6)	32.90	1 PC	M 32.90	—
7 REAR BOOT EMBLEM (E)	38.10	1 PC	M 38.10	—
8 REAR BOOT EMBLEM (VVTI)	37.80	1 PC	M 37.80	—
9 REAR CENTRE PANEL	700.10	1 PC	M 700.10	—
10 REAR CENTRE PANEL INNER TOP GARNISH	84.20	1 PC	M 84.20	—
			1,400.14	
		Less 25%	350.04	1,050.11
Special Net				
11 REVERSE SENSOR	200.00	1 SET	Shor 200.00	✓
			200.00	200.00
Labour				
12 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMP, KNOCK & REPAIR REAR BOOT, REAR SPARE TYRE COMPARTMENT, CUT, WELD & RENEW REAR PANEL	800.00	1 LA	800.00	650
13 PUTTY & RESPRAY ON REAR PANEL, REAR BOOT, REAR BUMPER & REAR SPARE TYRE PANEL	800.00	1 LA	800.00	650
14 RUSTPROOFING	30.00	1 LA	30.00	✓
			1,630.00	1,630.00
Total				S\$ 2,880.11
Add GST @ 7%				201.61
Total Amount Payable				S\$ 3,081.72

2580.11

45 #2050

5 day

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18014457/Ksd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-11-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 4210J	Veh. Inspected	SGG 9505G
Policy No.		Coverage (\$)	0.00
Claim No.	D18005956MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	08/08/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	MR053ZEC107121294	Colour	METALLIC GOLD
Odometer	185112	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/70 R14	MICHELIN	7 mm
L/H Front Tyre	185/70 R14	MICHELIN	7 mm
R/H Rear Tyre	185/70 R14	MICHELIN	7 mm
L/H Rear Tyre	185/70 R14	MICHELIN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	07/08/2018	Inspection Date	08/08/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGG 9505G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BUCKLED	385.90	385.90
6	REAR BUMPER CLIPS @\$3.89	NECESSARY	23.34	23.34
1	REAR BOOT INNER LOCK	DENTED	39.50	39.50
1	REAR BOOT EMBLEM (COROLLA)	NECESSARY	28.90	28.90
1	REAR BOOT EMBLEM (ALTIS)	NECESSARY	29.40	29.40
1	REAR BOOT EMBLEM (1.6)	NECESSARY	32.90	32.90
1	REAR BOOT EMBLEM (E)	NECESSARY	38.10	38.10
1	REAR BOOT EMBLEM (VVTI)	NECESSARY	37.80	37.80
1	REAR CENTRE PANEL	BENT	700.10	700.10
1	REAR CENTRE PANEL INNER TOP GARNISH	DISTORTED	84.20	84.20
	LESS 25% DISCOUNT		-350.03	-350.03
			1,050.11	1,050.11
	<u>SPECIAL NETT ITEMS</u>			
1	SET REVERSE SENSOR (SN)	SHORTED	200.00	200.00
			200.00	200.00
	<u>LABOUR</u>			
	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMP, KNOCK & REPAIR REAR BOOT, REAR SPARE TYRE COMPARTMENT, CUT, WELD & RENEW REAR PANEL.		800.00	650.00
	PUTTY & RESPRAY ON REAR PANEL, REAR BOOT, REAR BUMPER & REAR SPARE TYRE PANEL.		800.00	650.00
	RUSTPROOFING.		30.00	30.00
			1,630.00	1,330.00
	GRAND TOTAL		2,880.11	2,580.11
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,050.00

Report Ref No. CS/FCI18014457/Ksd3n2

MARKET VALUE: \$18,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$12,742.00=NETT VALUE: \$5,258.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.