

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0915/2018/PH
Date : 10-Aug-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Hee Yau Kua
Address : 29 First Street
Singapore 458299
Telephone : HP +65 81866311
Type of Claim : Third Party Claim
Policy No. : 2100508221-01
Vehicle No : **SLN 1768 X**
Model Code : AUDI A6 1.8 TFSI S-TRONIC
Model / Year : Apr-17
Engine No : CYG 018239
Chassis No : WAUZZZ4G9HN076062
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Aug-18
Place of Accident : Siglap Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax**Estimated Labour Charges for Accident Vehicle SLN 1768 X .**

S/N	Nature of Jobs	Estimated Charges	Surveyor's recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper and rhs front fender. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00	1000.
3	To respray front bumper, rhs front fender and rhs front door.	\$ 2,400.00	1650
4	To renew both front rim and carry out wheel alignment.	S/N \$ 280.00 ✓	
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 5,452.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 1768 X .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	BUMPER COVER <i>Repair</i>	\$ 2,650.00	*
2	FIXING PARTS FOR BUMPER <i>new</i>	\$ 464.00	*
3	ADAPTER - LH/RH } <i>new</i>	2 \$ 64.00	*
4	GUIDE PIECE - RH }	\$ 32.00	*
5	BRACE }	\$ 25.00	*
6	FENDER - RH <i>Dented</i>	\$ 1,220.00	✓
7	ATTACHMENT PARTS FOR FENDER ?	\$ 88.00	?
8	STONE GUARD FILM WING DOOR - RH <i>new</i>	\$ 105.00	✓
9	BRACE WING - RH ?	\$ 72.00	?
10	ALUMINIUM RIM <i>new</i>	2 \$ 1,451.00	✓
11	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		\$ 6,471.00	
TOTAL LABOUR CHARGES		\$ 5,452.00	
GRAND TOTAL		\$ 11,923.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 14/08/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant