

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0019977
Ng Chai Hiak

Page 1 of 2
Your ref. TP-SGT 2255E AXA
Job No. 69721
Our ref. 18.08.02
Payment
Date 7/8/2018

Attn

Vehicle No SKQ 7294C
Vehicle Model : Toyota Wish
Accident on ... 3/8/2018

Not Authorized
Resurvey 1-B.1
B4 pain
5 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Bonnet	698.80	25.00	R 524.10 X
1.00	Pc	Front bumper	574.90	25.00	R 431.18 ✓
1.00	Pc	Front bumper sponge	81.06	25.00	CM 60.80 ✓
1.00	Pc	Front fog lamp cover LH	75.11	25.00	56.33 ✓
1.00	Pc	Front fog lamp LH	248.20	25.00	M3 CM 186.15 ✓
1.00	Pc	Front bumper side holder LH	55.30	25.00	DIT 41.48 ✓
1.00	Pc	Front bumper side holder RH	55.30	25.00	DIT 41.48 ✓
1.00	Pc	Front headlamp LH	1,224.80	25.00	M3 CM 918.60 ✓
1.00	Pc	Front headlamp RH	1,224.80	25.00	M3 BR 918.60 ✓
1.00	Pc	Front brace panel	81.06	25.00	R 60.80 ✓
3.00	Pcs	Front bumper top clips	3.00	25.00	R 2.25 ✓
6.00	Pcs	Radiator grille clips	3.50	25.00	R 2.63 ✓
1.00	Pc	Radiator grille	262.50	25.00	CM 196.88 ✓
1.00	Pc	Front fender inner shield LH	152.70	25.00	CM 114.53 ✓
1.00	Pc	Front fog lamp side grille LH	66.78	25.00	50.09 ✓
10.00	Pcs	Front fender inner shield clips LH - 1	3.00	25.00	R 2.25 ✓
4.00	Pcs	Front fender inner shield clips LH - 2	3.50	25.00	R 2.63 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: _____
Date: _____

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及零件修理。准确的测量方式和和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0019977
Ng Chai Hiak

Page 2 of 2
Your ref. TP-SGT 2255E AXA
Job No. 69721
Our ref. 18.08.02
Payment
Date 7/8/2018

Attn

Vehicle No SKQ 7294C
Vehicle Model : Toyota Wish
Accident on ... 3/8/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Special nett item:					
1.00	Pc	Front number plate	35.00		<i>B7</i> 35.00 ✓
Labour & Misc:					
1.00		Towing fee	60.00		<i>Ang CM</i> 60.00 ✓
1.00		To knock dents on front support panel, front fender LH and renew of parts	450.00		<i>4201</i> 450.00
1.00		To spray paint	800.00		<i>7201</i> 800.00

Sub-Total 5,001.52
GST 7.00% 350.11
Total S\$ 5,351.63

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."



KAOLIN MOTOR TRADING CO

Thomson Road Post Office, P.O. Box 95, Singapore 915704

24 HOURS TOWING SERVICES

Tel: 6452 0716, 6458 4013

Registration No. 21645200K

CASH SALE
JOB ORDER

No. 7006970

Messrs

L H M/L

Date

3/8/18

Vehicle No. S/Q 7294C

Model

W/SV

Destination NANYANG CREES to wly

Time In

Time Out

Remarks YL89535

Amount \$ 60/-

- Change Spare Tyre / Jumpstart
- Basement / Multi Carpark
- Accident
- Using King Dolly (Extra Trailer)
- Lowered Bodykit / Suspension

- Loaded With Goods
- Dismantle Shaft / Brake / Equipment
- Open Door
- Crane up / Winch out

Driver

am

Received By

bizSAFE