



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216
Officer in Charge : QUAY SIEW TENG Tel : Email :

Customer :
GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn : Tel : Fax No. :

Quotation No. : QO18/08-1086	Quotation Date : 07/08/2018	Terms : 30 DAYS
Vehicle No. : SLP5867G	Chassis No. : MHFB29F3402011908	Third Party Insurer :
Model : VIOS		Date of Accident : 05/08/2018
Remarks : THIRD PARTY INSURER: AXA, INSURED'S VEH NO: SLP5867G, DOA: 05.08.2018		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR LICENSE PLATE GARNISH	1	59.8000 X	59.80
2	REAR LAMS	2	375.8000 X	751.60
3	REAR LAMP PANEL	2	238.9000 X	477.80
4	REAR LAMP PANEL CLIP HOLDER	4	9.5000 X	38.00
5	REAR END PANEL	1	694.7000 <i>repa</i> X	694.70
6	REAR END PANEL INNER TRIM	1	234.3000 X	234.30
7	REAR END PANEL INNER TRIM CLIPS	4	4.3000 X	17.20
8	REAR BUMPER	1	504.9000 <i>DE</i>	504.90
9	REAR BUMPER REFLECTORS	1	130.5000 X	130.50
10	REAR BUMPER SIDE RETAINERS	<i>21pc (RH)</i>	116.3000 <i>new</i>	232.60
11	REAR BUMPER SIDE HOLDERS	<i>21pc (RH)</i>	22.3000 <i>new</i>	44.60
12	REAR BUMPER YELLOW CLIPS	<i>21pc (RH)</i>	9.0000 <i>new</i>	18.00
13	REAR BUMPER REINFORCEMENT	1	323.0000 <i>BA</i>	323.00
14	REAR BUMPER CLIPS	10	4.3000 <i>new</i>	43.00
15	REAR BUMPER END SPLASHIELD COVER	2	89.8000 X	179.60
16	REAR LUGGAGE FLOOR PANEL	1	678.7000 X	678.70
17	REAR LUGGAGE FLOOR SIDE FOAM	2	75.0000 X	150.00
18	SPARE TYRE - CARDBOARD	1	145.0000 X	145.00
19	REAR FENDER	<i>2 RH repair</i>	969.7000 X	1,939.40
20	REAR FENDER AIR VENT	2	45.1000 X	90.20
21	REAR FENDER INNER TRIM	2	395.1000 X	790.20
22	REAR FENDER INNER TRIM CLIPS	12	4.3000 X	51.60
23	LESS 25% (ITEM 1-22)	1	-2,031.5800	-2,031.58

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : QUAY SIEW TENG Tel : Email :	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :

Quotation No. : QO18/08-1086	Quotation Date : 07/08/2018	Terms : 30 DAYS
Vehicle No. : SLP5867G	Chassis No. : MHFB29F3402011908	Third Party Insurer :
Model : VIOS	Date of Accident : 05/08/2018	
Remarks : THIRD PARTY INSURER: AXA, INSURED'S VEH NO: SLP5867G, DOA: 05.08.2018		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	REAR LICENSE PLATE	1	80.0000 X	80.00
25	REAR BUMPER PARKING SENSOR	1	450.0000 200 X	450.00
26	REAR LUGGAGE FLOOR PANEL INSULATOR	1	250.0000 X	250.00
27	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000 60	120.00
28	TO RUST-PROOFING OF THE AFFECTED AREAS	1	180.0000 20	180.00
29	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHERS, TO ENALBLE REPAIR	1	150.0000 60	150.00
30	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	60.0000 X	60.00
31	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	1,800.0000 450	1,800.00
32	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	2,000.0000 700	2,000.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
4 days
P/P
07/08/18 @ 1600
Resy b & paint

Sub Total	10,653.12
GST(7.00%)	745.72
Total (SGD)	11,398.84

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800