

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 64528211 FAX: 64517420

ESTIMATE

CHALLA VIVEKANADA REDDY
c/o 46 Lentor Plain
Singapore 786548

Not Notarized
1. B. I.
Resurvey B4 panels

11/12/18 86100h

5 days

Date: 08/08/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: MERCEDES BENZ E350 COUPE/ SLN 4023 S		
1 pc	rear bumper	1,675.00
1 pc	rear bumper lower pad	967.00
1 pc	rear bumper inner pad	764.00
1 pc	rear bumper reinforcement	859.00
2 pcs	rear bumper side pad	534.00
2 pcs	rear bumper side retainer	267.00
3 pcs	rear bumper reinforcement bracket	134.00
2 pcs	reverse sensor	86.00
1 pc	rear tail lamp	920.00
1 pc	rear end panel	780.00
1 pc	rear end panel garnish	954.00
1 pc	rear boot lid	417.00
2 pcs	rear boot lamp	1,735.00
1 pc	rear boot weatherstrip	1,350.00
1 pc	rear boot lock	319.00
1 pc	rear boot lock catch	257.00
1 pc	emblem 'E 350'	101.00
1 pc	emblem '7G Tronic'	97.00
1 pc	emblem 'logo'	86.00
1 pc	rear exhaust silencer LH	95.00
1 pc	rear exhaust silencer RH	1,457.00
		1,140.00
	sub total	15,033.00
	less 10%	1,503.30
	sub total	13,529.70
1 pc	C&C' emblem	45.00
	s.nett	
	sub total	13,574.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Balance brought forward.	13,574.70	
To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	500 1,200.00	
To check wiring system.	20 60.00	
To apply rust proofing.	30 120.00	
To apply waterproof sealant on affected areas.	nn 120.00	X
To spray painting on affected areas.	600 1,050.00	
To install reverse sensors	60.00	✓
To remove carpet & trimming to enable repair.	nn 60.00	X
To carry out exhaust works.	nn 120.00	X
To reset front seats head rest x2	120 200.00	
To dianogsed and reset ECU setting	300.00	X
Total	16,864.70	