

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

Not Authorized
11 Long 8?
Running After Paint
5 days

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: **Third Party**

Date: **07.08.2018**

Accident Date : **04.08.2018**

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "BMW 535I" Reg. No. SKG6783S Claiming Against Your Insured Reg. No. EC4567E			
1pc	Front Bumper	3.00	<i>Am</i> 1,390.00
10pcs	Front Bumper Clips		<i>me</i> 30.00
1pc	Front Bumper Emblem		<i>me</i> 75.00
1pc	Front Bumper Center Core		55.00
1pc	Front Bumper Bracket		<i>me</i> 10.00
1pc	Front Bumper Sponge		60.00
1pc	Front Bumper Side Sponge RH		15.00
1pc	Front Bumper Reinforcement		760.00
1pc	Front Bumper Top Retainer RH		196.00
1pc	Front Bumper Top Beam		190.00
1pc	Front Bumper Tow Cover		<i>me</i> 55.00
2pcs	Front Bumper Sensors	<i>h R / 1407</i> 275.00	<i>me</i> 550.00
4pcs	Front Bumper Sensor Holders	68.00	<i>me</i> 272.00
1pc	Front Bumper Sensor Wiring		140.00
1pc	Front Bumper Side Air Grille RH		85.00
1pc	Front Bumper Side Air Grille Moulding		<i>sun</i> 42.00
1pc	Front Bumper Fog Lamp RH		<i>sun</i> 292.00
1pc	Front Bumper Center Air Grille		<i>sun</i> 76.00
1pc	Front Bumper Headlamp Washer Cover Spring		7.00
1pc	Front Bumper Lower Air Duct		55.00
2pcs	Grilles	142.00	<i>me</i> 284.00
1pc	Headlamp Assy RH (HID)		<i>CMR</i> 3,260.00
1pc	Headlamp Lower Bracket RH		138.00
1pc	Support Panel		245.00
1pc	Radiator Ventilator Shutter		255.00
1pc	Front Bumper Headlamp Washer RH		<i>sun</i> 195.00
1pc	Front Bumper Headlamp Washer Lid		<i>sun</i> 55.00
1pc	Front Bumper Headlamp Washer Bracket		<i>sun</i> 8.00
1pc	Front Bumper Headlamp Washer Hose		<i>sun</i> 54.00
			8,849.00
1pc	Front Number Plate		<i>me</i> 45.00
To Conduct Front Electrical Check, Locking System, Adjust, Focus Headlamp etc			30.00
To Remove / Refit Air Con Condenser & Refill Gas			120.00
To Dismantle / Replace Front Parking Sensors, Reprogram PDC System			180.00
			9,224.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

C/F

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: **Third Party**

Date: **07.08.2018**

Accident Date : **04.08.2018**

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "BMW 535i" Reg. No. SKG6783S Claiming Against Your Insured Reg. No. EC4567E		
		B/F	9,224.00
	To Reprogram / Perform Adaptation to Front Adaptive, Directional Headlamp		180.00 1001
	Labour Charge - Panel Beating, Repairing Of Bonnet, Front O/S Fender, Front O/S Fender, Front O/S Door, Front Chassis Member and Parts Replacement		900.00 5001
	To Respray Affected Areas		1,000.00 8001
		Total :	<u>11,304.00</u>