

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0919/2018/NK
Date : 13-Aug-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured Veh No : SLE 3602 A

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Donald Chen Hwei Lai
Address : 6 Jalan Kebaya
Singapore 278295
Telephone : HP +97383960
Type of Claim : Third Party Claim
Policy No. : DHMOM120025591600
Vehicle No : **SKK 932 Y**
Model Code : AUDI A3 1.4 TFSI
Model / Year : Nov-14
Engine No : CZC 209832
Chassis No : WAUZZZ8V3F1042101
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 10-Aug-18
Place of Accident : Junction Of Commonwealth Ave & Ghim Moh Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKK 932 Y

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00 ✓
2	To dismantle and renew rear bumper. Reorganise rear crash management components. Reinstall all parts removed.	\$ 900.00 500
3	To respray rear bumper and rear lid.	\$ 1,400.00 1100
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>2,772.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 932 Y

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Deformed</i>	\$ 1,619.00	✓
2	REAR BUMPER FIXING PARTS	\$ 166.00	+
3	REAR BUMPER GUIDE SECTIONS LH / RH <i>2</i>	2 \$ 28.00	+
4	REAR BUMPER LOCKING MECHANISM	2 \$ 50.00	+
5	REAR BUMPER SPOILER <i>rec rec</i>	\$ 206.00	+
6	REAR BUMPER LIGHT REFLECTOR LH / RH <i>rec</i>	2 \$ 52.00	+
7	REAR REINFORCEMENT <i>?</i>	\$ 501.00	?
8	REAR BUMPER BRACKET LH / RH <i>?</i>	2 \$ 22.00	?
9	REAR BUMPER GUIDE SECTIONS LH / RH <i>rec</i>	2 \$ 114.00	+
10	REAR SENSORS INNER / OUTER <i>?</i>	2 \$ 421.00	?
11	PACKING ADHESIVE <i>?</i>	1 \$ 15.00	✓
12	AUDI LOGO <i>rec</i>	\$ 108.00	✓
13	"A3" CHROME EMBLEM <i>rec</i>	\$ 83.00	✓
14	"TFSI" CHROME EMBLEM <i>rec</i>	\$ 83.00	✓
15	NO PLATE <i>rec</i>	S/N \$ 25.00	+
16	SUNDRIES	\$ 300.00	?
TOTAL SPARE PARTS		: \$ 3,793.00	
TOTAL LABOUR CHARGES		: \$ 2,772.00	
GRAND TOTAL		: \$ 6,565.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 28/08/18.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorized, 04 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant