

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

ma3

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0919/2018/NK 28-Aug-18 Jeffery Tan 1 SKK 932 Y AUDI A3 1.4 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Rear Cross Panel <i>Dented</i>	\$ 317.00	✓
2	Rear cross panel reinforcement piece <i>Dented</i>	\$ 645.00	✓
3	Acrylic sealer <i>?</i> Special Nett	\$ 180.00	✓
4	Cavity wax <i>acc</i> Special Nett	\$ 140.00	✓
5	Stone chip Special Nett	\$ 180.00	✓
		\$ 1,462.00	
<u>LABORS</u>			
1	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse & relay trays, electrical and audio equipment. Special Nett	\$ 480.00	✓
2	To cut out and weld end panelling. Re-align rear lock carrier and renew damaged panels. Re-organize rear crash management components. Reinstall all parts removed.	\$ 2,400.00	<i>1250 .</i>
3	To respray end panelling. To carry out joint sealer works and stone chip treatment.	\$ 800.00	<i>550 .</i>
TOTAL		\$ 5,142.00	

Adrian Ling
sls