

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0884/2018/KS
Date : 2-Aug-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Choi Heng Yen Lionel
Address : 7 Palm Road
#01-05
Singapore 456442
Telephone : HP +65 97499297
Type of Claim : OWN DAMAGE CLAIMS
Policy No. : 2100503624-01
Vehicle No : **SLL 8299 Y**
Model Code : Audi A4 SEDAN 1.4 TFSI
Model / Year : Mar-17
Engine No : CVN 031097
Chassis No : WAUZZZF45HA115689
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 2-Aug-18
Place of Accident : 7 Palm Road S(456422)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLL 8299 Y.

S/N	Nature of Jobs	Estimated Charges	Surveyors's Recommendation
1	To remove and transfer front wire harness for headlights ,horns, fog lamps, outside temperature sensor and headlights washer assy.	S/N \$ 360.00 ✓	
2	To dismantle front bumper and lhs headlight Re-organise front crash management components. Reinstall all parts removed.	\$ 1,200.00 500	
3	To respray front bumper.	\$ 800.00 550	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>2,552.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 8299 Y.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Dehant</i>	\$ 1,849.00	✓
2	FRONT BUMPER FIXING PARTS <i>3 new</i>	\$ 245.00	✗
3	SECURING STRIP	\$ 60.00	✗
4	FRONT BUMPER LOWER CENTER GRILLE <i>3 new</i>	\$ 171.00	✓
5	LOWER CENTER CLOSING ELEMENT	\$ 180.00	✓
6	AIR GUIDE LH / RH <i>new</i>	2 \$ 146.00	✗
7	RADIATOR GRILLE <i>could</i>	\$ 972.00	✓
8	AIR GUIDE GRILLE <i>new</i>	\$ 118.00	✗
9	FOAM FILLER PIECE <i>3 new</i>	\$ 107.00	✗
10	BUMPER CARRIER	\$ 702.00	✗
11	GUIDE SECTION LH / RH <i>new</i>	\$ 64.00	✗
12	HEADLIGHT LH <i>new</i>	\$ 6,973.00	✗
13	FRONT NO PLATE <i>new</i>	\$ 25.00	✓
14	HEADLIGHT LH <i>new</i>	\$ 2,076.00	✗
15	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 13,988.00
TOTAL LABOUR CHARGES		:	\$ 2,552.00
GRAND TOTAL		:	\$ 16,540.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *08/08/18*
Authorised Date :
Excess Cost :
Liability :
Remarks : *At Authorised Repairs, 03 Days.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant