

REF:

CC3/ AIG18014487 / Aq3n2

ASS. REC. BY: Abrian LingMemorASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

310027180

Claims No.

557654659456

Sum Insured:

Excess:

2000 14/8/18

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

90K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 88/5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKE74166.

Yr Regn:

2012 / March.

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Audi S5 SB

C.C.

2995.

Colour

White.

A/C:

Insured / Std / NI / NA

Sp. Reading

39351

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAU2228T0CA0155982.

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size:

F: 255/35R19.

R: 255/35R19.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

08/08/18.

Survey held at

Premium.

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD AIG.

SKE74166-X

14/8/18 @ 3.40pm Informed Phua ex: \$2000 by email.

15/8/18 @ 5.27pm confirmed with Mr Boon final fig \$5750, 4 days.
(Car #8351, 59%.)

RECEIVED 30 NOV 2018

Date/Time, File Pass to?

☐

Preli. Report

1) 30/11/18

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Report Format:

MER-00

Lump Sum / L.B. (\$)

5750

Survey Fee:

200

Transportation:

10

S + RS, SI

Photos

Others

TOTAL

210

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 15 November 2018 5:27 PM
To: 'Boo seng yak'; SUR; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: RE: FINAL REVISION - SKE7416G - OD AIG - SURVEYED 8 AUG 18

Dear Mr Boo,

WITHOUT PREJUDICE

Confirm final fig \$ 5,750.00 before excess \$2,000.00 & GST and 4 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Monday, 1 October 2018 7:03 PM

To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SKE7416G - OD AIG - SURVEYED 8 AUG 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$5750.00 @ 4 days of repairs.

Your early closure is appreciated.

Best regards - jb

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 14 August 2018 3:40 PM
To: Claims; SUR
Subject: RE: RE : OD claim for SKE 7416 G on 07/028/2018

Dear Phua,

Please be informed that the excess of above vehicle is \$2,000.00.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Wednesday, 8 August 2018 10:29 AM
To: SUR <sur@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE : OD claim for SKE 7416 G on 07/028/2018

Good morning all ,

Here is the attachments of GIA report and estimate for your kind reference . ZKindly assist the claim .

Thank you .

Best Regards,
Phua
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2672C
Vehicle Details	
Vehicle No.:	SKE7416G
Vehicle to be Exported:	No
Intended De-registration Date:	14 Aug 2018
Vehicle Make:	AUDI
Vehicle Model:	S5 SPORTBACK 3.0 TFSI QU (FACELIFT)
Primary Colour:	White
Manufacturing Year:	2011
Engine No.:	CGW029519
Chassis No.:	WAUZZZ8T0CA015982
Maximum Power Output:	245.0 kW (328 bhp)
Open Market Value:	\$67,356.00
Original Registration Date:	29 Mar 2012
First Registration Date:	29 Mar 2012
Transfer Count:	0
Actual ARF Paid:	\$67,356.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Mar 2022
PARF Rebate Amount:	\$43,781.00
Intended COE Rebate Details	
COE Expiry Date:	28 Mar 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$79,304.00
COE Rebate Amount:	\$28,715.00
Total Rebate Amount:	\$72,496.00

The information contained herein is correct as at 14 Aug 2018

OK

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number **S8232672C**

Name
PAULINA HATTA

Birth Date: 25 Oct 1982
Issue Date: 30 Jul 2010

001879388J



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S8232672C**



Name

PAULINA HATTA

Race

CHINESE

Date of birth

25-10-1982

Sex

F

S8232672C

Country of birth


SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3A Motor cars without clutch pedals (Auto) =< 3000kg 30 Jul 2010
with =< 7 passengers, exclusive of the driver; and
other motor vehicles without clutch pedals =< 2500kg

NP 428A



Licence No: S8232672C



90715

NRIC No. **S8232672C**

Nationality

INDONESIAN

Date of issue

08-01-2010

APT BLK 101 CAIRNHILL CIRCLE #06-14
SINGAPORE 229809

NRIC No: S8232672C

Date: 18/04/2018

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0903/2018/KS
Date : 7-Aug-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Paulina Hatta
Address : 101 Cairnhill Circle
#06-14
Singapore 229809
Telephone : HP +65 96165001
Type of Claim : Own Damage claims
Policy No. : 2100297180
Vehicle No : **SKE 7416 G**
Model Code : Audi S5 SB 3.0 TFSI QU
Model / Year : Mar-12
Engine No : CGW 029519
Chassis No : WAUZZZ8T0CA0155982
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 7-Aug-18
Place of Accident : Merchanr Rd (Outside Riverside Point Next to CTE Exit)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKE 7416 G.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	
2	To dismantle and renew front bumper, rhs headlight and rhs front fender. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00 1000 ✓	
3	To respray front bumper and rhs front fender	\$ 1,500.00 1100 ✓	
4	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00 X.	
5	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>4,552.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMC 2030 E.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER COVER <i>del</i>	\$ 2,635.00	✓ 7108
2	FRONT BUMPER FIXING PARTS	\$ 222.00	+
3	FRONT BUMPER SECURING STRIP LH / RH	2 \$ 60.00	+
4	FRONT BUMPER CLOSING ELEMENT	\$ 195.00	+
5	FRONT BUMPER CLOSING ELEMENT ADAPTOR	\$ 107.00	+
6	AIR GUIDE GRILLE RH <i>new</i>	\$ 307.00	+
7	WHEEL SPOILER RH FRONT <i>new</i>	\$ 50.00	+
8	GUIDE PIECE RH <i>Not NCC</i>	\$ 37.00	? X
9	FRONT PARKING AID SENSOR <i>new</i>	\$ 211.00	+
10	FRONT PARKING AID SENSOR SEAL RING <i>new</i>	\$ 5.00	+
11	FRONT FENDER RH <i>Painted</i>	\$ 930.00	✓ 744
12	FRONT FENDER ATTACHMENT PARTS RH <i>Not New</i>	\$ 49.00	? X
13	FRONT FENDER BRACKET RH FRONT <i>Best</i>	\$ 50.00	✓ 40
14	FRONT FENDER BRACKET RH REAR <i>Not New</i>	\$ 50.00	? X
15	FRONT FENDER BRACKET LH <i>Best</i>	\$ 34.00	✓ X nn
16	FRONT FENDER BRACE RH <i>Best Not New</i>	\$ 106.00	? }
17	WHEEL HOUSING LINER RH <i>Not New</i>	\$ 163.00	? } X
18	WHEEL HOUSING ATTACHMENT PARTS RH <i>Not New</i>	\$ 38.00	? }
19	"V6T" CHROME EMBLEM <i>new</i>	\$ 108.00	✓ 86
20	HEADLIGHT MOUNTING RH <i>Not New</i>	\$ 109.00	+
SUB- TOTAL SPARE PARTS		\$ 5,466.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 7416 G.

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
21	HEADLIGHT RH <i>not new</i>	\$ 2,341.00	*
22	HALOGEN FOG LAMP RH <i>new</i>	\$ 236.00	*
23	LIFT CYLINDER RH <i>new</i>	\$ 241.00	*
24	ALUMINIUM RIM RH <i>Not new</i>	\$ 965.00	*
25	SUNDRIES <i>Not New</i>	\$ 300.00	? X
TOTAL SPARE PARTS		\$ 9,549.00	
TOTAL LABOUR CHARGES		\$ 4,552.00	
GRAND TOTAL		\$ 14,101.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 08/08/18
Authorised Date :
Excess Cost :
Liability :
Remarks : ~~Not~~ Authorised Repairs, 04 days

LK&P Ltd. To be notified to change notify
the Repairer's estimate, including:
• To resurvey before after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0903/2018/KS
Date	:	7-Aug-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi ADRIAN

4 DAYS - OK - JB - 1 Oct 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Paulina Hatta
Address	:	101 Cairnhill Circle
	:	#06-14
	:	Singapore 229809
Telephone	:	HP +65 96165001
Type of Claim	:	Own Damage claims
Policy No.	:	2100297180
Vehicle No	:	SKE 7416 G
Model Code	:	Audi S5 SB 3.0 TFSI QU
Model / Year	:	Mar-12
Engine No	:	CGW 029519
Chassis No	:	WAUZZZ8T0CA0155982
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	7-Aug-18
Place of Accident	:	Merchanr Rd (Outside Riverside Point Next to CTE Exit)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKE 7416 G.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To dismantle and renew front bumper, rhs headlight and rhs front fender. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00	\$ 1,000.00
3	To respray front bumper and rhs front fender	\$ 1,500.00	\$ 1,100.00
4	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00	
5	To carry out diagnostic checks.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 4,552.00	\$ 2,772.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMC 2030 E.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER COVER	\$ 2,635.00	\$ 2,108.00
2	FRONT BUMPER FIXING PARTS	\$ 222.00	
3	FRONT BUMPER SECURING STRIP LH / RH	2 \$ 60.00	
4	FRONT BUMPER CLOSING ELEMENT	\$ 195.00	
5	FRONT BUMPER CLOSING ELEMENT ADAPTOR	\$ 107.00	
6	AIR GUIDE GRILLE RH	\$ 307.00	
7	WHEEL SPOILER RH FRONT	\$ 50.00	
8	GUIDE PIECE RH	\$ 37.00	
9	FRONT PARKING AID SENSOR	\$ 211.00	
10	FRONT PARKING AID SENSOR SEAL RING	\$ 5.00	
11	FRONT FENDER RH	\$ 930.00	\$ 744.00
12	FRONT FENDER ATTACHMENT PARTS RH	\$ 49.00	
13	FRONT FENDER BRACKET RH FRONT	\$ 50.00	\$ 40.00
14	FRONT FENDER BRACKET RH REAR	\$ 50.00	
15	FRONT FENDER BRACKET LH	\$ 34.00	
16	FRONT FENDER BRACE RH	\$ 106.00	
17	WHEEL HOUSING LINER RH	\$ 163.00	
18	WHEEL HOUSING ATTACHMENT PARTS RH	\$ 38.00	
19	"V6T" CHROME EMBLEM	\$ 108.00	\$ 86.00
20	HEADLIGHT MOUNTING RH	\$ 109.00	
SUB- TOTAL SPARE PARTS		\$ 5,466.00	\$ 2,978.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKE 7416 G.

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
				\$ 2,978.00
21	HEADLIGHT RH		\$ 2,341.00	
22	HALOGEN FOG LAMP RH		\$ 236.00	
23	LIFT CYLINDER RH		\$ 241.00	
24	ALUMINIUM RIM RH		\$ 965.00	
25	SUNDRIES		\$ 300.00	
	TOTAL SPARE PARTS	:	\$ 9,549.00	\$ 2,978.00
	TOTAL LABOUR CHARGES	:	\$ 4,552.00	\$ 2,772.00
	GRAND TOTAL	:	\$ 14,101.00	\$ 5,750.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKE 7416 G

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0903/2018/MAS

29 Nov 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SKE 7416 G, Audi S5 SB 3.0 TFSI Qu

With reference to the above-mentioned vehicle, no. **SKE 7416 G**, claimant, **Ms. Paulina Hatta**, please find the related document per attached.

1. A copy of the Original invoice no. 85013173 – S\$4,012.50
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SKE 7416 G

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Aug 2018		10 Aug 2018 11:36 Edit Adj Rpt	S\$5,750.00 Edit Estimates	S\$5,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS Insured: PAULINA HATTA, ID: S8232672C, Tel: +6596165001, Email: PAULINA.HATTA@GMAIL.COM Vehicle Reg. No.: SKE7416G Claim Type: OD / 5576546594SG Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911 Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/08/2018] Driver/Custodian: PAULINA HATTA (35 / Female), NRIC: S8232672C, Tel: +6596165001 [Created by insurer] 07/08/2018 00:00 - :59 [76 Months and 9 Days From LTA Reg Date (Man Yr)] 2100297180 (Comprehensive) S\$2,000.00 View All Compose Case Mail																								
ASSOCIATED MAIL RECEIVED • AIG_SG (13/08/2018): SKE7416G / OD / 07/08/2018 / Coverage & Excess update																								
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Claim Documents

*SKE7416G (5576546594SG)
OD

Aug 7 2018 12:00AM
[PAULINA HATTA]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		Use Viewer	
Photos/Images															3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print			
1	14/11/18 17:30	General View													Load JPG	☒		
2	14/11/18 17:30	General View													Load JPG	☒		
3	14/11/18 17:30	General View													Load JPG	☒		
4	14/11/18 17:30	General View													Load JPG	☒		
5	14/11/18 17:30	General View													Load JPG	☒		
6	14/11/18 17:30	General View													Load JPG	☒		
7	14/11/18 17:30	General View													Load JPG	☒		
8	14/11/18 17:30	General View													Load JPG	☒		
9	14/11/18 17:30	General View													Load JPG	☒		
10	14/11/18 17:30	General View													Load JPG	☒		
11	14/11/18 17:30	General View													Load JPG	☒		
12	14/11/18 17:30	General View													Load JPG	☒		
13	14/11/18 17:30	General View													Load JPG	☒		
Documentation															1 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print			
1	10/08/18 17:14	Driver's Driving License													Load PDF			
2	10/08/18 17:14	ESTIMATE													Load PDF			
3	10/08/18 17:14	Singapore Accident Statement													Load PDF			
4	04/12/18 10:41	WORKSHOP INVOICE													Load PDF			
5	04/12/18 10:41	DISCHARGE VOUCHER													Load PDF			

Linked Accident Report Documents

			View	Use Viewer	
Assessment Reports			1 per page		☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	07/08/18 12:56	Accident Statement	1	Load HTM	
			3 per page		☒
Photos/Images				Thumbnail	Print
No	Finalized On	Premium Automobiles Pte Ltd (UBI)			
1	07/08/18 12:53	Accident Photo	1	Load JPG	☒
2	07/08/18 12:53	Accident Photo	1	Load JPG	☒
3	07/08/18 12:53	Accident Photo	1	Load JPG	☒
4	07/08/18 12:53	Accident Photo	1	Load JPG	☒
5	07/08/18 12:54	Accident Photo	1	Load JPG	☒
6	07/08/18 12:54	Accident Photo	1	Load JPG	☒
7	07/08/18 12:54	Accident Photo	1	Load JPG	☒
8	07/08/18 12:54	Accident Photo	1	Load JPG	☒
9	07/08/18 12:54	Accident Photo	1	Load JPG	☒
			1 per page		☒
Documentation				Thumbnail	Print
No	Finalized On	Premium Automobiles Pte Ltd (UBI)			
1	07/08/18 12:50	Sketch Plan	1	Load JPG	☒
2	07/08/18 12:50	Sketch Plan #2	1	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: ☐ Handling Insurer	
Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18014487/AQD3N2

Date: 04/12/2018

REFERENCE

Insured/Claimant: PAULINA HATTA Policy No: 2100297180
Date of Loss: 07/08/2018 Nature of Claim: OD Claim No: 5576546594SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKE7416G
Make & Model: AUDI S5 SPORTBACK, 3.0 TFSI QUATTRO (A) Engine No: CGW029519
Reg. Date: 29/03/2012 (Man. Year: 2011) Chassis No: WAUZZZ8T0CA015982
Colour: White Odometer: 39351 km
Engine Capacity: 2995 cc
Market Value/New Car Price: S\$90,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 255/35 R19 Rear Tyre Size: 255/35 R19
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,549.00	2,978.00	6,571.00	68.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,552.00	2,772.00	1,780.00	39.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,101.00	5,750.00	8,351.00	59.22
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	12,101.00	3,750.00	8,351.00	69.01
+ GST 7.00/7.00% (S\$)	847.07	262.50	584.57	69.01
Nett Amount (S\$)	12,948.07	4,012.50	8,935.57	69.01

INSPECTION

Date of Assignment: 10/08/2018
Date Inspected: 08/08/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER COVER	Deformed	2,635.00 FS	*2,108.00 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	222.00 FS	*- FS
3	2	*FRONT BUMPER SECURING STRIP LH / RH	Not Necessary	60.00 FS	*- FS
4	1	*FRONT BUMPER CLOSING ELEMENT	Not Necessary	195.00 FS	*- FS
5	1	*FRONT BUMPER CLOSING ELEMENT ADAPTOR	Not Necessary	107.00 FS	*- FS
6	1	*AIR GUIDE GRILLE RH	Not Necessary	307.00 FS	*- FS
7	1	*WHEEL SPOILER RH FRONT	Not Necessary	50.00 FS	*- FS
8	1	*GUIDE PIECE RH	Not Necessary	37.00 FS	*- FS
9	1	*FRONT PARKING AID SENSOR	Not Necessary	211.00 FS	*- FS
10	1	*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	5.00 FS	*- FS
11	1	*FRONT FENDER RH	Dented	930.00 FS	*744.00 FS
12	1	*FRONT FENDER ATTACHMENT PARTS RH	Not Necessary	49.00 FS	*- FS
13	1	*FRONT FENDER BRACKET RH FRONT	Bent	50.00 FS	*40.00 FS
14	1	*FRONT FENDER BRACKET RH REAR	Not Necessary	50.00 FS	*- FS
15	1	*FRONT FENDER BRACKET LH	Not Necessary	34.00 FS	*- FS
16	1	*FRONT FENDER BRACE RH	Not Necessary	106.00 FS	*- FS
17	1	*WHEEL HOUSING LINER RH	Not Necessary	163.00 FS	*- FS
18	1	*WHEEL HOUSING ATTACHMENT PARTS RH	Not Necessary	38.00 FS	*- FS
19	1	*V6T CHROME EMBLEM	Necessary	108.00 FS	*86.00 FS
20	1	*HEADLIGHT MOUNTING RH	Not Necessary	109.00 FS	*- FS
21	1	*HEADLIGHT RH	Not Necessary	2,341.00 FS	*- FS
22	1	*HALOGEN FOG LAMP RH	Not Necessary	236.00 FS	*- FS
23	1	*LIFT CYLINDER RH	Not Necessary	241.00 FS	*- FS
24	1	*ALUMINIUM RIM RH	Not Necessary	965.00 FS	*- FS
25	1	*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	9,549.00	2,978.00
--------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, RHS HEADLIGHT AND RHS FRONT FENDER. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	2,100.00	1,000.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	New	1,500.00	1,100.00
4	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	New	280.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECKS.	New	192.00	192.00
Gross Labour Cost (\$\$)			4,552.00	2,772.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >