

CS3/IPC18011907/ Usd3-1

Marcus
Ong Hi Li

ASSIGNMENT (01800)

IPC

10/08/2018

OD (1) W (1) P (1) / OD RES / EVA / INV / MV / CS

Job

SKF 5713G

Issued

SLA 7192K

a/W

AF Motorwork2

Tel

9753 0075

at

66 Bukit Ave 6 Ark

Pole

Claim No

17118/18/ vpus/020718

Sum

Payee

Mid

OR

D.O.A

28/06/2018

03/07/2018 @ 11am owner waiting

CA / P

24 HRS

1up

H.O.D. Endorsement

Unit

51pm @ 29/6/18

Personnel

Kenneth

Vehicle IN

(011)

Unit

(X)

SLA-7192K-x

- SLA5713G-x

03/8/18 Summit d/s \$4100 5 Lg.

(\$2,390.00 Red - 37%)

RECEIVED 16 AUG 2018

(18/1/13) W8

ASS. REC. BY: /10/0000/5

REF:

120

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD: 0 / WS / TP / RES / ADD / RES / EVA / INV / MV

To Inspect Vehicle No: 51457136at Workshop no: 17 F Volkswagenof: 66

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair on the time of inspection.

NS	O/S

Bal. or Market Value: 50k.

IDP: Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ Res: Yes or No

Lump Sum: _____ S Val: Yes or No

CA / REV / REP / 10/0000/5

Valid: 11/01/13

Date: _____ Person Contacted: _____

Date / Time: _____ 27437246no repair. Rep 10k.

RECEIVED 25 JUL 2013

Date/Time, File No

25/07/13

Type of Report

1) Type of Report

Date/Time, File No

2)

Report Form No

Lump Sum / 10/0000/5

Veh No: 51457136 Yr Regn: 6 12

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or CA/Make: Volkswagen Touran or 1390Colour: Silver A/C: Insured / Std / Nil / N/ASp. Reading: 128484 T/Radio: Insured / Std / Nil / N/A

Eng/No: _____

C/No: WVG22XIT2CW 107934Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 205/55 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mmRear: 6 mm

R/Bal: _____ mm

L/Bal: 6 mmD.O.A: 2/6/14D.O.I: 3/7/14 @ 1155am

Survey held at: _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Days Of Repair: _____

Resurvey No. of Trip: 2Survey Fee: 190

Transportation: _____

Add Fee: ☐ Site Insp (\$ _____) S + RS _____☐ Interview (\$ _____) Photos _____☐ Tech. Invs (\$ _____) Others _____☐ Weekend (\$ _____)TOTAL 190

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 10 August 2018 12:35 PM
To: Nivitha (LKK Auto); ASSIGNMENTS@LKKAUTO.COM
Cc: MT_Claim_SG; sur@lkkauto.com
Subject: RE: (URGENT - PRS): Your Ref: SLA 7192K ; Our Ref: PD/DL/1801135 (JC) Our Ref: 17/18/18/VP05/020718
Attachments: 20718 TP SURVEY REPORT.pdf

Hi Nivitha

Attached is the TP survey report.

Please let us have your surveyor's review and report.

Thanks,
Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 29 June, 2018 5:16 PM
To: ONG LI LI; ASSIGNMENTS@LKKAUTO.COM
Cc: MT_Claim_SG; sur@lkkauto.com
Subject: RE: (URGENT - PRS): Your Ref: SLA 7192K ; Our Ref: PD/DL/1801135 (JC) Our Ref: 17/18/18/VP05/020718

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joanna [mailto:Joanna@satwantlaw.com]
Sent: Friday, 29 June 2018 4:04 PM
To: 'ONG LI LI' <llong@lonpac.com>; 'MT_Claim_SG' <mt_claim@lonpac.com>; assignments@lkkauto.com; "SUR" <sur@lkkauto.com>
Cc: limdanny@satwantlaw.com.sg; 'Margaret Lim' <MargaretLim@satwantlaw.com.sg>; cordell@satwantlaw.com.sg; admin@afmotorworkz.com
Subject: RE: (URGENT - PRS): Your Ref: SLA 7192K ; Our Ref: PD/DL/1801135 (JC) Our Ref: 17/18/18/VP05/020718
Importance: High

WITHOUT PREJUDICE

Dear Li Li,

We refer to your email dated 29th June 2018.

We have been instructed to reject your surveyors and propose to engage Andrew How.

Kindly see attached letter and the workshop information as below:-

Workshop: AF Motorworkz Pte Ltd

Address: 66 Kallang Road, Singapore 417895

Contact: Kenneth How (9753 0086)

Kindly liaise directly with the workshop for the PRS on an urgent basis.

Thank you & Best Regards

Joanna Goh

Secretary

For and on behalf of

SATWANT & ASSOCIATES

Advocates & Solicitors | Notary Public | Commissioner for Oaths

Main Office: 11, Upper Macao Road, Singapore 588896 | tel: 6299 9470 | fax: 6299 5541

Branch Office: 11, Upper Macao Road, Singapore 588896 | tel: 6299 9470 | fax: 6299 5541

Email Confidentiality Warnings:

This message contains information which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you are notified that disclosing, copying, distribution or use of this information is strictly prohibited. If you have received this message in error, please notify us by e-mailing us at [joanna@satwantlaw.com] and delete it from your system. Unless the contents of this email relate to matters of the firm's engagement, any opinions, views and other information are expressed in the sender's personal capacity. You should not rely on this email and any file attached thereto. We take no responsibility for any loss or damage, whether caused by our own negligence or any loss results from a computer virus or a defect in the transmission of this email or any attached file

From: ONG LILIAN [mailto:llong@lonpac.com]

Sent: Friday, June 15, 2018 3:16 PM

To: Joanna Goh [mailto:joanna@satwantlaw.com]; assignments@lkkauto.com; 'SUR' (sur@lkkauto.com)

Cc: limdanny [mailto:limdanny@satwantlaw.com.sg]; Margaret Lim [mailto:margaretlim@satwantlaw.com.sg]; admin@afmotorworkz.com

Subject: RE: Your Ref: SLA 119218; Our Ref: PD/DL/1801135 (JC) Our Ref: 17/18/18/05/00000000

Without Prejudice

Save as

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle. We propose to use one of the motor surveyors on the following list to conduct the joint pre-repair survey as a single joint expert.

No.		Please tick ✓
1		
2	Xiang	
3	Taufikh	

4	Bry...		
5	Adri...		
6	Moh...	Consul	
7	Marg...		
8	Ken...		
9	Mu...	Aril Bin	
10	Sat...	Arrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these proposed vendors as a single joint expert.

Regards,
Ong Li Li
Senior Counsel | Lompac Insurance Bhd
300 Beach Road #04/07 The Concourse Singapore 199555
Tel : (65) 6296 2706 Ext. 254 Fax: (65) 6296 2706

From: Joanna Cordell [mailto:joanna@satwantlaw.com]
Sent: Friday, 18 2:38 PM
To: MT_Cordell@satwantlaw.com.sg; 'Margaret Lim'; cordell@satwantlaw.com.sg; admin@afmotorworkz.com
Cc: limdm@afmotorworkz.com
Subject: Your Ref: SLA 719 / Our Ref: PD/DL/1801135 (JC)
Importance: High

WITHOUT

Dear Sir,

PRS attached for your attention.

Thank you for your response.

Joanna Cordell
Secretary
For and on behalf of
SATWANT
Advocate
Main Office
Branch Office

Notary Public | Commissioner for Oaths
Singapore, Singapore 588996 | tel: 6299 9470 | fax: 6299 5541
5 Toa Payoh #02-03 Harsing Centre Singapore 319394 | tel: 6221 6114 | fax: 6266 6925

Email Confidential

This message and its contents are notified

which is subject to legal professional privilege and/or is confidential. If you are not the intended recipient, you should not disseminate, disclosure, copying, distribution or use of this information is strictly prohibited. If you have received this

message in
relate to ma
capacity. Yo
own neglig.

may be by e-mailing us at [franna@catwantlaw.com] and delete it from your system. Unless the contents of this email
of the firm's engagement, any opinions, views and other information are expressed in the sender's personal
email and any file attached to it. We take no responsibility for any loss or damage, whether caused by our
errors from a computer virus or a defect in the transmission of this email or any attached file

This email has been checked for viruses by AVG antivirus software.
www.avg.com

66, KAKI BUKIT AVE 6, ARK@KB
SINAGPORE 417895
TEL: 6384 9931 | FAX: 6384 9932
www.afmotorworkz.com.sg
Co. Reg. No.: 201525508Z

Invoice No : AFM-3155-Q18

INVOICE

Claimant:

Date of Invoice : 31/7/2018

C/o. M/s. AF Motorworkz Pte Ltd

66, KAKI BUKIT AVE 6, ARK@KB
SINAGPORE 417895

Claim Type : Third Party

Date of Accident 28/6/2018

Vehicle Reg. No : SKF5713G

Vehicle Make/Model : VOLKSWAGEN TOURAN

Description**Amount (S\$)**

Lump Sum Repairs As Per Recommendation.

\$ 6,490.00

Total \$ 6,490.00

Singapore Dollar : SIX THOUSAND FOUR HUNDRED AND NINETY ONLY



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address 1 Simei St 3 #02 24 S(529890)

Mobile 9295 2204 Fax 6722 8508 Email pasvcs@hotmail.com

Business Reg 201404434D

INVOICE

Mr Cheong Kin Whye
Blk 522b Tampines Central 7
#05-23
Singapore 522522

Invoice No. : HA/1807-60
Date : 28/07/2018

Descriptions	Amount (SGD)
Services rendered for appraiser / inspection report :-	
Survey Fee	
Photographs	
Transport Fees	
Re-inspection Fees	
Total :	SGD : \$ 494.00
SGD Dollar : Four Hundred Ninety Four Dollars Only.	
Our Reference : PAS/TP/0070718	
Vehicle No. : SKF5713G	
Make & Model : Volkswagen Touran	
Your Claim No. : Third Party Claim	

Notes:

All cheque payment should be Crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD".

Please indicate our "INVOICE NO." on the reverse side of the cheque.

Should you have any enquiries, please do not hesitate to contact us.



For PROMINENT APPRAISER SERVICES PTE LTD



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0070718

Date of Report : 28/07/2018

To : Mr Cheong Kin Whye
Blk 522b Tampines Central 7
#05-23
Singapore 522522

Date of Assignment : 03/07/2018
Report requested by : Mr Cheong Kin Whye
Date of Accident : 28/06/2018
Date of Inspection : 03/07/2018
Claim No. : Third Party Claim
Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SKF5713G
Make & Model : Volkswagen Touran
Date of Registration : 14/06/2012
Colour : Met. Silver

Engine Capacity (cc) : 1390cc
Mileage (km) : 128484km
Chassis / Frame No. : WVGZZZ1TZW107934
Engine No. : CAV406107

TYRE CONDITION

Front LH : 6 mm
Make : Pirelli

Front RH : 6 mm
Make : Pirelli

Rear LH : 6 mm
Make : Pirelli

Rear RH : 6 mm
Make : Pirelli

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. AF Motorworkz Pte Ltd
66, Kaki Bukit Ave 6, ARK @ KB, Singapore 417895

ASSESSMENT

Repairer's Estimate : \$ 9,655.67
Revised Amount : \$ 8,111.66
Less Excess : \$ -
Recommended Reserve : \$ 6,490.00 (Lump Sum)

Estimated Normal Period of Repairs : 8 Working Days

Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

Vehicle No : SKF5713G

Report No. : PAS/TP/0070718

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. AF Motorworkz Pte Ltd, 66, Kaki Bukit Ave 6, ARK @ KB, Singapore 417895.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the rear portion.

DAMAGES

The tailgate, rear bumper, rear end panel, rear floor panel, LHR chassis member, rear fenders, LH taillamp, LH reflector, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$8,111.66.

CONCLUSION


The repairer has agreed to undertake the repairs at a lump sum of SGD \$6,490.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,
Prominent Appraiser Services Pte Ltd


Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SKF5713G

Report No. : PAS/TP/0070718

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (\$)	Our Assessment (\$)
1	1 pc	Tailgate	Dented/Distorted	\$ 1,704.60	\$ 1,704.60
2	1 pc	Tailgate emblem (Logo)	Necessary	\$ 76.40	\$ 76.40
3	1 pc	Tailgate emblem (Touran)	Necessary	\$ 57.90	\$ 57.90
4	1 pc	Tailgate emblem (TSi)	Necessary	\$ 40.70	\$ 40.70
5	2 pcs	Tailgate lamp R/L	LH Cracked	\$ 719.20	\$ 359.60
6	1 pc	Tailgate lock	Refit	\$ 270.40	\$ -
7	1 pc	Tailgate inner trim	Dented/Cracked	\$ 328.20	\$ 328.20
8	1 pc	Tailgate weatherstrip	Torn/Necessary	\$ 254.40	\$ 254.40
9	2 pcs	Tail lamp R/L	LH Cracked	\$ 645.40	\$ 322.70
10	1 pc	Rr bumper	Dented	\$ 1,346.10	\$ 1,346.10
11	1 pc	Rr bumper reflector LH	Refit	\$ 96.20	\$ -
12	2 pcs	Rr bumper side guide R/L	Cracked/Necessary	\$ 119.20	\$ 119.20
13	1 pc	Rr bumper centre guide	Dented/Cracked	\$ 88.20	\$ 88.20
14	1 pc	Rr bumper reinforcement	Dented	\$ 473.50	\$ 473.50
15	1 pc	Rr end panel	Dented/Distorted	\$ 721.60	\$ 721.60
16	1 pc	Rr end panel trim	Cracked/Deformed	\$ 164.30	\$ 164.30
17	1 pc	Rr taillamp panel LH	Dented/Repair	(Refer labour no. 6 & 7)	
18	1 pc	Rr fender LH	Dented/Repair	(Refer labour no. 6 & 7)	
				\$ 7,106.30	\$ 6,057.40
Less Discount : 10%				\$ 710.63	\$ 605.74
List Parts Sub-Total :				\$ 6,395.67	\$ 5,451.66
1	1 pc	Rr windscreen sealant	Necessary	\$ 40.00	\$ 40.00
2	1 set	Reverse sensor	Dented/Damaged	\$ 220.00	\$ 220.00
3	1 pc	Rr end panel sealant	Necessary	\$ 40.00	\$ 40.00
Special Nett Sub-Total :				\$ 300.00	\$ 300.00
Parts Total :				\$ 6,695.67	\$ 5,751.66

3665
3298.5



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SKF5713G

Report No. : PAS/TP/0070718

S/No.	Labour Descriptions	Repairer's Estimate (\$)	Our Assessment (\$)
1	To remove and reinstall rear interior trims, garnishes, etc. for necessary repairs.	\$ 120.00	\$ 100.00 80
2	To remove, replace and reinstall rear reverse sensors & control unit.	\$ 60.00	\$ 50.00 ✓
3	To check rear electrical wiring system.	\$ 60.00	\$ 50.00 30
4	To transfer tailgate component parts to new tailgate.	\$ 120.00	1^ \$ 100.00 X
5	To transfer rear windscreen to new tailgate.	\$ 120.00	1^ \$ 120.00 X
6	To straighten, repair, realign on affected area and replace damaged parts.	\$ 1,200.00	\$ 880.00 600
7	To spray painting, blending on affected and adjacent area.	\$ 1,200.00	\$ 1,000.00 800
8	To spray anti-rust coating on new and affected panels.	\$ 80.00	\$ 60.00 50
Labour Total :		\$ 2,960.00	\$ 2,360.00
Total (Parts & Labour) :		\$ 9,655.67	\$ 8,111.66

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 6,490.00

Under normal circumstances, the repairs should be completed within a reasonable period of **8 Working Days**.

64 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CS3/LPC18011907/Usd3e2-1		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 21-08-2018		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLA 7192K	Veh. Inspected	SKF 5713G	
Policy No.		Coverage (\$)	0.00	
Claim No.	17/18/18/VP05/020718	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	10/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN TOURAN (A)	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WVGZZZ1TZCW107934	Colour	SILVER	
Odometer	128484	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	PIRELLI	6 mm	
L/H Front Tyre	205/55 R16	PIRELLI	6 mm	
R/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
L/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/06/2018	Inspection Date	03/07/2018	
Survey held at	AF MOTORWORKZ PTE LTD 66 KAKI BUKIT AVENUE 6 SINGAPORE 417895			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKF 5713G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE	TO REPAIR SEE LABOUR	1,704.60	-
1	TAILGATE EMBLEM (LOGO)	NECESSARY	76.40	76.40
1	TAILGATE EMBLEM (TOURAN)	NECESSARY	57.90	57.90
1	TAILGATE EMBLEM (TSI)	NECESSARY	40.70	40.70
2	TAILGATE LAMP R/L @\$359.60 (CRACKED)	NOT CONSISTENT WITH THE IMPACT	719.20	-
1	TAILGATE LOCK	NOT NECESSARY	270.40	-
1	TAILGATE INNER TRIM	NOT NECESSARY	328.20	-
1	TAILGATE WEATHERSTRIP	TORN	254.40	254.40
2	TAIL LAMP R/L @\$322.70	N/S CRACKED	645.40	322.70
1	RR BUMPER	DENTED	1,346.10	1,346.10
1	RR BUMPER REFLECTOR LH	NOT NECESSARY	96.20	-
2	RR BUMPER SIDE GUIDE R/L @\$59.60	CRACKED / NECESSARY	119.20	119.20
1	RR BUMPER CENTRE GUIDE	CRACKED	88.20	88.20
1	RR BUMPER REINFORCEMENT	BENT	473.50	473.50
1	RR END PANEL	DENTED	721.60	721.60
1	RR END PANEL TRIM	TWISTED	164.30	164.30
1	RR TAILLAMP PANEL LH (NPA)	NOT NECESSARY	-	-
1	RR FENDER LH (NPA)	NOT NECESSARY	-	-
	LESS 10% DISCOUNT		-710.63	-366.50
			6,395.67	3,298.50
<u>SPECIAL NETT ITEMS</u>				
1	RR WINDSCREEN SEALANT (SN)	NOT NECESSARY	40.00	-
1	SET REVERSE SENSOR (SN)	SHORTED	220.00	200.00
1	RR END PANEL SEALANT (SN)	NECESSARY	40.00	40.00
			300.00	240.00
<u>LABOUR</u>				
	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, ETC. FOR NECESSARY REPAIRS.		120.00	80.00

Report Ref No. CS3/LPC18011907/Usd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No..2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REPLACE AND REINSTALL REAR REVERSE SENSORS & CONTROL UNIT.		60.00	50.00
	TO CHECK REAR ELECTRICAL WIRING SYSTEM.		60.00	30.00
	TO TRANSFER TAILGATE COMPONENT PARTS TO NEW TAILGATE.	NOT NECESSARY	120.00	-
	TO TRANSFER REAR WINDSCREEN TO NEW TAILGATE.	NOT NECESSARY	120.00	-
	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF TAILGATE.		1,200.00	600.00
	TO SPRAY PAINTING, BLENDING AND ADJACENT AREA.		1,200.00	800.00
	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.		80.00	50.00
			2,960.00	1,610.00
	GRAND TOTAL		9,655.67	5,148.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,100.00

Report Ref No. CS3/LPC18011907/Usd3e2-1

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.