

Surveyor:

Kenneth

DOI:

8/8/18

Date / Time:

8/8/18

Registered in Merimen:

Pre-assign / CCU / FTE

GBC 7014A



Insured Vehicle No.:

Sun Sh systems P/L

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

6/8/2018

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Shiri B. Samadi

Driver Tel No.:

96744232

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

MLW 51378 21805

NISSAN NAVO

BKE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

GBC 7014A

JLR 8974

SLG 1582B



INSRS:

WSP:

Tel:

Liability:

RMKS:

on CT1



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Guan motor TP



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

Date / Time	STAGE	DATE / PIC
12/8	SLG 1582B - X; GBC 7014 A - X	
12/8	- Please redirect claim to Myrian vehicle	
16/8/2018	check with Boon Sen, to check BOLA as foreign is 2nd vehicle. KIV rply.	
23/8/2018	SINCE 91 CONFIRM HE HIT MALAYSIA VEHICLE WHICH MOVED FORWARD TO HIT 1ST VEHICLE THE BOLA IS NOT APPLICABLE.	
24/8/2018	PIR not around, call tomorrow	
24/8/2018	confirm accident statement explain to her, BOLA does not apply as the second vehicle is foreign vehicle. She agreed to settle and covers. HEP will be attached. send letter to CT pass file to finalize ✓	
	pass file to type mandate report	
	After repair photo ✓	
	RECEIVED 12 NOV 2018	

PRELIMINARY ADVICE	Date/Time: 16/8/2018	Sent By: HMK
--------------------	----------------------	--------------

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	SS 3,900.00 (6 days) Reduction: 46.67 %		Email <input type="checkbox"/> Call <input type="checkbox"/>

FINAL SETTLEMENT	Date/Time: 24/12/2018	Confirm with: Ah Hing	Email <input type="checkbox"/> Call <input checked="" type="checkbox"/>
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No.: 28		If NO or B 28, Ass. Lis: 100%
Repair Cost:	SS 3,900.00		3 car chain collision, 01D last car.
Loss of Rental (LOR):	SS 900.00 (9 days) x 100.00		
Loss of Use (LOU):	SS - (\$ x days)		
Loss of Income (LOI):	SS - (\$ x days)		
LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]			
GIA/LTA Search	SS 7.45		
Medical:	SS -		
Disbursement:	SS - (e.g. Tow/ Independent)		
Legal Cost	SS -		
Total:	SS 4,807.45	Global Sum SS:	

FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input checked="" type="checkbox"/>
Payee 1:	SS 4,807.45	Name 1: Guan Motor Works	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

ASS. REC. BY:

REF: 0721

ASSIGNMENT

Kenneth

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Guan Motor

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLG 7582B Yr Regn: 09, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Hit Lancer c.c. 1590

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 43614 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: JMY SC 41 AG-01 005895

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modf: NII / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R4
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO YOKO or

Front		Rear
R/Bal. <u>2</u> mm		R/Bal. <u>2</u> mm
L/Bal. <u>2</u> mm		L/Bal. <u>2</u> mm
D.O.A. <u>8/8/18</u>		D.O.I. <u>8/8/18</u>

Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>10/8</u>	<u>File pass to Catherine</u>

US\$3,900.00 (Re. \$3,413.48 / 46.67%)

Date/Time, File Pass to? : Prell. Report
 : Final Report

1) _____
2) _____

Report Format : _____
Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	_____
Transportation:	_____
S + RS:	_____ \$
Fuel:	_____
Others:	_____
TOTAL	_____

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

KF

Not Authorized
 L1 Rep @ 3900k
 Assembly After Paint

6 days

REPAIR ESTIMATE FOR SLG1582B

8-8-18

No.	Qty	List Items			
1	1	Rear bumper	\$	B ₁	739.00 ✓
2	2	Rear bumper reflector	\$	M/SUPPS	68.00 ✓
3	1	Rear bumper tow cover	\$	RD	18.00 ✓
4	1 set	Rear bumper clips	\$	M	30.00 ✓
5	2	Rear bumper side retainer	\$	D17	48.00 ✓
6	1	Rear bumper inner top beam	\$	B ₁	72.00 ✓
7	1	Rear bumper inner reinforcement	\$	B ₁	184.00 ✓
8	2	Rear number plate lamp	\$	CM	96.00 ✓
9	1	Rear boot lid	\$	B ₁	778.20 ✓
10	1	Rear boot centre "MITSUBISHI" logo	\$	M	48.00 ✓
11	1	Rear boot "LANCER" emblem	\$	M	40.00 ✓
12	1	Rear boot "EX" emblem	\$	M	34.00 ✓
13	1 set	Rear boot inner trim clips	\$	M	50.00 ✓
14	2	Rear boot lamp	\$	S ₁	166.00 X
15	1	Rear boot top lock	\$	RD	62.00 ✓
16	1	Rear boot lower lock catch	\$	R	26.00 X
17	1	Rear tailgate weatherstrip	\$	RD/D17	134.00 50JIN
18	2	Taillamp	\$	S ₁	750.00 X
19	1	Rear end panel	\$	B ₁	452.00 ✓
20	1	Rear end panel top garnish	\$	RD	145.00 ✓
21	1	Rear spare tyre top board	\$	CM	141.00 ✓
22	1	Rear lower exhaust silencer	\$	RD	442.00 120JIN
23	3	Rear lower exhaust silencer mounting	\$	S ₁	114.00 X
			\$		4,637.20
			Less 10%	\$	463.72
			Total :	\$	4,173.48

Special Nett Items

24	1	Rear boot "C&C" emblem	\$	M	35.00 ✓
25	1	Rear number plate	\$	M/S	45.00 ✓
26	1 set	Rear end panel sealant	\$	M	50.00 30JIN
27	1 set	Reverse sensors	\$	RD	250.00 200JIN
			Total :	\$	380.00

Labour

1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$	1,200.00 7001
2	To putty and spray Spray Paintings charges.	\$	1,200.00 8001
3	To check wirings and lightings.	\$	40.00 201
4	To remove, refix reverse sensors.	\$	80.00 501
5	To remove, refit boot lid fittings.	\$	80.00 501

7 day

6	To remove, refit rear exhaust silencer.	\$ 80.00	602
7	To supply and apply anti rust treatment	\$ 80.00	601
Total :		\$ 2,760.00	

Total Parts and Labour : \$ 7,313.48

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

Not Authorized
61 Sing B?
Resony After Paint

6 days

REPAIR ESTIMATE FOR SLG1582B

8-8-18

No.	Qty	List Items			
1	1	Rear bumper	\$	Rs	739.00 ✓
2	2	Rear bumper reflector	\$	MIS	68.00 ✓
3	1	Rear bumper tow cover	\$	NU	18.00 ✓
4	1 set	Rear bumper clips	\$	NU	30.00 ✓
5	2	Rear bumper side retainer	\$	D11	48.00 ✓
6	1	Rear bumper inner top beam	\$		72.00 ?
7	1	Rear bumper inner reinforcement	\$		184.00 ?
8	2	Rear number plate lamp	\$		96.00 ?
9	1	Rear boot lid	\$	Rs	778.20 ✓
10	1	Rear boot centre "MITSUBISHI" logo	\$	NU	48.00 ✓
11	1	Rear boot "LANCER" emblem	\$	NU	40.00 ✓
12	1	Rear boot "EX" emblem	\$	NU	34.00 ✓
13	1 set	Rear boot inner trim clips	\$	NU	50.00 ✓
14	2	Rear boot lamp	\$	Sm	166.00 X
15	1	Rear boot top lock	\$	NU	62.00 ✓
16	1	Rear boot lower lock catch	\$	R	26.00 X
17	1	Rear tailgate weatherstrip	\$	NU/D11	134.00 50Jm
18	2	Taillamp	\$	Sm	750.00 X
19	1	Rear end panel	\$		452.00 ?
20	1	Rear end panel top garnish	\$	NU	145.00 ✓
21	1	Rear spare tyre top board	\$		141.00 ?
22	1	Rear lower exhaust silencer	\$		442.00 ?
23	3	Rear lower exhaust silencer mounting	\$	Sm	114.00 X
			\$		4,637.20
Less 10%			\$		463.72
Total :			\$		4,173.48

Special Nett Items

24	1	Rear boot "C&C" emblem	\$	NU	35.00 ✓
25	1	Rear number plate	\$	MIS	45.00 ✓
26	1 set	Rear end panel sealant	\$		50.00 ?
27	1 set	Reverse sensors	\$	NU	250.00 200Jm
Total :			\$		380.00

Labour

1	Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$	1,200.00	7001
2	To putty and spray Spray Paintings charges.	\$	1,200.00	8001
3	To check wirings and lightings.	\$	40.00	201
4	To remove, refix reverse sensors.	\$	80.00	501
5	To remove, refit boot lid fittings.	\$	80.00	501

6	To remove, refit rear exhaust silencer.	\$	80.00	<i>602</i>
7	To supply and apply anti rust treatment	\$	80.00	<i>601</i>
	Total :	\$	<u>2,760.00</u>	

Total Parts and Labour : \$ 7,313.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Mei Kwan (LKKAuto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 16 August, 2018 2:29 PM
To: Mei Kwan (LKKAuto)
Cc: Poh Kin (LKKAuto); Hsiao Tong (LKKAuto); Admin A
Subject: RE: Direct Settlement - Accident Involving GBC7014A (OI : CAI - TBA) and SLG1582B (TP : LKK REF - CC6/CTI18014493/Kfa3) on 06/08/2018 / our ref: SNM18D03836C02 insured report.PDF

Attachments:

Follow Up Flag: Follow up
Flag Status: Completed

Categories: HMK

Dear Mei Kwan,

Pls find Insured report.

As Bola still apply as there is only 1 malaysian vehicle, pls redirect the claim to Malaysian vehicle JLR8974.

Thank you.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Thursday, 16 August, 2018 8:59 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Lucas Lee <lucas.lee@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Poh Kin (LKKAuto) <pohkin@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Direct Settlement - Accident Involving GBC7014A (OI : CAI - TBA) and SLG1582B (TP : LKK REF - CC6/CTI18014493/Kfa3) on 06/08/2018

WITHOUT PREJUDICE

Dear Sir /Madam,

We refer to the above matter.

Poh Kin (LKKAuto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 23 August 2018 4:30 PM
To: Mei Kwan (LKKAuto)
Cc: Poh Kin (LKKAuto); Hsiao Tong (LKKAuto); Admin A
Subject: RE: Direct Settlement - Accident Involving GBC7014A (OI : CAI - TBA) and SLG1582B (TP : LKK REF - CC6/CTI18014493/Kfa3) on 06/08/2018 / our ref: SNM18D03836C02

Dear Mei Kwan,

Have done check with my colleague.

We confirm Bola does not apply as Malaysian vehicle is in the middle.

Sorry for the inconvenience and misunderstanding.

Thank you.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Chong Boon Sen
Sent: Monday, 20 August, 2018 3:36 PM
To: 'Mei Kwan (LKKAuto)' <Meikwan@lkkauto.com>
Cc: 'Poh Kin (LKKAuto)' <pohkin@lkkauto.com>; 'Hsiao Tong (LKKAuto)' <chewht@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving GBC7014A (OI : CAI - TBA) and SLG1582B (TP : LKK REF - CC6/CTI18014493/Kfa3) on 06/08/2018 / our ref: SNM18D03836C02

Dear Mei Kwan,

Have done a check on Bola exclusion.

Bola applies as circumstance is not under Bola exclusion.

Poh Kin (LKKAuto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 20 August 2018 3:36 PM
To: Mei Kwan (LKKAuto)
Cc: Poh Kin (LKKAuto); Hsiao Tong (LKKAuto); Admin A
Subject: RE: Direct Settlement - Accident Involving GBC7014A (OI : CAI - TBA) and SLG1582B (TP : LKK REF - CC6/CTI18014493/Kfa3) on 06/08/2018 / our ref: SNM18D03836C02

Dear Mei Kwan,

Have done a check on Bola exclusion.

Bola applies as circumstance is not under Bola exclusion.

We await your further update.

Thank you.

Regards,

Chong Boon Sen 
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Chong Boon Sen
Sent: Thursday, 16 August, 2018 2:29 PM
To: 'Mei Kwan (LKKAuto)' <Meikwan@lkkauto.com>
Cc: Poh Kin (LKKAuto) <pohkin@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving GBC7014A (OI : CAI - TBA) and SLG1582B (TP : LKK REF - CC6/CTI18014493/Kfa3) on 06/08/2018 / our ref: SNM18D03836C02

Dear Mei Kwan,

Pls find Insured report.

As Bola still apply as there is only 1 malaysian vehicle, pls redirect the claim to Malaysian vehicle JLR8974.

Poh Kin (LKKAuto)

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Monday, 24 December 2018 11:59 AM
To: Poh Kin (LKKAuto); Admin A
Cc: Chong Boon Sen; Alfred Toh; Chee So Chow; Hsiao Tong (LKKAuto)
Subject: RE: <Seek Mandate> Direct Settlement - Accident Involving GBH 7281T (OI: SNM18D03836C02/1) and SH 9329B (TP : LKK REF - CTI18014493/Kfa3) on 06/08/2018

LKK REF - CTI18014493/Kfa3
CTI REF - SNM18D03836C02/1 (GBH7281T)

Dear Poh Kin

We refer to your email of 18 December 2018 pertaining to the above matter.

Please proceed to resolve the property damage claim at \$4,807.45.

We await your payment advice to enable Boon Sen to act accordingly.

Best Regards

Alfred Toh
Senior Executive
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: +65 6389 6183
FAX: +65 6224 7478/6224 7175
Email: claimsdept@sg.cntaiping.com
alfred.toh@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Poh Kin (LKKAuto) [mailto:pohkin@lkkauto.com]
Sent: Tuesday, December 18, 2018 11:12 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Admin A <admin-a@lkkauto.com>
Subject: <Seek Mandate> Direct Settlement - Accident Involving GBH 7281T (OI: SNM18D03836C02/1) and SH

Poh Kin (LKKAuto)

From: Poh Kin (LKKAuto)
Sent: Tuesday, 18 December 2018 11:12 AM
To: claimsdept@sg.cntaiping.com
Cc: Chong Boon Sen; 'alfred.toh@sg.cntaiping.com'; Admin A
Subject: <Seek Mandate> Direct Settlement - Accident Involving GBH 7281T (OI : CTI - SNM18D03836C02) and SH 9329B (TP : LKK REF - CTI18014493/Kfa3) on 06/08/2018

Attachments: LKK ADJUSTMENT REPORT.pdf; LKK INSPECTION REPORT.pdf; LKK RESURVEY PHOTO.pdf; LKK RESURVEY PHOTO-AFTER REPAIR.pdf; LKK SURVEY PHOTO.pdf; TP_LOD SLG 1582B.pdf

Importance: High

WITHOUT PREJUDICE

Our Ref: CC6/CTI18014493/Kfa3
Your Ref: SNM18D03836C02

Dear Sir/madam,

ROAD TRAFFIC ACCIDENT INVOLVING NOS. GBC 7014A (OI), SLG 1582B (TP) AND OTHERS ALONG BKE TOWARDS PIE ON 06/08/2018

We refer to the above matter.

Liability: The said chain collision involved 3 vehicles whereby TP was the **first** vehicle and our insured was the **last** vehicle. Bola does not apply on this matter as Malaysia vehicle is in the middle.

We did clarify with Insured (PIC/ Ms Regina) the nature of the accident and They agree to settle and aware that NCD (if any) would be affected.

We seek your approval to offer Third Party repairer "**Guan Motor Works**" at **\$ 4,807.49(all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair	\$ 7,313.48	\$ 3,900.00
2. Loss of Rental	\$ 1,080.00 (\$120.00 x 9 days)	\$ 900.00 (\$100.00 x 9 days)
3. LTA search fee	\$ 7.49	\$ 7.49
Total	\$ 8,400.97	\$ 4,807.49

****6 days recommendation for repair + 2 days PRI + 1 day weekend = 9 days**

Enclosed here with all the relevant documents for your perusal.

For your approval please.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18014493/Kfa3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 26-02-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 7014A	Veh. Inspected	SLG 1582B
Policy No.	DMCVSN1328231805	Coverage (\$)	0.00
Claim No.	SNM18D03836C02/1	Excess (\$)	0.00
Assign From		Assign Date	08/08/2018

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI LANCER (A)	c.c	1590
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JMYSRCY1AGU005895	Colour	METALLIC GREY
Odometer	43614	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	YOKOHAMA	8 mm
L/H Front Tyre	205/60 R16	YOKOHAMA	8 mm
R/H Rear Tyre	205/60 R16	YOKOHAMA	8 mm
L/H Rear Tyre	205/60 R16	YOKOHAMA	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/08/2018	Inspection Date	08/08/2018
Survey held at	GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 1582B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BENT	739.00	739.00
2	REAR BUMPER REFLECTOR	N/S CRACKED	68.00	34.00
1	REAR BUMPER TOW COVER	DENTED	18.00	18.00
1	SET REAR BUMPER CLIPS	NECESSARY	30.00	30.00
2	REAR BUMPER SIDE RETAINER	DISTORTED	48.00	48.00
1	REAR BUMPER INNER TOP BEAM	BENT	72.00	72.00
1	REAR BUMPER INNER REINFORCEMENT	BUCKLED	184.00	184.00
2	REAR NUMBER PLATE LAMP	CRACKED	96.00	96.00
1	REAR BOOT LID	BENT	778.20	778.20
1	REAR BOOT CENTRE 'MITSUBISHI' LOGO	NECESSARY	48.00	48.00
1	REAR BOOT 'LANCER' EMBLEM	NECESSARY	40.00	40.00
1	REAR BOOT 'EX' EMBLEM	NECESSARY	34.00	34.00
1	SET REAR BOOT INNER TRIM CLIPS	NECESSARY	50.00	50.00
2	REAR BOOT LAMP	SERVICEABLE	166.00	-
1	REAR BOOT TOP LOCK	DENTED	62.00	62.00
1	REAR BOOT LOWER LOCK CATCH	TO REPAIR SEE LABOUR	26.00	-
2	TAILLAMP	SERVICEABLE	750.00	-
1	REAR END PANEL	BENT	452.00	452.00
1	REAR END PANEL TOP GARNISH	DENTED	145.00	145.00
1	REAR SPARE TYRE TOP BOARD	CRACKED	141.00	141.00
3	REAR LOWER EXHAUST SILENCER MOUNTING	SERVICEABLE	114.00	-
	LESS 10% DISCOUNT		-406.12	-297.12
			3,655.08	2,674.08
1	REAR TAILGATE WEATHERSTRIP (50%) (SN)	DENTED / DISTORTED	134.00	67.00
1	REAR LOWER EXHAUST SILENCER (LOCAL REPAIR) (SN)	DENTED	442.00	120.00
	LESS 10% DISCOUNT		-57.60	-
			518.40	187.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BOOT 'C&C' EMBLEM (SN)	NECESSARY	35.00	35.00
1	REAR NUMBER PLATE (SN)	MISSING	45.00	45.00
1	SET REAR END PANEL SEALANT (SN)	NECESSARY	50.00	30.00
1	SET REVERSE SENSORS (SN)	DENTED	250.00	200.00
			380.00	310.00
	<u>LABOUR</u>			
	LABOUR CHARGES FOR REMOVE/REFIT ,PANEL BEATING ,CUTTING WELDING AND REPLACEMENT OF DAMAGES INCLUSIVE OF THE REPAIR OF REAR BOOT LOWER LOCK CATCH .		1,200.00	700.00
	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES.		1,200.00	800.00
	TO CHECK WIRING AND LIGHTINGS.		40.00	20.00
	TO REMOVE ,REFIX REVERSE SENSORS.		80.00	50.00
	TO REMOVE,REFIT BOOT LID FITTINGS.		80.00	50.00
	TO REMOVE,REFIT REAR EXHAUST SILENCER.		80.00	60.00
	TO SUPPLY AND APPLY ANTI RUST TREATMENT.		80.00	60.00
			2,760.00	1,740.00
GRAND TOTAL			7,313.48	4,911.08
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,900.00

Report Ref No. CC6/CTI18014493/Kfa3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.