

INS. CASE OWNER:

NORRISH

CC 6, AUG 180

14494, U has 3/4

LKK:
IDAC:

ASSIGNMENT

Mupens

DOE:

10/18/18

Date / Time:

10/18/18

Registered in Merimen:

10/18/18

Pre-assign / CCU / FTE

SLW 7885D



Insured Vehicle No.:

Claim No.:

007009677A 6G

Name of Insured:

TUNG KEBUTY

Policy No.:

180002002

Insured Tel No.:

HP:

Make / Model:

Mit. offrage

Excess Sec II :SS

D.O.A.:

218/2018

Place of Accident:

JUN ISHAK

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

UM 60H WPK

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

90033626

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

FBN 584 J



INSRS:

WSP:

Tel:

Liability:

RMKS:

6774

11/18/18



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time:

10/18

WPK

FBN 584 J - X

SLW 7885D - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Of:

After call ltr to Of:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to Of:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

10/18/18 @ 10:18 AM

REPORT TO OJD, CONTINUED ACCIDENT

DETAILS & CROSSING JUNCTION OF ROAD

LINK. INFORMED TP CERTAIN & LIABILITY.

OI WAS HIS FRIEND. AGREED TO SETTLE

IN AMOUNT NOT KNOWN.

- BUILT LIABILITY CLERK

- MINORISED.

- ORIGINAL TP LOW IN

- SEND ACCEPTANCE BUILT TO TP.

- ALL DONE IN ORDER.

- TO CLOSE.

RECEIVED 16 NOV 2018

PRELIMINARY ADVICE

Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$ 3,018.29

(5 days)

Reduction:

15 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

4a

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 3,229.50

COLD FROM WINDY ROAD

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$ 100.00

(520 x 5 days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

S\$ 2.00

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

Total:

S\$ 3,331.50

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 3,331.50

Name 1:

BAN HOCK HIN CO. PTE LTD

Payee 2 (Not if N/A):

S\$

Name 2:

Payee 3 (Not if N/A):

S\$

Name 3:

ASS REC BY: Marcus

REF:

Acc /

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 7BN 584J

at Workshop m/c: BHM

of: _____

Insured: S L W 7885D

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 1623M 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 7BN 584J Yr Reg: 7 18

Type: M/Cat / M/Cycle / Bus / Van / Lorry / Taxi / Private Motor /

Truck / Trailer or

Make: Yamaha NMAX 155 155

Colour: white / she A/C: Insured / Std / Nil / NA

Sp Reading: 148 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: MH356431000005952

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or ok

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110-70-13

R: 130-70-15

BS / JUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 89

Rear: 89

R/Bal: _____ mm

R/Bal: _____ mm

L/Bal: _____ mm

L/Bal: _____ mm

D.O.A: 2/8/18

D.O.I: 10/8/18

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Dr. 015 124

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 784

P/P 43,018.30

(RWD: 4570.70 / 15%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

5 - RS 3)

Phone

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. 187000280K
MOTORCYCLE ACCESSORIES / SERVICE CENTRE
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

QUOTATION

Customer

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

NO. : 32857

- Rev. 1

DATE : 06/08/2018
CLAIM NO. : 11172
POLICY NO. :
FROM : RAYMOND

VEHICLE NO : FBN0584J
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY P/N: 29561	REPLACE	1.00	\$360.00	360.00
2	AXLE FRONT WHEEL P/N: 59126	REPLACE	1.00	\$12.00	12.00
3	BEARING P/N: 58460	REPLACE	2.00	\$9.00	18.00
4	BEARING STEERING CONE LOWER P/N: 58120	REPLACE	1.00	\$12.00	12.00
5	BEARING STEERING CONE UPPER P/N: 36392	REPLACE	1.00	\$28.00	28.00
6	BELLY PAN P/N: 58094	REPLACE	1.00	\$19.00	19.00
7	BOARD FOOTREST LH	REPLACE	1.00	\$24.00	24.00
8	BOARD FOOTREST RH	REPLACE	1.00	\$24.00	24.00
9	BRACKET BAR HANDLE P/N: 58191	REPLACE	1.00	\$38.00	38.00
10	BRACKET MASTER CYL RH	REPLACE	1.00	\$9.00	9.00
11	COVER BALL RACE 2	REPLACE	1.00	\$3.00	3.00
12	COVER FRONT	REPLACE	1.00	\$44.00	44.00
13	COVER FRONT LOWER (WHITE) P/N: 58106	REPLACE	1.00	\$16.00	16.00
14	COVER SIDE CENTRE LH (WHITE) P/N: 58097	REPLACE	1.00	\$42.00	42.00



S/N	Description	Action	Qty	Unit Price	one	Amount
15	COVER SIDE CENTRE RH (WHITE) P/N: 58117	REPLACE	1.00	\$42.00	one	42.00 ✓
16	COWLING BODY RH	REPLACE	1.00	\$38.00	one	38.00 ✓
17	COWLING FRONT LH (WHITE) P/N: 58179	REPLACE	1.00	\$32.00	one	32.00 ✓
18	COWLING FRONT RH (WHITE) P/N: 58081	REPLACE	1.00	\$21.00	one	21.00 ✓
19	EMBLEM (YAMAHA) LOGO P/N: 57069	REPLACE	2.00	\$10.00	one	20.00 ✓
20	FENDER INNER	REPLACE	1.00	\$52.00	one	52.00 ✓
21	FILTER AIR P/N: 58151	REPLACE	1.00	\$28.00	one	28.00 ✓
22	FORK FRONT ASSY	REPLACE	1.00	\$554.00	one	554.00 ✓
23	HEADLAMP ASSY P/N: 58174	REPLACE	1.00	\$299.00	one	299.00 ✓
24	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING PARTS QUOTED	Supply/Install	1.00	\$400.00	300	400.00 ✓
25	LAMP SIGNAL FRONT LH	REPLACE	1.00	\$34.00	one	34.00 ✓
26	LAMP SIGNAL FRONT RH	REPLACE	1.00	\$34.00	one	34.00 ✓
27	MIRROR RH P/N: 58187	REPLACE	1.00	\$35.00	one	35.00 ✓
28	MUDGUARD FRONT (WHITE) P/N: 58087	REPLACE	1.00	\$49.00	one	49.00 ✓
29	PANEL 1	REPLACE	1.00	\$19.00	one	19.00 ✓
30	PLATE DISC BRAKE FRONT P/N: 58182	REPLACE	1.00	\$70.00	one	70.00 ✓
31	POWDER COAT BRACKET REAR BOX P/N: 40560	REPLACE	1.00	\$140.00	one	140.00 X
32	PROTECTOR EXHAUST P/N: 58086	REPLACE	1.00	\$38.00	one	38.00 ✓
33	RACE BALL 1 P/N: 55220	REPLACE	1.00	\$12.00	one	12.00 ✓
34	RACE BALL 2 P/N: 55216	REPLACE	1.00	\$12.00	one	12.00 ✓
35	RETAINER BALL BEARING P/N: 55215	REPLACE	1.00	\$12.00	one	12.00 ✓



S/N	Description	Action	Qty	Unit Price	Amount
36	RIM SPORT FRONT P/N 58148	REPLACE	1.00	\$238.00	238.00
37	SPACER WHEEL AXLE FRONT	REPLACE	1.00	\$6.00	6.00
38	SPRAY PAINT FIBER BOX	Re Spray	1.00	\$250.00	250.00
39	STICKER (SINGPOST) BOX REAR 2018 P/N 58517	REPLACE	1.00	\$180.00	180.00
40	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER) STD P/N 45833		2.00	\$35.00	70.00
41	VALVE RIM P/N 27762	REPLACE	1.00	\$13.00	13.00
42	WINDSHIELD P/N 58073	REPLACE	1.00	\$56.00	56.00

SUB TOTAL

\$3,503.00

GST @ 7 %

\$245.21

GRAND TOTAL

\$3,748.21

Validity 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

Let Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To replace damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No help/modifications is allowed
- Supplementary works must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

7-2097
100%
1887.30
3018.30





BAN HOCK HIN
Co., Pte Ltd

Co Reg No: 19700208K

MOTORCYCLE ACCESSORIES / SERVICE CENTRE
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

QUOTATION

Customer :

NO. : 32857

- Rev. 2

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

DATE : 06/08/2018
CLAIM NO. : 11172
POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBN0584J
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY P/N: 29561	REPLACE	1.00	\$280.00	280.00
2	AXLE FRONT WHEEL P/N: 59126	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
3	BEARING P/N: 56460	REPLACE	2.00	\$9.00 Disc %: 10.00	16.20
4	BEARING STEERING CONE LOWER P/N: 58120	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
5	BEARING STEERING CONE UPPER P/N: 36392	REPLACE	1.00	\$28.00 Disc %: 10.00	25.20
6	BELLY PAN P/N: 58094	REPLACE	1.00	\$19.00 Disc %: 10.00	17.10
7	BOARD FOOTREST LH	REPLACE	1.00	\$24.00 Disc %: 10.00	21.60
8	BOARD FOOTREST RH	REPLACE	1.00	\$24.00 Disc %: 10.00	21.60
9	BRACKET BAR HANDLE P/N: 58191	REPLACE	1.00	\$38.00 Disc %: 10.00	34.20
10	COVER BALL RACE 2	REPLACE	1.00	\$3.00 Disc %: 10.00	2.70
11	COVER FRONT	REPLACE	1.00	\$44.00 Disc %: 10.00	39.60
12	COVER FRONT LOWER (WHITE) P/N: 58106	REPLACE	1.00	\$16.00 Disc %: 10.00	14.40
13	COVER SIDE CENTRE LH (WHITE) P/N: 58097	REPLACE	1.00	\$42.00 Disc %: 10.00	37.80
14	COVER SIDE CENTRE RH (WHITE) P/N: 58117	REPLACE	1.00	\$42.00 Disc %: 10.00	37.80



S/N	Description	Action	Qty	Unit Price	Amount
15	EMBLEM (YAMAHA) LOGO P/N: 57069	REPLACE	2.00	\$10.00 Disc %: 10.00	18.00
16	FENDER INNER	REPLACE	1.00	\$52.00 Disc %: 10.00	46.80
17	FILTER AIR P/N: 58151	REPLACE	1.00	\$28.00 Disc %: 10.00	25.20
18	FORK FRONT ASSY	REPLACE	1.00	\$654.00 Disc %: 10.00	588.60
19	HEADLAMP ASSY P/N: 58174	REPLACE	1.00	\$299.00 Disc %: 10.00	269.10
20	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING PARTS QUOTED.	Supply/Install	1.00	\$300.00	300.00
21	LAMP SIGNAL FRONT LH	REPLACE	1.00	\$34.00 Disc %: 10.00	30.60
22	LAMP SIGNAL FRONT RH	REPLACE	1.00	\$34.00 Disc %: 10.00	30.60
23	MIRROR RH P/N: 58187	REPLACE	1.00	\$35.00 Disc %: 10.00	31.50
24	MUDGUARD FRONT (WHITE) P/N: 58087	REPLACE	1.00	\$49.00 Disc %: 10.00	44.10
25	PROTECTOR EXHAUST P/N: 58086	REPLACE	1.00	\$38.00 Disc %: 10.00	34.20
26	RACE BALL 1 P/N: 55220	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
27	RACE BALL 2 P/N: 55216	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
28	RETAINER BALL BEARING P/N: 55215	REPLACE	1.00	\$12.00 Disc %: 10.00	10.80
29	RIM SPORT FRONT P/N: 58148	REPLACE	1.00	\$238.00 Disc %: 10.00	214.20
30	SPRAY PAINT FIBER BOX	Spray	1.00	\$250.00	250.00
31	STICKER (SINGPOST) BOX REAR 2018 P/N: 58517	REPLACE	1.00	\$180.00	180.00
32	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER) STD P/N: 45833		1.00	\$35.00	35.00
33	VALVE RIM P/N: 27762	REPLACE	1.00	\$13.00 Disc %: 10.00	11.70
34	WINDSHIELD P/N: 58073	REPLACE	1.00	\$56.00 Disc %: 10.00	50.40
35	BRACKET MASTER CYLINDER RH P/N: 60166	Replace	1.00	\$9.00 Disc %: 10.00	8.10



S/N	Description	Action	Qty	Unit Price	Amount
36	COWLING BODY RH P/N: 59594	Replace	1.00	\$38.00 Disc %: 10.00	34.20
37	COWLING FRONT LH (WHITE) P/N: 58179	Replace	1.00	\$32.00 Disc %: 10.00	28.80
38	COWLING FRONT RH (WHITE) P/N: 58081	Replace	1.00	\$21.00 Disc %: 10.00	18.90
39	PANEL 1 P/N: 59584	Replace	1.00	\$19.00 Disc %: 10.00	17.10
40	PLATE DISC BRAKE FRONT P/N: 58182	Replace	1.00	\$70.00 Disc %: 10.00	63.00
41	TYRE 110/70-13 DUNLOP F11 P/N: 57991	Replace <i>POD</i>	1.00	\$86.00 <i>Cur</i>	86.00

SUB TOTAL

\$3,018.30

GST @ 7 %

\$211.28

GRAND TOTAL

\$3,229.58

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

Acknowledge & Accepted By

BAN HOCK HIN CO PTE LTD



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.





BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 19700288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 32857

- Rev. 1

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

DATE : 06/08/2018

CLAIM NO. : 11172

POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBN0584J
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY P/N: 29561	REPLACE	1.00	\$360.00	360.00
2	AXLE FRONT WHEEL P/N: 59126	REPLACE	1.00	\$12.00	12.00
3	BEARING P/N: 56460	REPLACE	2.00	\$9.00	18.00
4	BEARING STEERING CONE LOWER P/N: 58120	REPLACE	1.00	\$12.00	12.00
5	BEARING STEERING CONE UPPER P/N: 36392	REPLACE	1.00	\$28.00	28.00
6	BELLY PAN P/N: 58094	REPLACE	1.00	\$19.00	19.00
7	BOARD FOOTREST LH	REPLACE	1.00	\$24.00	24.00
8	BOARD FOOTREST RH	REPLACE	1.00	\$24.00	24.00
9	BRACKET BAR HANDLE P/N: 58191	REPLACE	1.00	\$38.00	38.00
10	BRACKET MASTER CYL RH	REPLACE	1.00	\$9.00	9.00
11	COVER BALL RACE 2	REPLACE	1.00	\$3.00	3.00
12	COVER FRONT	REPLACE	1.00	\$44.00	44.00
13	COVER FRONT LOWER (WHITE) P/N: 58106	REPLACE	1.00	\$16.00	16.00
14	COVER SIDE CENTRE LH (WHITE) P/N: 58097	REPLACE	1.00	\$42.00	42.00



S/N	Description	Action	Qty	Unit Price		Amount
15	COVER SIDE CENTRE RH (WHITE) P/N: 58117	REPLACE	1.00	\$42.00	?	42.00
16	COWLING BODY RH	REPLACE	1.00	\$38.00	?	38.00
17	COWLING FRONT LH (WHITE) P/N: 58179	REPLACE	1.00	\$32.00	?	32.00
18	COWLING FRONT RH (WHITE) P/N: 58081	REPLACE	1.00	\$21.00	?	21.00
19	EMBLEM (YAMAHA) LOGO P/N: 57069	REPLACE	2.00	\$10.00	see	20.00
20	FENDER INNER	REPLACE	1.00	\$52.00	?	52.00
21	FILTER AIR P/N: 58151	REPLACE	1.00	\$28.00	?	28.00
22	FORK FRONT ASSY	REPLACE	1.00	\$654.00	?	654.00
23	HEADLAMP ASSY P/N: 58174	REPLACE	1.00	\$299.00	see	299.00
24	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING PARTS QUOTED.	Supply/Install	1.00	\$400.00	300	400.00
25	LAMP SIGNAL FRONT LH	REPLACE	1.00	\$34.00	see	34.00
26	LAMP SIGNAL FRONT RH	REPLACE	1.00	\$34.00	see	34.00
27	MIRROR RH P/N: 58187	REPLACE	1.00	\$35.00	Bro/ny	35.00
28	MUDGUARD FRONT (WHITE) P/N: 58087	REPLACE	1.00	\$49.00	cm	49.00
29	PANEL 1	REPLACE	1.00	\$19.00	?	19.00
30	PLATE DISC BRAKE FRONT P/N: 58182	REPLACE	1.00	\$70.00	11	70.00 X
31	POWDER COAT BRACKET REAR BOX P/N: 40560	REPLACE	1.00	\$140.00	n	140.00 X
32	PROTECTOR EXHAUST P/N: 58086	REPLACE	1.00	\$38.00	cut	38.00
33	RACE BALL 1 P/N: 55220	REPLACE	1.00	\$12.00	?	12.00
34	RACE BALL 2 P/N: 55216	REPLACE	1.00	\$12.00	?	12.00
35	RETAINER BALL BEARING P/N: 55215	REPLACE	1.00	\$12.00	?	12.00



S/N	Description	Action	Qty	Unit Price	Amount
36	RIM SPORT FRONT P/N: 58148	REPLACE	1.00	\$238.00	238.00
37	SPACER WHEEL AXLE FRONT	REPLACE	1.00	\$6.00	6.00
38	SPRAY PAINT FIBER BOX	<u>Re</u> Spray	1.00	\$250.00	250.00
39	STICKER (SINGPOST) BOX REAR 2018 P/N: 58517	REPLACE	1.00	\$180.00	180.00
40	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER) STD P/N: 45833		2.00	\$35.00	70.00
41	VALVE RIM P/N: 27762	REPLACE	1.00	\$13.00	13.00
42	WINDSHIELD P/N: 58073	REPLACE	1.00	\$56.00	56.00
SUB TOTAL					\$3,503.00
GST @ 7 %					\$245.21
GRAND TOTAL					\$3,748.21

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 1623M

Vehicle Details

Vehicle No.: FBN584J

Vehicle to be Exported: No

Intended De-registration Date: 10 Aug 2018

Vehicle Make: YAMAHA

Vehicle Model: NMAX155 ABS

Primary Colour: White

Manufacturing Year: 2018

Engine No.: G3H6E0007700

Chassis No.: MH3SG431000005952

Maximum Power Output: -

Open Market Value: \$2,350.00

Original Registration Date: 03 Jul 2018

First Registration Date: 03 Jul 2018

Transfer Count: 0

Actual ARF Paid: \$353.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 02 Jul 2028

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$7,602.00

COE Rebate Amount: \$7,521.00

Total Rebate Amount: \$7,521.00

The information contained herein is correct as at 10 Aug 2018

OK

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBN584J		
Vehicle Type :	P01 - Passenger Scooter		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	YAMAHA		
Vehicle Model :	NMAX155 ABS		
Chassis No. :	MH35G431000005952		
Propellant :	Petrol		
Engine No. :	G3H6E0007700		
Engine Capacity :	155 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	295 kg		
Unladen Weight :	128 kg		
Year Of Manufacture :	2018		
Original Registration Date :	03 Jul 2018		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$7,602.00		
COE Expiry Date :	02 Jul 2028		
Road Tax Expiry Date :	02 Jul 2019		
Inspection Due Date :	02 Jul 2021		
Intended Transfer Date :	09 Aug 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

15 AUGUST 2018

TREND REALTY
BLOCK 145 JALAN BUKIT MERAH
#08-1098
SINGAPORE 1601145

By Post & By Email

Dear Sir/Madam,

OUR REF : CC6/AIG18014494/Uha3
YOUR REF : SLW 7885D
ACCIDENT INVOLVING SLW 7885D AND FBN 584J ALONG JALAN ISHAK ON
02.08.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of FBN 584J against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle FBN 584J. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vic Alpeh
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Daisylin65@gmail.com
(Email)

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Wednesday, 15 August, 2018 10:31 AM
To: Daisylim65@gmail.com
Cc: Admin A; Vic (LKKAUTO)
Subject: YOUR REF: SLW 7885D_ACCIDENT INVOLVING SLW 7885D AND FBN 584J ALONG JALAN ISHAK ON 02.08.2018



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

15 AUGUST 2018

TREND REALTY
BLOCK 145 JALAN BUKIT MERAH
#08-1098
SINGAPORE 1601145

By Post & By Email

Dear Sir/Madam,

OUR REF : CC6/AIG18014494/Uha3
YOUR REF : SLW 7885D
ACCIDENT INVOLVING SLW 7885D AND FBN 584J ALONG JALAN ISHAK ON 02.08.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of FBN 584J against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle FBN 584J. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, Singapore Post Ltd ("the third party claimant") of 10 Eunos Road 2
#05-37 Singapore Post Centre (Singapore) (address), owner of FBW584J (vehicle no.) hereby
 authorize Ban Hock Hin Co. Pte Ltd ("the workshop") to act for
 me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my
 vehicle no. FBW584J that was damaged pursuant to the accident which occurred on 01/08/2018
 (date) along Junction of Jalan Ishak & Lor Mawikan (location) involving vehicle
 no/s FBW584J & SLW785D ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
 and the workshop is further authorized to receive payment further to settlement of my claim with
 payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
 prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
 vehicle/s is concerned.

Dated this 14th (day) of November (month) 2018 (year)



Signed by "the third party claimant"




Signed by "the workshop"

Singapore Post Limited
(Reg. No. 199201623M)

RELEASE VOUCHER **(AIG Express Third Party Claim)**

"We/I, Ram Hock Hin Co. Pte Ltd 6 Defu Lane 4 S(539410)
 ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of
 American Home Assurance Company Singapore LKK Auto Consultants Pte Ltd
 (name of surveyor) with respect to the amount claimed for \$3,229.58 (repair costs), \$100.00
 (loss of use/rental), \$2.00 (search fees) for vehicle no. FBN584J that was damaged
 pursuant to the accident which occurred on 02/08/2018 (date) along Junction of Jalan Ishak
x Lor Marican (location)
 involving vehicles no/s. FBN584J x SLW788D. This is pursuant to the inspection conducted
 on 10/08/18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Singapore Post Ltd
 ("the third party claimant") of vehicle no. FBN584J to make the claim as set out in the above
 paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit.
 We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify American Home Assurance for all damages, loss and/or
 expense that they will or have already incurred in the event that "the third party claimant" after the above
 said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to
 costs of repairs and/or rental and/or loss of use pursuant to the damage to FBN584J (vehicle no.)
 as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third
 party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice
 and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive
 jurisdiction over any dispute arising out of the same.

Dated this 14th (day) of November (month) 2018 (year)



Signed by appointed surveyor

[Signature]



Signed by "the workshop" (with chop)



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

TAX INVOICE

GST Reg No. : M2-0010542-7

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Invoice No. : DLCR40099254-111172
Invoice Date : 26/10/2018
Payment Due Date : 25/11/2018

CLAIM NO. : 11172
POLICY NO. :
VEHICLE NO. : FBN0584J
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT BODY	REPLACE	1	\$280.00	\$280.00
2	AXLE FRONT WHEEL	REPLACE	1	\$12.00	\$10.80
				Disc %: 10%	
3	BEARING	REPLACE	2	\$9.00	\$16.20
				Disc %: 10%	
4	BEARING STEERING CONE LOWER	REPLACE	1	\$12.00	\$10.80
				Disc %: 10%	
5	BEARING STEERING CONE UPPER	REPLACE	1	\$28.00	\$25.20
				Disc %: 10%	
6	BELLY PAN	REPLACE	1	\$19.00	\$17.10
				Disc %: 10%	
7	BOARD FOOTREST LH	REPLACE	1	\$24.00	\$21.60
				Disc %: 10%	
8	BOARD FOOTREST RH	REPLACE	1	\$24.00	\$21.60
				Disc %: 10%	
9	BRACKET BAR HANDLE	REPLACE	1	\$38.00	\$34.20
				Disc %: 10%	
10	COVER BALL RACE 2	REPLACE	1	\$3.00	\$2.70
				Disc %: 10%	
11	COVER FRONT	REPLACE	1	\$44.00	\$39.60
				Disc %: 10%	
12	COVER FRONT LOWER (WHITE)	REPLACE	1	\$16.00	\$14.40
				Disc %: 10%	
13	COVER SIDE CENTRE LH (WHITE)	REPLACE	1	\$42.00	\$37.80
				Disc %: 10%	
14	COVER SIDE CENTRE RH (WHITE)	REPLACE	1	\$42.00	\$37.80
				Disc %: 10%	
15	EMBLEM (YAMAHA) LOGO	REPLACE	2	\$10.00	\$18.00
				Disc %: 10%	
16	FENDER INNER	REPLACE	1	\$52.00	\$46.80
				Disc %: 10%	
17	FILTER AIR	REPLACE	1	\$28.00	\$25.20
				Disc %: 10%	



S/N	Description	Action	Qty	Unit Price	Amount
18	FORK FRONT ASSY	REPLACE	1	\$654.00	\$588.60
				Disc %: 10%	
19	HEADLAMP ASSY	REPLACE	1	\$299.00	\$269.10
				Disc %: 10%	
20	LAMP SIGNAL FRONT LH	REPLACE	1	\$34.00	\$30.60
				Disc %: 10%	
21	LAMP SIGNAL FRONT RH	REPLACE	1	\$34.00	\$30.60
				Disc %: 10%	
22	MIRROR RH	REPLACE	1	\$35.00	\$31.50
				Disc %: 10%	
23	MUDGUARD FRONT (WHITE)	REPLACE	1	\$49.00	\$44.10
				Disc %: 10%	
24	PROTECTOR EXHAUST	REPLACE	1	\$38.00	\$34.20
				Disc %: 10%	
25	RACE BALL 1	REPLACE	1	\$12.00	\$10.80
				Disc %: 10%	
26	RACE BALL 2	REPLACE	1	\$12.00	\$10.80
				Disc %: 10%	
27	RETAINER BALL BEARING	REPLACE	1	\$12.00	\$10.80
				Disc %: 10%	
28	RIM SPORT FRONT	REPLACE	1	\$238.00	\$214.20
				Disc %: 10%	
29	STICKER (SINGPOST) BOX REAR 2018	REPLACE	1	\$180.00	\$180.00
30	VALVE RIM	REPLACE	1	\$13.00	\$11.70
				Disc %: 10%	
31	WINDSHIELD	REPLACE	1	\$56.00	\$50.40
				Disc %: 10%	
32	SPRAY PAINT FIBER BOX	Spray	1	\$250.00	\$250.00
33	LABOUR	Supply/Install	1	\$300.00	\$300.00
34	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER) STD		1	\$35.00	\$35.00
35	PLATE DISC BRAKE FRONT	Replace	1	\$70.00	\$63.00
				Disc %: 10%	
36	TYRE 110/70-13 DUNLOP F11	Replace	1	\$86.00	\$86.00
37	BRACKET MASTER CYLINDER RH	Replace	1	\$9.00	\$8.10
				Disc %: 10%	
38	COWLING BODY RH	Replace	1	\$38.00	\$34.20
				Disc %: 10%	
39	COWLING FRONT LH (WHITE)	Replace	1	\$32.00	\$28.80
				Disc %: 10%	
40	COWLING FRONT RH (WHITE)	Replace	1	\$21.00	\$18.90
				Disc %: 10%	
41	PANEL 1	Replace	1	\$19.00	\$17.10
				Disc %: 10%	

Signature




<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
		SUB TOTAL			\$3,018.30
		GST @ 7 %			\$211.28
		GRAND TOTAL			<u>\$3,229.58</u>

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



Printed by : RAYMOND





**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-122129
Date of Request: 08/08/2018

Your Ref No: Online Purchase

Ban Hock Hin Co. Pte Ltd
No. 6 Defu Lane 4
Singapore 539410

Dear Sir/Madam,

Enquiry Date 08/08/2018
Enquiry By Tan Chok Lok
TP Vehicle No. SLW7885D
Accident Date 02/08/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLW7885D	AIG Asia Pacific Insurance Pte. Ltd.	01/03/2018-05/12/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-122129
Date of Request: 08/08/2018

Your Ref No: Online Purchase

Ban Hock Hin Co. Pte Ltd
No. 6 Defu Lane 4
Singapore 539410

Dear Sir/Madam,

Enquiry Date 08/08/2018
Enquiry By Tan Chok Lok
TP Vehicle No. SLW7885D
Accident Date 02/08/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Aug 2018 Edit Reg		10 Aug 2018 00:00 Edit Adj Rpt	S\$3,018.30 Edit Estimates	S\$3,018.30 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TREND REALTY, Co. Reg. No.: 53168112B								
Main Claimant:	SINGAPORE POST LIMITED, Co. Reg. No.: 199201623M								
Vehicle Reg. No.:	FBN584J	Date of Loss:	02/08/2018 00:00 - :59 [30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 00768967745G	Policy/Cover Note No.:	1800020025 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLW7885D	Policy No. (Claimant):	-						
		Excess:							
Repairer:	San Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 21/08/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG (13/08/2018): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBN584J (0076896774SG)
[SLW7885D]
TP
SINGAPORE POST LIMITED
Aug 2 2018 12:00AM
[TREND REALTY]
Ban Hock Hin Co. Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Video															1 per page		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	17/08/18 14:11	Video - Accident 01 VIDEO FOOTAGE										1	Load MP4				
Letters/Correspondences															1 per page		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown										1	Edit				
Assessment Reports															1 per page		☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail		Print			
1	13/08/18 10:55	Accident Statement From: SC - Reg. No: SLW7885D, Claimant: TREND REALTY										1	Load HTM				
Photos/Images															3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	25/10/18 18:29	Reinspection Photo										1	Load JPG	☒			
2	25/10/18 18:29	Reinspection Photo										1	Load JPG	☒			
3	25/10/18 18:29	Reinspection Photo										1	Load JPG	☒			
4	25/10/18 18:29	Reinspection Photo										1	Load JPG	☒			
5	25/10/18 18:29	Reinspection Photo										1	Load JPG	☒			
6	25/10/18 18:29	Reinspection Photo										1	Load JPG	☒			
7	25/10/18 18:29	Reinspection Photo										1	Load JPG	☒			
8	25/10/18 18:29	Reinspection Photo										1	Load JPG	☒			
9	25/10/18 18:29	Reinspection Photo										1	Load JPG	☒			
10	25/10/18 18:29	Reinspection Photo										1	Load JPG	☒			
11	25/10/18 18:29	Reinspection Photo										1	Load JPG	☒			
12	25/10/18 18:29	Reinspection Photo										1	Load JPG	☒			
13	25/10/18 18:29	Reinspection Photo										1	Load JPG	☒			
14	25/10/18 18:29	Reinspection Photo										1	Load JPG	☒			
15	25/10/18 18:29	Reinspection Photo										1	Load JPG	☒			
16	25/10/18 18:29	Reinspection Photo										1	Load JPG	☒			
17	25/10/18 18:29	Reinspection Photo										1	Load JPG	☒			
18	25/10/18 18:30	Reinspection Photo										1	Load JPG	☒			
19	25/10/18 18:30	Reinspection Photo										1	Load JPG	☒			
20	25/10/18 18:30	Reinspection Photo										1	Load JPG	☒			
21	25/10/18 18:30	Reinspection Photo										1	Load JPG	☒			
22	25/10/18 18:30	Reinspection Photo										1	Load JPG	☒			
23	25/10/18 18:30	Reinspection Photo										1	Load JPG	☒			
24	25/10/18 18:30	Reinspection Photo										1	Load JPG	☒			
25	25/10/18 18:30	Reinspection Photo										1	Load JPG	☒			
26	25/10/18 18:30	Reinspection Photo										1	Load JPG	☒			

Video			1 per page		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
27	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
28	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
29	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
30	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
31	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
32	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
33	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
34	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
35	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
36	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
37	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
38	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
39	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
40	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
41	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
42	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
43	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
44	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
45	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
46	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
47	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
48	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
49	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
50	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
51	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
52	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
53	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
54	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
55	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
56	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
57	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
58	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
59	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
60	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
61	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
62	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
63	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
64	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
65	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
66	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
67	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
68	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
69	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
70	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
71	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
72	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
73	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
74	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
75	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒
76	25/10/18 18:30	Reinspection Photo	1	Load JPG	☒

Video			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/08/18 21:34	TP ESTIMATE - MARKED	 Load PDF	
2	14/08/18 21:34	TP GIA REPORT	 Load PDF	
3	15/08/18 10:42	EMAIL TO OI	 Load PDF	
4	15/08/18 10:42	LETTER TO OI	 Load PDF	
5	30/11/18 12:25	WORKSHOP INVOICE	 Load PDF	
6	30/11/18 12:25	Release Voucher	 Load PDF	
7	30/11/18 12:25	AUTHORISATION TO ACT FORM	 Load PDF	
8	30/11/18 12:25	GIA SEARCH	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLW7885D (Insd veh)	Model:	YAMAHA NMAX155 155CC
	FBN584J (TP veh)		
Date of Accident:	02/08/2018		

Global Sum Settlement	: [] Yes	: [X] No	
Repair Estimate	: \$		3,840.23
Final Repair Cost	: \$		3,229.58
Loss of Use	: \$		100.00
			5.00 days at \$20.00 per day
Rental (if any)	: \$		0.00
			days
LTA / GIA Search Fee	: \$		2.00
Others:	: \$		0.00
	: \$		
Final Settlement Sum	: \$		3,331.58

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Ban Hock Hin Co. Pte Ltd	: \$	3,331.58
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

30 Nov
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18014494/UHA3Q2

Date: 30/11/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800020025

Claimant Vehicle No : FBN584J

Insured Vehicle No : SLW7885D

Date of Loss: 02/08/2018

Nature of Claim: TP

Claim No: 0076896774SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN584J**

Make & Model: YAMAHA NMAX155, 155cc

Engine No: G3H6E0007700

Reg. Date: 03/07/2018 (Man. Year: 2018)

Chassis No: MH3SG431000005952

Colour: White/Blue

Odometer: 148 km

Engine Capacity: 155 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110-70-13

Rear Tyre Size: 130-70-15

Front Left Side: Dunlop 9 mm

Rear Left Side: Dunlop 9 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,509.00	2,153.30	355.70	14.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,080.00	865.00	215.00	19.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,589.00	3,018.30	570.70	15.90
+ GST 7.00/7.00% (S\$)	251.23	211.28	39.95	15.90
Nett Amount (S\$)	3,840.23	3,229.58	610.65	15.90
+ Loss of Use (5.0 x S\$20.00/day) (S\$)		100.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,331.58		

INSPECTION

Date of Assignment: 10/08/2018

Date Inspected: 10/08/2018 Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)

No. 6 Defu Lane 4

Singapore 539410

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AXLE FRONT WHEEL	Bent	12.00 F	*12.00 FL
2	2		*BEARING	Necessary	18.00 F	*18.00 FL
3	1		*BEARING STEERING CONE LOWER	Necessary	12.00 F	*12.00 FL
4	1		*BEARING STEERING CONE UPPER	Necessary	28.00 F	*28.00 FL
5	1		*BELLY PAN	Cut	19.00 F	*19.00 FL
6	1		*BOARD FOOTREST LH	Deformed	24.00 F	*24.00 FL
7	1		*BOARD FOOTREST RH	Cut	24.00 F	*24.00 FL
8	1		*BRACKET BAR HANDLE	Bent	38.00 F	*38.00 FL
9	1		*BRACKET MASTER CYL RH	Cracked	9.00 F	*9.00 FL
10	1		*COVER BALL RACE 2	Necessary	3.00 F	*3.00 FL
11	1		*COVER FRONT	Cracked	44.00 F	*44.00 FL
12	1		*COVER FRONT LOWER (WHITE)	Broken	16.00 F	*16.00 FL
13	1		*COVER SIDE CENTRE LH (WHITE)	Broken	42.00 F	*42.00 FL
14	1		*COVER SIDE CENTRE RH (WHITE)	Cracked	42.00 F	*42.00 FL
15	1		*COWLING BODY RH	Cracked	38.00 F	*38.00 FL
16	1		*COWLING FRONT LH (WHITE)	Cracked	32.00 F	*32.00 FL
17	1		*COWLING FRONT RH (WHITE)	Cracked	21.00 F	*21.00 FL
18	1		*EMBLEM (YAMAHA) LOGO	Necessary	20.00 F	*20.00 FL
19	1		*FENDER INNER	Cracked	52.00 F	*52.00 FL
20	1		*FILTER AIR	Deformed	28.00 F	*28.00 FL
21	1		*FORK FRONT ASSY	Bent	654.00 F	*654.00 FL
22	1		*HEADLAMP ASSY	Scratched	299.00 F	*299.00 FL
23	1		*LAMP SIGNAL FRONT LH	Scratched	34.00 F	*34.00 FL
24	1		*LAMP SIGNAL FRONT RH	Scratched	34.00 F	*34.00 FL
25	1		*MIRROR RH	Broken / Missing	35.00 F	*35.00 FL
26	1		*MUDGUARD FRONT (WHITE)	Cracked	49.00 F	*49.00 FL
27	1		*PANEL 1	Cracked	19.00 F	*19.00 FL
28	1		*PLATE DISC BRAKE FRONT	Bent	70.00 F	*70.00 FL
29	1		*POWDER COAT BRACKET REAR BOX	Repair	140.00 F	*- FL
30	1		*PROTECTOR EXHAUST	Cut	38.00 F	*38.00 FL
31	1		*RACE BALL 1	Necessary	12.00 F	*12.00 FL
32	1		*RACE BALL 2	Necessary	12.00 F	*12.00 FL
33	1		*RETAINER BALL BEARING	Necessary	12.00 F	*12.00 FL
34	1		*RIM SPORT FRONT	Dented	238.00 F	*238.00 FL
35	1		*SPACER WHEEL AXLE FRONT	Not Necessary	6.00 F	*- FL
36	1		*STICKER (SINGPOST) BOX REAR 2018	Necessary	180.00 FS	*180.00 FS
37	1		*VALVE RIM	Necessary	13.00 F	*13.00 FL
38	1		*WINDSHIELD	Scratched	56.00 F	*56.00 FL
39	1		*TYRE 110/70-13 DUNLOP F11	Cut	86.00 FS	*86.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc

Sub Total (S\$)	2,509.00	2,363.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	209.70
Total Parts (S\$)	2,509.00	2,153.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	ALIGNMENT BODY	New	360.00	280.00
2	LABOUR-FOR DISMANTLING AND ASSEMBLING PARTS QUOTED	New	400.00	300.00
3	SPRAY PAINT FIBER BOX	New	250.00	250.00
4	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER)	New	70.00	35.00
Gross Labour Cost (S\$)			1,080.00	865.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >