

INS. CASE OWNER:

CC 4, 400 180 14502, K #372

LKK:

IDAC:

Surveyor:

KSL

DOI:

ASSIGNMENT

13/8/2018

Date / Time:

10.8.18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJC290Y

Name of Insured:

Max Kimh Long

Insured Tel No.:

HP:

96945578

Excess Sec II :SS

D.O.A:

6/8/18

Claim No.:

18/18/18/VPO5020819

Policy No.:

218 VPO5018660

Make / Model:

7. Esteima

Place of Accident:

Sjatew west link

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJC290Y



INSRS:

WSP:

Tel:

Liability:

RMKS:

Ah Lim



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

11/8
11/8

SJC290Y-X; SJC290Y-X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

18.6.19

Email WSP to Liability Centre.

08.11.19

FILE PASS TO TYPIST TO PREPARE REPORT.

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: KSL

Repair Cost:

46 S\$2,350

(4 days)

Reduction:

43 %

Email

Call

FINAL SETTLEMENT

Date/Time: 13.12.19

Confirm with: Mui Hong

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

15

If NO or B 28, Ass. Lia:

Repair Cost:

01/6/17

S\$2,407.50

OID CHANGED LANE 411 TP.

Loss of Rental (LOR):

S\$ -

(days)

Loss of Use (LOU):

S\$ 330.00

(S\$80

x 4 days)

Loss of Income (LOI):

S\$ -

(\$

x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$2.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$2,129.50

Global Sum S\$:

FINAL PAYMENT

Date/Time: 13.12.19

Confirm with: Mui Hong

Email

Call

Payee 1:

S\$2,129.50

Name 1:

AH LIM MOTOR COMPANY

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

+450

COPY SENT

(08/11/93) wef

REF:

LPC

ASS. REC. BY:

ASSIGNMENT

From:

Date: 13/8/18

Estimated Cost:

OP: ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJF 2324C

at Workshop m/s

Ah Lim Motor

of

No. 10 AMK Ind. Park 2A # 01-09

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

1pm @ overnitting

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

833k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJF 2324C

Yr Regn:

05 of

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic

c.c

1799

Colour:

A.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

155303

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

J14MFD15308S215621

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/40ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

6/18/18

D.O.I.

13/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/8 file parts estimate

1/5: +2,250 (RED: +1,718.40 43%)

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 0212Z

Vehicle Details

Vehicle No.: SJF2324C
Vehicle to be Exported: No
Intended De-registration Date: 07 Aug 2018
Vehicle Make: HONDA
Vehicle Model: CIVIC 1.8L M
Primary Colour: White
Manufacturing Year: 2008
Engine No.: R18A13034181
Chassis No.: JHMF15308S215621
Maximum Power Output: 103.0 kW (138 bhp)
Open Market Value: \$21,208.00
Original Registration Date: 23 May 2008
First Registration Date: 23 May 2008
Transfer Count: 0
Actual ARF Paid: \$21,208.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 22 May 2023
COE Category: B - Car (1601cc & above)
COE Period(Years): 5
PQP Paid: \$19,356.00
COE Rebate Amount: \$18,544.00
Total Rebate Amount: \$18,544.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 07 Aug 2018

OK



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : KHOO CHOON BENG
BLK 419 YISHUN AVE 11
#06-383
SINGAPORE 760419

TEL: 96969788

ATTN:

Your Ref No: SJF2324C

Claim Type: Third Party

Accident Date: 06/08/2018

TP Veh Reg No: SJL290Y

Estimate No: MC0913336

Date: 08 Aug 2018

Policy No: P0663936

Veh Reg No: SJF2324C

Make/Model: HONDA CIVIC 1.8L M

*Not Withheld
11 Sep 87
Resurvey After Paint
4 days*

Estimate Repair Cost to Vehicle No :SJF2324C

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 HEADLAMP RH	1 PC	912.10	✓
2 FRONT BUMPER	1 PC	638.00	✓
3 FRONT BUMPER SIDE RETAINER RH	1 PC	12.00	✓
4 FRONT BUMPER CLIPS	10 PC	39.00	✓
5 FRONT BUMPER LOWER SPOILER - CHECK PRICE	1 PC	0.00	X
6 FRONT FENDER RH	1 PC	537.50	✓
7 FRONT FENDER COWLING RH	1 PC	94.80	✓
8 FRONT FENDER COWLING CLIPS	8 PC	28.00	✓
9 FRONT WHEEL BEARING	1 PC	109.40	X
10 FRONT WHEEL HUB	1 PC	170.80	X
11 FRONT LOWER ARM	1 PC	202.10	X
12 FRONT SHOCK ABSORBER	1 PC	334.30	X
13 FRONT SHOCK ABSORBER TOP MOUNTING	1 PC	45.00	✓
		3,123.00	
		Less 20%	624.60
			2,498.40
Special Nett			
14 TYRE RHR - CHECK PRICE	1 PC	0.00	X
15 SPORT RIM RHR - CHECK PRICE	1 PC	0.00	✓
		0.00	0.00
LABOUR			
16 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	2cl
17 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	6cl
18 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	250.00	X
19 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	400cl
20 TO SPRAY FRONT BUMPER, FRONT BUMPER SPOILER, FRONT FENDER RH.	1 PC	600.00	55cl
		1,470.00	1,470.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

62507387

6241
2360

255

SURVEYOR COPY

M/S : KHOO CHOON BENG
BLK 419 YISHUN AVE 11
#06-383
SINGAPORE 760419

TEL: 96969788

ATTN:

Your Ref No: SJF2324C

Claim Type: Third Party

Accident Date: 06/08/2018

TP Veh Reg No: SJL290Y

Estimate No: MC0913336
Date: 08 Aug 2018
Policy No: P0663936
Veh Reg No: SJF2324C
Make/Model: HONDA CIVIC 1.8L M

L/KC
Remainder
1.15pm

Not withashw
6/1 Aug 07

L/s repair necessary after paint
4 days

Estimate Repair Cost to Vehicle No :SJF2324C

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 HEADLAMP RH	1 PC	912.10	✓
2 FRONT BUMPER	1 PC	638.00	✓
3 FRONT BUMPER SIDE RETAINER RH	1 PC	12.00	✓
4 FRONT BUMPER CLIPS	10 PC	39.00	✓
5 FRONT BUMPER LOWER SPOILER - CHECK PRICE	1 PC	0.00	X
6 FRONT FENDER RH	1 PC	537.50	✓
7 FRONT FENDER COWLING RH	1 PC	94.80	✓
8 FRONT FENDER COWLING CLIPS	8 PC	28.00	X
9 FRONT WHEEL BEARING	1 PC	109.40	X
10 FRONT WHEEL HUB	1 PC	170.80	X
11 FRONT LOWER ARM	1 PC	202.10	X
12 FRONT SHOCK ABSORBER	1 PC	334.30	X
13 FRONT SHOCK ABSORBER TOP MOUNTING	1 PC	45.00	✓
		3,123.00	
	Less 20%	624.60	2,498.40
Special Nett			
14 TYRE RHR - CHECK PRICE	1 PC	0.00	X
15 SPORT RIM RHR - CHECK PRICE	1 PC	0.00	100 ✓
		0.00	0.00
LABOUR			
16 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	20 ✓
17 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	60 ✓
18 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	250.00	X
19 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	800 ✓
20 TO SPRAY FRONT BUMPER, FRONT BUMPER SPOILER, FRONT FENDER RH.	1 PC	600.00	550 ✓
		1,470.00	1,470.00

- To survey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Co.

Acknowledged by Repairer
Signature: _____
Date: _____





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind, Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : KHOO CHOON BENG
BLK 419 YISHUN AVE 11
#06-383
SINGAPORE 760419

TEL: 96969788

ATTN:

Your Ref No: SJF2324C

Claim Type: Third Party

Accident Date: 06/08/2018

TP Veh Reg No: SJL290Y

Estimate No: MC0913336
Date: 08 Aug 2018
Policy No: P0663936
Veh Reg No: SJF2324C
Make/Model: HONDA CIVIC 1.8L M

Estimate Repair Cost to Vehicle No :SJF2324C

Description	Quantity	List Price	Amount
		SS	SS
		Total	S\$ 3,968.40
		Add GST @ 7%	277.79
		Total Amount Payable	S\$ 4,246.19

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND TWO HUNDRED FORTY SIX AND CENTS NINETEEN ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE



ke AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimunc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : KHOO CHOON BENG
BLK 419 YISHUN AVE 11
#06-383
SINGAPORE 760419

TEL: 96969788

ATTN:

Your Ref No: SJF2324C

Claim Type: Third Party

Accident Date: 06/08/2018

TP Veh Reg No: SJL290Y

Claim No: MC0913336
No: MF1900433
Date: 16 Jul 2019
Policy No: P0663936
Veh Reg No: SJF2324C
Make/Model: HONDA CIVIC 1.8L M

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SJF2324C

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 HEADLAMP RH	1 PC	912.10	
2 FRONT BUMPER	1 PC	638.00	
3 FRONT BUMPER SIDE RETAINER RH	1 PC	12.00	
4 FRONT BUMPER CLIPS	10 PC	39.00	
5 FRONT FENDER RH	1 PC	537.50	
		2,138.60	
	Less 20%	427.72	1,710.88
Special Nett			
6 SPORT RIM RHR	1 PC	100.00	
		100.00	100.00
LABOUR			
7 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	20.00	
8 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	60.00	
9 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	400.00	
10 TO SPRAY FRONT BUMPER,FRONT BUMPER SPOILER, FRONT FENDER RH.	1 PC	550.00	
		1,030.00	1,030.00

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : KHOO CHOON BENG
BLK 419 YISHUN AVE 11
#06-383
SINGAPORE 760419

TEL: 96969788

ATTN:

Your Ref No: SJF2324C

Claim Type: Third Party

Accident Date: 06/08/2018

TP Veh Reg No: SJL290Y

Claim No: MC0913336
No: MF1900433
Date: 16 Jul 2019
Policy No: P0663936
Veh Reg No: SJF2324C
Make/Model: HONDA CIVIC 1.8L M

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SJF2324C

Description	Quantity	List Price	Amount
		SS	SS
		Total	S\$ 2,840.88
		Lump Sum Less 20%	-568.18
		Sub Total	S\$ 2,272.70
		Less Rounding	-22.70
		Lum Sum Repair	S\$ 2,250.00
		Less Excess	S\$ 0.00
		Amount Before GST	S\$ 2,250.00
		Add GST @ 7%	157.50
		Total Amount Payable	S\$ 2,407.50

TOTAL: SINGAPORE DOLLAR TWO THOUSAND FOUR HUNDRED AND SEVEN AND CENTS FIFTY ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 14/08/2018

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

Nivitha (LKK Auto)

From: ONG LI LI <llongli@ahlimmotor.com.sg>
Sent: Wednesday, 8 August 2018 10:41
To: zila; Nivitha (LKK Auto)
Cc: MT_Claim_SG
Subject: RE: TP / OUR CLIENT SJF2324C DO NOT FORGET TO CHECK NO. 101611636 YOUR INSURED VEHICLE
Attachments: 2324 - LKK Auto

10:41am @ 1016116
Person @ zila
vehicle not in

Without Prejudice

Dear Zila

Please liaise with our appointed surveyor.

Dear Nivitha

Fya

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance
300 Beach Road #17-04/07 The Centennial
Tel : (65) 6250 7388 Ext. 254 Fax : (65) 6250 7389

From: zila [mailto:zila@ahlimmotor.com.sg]
Sent: Wednesday, 8 August, 2018 5:18 PM
To: MT_Claim_SG
Subject: TP / OUR CLIENT SJF2324C DO NOT FORGET TO CHECK NO. 101611636 YOUR INSURED VEHICLE

Hi Claims Dept,

Please kindly arrange survey.

Note: Vehicle is not in. - To be arranged

Thanks.

--
Best Regards, Zila Ah Lim Motor Tel: (65) 6250 7388 Ext. 254

Mei Kwan (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Friday, 17 August, 2018 2:41 PM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: TP / OUR CLIENT SJF2324C DOA: 06/08/2018 POLICY NO. P0663936 YOUR INSURED SJL290Y Our Ref: 18/18/18/VP05/020819
Attachments: 17082018144015.pdf

Follow Up Flag: Follow up
Flag Status: Completed

Categories: HMK

Dear Mei Kwan,

Attached copy of insured's GIA report for your attention.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]

Sent: Friday, 17 August, 2018 2:32 PM

To: ONG LI LI

Cc: MT_Claim_SG; Thin Thin (LKKAUTO); Vivian Lau (LKKAUTO); Admin A

Subject: RE: TP / OUR CLIENT SJF2324C DOA: 06/08/2018 POLICY NO. P0663936 YOUR INSURED SJL290Y Our Ref: 18/18/18/VP05/020819

WITHOUT PREJUDICE

LPC ref: 18/18/18/VP05/020819

LKK REF: CC4/LPC18014502/Kua3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SJF 2324C

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Please take note that the case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

To: MT_Claim_SG

Subject: TP / OUR CLIENT SJF2324C DOA: 06/08/2018 POLICY NO. P0663936 YOUR INSURED SJL290Y

Hi Claims Dept,

Please kindly arrange survey.

Note: Vehicle is not in. - To be arrange

Thanks.

--

Best Regards, Zila Ah Lim Motor Tel: 64831244 Fax: 64836170



This email has been checked for viruses by AVG antivirus software.
www.avg.com

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

Our Ref : MC0913336
Your Ref : 18/VP05/020819
Date : 03/01/2020

LONPAC INSURANCE BHD
300 BEACH ROAD #17-04
THE CONCOURSE
SINGAPORE 199555

Dear Sir/Madam,

Request for Direct Settlement for Accident involving our client's vehicle SJF2324C and your Insured SJL290Y ON 06/08/2018 17:40 ALONG SELETAR WEST LINK

We refer to the above matter and return herewith the discharge Voucher duly signed by our client and we look forward to early receipt of the remittance amount of \$2,729.50 soonest.

Thank You.

Yours faithfully,

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

Kee Mui Hong



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18014502/Kea3n2		
300 BEACH ROAD		Date : 13-01-2020		
#17-04/07 THE CONCOURSESINGAPORE 199555		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJL 290Y	Veh. Inspected	SJF 2324C	
Policy No.	Z18VP05018660	Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020819	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	10/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC (A)	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JHMF15308S215621	Colour	METALLIC PEARL WHITE	
Odometer	155303	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 ZR18	PIRELLI	8 mm	
L/H Front Tyre	225/40 ZR18	PIRELLI	8 mm	
R/H Rear Tyre	225/40 ZR18	PIRELLI	8 mm	
L/H Rear Tyre	225/40 ZR18	PIRELLI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/08/2018	Inspection Date	13/08/2018	
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJF 2324C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HEADLAMP RH	CUT	912.10	912.10
1	FRONT BUMPER	MTG CRACKED	638.00	638.00
1	FRONT BUMPER SIDE RETAINER RH	NECESSARY	12.00	12.00
10	FRONT BUMPER CLIPS	NECESSARY	39.00	39.00
1	FRONT BUMPER LOWER SPOILER (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT FENDER RH	BENT	537.50	537.50
1	FRONT FENDER COWLING RH	SERVICEABLE	94.80	-
8	FRONT FENDER COWLING CLIPS	NOT NECESSARY	28.00	-
1	FRONT WHEEL BEARING	NOT NECESSARY	109.40	-
1	FRONT WHEEL HUB	SERVICEABLE	170.80	-
1	FRONT LOWER ARM	SERVICEABLE	202.10	-
1	FRONT SHOCK ABSORBER	SERVICEABLE	334.30	-
1	FRONT SHOCK ABSORBER TOP MOUNTING	SERVICEABLE	45.00	-
	LESS 20% DISCOUNT		-624.60	-427.72
			2,498.40	1,710.88
SPECIAL NETT ITEMS				
1	TYRE RHR (NPA) (SN)	SERVICEABLE	-	-
1	SPORT RIM RHR (LOCAL REPAIR)(SN)	DENTED	100.00	100.00
			100.00	100.00
LABOUR				
	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	20.00
	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.		80.00	60.00
	TO DISMANTLE ,REPLACE AND REINSTALL UNDERCARRIAGE .	NOT NECESSARY	250.00	-
	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD .TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME.INCLUSIVE OF THE REPAIR OF FRONT BUMPER LOWER SPOILER .		500.00	400.00

Report Ref No. CC4/LPC18014502/Kea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO SPRAY FRONT BUMPER ,FRONT BUMPER SPOILER ,FRONT FENDER RH .		600.00	550.00
			1,470.00	1,030.00
GRAND TOTAL			4,068.40	2,840.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,250.00

Report Ref No. CC4/LPC18014502/Kea3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.