



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : KHOO CHOON BENG
BLK 419 YISHUN AVE 11
#06-383
SINGAPORE 760419

TEL: 96969788

ATTN:

Your Ref No: SJF2324C

Claim Type: Third Party

Accident Date: 06/08/2018

TP Veh Reg No: SJL290Y

Estimate No: MC0913336

Date: 08 Aug 2018

Policy No: P0663936

Veh Reg No: SJF2324C

Make/Model: HONDA CIVIC 1.8L M

*Not Withheld
11 Sep 07
Resurvey After Paint
4 days*

Estimate Repair Cost to Vehicle No :SJF2324C

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 HEADLAMP RH	1 PC	912.10	✓
2 FRONT BUMPER	1 PC	638.00	✓
3 FRONT BUMPER SIDE RETAINER RH	1 PC	12.00	✓
4 FRONT BUMPER CLIPS	10 PC	39.00	✓
5 FRONT BUMPER LOWER SPOILER - CHECK PRICE	1 PC	0.00	x
6 FRONT FENDER RH	1 PC	537.50	✓
7 FRONT FENDER COWLING RH	1 PC	94.80	?
8 FRONT FENDER COWLING CLIPS	8 PC	28.00	?
9 FRONT WHEEL BEARING	1 PC	109.40	x
10 FRONT WHEEL HUB	1 PC	170.80	x
11 FRONT LOWER ARM	1 PC	202.10	x
12 FRONT SHOCK ABSORBER	1 PC	334.30	x
13 FRONT SHOCK ABSORBER TOP MOUNTING	1 PC	45.00	✓
		3,123.00	
		Less 20%	624.60
			2,498.40
Special Nett			
14 TYRE RHR - CHECK PRICE	1 PC	0.00	x
15 SPORT RIM RHR - CHECK PRICE	1 PC	0.00	✓
		0.00	0.00
LABOUR			
16 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	2cl
17 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	6cl
18 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	250.00	x
19 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	80cl
20 TO SPRAY FRONT BUMPER, FRONT BUMPER SPOILER, FRONT FENDER RH.	1 PC	600.00	55cl
		1,470.00	1,470.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : KHOO CHOON BENG
BLK 419 YISHUN AVE 11
#06-383
SINGAPORE 760419

TEL: 96969788

ATTN:

Your Ref No: SJF2324C
Claim Type: Third Party
Accident Date: 06/08/2018
TP Veh Reg No: SJL290Y

Estimate No: MC0913336
Date: 08 Aug 2018
Policy No: P0663936
Veh Reg No: SJF2324C
Make/Model: HONDA CIVIC 1.8L M

Estimate Repair Cost to Vehicle No :SJF2324C

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 3,968.40
		Add GST @ 7%	277.79
		Total Amount Payable	S\$ 4,246.19

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND TWO HUNDRED FORTY SIX AND CENTS NINETEEN ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY


AUTHORISED SIGNATURE