

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

SLC 9330E

Not Allowed
2/5 11/2006
7dy.
10/8/18

QTY	PARTICULAR		
1 PCS	BOOTLID	1766.10	boot/worped \$1,866.20
1 PCS	BOOTLID REAR LOGO		RM \$68.50
1 PCS	BOOTLID '520I' EMBLEM		RM \$66.80
2 PCS	BOOTLID REFLECTORS @\$485.30	466.20	M/crm \$970.60 1PC
1 PCS	BOOTLID INNER LOCK		11 \$299.08 X
1 PCS	BOOTLID WEATHERSTRIP	266.05	4w1 \$275.00
2 PCS	TAILLAMPS @\$688.50	1585	M/crm \$1,377.00 1PC
1 PCS	REAR BUMPER	1545	705 \$1,866.20
1 PCS	REAR BUMPER LOWER SKIRTING		NZ \$650.00 X
2 PCS	REAR BUMPER REFLECTORS @\$75.00		M/crm \$150.00 PC
4 PCS	REAR BUMPER PDC SENSORS @\$305.00	266	M/crm \$1,220.00 1PC
1 PCS	REAR BUMPER PDC SENSORS WIRE		11 \$313.54X
1 PCS	REAR BUMPER TOP GUIDE		CRM \$199.02
1 PCS	REAR BUMPER REINFORCEMNT	640.92	RM \$755.01
1 PCS	REAR BUMPER LOWER GUIDE		CRM \$185.13
2 PCS	REAR BUMPER SIDE RETAINERS @\$115.00		M/crm \$230.00 1PC
1 PCS	REAR BUMPER INNER ADAPTER		11 \$185.00 X
1 PCS	REAR END PANEL	1018.57	Subj 11 \$1,122.10
1 PCS	REAR END PANEL TOP GARNISH	288.01	4w1 \$311.20
1 PCS	REAR FENDER N/S		11 \$1,412.30X
1 PCS	REAR FENDER INNER TRIM N/S		Defayed \$366.05
1 PCS	REAR FENDER INNER SIDE MEMBER N/S		Subj 11 \$699.01
1 PCS	TAILLAMP SIDE GARNISH N/S		CRM \$18.50
1 PCS	REAR AIR VENT N/S		7.5 \$66.50
1 PCS	REAR EXHAUST ASSY	1810	Subj/4w1 \$1,880.10
1 PCS	REAR EXHAUST HEAT SHIELD N/S	181.30	705 \$299.20
1 PCS	REAR FENDER UNDER COVER N/S	295.50	705 \$322.20
1 PCS	REAR TAILLAMP HOUSING PANEL N/S	166.30	Subj \$366.20
1 PCS	REAR WINDSCREEN MOULDING		11 \$148.50 X
1 PCS	REAR SHOCK ABSORBER N/S		11 \$522.30 X
1 PCS	REAR WHEEL HUB BEARING N/S		11 \$645.10 X
			\$18,856.34
	S.NETT		
1 PCS	REAR WINDSCREEN SEALANT		11 \$80.00 X
1 PCS	REAR END PANEL SEALANT		RM \$80.00 10
1 PCS	REAR FLOOR PANEL INSULATOR		RM \$380.00/50

11198.46
500
10638.53

1 SET

REAR EXHAUST CHROME PIPE

∞ \$300.00 /20

LABOUR CHARGES:

TO CHECK WIRING	\$80.00	30
TO DISMENTLE & REPLACING REAR PDC SENSOR	\$100.00	50
TO DISMENTLE & REFIX BOOTLID MECHANISM	\$100.00	80
TO DISMENTLE & REFIX REAR WINDSCREEN	11 \$150.00	X
TO DISMENTLE & REFIX SEAT,CUSHION,UPHOLSTREY	\$150.00	100
TO DISMENTLE & REFIX REAR EXHAUST	\$150.00	100
TO DISMENTLE & REFIX REAR UNDERCARRIAGE	11 \$180.00	X
TO DISMENTLE & REFIX PETROL TANK	11 \$100.00	X
TO REPROGRAMME & RESET FAULT CODE	11 \$200.00	X
TO SPRAY RUST PROOFING	\$120.00	100
LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED	\$2,200.00	1400
& REPLACING PARTS		
TO PUTTY & SPRAY PAINTING	\$1,800.00	1200

TOTAL

\$25,026.34

14018.5
1124

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: