

ASSIGNMENT

15/8/2018

Date/Time:

8/8/18

Registered in:

10/8/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SHC 2533E

Name of Insured : CTR

Insured Tel No. : HP:

Excess Sec II : S\$ D.O.A : 2/8/18

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : Neo Chin Seng

Driver Tel No. : 93228865 (V/L: YES / NO)

Claim No. : MCT 18080179

Policy No. : MCOM0015

Make / Model : H-10MQ

Place of Accident : SEE > BKE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

INSRS:
WSP: Syntex
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

17/8/2018

HMK

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Tanjah

Repair Cost:

P/P

S\$ 5867.00

(4 days)

Reduction:

\$202.80

%

21

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email:

Call:

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

28

Repair Cost:

(W/M)

S\$

6277.69

Loss of Rental (LOR):

S\$

-

(days)

Loss of Use (LOU):

S\$

550

(550 x 11 days)

Loss of Income (LOI):

S\$

-

(5 x 11 days)

LOR only ☐ LOU only ☒

LOR + LOU

☐ LOR + LOI

(Tick only one)

GIA/LTA Search

S\$

7.45

Medical:

S\$

-

Disbursement:

S\$

-

Legal Cost

S\$

-

Total:

S\$

6835.14

Global Sum S\$:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email:

Call:

Payee 1:

S\$

6835.14

Payee 1:

Sng An Tee

Panel

Repair

Pte Ltd

Payee 2: (Strike if N/A)

S\$

-

Payee 3: (Strike if N/A)

S\$

-

Tanpin

REF: III

14808/Tlfaz-f.

CoE 2023 July

2028 July

From: Date: 15082018

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJG 9690T

at Workshop m/s Sng Ah Tee

of Blk 3 Pioneer Rd North #01-18

Insured

Policy No.

Claims No.

Sum Insured Excess:

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Ball. or Market Value: 429K.

IDAC Accident Report Consistent? Yes or No

GIA / FR Seen: Consistent? Yes or No

Est. Repairs: 9 days Res: Yes or No

Lump Sum: 1-1-1 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJG 9690T

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Fit

Colour: Blue

Sp. Reading: 95625

Eng No:

C No: GE 61090633.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 155/65R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

R/Bal: mm

L/Bal: mm

D.O.A.

Survey held at Sng Ah Tee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Diagram of vehicle damage

N/S	O/S

P/P \$5867.1- (Red - \$2103.80 / 76.1%)

Date/Time: File Pass to:

☐ : Preli. Report

☐ : Final Report

Date/Time: File Return to:

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ Site Insp \$

☐ Interview \$

☐ Tech Insp \$

☐ Weekend \$

Survey Fee:

Transportation:

Other:

Other:

Report Format:

Lump Sum / I.B.F. \$

孫亞弟汽車燒焊私人有限公司
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB, Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ004132

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION:

CONTACT: 62238122

FAX NO: 62244174

DATE 15/08/2018

ACCIDENT DATE: 07/08/2018

VEHICLE NO: SJG9690T

CHASSIS/ENG.NO: GE61090633

VEHICLE MODEL: HONDA FIT

CLAIM NO:

POLICY NO: 9690

REMARK: 5067-INDIA TP AGST SHC2533E

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER	474.40	20	379.52	379.52
2	10	PC	REAR BUMPER CLIPS	3.90	20	3.12	31.20
3	2	PC	REAR BUMPER RETAINER	16.50	20	13.20	26.40
4	1	PC	REAR BUMPER TOWING COVER	13.30	20	10.64	10.64
5	1	PC	REAR BOOT LID	771.50	20	617.20	617.20
6	1	PC	REAR BOOT FIT STICKER	27.50	20	22.00	22.00
7	1	PC	REAR BOOT TRIMBOARD	100.20	20	80.16	80.16
8	1	PC	REAR BOOT LOCK	189.50	20	151.60	151.60
9	1	PC	REAR END PANEL	276.50	20	221.20	221.20
10	1	PC	REAR END PANEL TOP GARNISH	60.80	20	48.64	48.64
11	1	PC	REAR END PANEL RUBBER	92.30	20	73.84	73.84
12	2	PC	REAR WINDSCREEN MOULDING	36.50	20	29.20	58.40
13	2	PC	REAR FENDER	652.40	20	521.92	1043.84
14	1	PC	FRT BUMPER	523.50	20	418.80	418.80
15	10	PC	FRT BUMPER CLIPS	3.90	20	3.12	31.20
16	2	PC	FRT BUMPER RETAINER	13.80	20	11.04	22.08
17	1	PC*	FRT BUMPER REINFORCEMENT	231.20	20	184.96	184.96
18	1	PC	FRT GRILLE	137.50	20	110.00	110.00
19	1	PC	FRT GRILLE EMBLEM	23.40	20	18.72	18.72
20	1	PC	FRT BONNET	433.80	20	347.04	347.04

JOYCE

PAGE: 1 of 3

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

RR Tail Lamp LH - 206.20
RR Tail Lamp RH - 206.20
RR Sponge Trail - 220.40
RR Tool box - 200.00
Ndis

26.60
20% 341.28
200
541.28

孫亞弟汽車燒焊私人有限公司
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ004132

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION :

CONTACT : 62238122

FAX NO: 62244174

DATE 15/08/2018

ACCIDENT DATE : 07/08/2018

VEHICLE NO : SJG9690T

CHASSIS/ENG.NO : GE61090633

VEHICLE MODEL : HONDA FIT

CLAIM NO :

POLICY NO :

REMARK : 9690
5067-INDIA TP AGST
SHC2533E

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
21	1	PC	FRT BONNET INSULATOR	55.00	20	44.00	44.00
22	7	PC	FRT BONNET INSULATOR CLIPS	3.80	20	3.04	21.28
23	2	PC	FRT BONNET HINGE	31.00	20	24.80	49.60
24	1	PC	FRT BONNET LOCK	90.60	20	72.48	72.48

SUB-TOTAL: 4,084.80

\$3990.20

**** SPECIAL NETT PRICE ****

1	1	PC	REAR WINDSCREEN SEALANT	40.00		40.00	40.00
2	1	PC	REAR PARKING REVERSE SENSOR	280.00		280.00	280.00
3	1	PC	FRT NUMBER PLATE	35.00		35.00	35.00

SUB-TOTAL: 355.00

\$241

**** WORK LABOUR ****

TO KNOCK, WELD REMOVE AND REPLACE ABOVE PARTS	1500.00	1200	1,500.00
TO REMOVE & REFIX RR WINDSCREEN	150.00	120	150.00
TO PUTTY & RESPRAY PAINTING ON AFFECTED AREAS	1600.00	1300	1,600.00
TO REMOVE & FIX TRIMS	150.00	60	150.00
TO CHECK WIRING	30.00	30	30.00
TO APPLY ANTI RUST COAT	100.00	50	100.00

JOYCE

PAGE: 2 of 3

(Signature)

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ004132

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION:

CONTACT: 62238122

FAX NO: 62244174

DATE : 15/08/2018
ACCIDENT DATE : 07/08/2018
VEHICLE NO : SJG9690T
CHASSIS/ENG.NO : GE61090633
VEHICLE MODEL : HONDA FIT
CLAIM NO :
POLICY NO :
REMARK : 97690
5067 INDIA TP AGST
SHC2533E

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
------	-----	------	-------------	-------	--------	-------------	-----------

SUB-TOTAL 3,530.00

2760 ✓

Tanjin 9749574

up

hump

Repair after repair

sure 1 hour on

9 days

15/6/18 1120

total \$4832.00

partly part ok?

the repair - sham 21/2019

2290.72

541.28

275

2760

5867

JOYCE



PAGE: 3 of 3

SUB-TOTAL : S\$ 7,969.80

ADD 7% GST. S\$ 557.89

GRAND TOTAL : S\$ 8,527.69

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB Reg / GST Reg. No: 200810440N

EST/QUOTE NO. SQ004132

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION:

CONTACT: 62238122

FAX NO: 62244174

DATE 15/08/2018

ACCIDENT DATE : 07/08/2018

VEHICLE NO : SJG9690T

CHASSIS/ENG.NO : GE61090633

VEHICLE MODEL : HONDA FIT

CLAIM NO :

POLICY NO :

REMARK

5067 INDIA TP AGST
SHC2533E

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER	474.40	20	379.52	379.52
2	10	PC	REAR BUMPER CLIPS	3.90	20	3.12	31.20
3	2	PC	REAR BUMPER RETAINER	16.50	20	13.20	26.40
4	1	PC	REAR BUMPER TOWING COVER	13.30	20	10.64	10.64
5	1	PC	REAR BOOT LID	771.50	20	617.20	617.20
6	1	PC	REAR BOOT FIT STICKER	27.50	20	22.00	22.00
7	1	PC	REAR BOOT TRIMBOARD	100.20	20	80.16	80.16
8	1	PC	REAR BOOT LOCK	189.50	20	151.60	151.60
9	1	PC	REAR END PANEL	276.50	20	221.20	221.20
10	1	PC	REAR END PANEL TOP GARNISH	60.80	20	48.64	48.64
11	1	PC	REAR END PANEL RUBBER	92.30	20	73.84	73.84
12	2	PC	REAR WINDSCREEN MOULDING	36.50	20	29.20	58.40
13	2	PC	REAR FENDER	652.40	20	521.92	1,043.84
14	1	PC	FRT BUMPER	523.50	20	418.80	418.80
15	10	PC	FRT BUMPER CLIPS	3.90	20	3.12	31.20
16	2	PC	FRT BUMPER RETAINER	13.80	20	11.04	22.08
17	1	PC	FRT BUMPER REINFORCEMENT	231.20	20	184.96	184.96
18	1	PC	FRT GRILLE	137.50	20	110.00	110.00
19	1	PC	FRT GRILLE EMBLEM	23.40	20	18.72	18.72
20	1	PC	FRT BONNET	433.80	20	347.04	347.04

JOYCE

PAGE: 1 of 3

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ004132

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION:

CONTACT: 62238122

FAX NO: 62244174

DATE 15/08/2018

ACCIDENT DATE : 07/08/2018

VEHICLE NO : SJG9690T

CHASSIS/ENG.NO : GE61090633

VEHICLE MODEL : HONDA FIT

CLAIM NO :

POLICY NO :

REMARK : 5067 INDIA TP AGST
SHC2533E

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
21	1	PC	FRT BONNET INSULATOR	55.00	20	44.00	44.00
22	7	PC	FRT BONNET INSULATOR CLIPS	3.80	20	3.04	21.28
23	2	PC	FRT BONNET HINGE	31.00	20	24.80	49.60
24	1	PC	FRT BONNET LOCK	90.60	20	72.48	72.48

SUB-TOTAL: 4,084.80

** SPECIAL NETT PRICE **

1	1	PC	REAR WINDSCREEN SEALANT	40.00		40.00	40.00
2	1	PC	REAR PARKING REVERSE SENSOR	280.00		280.00	280.00
3	1	PC	FRT NUMBER PLATE	35.00		35.00	35.00

SUB-TOTAL 355.00

** WORK LABOUR **

TO KNOCK, WELD REMOVE AND REPLACE ABOVE PARTS	1500.00	1,500.00
TO REMOVE & REFIX RR WINDSCREEN	150.00	150.00
TO PUTTY & RESPRAY PAINTING ON AFFECTED AREAS	1600.00	1,600.00
TO REMOVE & FIX TRIMS	150.00	150.00
TO CHECK WIRING	30.00	30.00
TO APPLY ANTI RUST COAT	100.00	100.00

JOYCE

PAGE: 2 of 3

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ004132

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION:

CONTACT: 62238122

FAX NO: 62244174

DATE 15/08/2018

ACCIDENT DATE : 07/08/2018

VEHICLE NO : SJG9690T

CHASSIS/ENG.NO : GE61090633

VEHICLE MODEL : HONDA FIT

CLAIM NO :

POLICY NO :

REMARK : 5067 INDIA TP AGST
SHC2533E

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
SUB-TOTAL							3,530.00

Tanpin 97495749
"up"

lump sum
Resurvey after repair
sure 1 hour for work

9 days.

15/6/18 1120

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

JOYCE



PAGE: 3 of 3

SUB-TOTAL : S\$ 7,969.80

ADD 7% GST. S\$ 557.89

GRAND TOTAL : S\$ 8,527.69

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5067J
Vehicle Details	
Vehicle No.:	SJG9690T
Vehicle to be Exported:	No
Intended De-registration Date:	31 Aug 2018
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	L13A4101051
Chassis No.:	GE61090633
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$12,436.00
Original Registration Date:	22 Jul 2008
First Registration Date:	22 Jul 2008
Transfer Count:	1
Actual ARF Paid:	\$10,308.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jul 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$18,583.00
COE Rebate Amount:	\$18,173.00
Total Rebate Amount:	\$18,173.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 07 Aug 2018

OK

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Wednesday, 15 August 2018 11:04 AM
To: 'admin@sngahtee.com'
Cc: Hsiao Tong (LKKAUTO); Admin A; assignments
Subject: ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE SHC 2533E, SJG 9690T AND OTHER ON 07/08/2018

Importance: High

WITHOUT PREJUDICE

Our Ref: CC4/III18014508/fa3
Your Ref: SJG 9690T

Dear Joyce,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE SHC 2533E, SJG 9690T AND OTHER ON 07/08/2018

We refer to above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

In the meantime, Kindly arrange for TP survey ASAP.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Received Message

This mail is associated with :

***SJG9690T (MCT18080179)**
[SHC2533E]

TP

GUAN YONGHE

Aug 7 2018 12:00AM

[-]

Sng Ah Tee Motor & Panel Service Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 29/10/2019 12:32 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6945.14) - SJG9690T - Claim Handler: Sundari Nagarajan

Approved:6945.14:Request TP WS to issue Tax invoice for Repairs in III's favour

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 8 August 2018 12:08 PM
To: ADMIN SAT; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: Sundari Nagarajan - III
Subject: RE: ACCIDENT INVOLVING OUR CLIENT VEHICLE SJG9690T AND YOUR INSURED SHC2533E ON 07/08/2018
Attachments: SJG9690T.PDF

2:16pm 8/8/18
person @ jayle
vehicle not in

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SJG9690T and let us have your report urgently.

This claim will be handled by Ms Sundari.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: ADMIN SAT [mailto:admin@sngahtee.com]

Sent: 08 August, 2018 10:52 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Re: ACCIDENT INVOLVING OUR CLIENT VEHICLE SJG9690T AND YOUR INSURED SHC2533E ON 07/08/2018

Hi,


LKK AUTO

Thanks

Best Regards

Joyce Tan | admin@sngahtee.com

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



From: Motor Claim - III

Sent: Wednesday, August 08, 2018 10:40 AM

To: ADMIN SAT

Subject: RE: ACCIDENT INVOLVING OUR CLIENT VEHICLE SJG9690T AND YOUR INSURED SHC2533E ON 07/08/2018

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: ADMIN SAT [mailto:admin@sngahtee.com]

Sent: 07 August, 2018 5:21 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: ACCIDENT INVOLVING OUR CLIENT VEHICLE SJG9690T AND YOUR INSURED SHC2533E ON 07/08/2018

Hi ,

Have your insured reported the accident?

Is liability in our favour?

Hope to hear from you.

Thanks you

Best Regards

Joyce Tan | admin@sngahtee.com

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457

TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

...CLAIM SUBFOLDER...(Pending for Survey Report)
Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Aug 2018 Edit Reg		08 Aug 2018 00:00 Edit Adj Rpt	S\$5,867.00 Edit Estimates	S\$5,867.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	COMFORT TRANSPORTATION PTE LTD, ID: 199303821R		
Main Claimant:	GUAN YONGHE, ID: S7265067J		
Vehicle Reg. No.:	SJG9690T	Date of Loss:	07/08/2018 00:00 - :59 [120 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18080179	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHC2533E	Policy No. (Claimant):	GA273932
		Excess:	
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 21/08/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (29/10/2019): Alert - Adj Mandate Approved (S\$6945.14) - SJG9690T - Claim Handler: Sundari Nag...
- III_SG (23/09/2019): Alert - Adj Mandate Maintained - SJG9690T - Claim Handler: Sundari Nagarajan
- III_SG (22/08/2019): Alert - Adj Mandate Maintained - SJG9690T - Claim Handler: Sundari Nagarajan
- III_SG (14/08/2018): Alert - Adj Mandate Approved (S\$0.00) - SJG9690T - Claim Handler: Sundari Nagara...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJG9690T (MCT18080179)
[SHC2533E]
TP
GUAN YONGHE
Aug 7 2018 12:00AM
[COMFORT TRANSPORTATION PTE LTD]
Sng Ah Tee Motor & Panel Service Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/08/19 17:26	Odometer Reading	 Load JPG	☒
2	15/08/19 17:26	General View	 Load JPG	☒
3	15/08/19 17:26	General View	 Load JPG	☒
4	15/08/19 17:26	General View	 Load JPG	☒
5	15/08/19 17:26	General View	 Load JPG	☒
6	15/08/19 17:26	General View	 Load JPG	☒
7	15/08/19 17:26	General View	 Load JPG	☒
8	15/08/19 17:26	General View	 Load JPG	☒
9	15/08/19 17:26	General View	 Load JPG	☒
10	15/08/19 17:26	General View	 Load JPG	☒
11	15/08/19 17:26	General View	 Load JPG	☒
12	15/08/19 17:26	General View	 Load JPG	☒
13	15/08/19 17:26	General View	 Load JPG	☒
14	15/08/19 17:26	General View	 Load JPG	☒
15	15/08/19 17:26	General View	 Load JPG	☒
16	15/08/19 17:26	General View	 Load JPG	☒
17	15/08/19 17:26	General View	 Load JPG	☒
18	15/08/19 17:26	General View	 Load JPG	☒
19	15/08/19 17:26	General View	 Load JPG	☒
20	15/08/19 17:26	General View	 Load JPG	☒
21	15/08/19 17:26	General View	 Load JPG	☒
22	15/08/19 17:26	General View	 Load JPG	☒
23	15/08/19 17:26	General View	 Load JPG	☒
24	15/08/19 17:26	General View	 Load JPG	☒
25	15/08/19 17:26	General View	 Load JPG	☒
26	15/08/19 17:26	General View	 Load JPG	☒
27	15/08/19 17:26	General View	 Load JPG	☒
28	15/08/19 17:26	General View	 Load JPG	☒
29	15/08/19 17:26	General View	 Load JPG	☒
30	15/08/19 17:26	General View	 Load JPG	☒
31	15/08/19 17:26	General View	 Load JPG	☒
32	15/08/19 17:26	General View	 Load JPG	☒
33	15/08/19 17:26	General View	 Load JPG	☒
34	15/08/19 17:26	General View	 Load JPG	☒
35	15/08/19 17:26	General View	 Load JPG	☒
36	15/08/19 17:26	General View	 Load JPG	☒
37	15/08/19 17:26	General View	 Load JPG	☒
38	15/08/19 17:26	General View	 Load JPG	☒
39	15/08/19 17:26	General View	 Load JPG	☒
40	15/08/19 17:26	General View	 Load JPG	☒
41	15/08/19 17:26	General View	 Load JPG	☒
42	15/08/19 17:26	General View	 Load JPG	☒
43	15/08/19 17:26	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	15/08/19 17:26	General View	 Load JPG	☒
45	15/08/19 17:26	General View	 Load JPG	☒
46	15/08/19 17:26	General View	 Load JPG	☒
47	15/08/19 17:26	General View	 Load JPG	☒
48	15/08/19 17:26	General View	 Load JPG	☒
49	15/08/19 17:26	General View	 Load JPG	☒
50	15/08/19 17:26	General View	 Load JPG	☒
51	15/08/19 17:26	General View	 Load JPG	☒
52	15/08/19 17:26	General View	 Load JPG	☒
53	15/08/19 17:26	General View	 Load JPG	☒
54	15/08/19 17:26	General View	 Load JPG	☒
55	15/08/19 17:26	General View	 Load JPG	☒
56	15/08/19 17:26	General View	 Load JPG	☒
57	15/08/19 17:26	General View	 Load JPG	☒
58	15/08/19 17:26	General View	 Load JPG	☒
59	15/08/19 17:26	General View	 Load JPG	☒
60	15/08/19 17:26	General View	 Load JPG	☒
61	15/08/19 17:26	General View	 Load JPG	☒
62	15/08/19 17:26	General View	 Load JPG	☒
63	15/08/19 17:26	Reinspection Photo	 Load JPG	☒
64	15/08/19 17:26	Reinspection Photo	 Load JPG	☒
65	15/08/19 17:26	Reinspection Photo	 Load JPG	☒
66	15/08/19 17:26	Reinspection Photo	 Load JPG	☒
67	15/08/19 17:26	Reinspection Photo	 Load JPG	☒
68	15/08/19 17:26	Reinspection Photo	 Load JPG	☒
69	15/08/19 17:26	Reinspection Photo	 Load JPG	☒
70	15/08/19 17:26	Reinspection Photo	 Load JPG	☒
71	15/08/19 17:26	Reinspection Photo	 Load JPG	☒
72	15/08/19 17:26	Reinspection Photo	 Load JPG	☒
73	15/08/19 17:26	Reinspection Photo	 Load JPG	☒
74	15/08/19 17:27	Reinspection Photo-before paint	 Load JPG	☒
75	15/08/19 17:27	Reinspection Photo-before paint	 Load JPG	☒
76	15/08/19 17:27	Reinspection Photo-before paint	 Load JPG	☒
77	15/08/19 17:27	Reinspection Photo-before paint	 Load JPG	☒
78	15/08/19 17:27	Reinspection Photo-before paint	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/08/18 15:34	TP GIA REPORT	 Load PDF	
2	10/08/18 15:34	ACKNOWLEDGEMENT EMAIL TO III DD 08.08.2018	 Load PDF	
3	17/08/18 11:40	TP ESTIMATE - MARKED	 Load PDF	
4	21/08/19 09:56	LTA SEARCH	 Load PDF	
5	21/08/19 09:56	LOD	 Load PDF	
6	18/03/20 10:30	WORKSHOP INVOICE	 Load PDF	
7	18/03/20 10:30	AUTHORISATION TO ACT FORM	 Load PDF	
8	18/03/20 10:30	DISCHARGE VOUCHER	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	13/08/18 08:42	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18014508/T1GA3Q2
Date: 18/03/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
Claimant Vehicle No: SJG9690T Insured Vehicle No: SHC2533E
Date of Loss: 07/08/2018 Nature of Claim: TP Claim No: MCT18080179

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJG9690T Engine No: L13A4101051
Make & Model: HONDA FIT, 1.3 G (A) Chassis No: GE61090633
Reg. Date: 22/07/2008 (Man. Year: 2008) Odometer: 95025 km
Colour: Blue
Engine Capacity: 1339 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/60 R14 Rear Tyre Size: 185/60 R14
Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,981.08	3,107.00	1,874.08	37.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	2,760.00	770.00	21.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,511.08	5,867.00	2,644.08	31.07
+ GST 7.00/7.00% (S\$)	595.78	410.69	185.09	31.07
Nett Amount (S\$)	9,106.86	6,277.69	2,829.17	31.07
+ Loss of Use (11.0 x S\$50.00/day) (S\$)		550.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,835.14		

INSPECTION

Date of Assignment: 08/08/2018
Date Inspected: 15/08/2018 Inspected At: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Blk 3 Pioneer Road North, #01-18 Singapore 628457
Estimated Period of Repair: 9.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Aug 2019)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJG9690T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	474.40 FL	*474.40 FL
2	10		*REAR BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
3	2		*REAR BUMPER RETAINER	Necessary	33.00 FL	*33.00 FL
4	1		*REAR BUMPER TOWING COVER	Repair	13.30 FL	*- FL
5	1		*REAR BOOT LID	Bent	771.50 FL	*771.50 FL
6	1		*REAR BOOT FIT STICKER	Necessary	27.50 FL	*27.50 FL
7	1		*REAR BOOT TRIMBOARD	Not Necessary	100.20 FL	*- FL
8	1		*REAR BOOT LOCK	Dented	189.50 FL	*189.50 FL
9	1		*REAR END PANEL	Bent	276.50 FL	*276.50 FL
10	1		*REAR END PANEL TOP GARNISH	Deformed	60.80 FL	*60.80 FL
11	1		*REAR END PANEL RUBBER	Twisted	92.30 FL	*92.30 FL
12	2		*REAR WINDSCREEN MOULDING	Necessary	73.00 FL	*73.00 FL
13	2		*REAR FENDER	Repair	1,304.80 FL	*- FL
14	1		*FRT BUMPER	Repair	523.50 FL	*- FL
15	10		*FRT BUMPER CLIPS	Not Necessary	39.00 FL	*- FL
16	2		*FRT BUMPER RETAINER	Not Necessary	27.60 FL	*- FL
17	1		*FRT BUMPER REINFORCEMENT	Bent	231.20 FL	*231.20 FL
18	1		*FRT GRILLE	Cut	137.50 FL	*137.50 FL
19	1		*FRT GRILLE EMBLEM	Necessary	23.40 FL	*23.40 FL
20	1		*FRT BONNET	Bent	433.80 FL	*433.80 FL
21	1		*FRT BONNET INSULATOR	Not Necessary	55.00 FL	*- FL
22	7		*FRT BONNET INSULATOR CLIPS	Not Necessary	26.60 FL	*- FL
23	2		*FRT BONNET HINGE	Repair	62.00 FL	*- FL
24	1		*FRT BONNET LOCK	Repair	90.60 FL	*- FL
25	1		*RR TAIL LAMP LH	Cracked	206.20 FL	*206.20 FL
26	1		*RR SPONGE TRAY	Cracked	220.40 FL	*220.40 FL
27	1		*RR TOOL BOX	Distorted	200.00 FS	*200.00 FS
28	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
29	1		*REAR PARKING REVERSE SENSOR	Not Working	280.00 FS	*200.00 FS
30	1		*FRT NUMBER PLATE	Bent	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,087.60	3,765.00
- List Item Discount on L Items 20.00/20.00% (S\$)	1,106.52	658.00
Total Parts (S\$)	4,981.08	3,107.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCK ,WELD REMOVE AND REPLACE ABOVE PARTS	New	1,500.00	1,200.00
2	TO REMOVE & REFIX RR WINDSCREEN	New	150.00	120.00
3	TO PUTTY & RESPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	1,300.00
4	TO REMOVE & FIX TRIMS	New	150.00	60.00
5	TO CHECK WIRING	New	30.00	30.00
6	TO APPLY ANTI RUST COAT	New	100.00	50.00
Gross Labour Cost (S\$)			3,530.00	2,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >