

S. REC. BY:

REF:

CS/EGT 18014513/4703ⁿ²

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Yee per Li

of

EGT

Date/Time:

13/8/18 @ 11:25am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKT 4270A

Insured:

XD 5423A

at Workshop m/s

Fastech Auto

Tel:

67465405

of

1 Kaki Bkt Ave 6 #01-46

Policy No:

Claim No:

XD 5423A / SL / p

Sum Insured:

Excess:

Make of Veh:

D.O.A. 07/08/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

11:30am @ 13/8/18

Person Contacted:

Nancy

Vehicle:

IN / OUT

Date/Time

Action/Instruction

(✓) Estimate

23/8/18

Revert via email pending estimate

(08/11/13) waf

ASS. REC. BY: MDV/LS

REF:

ER1/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKT4270Aat Workshop m/s Li

of _____

Insured: XD 5423A

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 736

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 15 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTAS6447

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKT4270AYr Regn: 6 15Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: HardemobilioC.C. 1497Colour: white

A/C: Insured / Std / Nil / NA

Sp. Reading: 76091

T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: MRH DD 4870F-P 000121Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185 / 65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 7/8/18D.O.A. 10/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s & Rf.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	roof lining done at 645/10th day 9500
	with 18553
21/2/19	L/S 16500 cost and with other. Cred.
	(Cred: 15666.40 : 32%)

RECEIVED 22 FEB 2019

Date/Time, File Pass to?



: Prel. Report

1) up typst

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 15

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$ _____)



: Interview (\$ _____)



: Tech. Invs (\$ _____)



: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ - R6, \$ _____

Photos _____

Others _____

TOTAL

Report Format: TPLump Sum / I.B.I. (\$) 16500

350



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18014513/Utd3

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 10-08-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 5423A	Veh. Inspected	SKT 4270A
Policy No.		Coverage (\$)	0.00
Claim No.	XD 5423A/SL/pl	Excess (\$)	0.00
Assign From		Assign Date	10/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	07/08/2018	Inspection Date	10/08/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 13 August 2018 11:25 AM
To: 'admin-d@lkkauto.com'
Cc: 'ASSIGNMENTS@LKKAUTO.COM'
Subject: OI : XD5423A / TP : SKT4270A/LKK / DOA : 07/08/2018
Attachments: 3RD VEH - OI - XD5423A - SAS.pdf; 2ND VEH - SKT4270A - SAS.pdf; 2ND VEH - SKT4270A - PRS FORM.pdf; 1ST VEH - GBF4766S - SAS.pdf

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : NANCY LAM @ 6746 5405

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID: +65 6829 9194
Tel: +65 6829 9199
Fax: +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

ERGO

Date: 10.08.2018
Our Reference: XD 5423A/SL/pl
Your Reference: SKT 4270A

To: FASTECH AUTO PTE LTD

Sent via Fax
or
Email nancy.lam@fastechauto.com.sg

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SKT 4270A
Insured's Vehicle: XD 5423A
Date Of Accident: 07.08.2018

We acknowledge receipt of your request for PRS on: 08.08.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK AUTO

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPk	JP Knights Pte Ltd	VAC	Vicom Ltd

☒	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐	Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐	Our Insured's driver has not reported the accident to us todate.
☒	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				<u>FAX : 6829 9247</u>

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 23 August 2018 5:28 PM
To: Admin-D (LKKAuto); 'Survey Report (ERGO Insurance Pte. Ltd.); assignments
Cc: SUR
Subject: RE: XD5423A / TP : SKT4270A/LKK / DOA : 07/08/2018

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SKT 4270A on 10/08/2018
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 13 August 2018 11:30 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments
<assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: XD5423A / TP : SKT4270A/LKK / DOA : 07/08/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Monday, 13 August 2018 11:25 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>
Subject: OI : XD5423A / TP : SKT4270A/LKK / DOA : 07/08/2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 5196G

Vehicle Details

Vehicle No.: SKT4270A

Vehicle to be Exported: No

Intended De-registration Date: 13 Aug 2018

Vehicle Make: HONDA

Vehicle Model: MOBILIO SV 1.5 CVT

Primary Colour: White

Manufacturing Year: 2015

Engine No.: L15Z12100544

Chassis No.: MRHDD4870FP000121

Maximum Power Output: 88.0 kW (118 bhp)

Open Market Value: \$18,676.00

Original Registration Date: 08 Jun 2015

First Registration Date: 08 Jun 2015

Transfer Count: 1

Actual ARF Paid: \$13,676.00 *6838*

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 07 Jun 2025

PARF Rebate Amount: \$10,257.00

Intended COE Rebate Details

COE Expiry Date: 07 Jun 2025

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$67,749.00

COE Rebate Amount: \$46,190.00

Total Rebate Amount: \$56,447.00

The information contained herein is correct as at 10 Aug 2018

OK

- Change in SMRT CEO (Apr 2018), Management & Other...
- Decided to cancel order for BMW but deposit can't...
- SAFRA Card expiring. Should extend?

Honda Mobilio

Price Range

Depreciation

2015

Vehicle Type



Submit

Advanced Search

Home » Used Cars » Car Lingual » Honda Mobilio 1.5A RS i-VTEC Luxe

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



Lalamove -
Get 10% Off

Choose from
different vehicle
types & deliver in
2 hrs.

Lalamove
Compare

Honda Mobilio 1.5A RS i-VTEC Luxe

Overview

Financial

Accessories

Similar

Research

Photos

Map



carlingual
SPEAKING THE DIFFERENT LANGUAGES OF CARS



Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price **\$73,800**Depreciation **\$9,940 /yr**

View models with similar depreciation

Reg Date **17-Apr-2015**
(6yrs 8mths 6days COE left)Manufactured **2015**Mileage **78,000 km (23.5k /yr)**Transmission **Auto**Engine Cap **1,497 cc**Road Tax **\$684 /yr**Power **88.0 kW (118 bhp)**
View specs of the Honda Mobilio (2015-2017)Curb Weight **1,160 kg**Features **1.5L SOHC VTEC Engine, 118Bhp, CVT Auto Transmission, Multi Function Steering Control, Airbags, Climate Control, Retractable Side Mirrors.**Accessories **Leather Seats, Bluetooth Interface, USB And HDMI, GPS Navigation, Reverse Camera And Sensors, Iroad V9 Front And Rear Recorder, Solar Film.**Description **1 Owner Only, Beautiful White Unit From Agent That Comes With 5 Years Warranty. Fuel Efficient 7 Seaters MPV! Please Feel Free To Call Our Friendly Sales Consultants Now For More Details.**COE **\$65,001**OMV **\$19,587**ARF **\$14,587**Dereg Value **\$54,411 as of today (change)**No. of Owners **1**Type of Veh **MPV**Category **PARF Car**Availability **Available**

Add to Shortlist

Add to Compare

Add a Note



Location Map



Price Analysis

Seller Information

Company

Car Lingual

» dealer's pricelist

» 13 vehs sold | 19 vehs available

Address

1 Bukit Batok Crescent #04-58/59/60/61

Search cars nearby this location

Location

WCEGA Plaza

Office No

64633777



Honda Mobilio

Price Range

Depreciation

2015

Vehicle Type



Submit

Advanced Search

Home » Used Cars » Kah Motor » Honda Mobilio 1.5A RS i-VTEC Luxe

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Honda Mobilio 1.5A RS i-VTEC Luxe

Overview

Financial

Accessories

Similar

Research

Photos

Map

PREMIUM AD

KAHMOTOR
 (A MEMBER OF ORIENTAL HOLDINGS GROUP)

KAH CERTIFIED PRE-OWNED CARS.
 CHECKED BY EXPERTS. APPROVED BY YOU.

KAH CERTIFIED
 Pre-owned
Add to Shortlist
Tweet

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price **\$79,900**Depreciation **\$10,130 /yr**

View models with similar depreciation

Reg Date **22-Jul-2015**

(6yrs 11mths 11days COE left)

Manufactured **2015**Mileage **63,100 km (20.7k /yr)**Transmission **Auto**Engine Cap **1,497 cc**Road Tax **\$684 /yr**Power **88.0 kW (118 bhp)**
View specs of the Honda Mobilio (2015-2017)Curb Weight **1,160 kg**Features **Leather Seat, Sport Rims, video Recording
Camera, reverse Camera And New Paint Work.**Accessories **-**Description **Warranty Expire In 21/7/2020.**COE **\$66,000**OMV **\$18,935**ARF **\$18,935**Dereg Value **\$60,076 as of today (change)**No. of Owners **1**Type of Veh **MPV**Category **PAFF Car, Premium Ad Car**Availability **Available**

PREMIUM AD

Add to Shortlist

Add to Compare

Add a Note

Posted on: 09-Jun-2018 | Last Updated on: 26-Jun-2018

Tags: Honda Mobilio, 2015 Honda Mobilio, Honda, Mobilio, Used Honda



Price Analysis

Seller Information

Company

Kah Motor

 • dealer's pricelist
 • 0 vehs sold | 3 vehs available

Address

370 Ubi Road 3

Search cars nearby this location

Office No

68406888

Contact Person(s)

Honda

96602010

Upfront Payment

* more Financial info

Transfer Fee

\$25

?

moneysmart.sg/home-loan

Compare

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

NOT Allowed
N/A
10/8/18
2/5 165000
1527.

VEHICLE NO: SKT 4270A

QTY	PARTICULAR		
1 PCS	REAR WINDSCREEN	825.60	shopped \$1,200.60 ✓
1 PCS	REAR WINDSCREEN MOULDING	112.30	rec \$161.10 ✓
1 PCS	REAR WINDSCREEN INNER TRIM O/S		11 \$845.10 X
1 PCS	TAILGATE	1125	Body \$1,266.30 ✓
1 PCS	TAILGATE 'H' LOGO	32.50	rec \$45.80 ✓
1 PCS	TAILGATE MOBILIO EMBLEM	45.00	rec \$48.80 ✓
1 PCS	TAILGATE 'RS' EMBLEM	42.00	rec \$45.00 ✓
1 PCS	TAILGATE EMBLEM O/S	46.20	rec \$48.80 ✓
2 PCS	TAILGATE REFLECTORS @\$488.10	214.30	o/s 310 \$976.20 1PC
1 PCS	TAILGATE OUTER GARNISH	215.30	Dis/cue \$385.40 ✓
1 PCS	TAILGATE INNER LOCK	178.20	twi/ym \$266.20 ✓
1 PCS	TAILGATE LOCK STRIKER		11 \$68.50 X
1 PCS	TAILGATE INNER TRIM BOARD	285.80	De/cue \$650.10 ✓
1 SET	TAILGATE INNER TRIM BOARD CLIPS		rec \$50.00 ✓
1 PCS	TAILGATE WEATHERSTRIP	101.50	twi \$188.20 ✓
1 PCS	TAILGATE TOP SPOILER	650.00	5 na \$850.00 ✓
2 PCS	TAILGATE HINGES @\$150.00	95.00	o/s 310 \$300.00 1PC
1 PCS	TAILGATE REAR WIPER MOTOR		11 \$422.10 X
1 PCS	REAR BUMPER	463.70	o/s \$845.10 ✓
2 PCS	REAR BUMPER SIDE RETAINERS @\$45.00		3ent \$90.00 ✓
1 SET	REAR BUMPER CLIPS		rec \$50.00 ✓
1 PCS	REAR BUMPER TOP PROTECTOR	241.50	o/s \$311.20 ✓
1 PCS	REAR BUMPER TOP PROTECTOR CHROME	112.80	cue \$288.50 ✓
1 PCS	REAR BUMPER REFLECTOR O/S	45.00	cue \$85.00 ✓
1 PCS	REAR END PANEL	314.70	Body \$611.20 ✓
1 PCS	REAR END PANEL TOP GARNISH		twi \$298.30 ✓
1 PCS	REAR FENDER O/S	1064.30	o/s \$1,105.10 ✓
1 PCS	REAR FENDER GLASS O/S	720.50	shopped \$880.50 ✓
1 PCS	REAR FENDER INNER TRIM BOARD	466.01	o/s \$620.10 ✓
1 PCS	REAR FENDER INNER HOUSING PANEL O/S		Body \$971.10 ✓
1 PCS	REAR FENDER UNDERSHIELD O/S	121.50	Twia \$188.20 ✓
1 PCS	REAR EXHAUST		rec \$688.50 X
1 SET	REAR FENDER UNDERSHIELD CLIPS O/S		rec \$30.00 ✓
1 PCS	REAR AIR VENT O/S		11 \$65.00 X
2 PCS	TAILLAMPS @\$680.10	280.50	o/s 310 \$1,360.20 1PC
1 PCS	TAILLAMP HOUSING PANEL O/S	184.20	Dis \$299.20 ✓
1 PCS	REAR DOOR O/S	745.30	3ent \$1,008.10 ✓
1 PCS	REAR DOOR INNER LOCK O/S	299.20	twi/ym \$311.20 ✓
1 PCS	REAR DOOR INNER TRIM BOARD O/S	481.50	De/cue \$788.20 ✓
1 SET	REAR DOOR INNER TRIM BOARD CLIPS O/S		rec \$50.00 ✓
1 PCS	REAR DOOR GLASS REGULATOR O/S		11 \$299.10 X

207

1 PCS	REAR DOOR GLASS REGULATOR MOTOR O/S	1 1	\$488.20	X
1 PCS	REAR FENDER INNER TOP GARNISH O/S 245-60	1 3	\$311.20	✓
1 PCS	REAR FENDER INNER SPEAKER O/S	CR	\$250.00	✓
1 PCS	ROOF LINING TRIM 1066-50	De/napth	\$1,488.10	✓
1 PCS	ROOF LINING TRIM CLIPS	ser	\$50.00	✓
1 PCS	REAR FLOOR PANEL	crnapth/ser	\$1,120.10	✓
1 PCS	REAR FLOOR PANEL TOP BOARD	NF	\$660.10	X
1 PCS	REAR FLOOR SIDE PANEL O/S	Soly, D	\$299.20	✓
1 PCS	REAR BACK ROLL SEAT	~	\$722.50	X
1 PCS	REAR BACK ROLL SEAT COVER O/S	De	\$85.00	✓
1 PCS	BONNET	~	\$866.20	X
1 PCS	FRONT BUMPER 512-30	10/De	\$745.30	✓
2 PCS	FRONT BUMPER SIDE RETAINERS @ \$45.00	Best	\$90.00	✓
1 SET	FRONT BUMPER CLIPS	De	\$35.00	✓
2 PCS	FRONT BUMPER FOG LAMPS @ \$420.00 305-x2=610	CR	\$840.00	✓
2 PCS	FRONT BUMPER FOG LAMP COVERS \$125.00 85-x2=170	FWI	\$250.00	✓
1 PCS	FRONT BUMPER CENTRE GRILLE 182-30	De/FWI	\$211.20	✓
1 PCS	FRONT BUMPER REINFORCEMENT	DD	\$315.30	✓
1 PCS	FRONT GRILLE 242-60	CR	\$300.60	✓
1 PCS	FRONT GRILLE OUTER CHROME 250-00	CR	\$322.30	✓
1 PCS	FRONT GRILLE 'H' LOGO	De	\$38.50	✓
2 PCS	FRONT BUMPER FOG LAMP CHROME MOULDINGS @ \$118.00 85-x2=170	De	\$236.00	✓
1 PCS	FRONT SUPPORT PANEL	~	\$544.20	X
1 PCS	FRONT SUPPORT PANEL TOP GARNISH	1 1	\$211.90	X
2 PCS	HEADLAMPS @ \$1500.00 820-20 x2 = 1640-40	CR	\$3,000.00	✓
1 PCS	AIR CON CONDENSER	1 1	\$866.20	X
1 PCS	RADIATOR	1 1	\$1,422.30	X
1 PCS	RADIATOR FAN MOTOR	1 1	\$388.00	X
1 PCS	RADIATOR FAN BLADE	1 1	\$105.00	X
1 PCS	RADIATOR FAN COWLING	1 1	\$145.00	X
2 PCS	FRONT FENDERS @ \$681.00	~	\$1,362.00	X
2 PCS	FRONT FENDER INNERSHIELDS @ \$115.00	1 1	\$230.00	X
1 PCS	ALTERNATOR	1 1	\$1,205.00	X
			\$38,266.40	
	S.NETT			
1 PCS	REAR LICENCE PLATE W/HOLDER	1 1	\$50.00	X
1 SET	REAR BUMPER REVERSE SENSOR	short	\$280.00	200
1 PCS	REAR WINDSCREEN SOLAR FILM	ser	\$280.00	180
1 PCS	REAR FENDER GLASS SOLAR FILM	ser	\$250.00	120
1 PCS	REAR END PANEL SEALANT	ser	\$50.00	✓
1 SET	REAR FLOOR PANEL INSULATOR	ser	\$180.00	✓
1 PCS	REAR SPORT RIM O/S	SOL	\$600.00	X
1 SET	REAR DOOR FRAME BLACK STICKER O/S	ser	\$80.00	60
1 PCS	FRONT LICENCE PLATE W/HOLDER	3rd	\$50.00	40
1 BOT	RADIATOR COOLANT	1 1	\$50.00	X
	LABOUR CHARGES:			
	TOWING CHARGE		\$120.00	60
	TO CHECK WIRING		\$80.00	30

202

16376.61

14701.28

TO DISMANTLE & REPLACING REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REPLACING REAR WINDSCREEN	\$150.00	120
TO DISMANTLE & REPLACING REAR FENDER GLASS O/S	\$150.00	100
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY	\$150.00	100
TO DISMANTLE & REFIX REAR EXHAUST	\$100.00	60
TO MOUNT VEHICLE ON CAR O-LINER	11 \$380.00	X
TO DISMANTLE & REFIX REAR DOOR MECHANISM	\$100.00	60
TO REFILL AIR CON GAS	11 \$120.00	X
TO SPRAY RUST PROOFING	\$300.00	120
LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTED & REPLACING PARTS	\$3,800.00	2400
TO PUTTY & SPRAY PAINTING	\$3,000.00	2000
TO	\$48,666.40	

20631.48

Like Auto Components hereby notify

(its Repairer) of the following:

- To resurvey paint after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18014513/Utd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 26-02-2019		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 5423A	Veh. Inspected	SKT 4270A	
Policy No.		Coverage (\$)	0.00	
Claim No.	XD 5423A/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	13/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA MOBILIO (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	MRHDD4870FP000121	Colour	WHITE	
Odometer	76091	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	DUNLOP	6 mm	
L/H Front Tyre	185/65 R15	DUNLOP	6 mm	
R/H Rear Tyre	185/65 R15	DUNLOP	6 mm	
L/H Rear Tyre	185/65 R15	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/08/2018	Inspection Date	10/08/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 4270A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN	SHATTERED	1,200.60	825.60
1	REAR WINDSCREEN MOULDING	NECESSARY	161.10	112.30
1	REAR WINDSCREEN INNER TRIM O/S	NOT NECESSARY	845.10	-
1	TAILGATE	BADLY DENTED	1,266.30	1,125.00
1	TAILGATE "H" LOGO	NECESSARY	45.80	32.50
1	TAILGATE MOBILIO EMBLEM	NECESSARY	48.80	45.00
1	TAILGATE "RS" EMBLEM	NECESSARY	45.00	42.00
1	TAILGATE EMBLEM O/S	NECESSARY	48.80	46.20
2	TAILGATE REFLECTORS @\$488.10	O/S BROKEN	976.20	214.30
1	TAILGATE OUTER GARNISH	DISTORTED / CRACKED	385.40	215.30
1	TAILGATE INNER LOCK	TWISTED / JAMMED	266.20	178.20
1	TAILGATE LOCK STRIKER	NOT NECESSARY	68.50	-
1	TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	650.10	285.80
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	50.00	50.00
1	TAILGATE WEATHERSTRIP	TWISTED	188.20	101.50
1	TAILGATE TOP SPOILER	CRACKED	850.00	650.00
2	TAILGATE HINGES @\$150.00	O/S BENT	300.00	95.00
1	TAILGATE REAR WIPER MOTOR	NOT NECESSARY	422.10	-
1	REAR BUMPER	DISTORTED	845.10	463.70
2	REAR BUMPER SIDE RETAINERS @\$45.00	BENT	90.00	90.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR BUMPER TOP PROTECTOR	DISTORTED	311.20	241.50
1	REAR BUMPER TOP PROTECTOR CHROME	CRACKED	288.50	112.80
1	REAR BUMPER REFLECTOR O/S	CRACKED	85.00	45.00
1	REAR END PANEL	BADLY DENTED	611.20	314.70
1	REAR END PANEL TOP GARNISH	TWISTED	298.30	298.30
1	REAR FENDER O/S	DISTORTED	1,105.10	1,064.30
1	REAR FENDER GLASS O/S	SHATTERED	880.50	720.50
1	REAR FENDER INNER TRIM BOARD	DISTORTED	620.10	466.01

Report Ref No. CS/EG18014513/Utd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER INNER HOUSING PANEL O/S	BADLY DENTED	971.10	971.10
1	REAR FENDER UNDERSHIELD O/S	TORN	188.20	121.50
1	REAR EXHAUST	TO REPAIR SEE LABOUR	688.50	-
1	SET REAR FENDER UNDERSHIELD CLIPS O/S	NECESSARY	30.00	30.00
1	REAR AIR VENT O/S	NOT NECESSARY	65.00	-
2	TAILLAMPS @\$680.10	O/S BROKEN	1,360.20	280.50
1	TAILLAMP HOUSING PANEL O/S	DISTORTED	299.20	184.20
1	REAR DOOR O/S	BENT / BUCKLED	1,008.10	745.30
1	REAR DOOR INNER LOCK O/S	TWISTED / JAMMED	311.20	299.20
1	REAR DOOR INNER TRIM BOARD O/S	DEFORMED / CRACKED	788.20	481.50
1	SET REAR DOOR INNER TRIM BOARD CLIPS O/S	NECESSARY	50.00	50.00
1	REAR DOOR GLASS REGULATOR O/S	NOT NECESSARY	299.10	-
1	REAR DOOR GLASS REGULATOR MOTOR O/S	NOT NECESSARY	488.20	-
1	REAR FENDER INNER TOP GARNISH O/S	DISTORTED	311.20	245.60
1	REAR FENDER INNER SPEAKER O/S	CRACKED	250.00	250.00
1	ROOF LINING TRIM	DEFORMED / WARPED	1,488.10	1,066.50
1	ROOF LINING TRIM CLIPS	NECESSARY	50.00	50.00
1	REAR FLOOR PANEL	CRUMPLED / BUCKLED	1,120.10	1,120.10
1	REAR FLOOR PANEL TOP BOARD	NOT FITTED	660.10	-
1	REAR FLOOR SIDE PANEL O/S	BADLY DENTED	299.20	299.20
1	REAR BACK ROLL SEAT	TO REPAIR SEE LABOUR	722.50	-
1	REAR BACK ROLL SEAT COVER O/S	DEFORMED	85.00	85.00
1	BONNET	TO REPAIR SEE LABOUR	866.20	-
1	FRONT BUMPER	DENTED / DEFORMED	745.30	512.30
2	FRONT BUMPER SIDE RETAINER @\$45.00	BENT	90.00	90.00
1	SET FRONT BUMPER CLIPS	NECESSARY	35.00	35.00
2	FRONT BUMPER FOG LAMPS @\$420.00	CRACKED	840.00	610.00
2	FRONT BUMPER FOG LAMP COVERS @\$125.00	TWISTED	250.00	170.00

Report Ref No. CS/EG18014513/Utd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER CENTRE GRILLE	DEFORMED / TWISTED	211.20	182.30
1	TWISTED REINFORCEMENT	DENTED	315.30	315.30
1	FRONT GRILLE	CRACKED	300.60	242.60
1	FRONT GRILLE OUTER CHROME	CRACKED	322.30	250.00
1	FRONT GRILLE "H" LOGO	NECESSARY	38.50	38.50
2	FRONT BUMPER FOG LAMP CHROME MOULDINGS @\$118.00	NECESSARY	236.00	170.00
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	544.20	-
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	211.90	-
2	HEADLAMPS @\$1500.00	CRACKED	3,000.00	1,640.40
1	AIR CON CONDENSER	NOT NECESSARY	866.20	-
1	RADIATOR	NOT NECESSARY	1,422.30	-
1	RADIATOR FAN MOTOR	NOT NECESSARY	388.00	-
1	RADIATOR FAN BLADE	NOT NECESSARY	105.00	-
1	RADIATOR FAN COWLING	NOT NECESSARY	145.00	-
2	FRONT FENDERS @\$681.00	TO REPAIR SEE LABOUR	1,362.00	-
2	FRONT FENDER INNERSHIELDS @\$115.00	NOT NECESSARY	230.00	-
1	ALTERNATOR	NOT NECESSARY	1,205.00	-
	LESS 20% DISCOUNT		-	-3,684.32
			38,266.40	14,737.29
	<u>SPECIAL NETT ITEMS</u>			
1	REAR LICENCE PLATE W/HOLDER (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR WINDSCREEN SOLAR FILM (SN)	NECESSARY	280.00	180.00
1	REAR FENDER GLASS SOLAR FILM (SN)	NECESSARY	250.00	120.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	SET REAR FLOOR PANEL INSULATOR (SN)	NECESSARY	180.00	180.00
1	REAR SPORT RIM O/S (SN)	SERVICEABLE	600.00	-
1	SET REAR DOOR FRAME BLACK STICKER O/S (SN)	NECESSARY	80.00	60.00
1	FRONT LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00

Report Ref No. CS/EGI18014513/Utd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOT RADIATOR COOLANT (SN)	NOT NECESSARY	50.00	-
			1,870.00	830.00
	LABOUR			
	TOWING CHARGE.		120.00	60.00
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REPLACING REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REPLACING REAR FENDER GLASS O/S.		150.00	100.00
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		150.00	100.00
	TO DISMANTLE & REFIX REAR EXHAUST.		100.00	60.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	TO DISMANTLE & REFIX REAR DOOR MECHANISM.		100.00	60.00
	TO REFILL AIR CON GAS.	NOT NECESSARY	120.00	-
	TO SPRAY RUST PROOFING.		300.00	120.00
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEDED & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR EXHAUST,REAR BACK ROLL SEAT,BONNET,FRONT SUPPORT PANEL AND FRONT FENDERS.		3,800.00	2,400.00
	TO PUTTY & SPRAY PAINTING.		3,000.00	2,000.00
			8,530.00	5,100.00
	GRAND TOTAL		48,666.40	20,667.29
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			16,500.00

Report Ref No. CS/EGI18014513/Utd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.