

ASS. REC. BY

REF

03/CTI18014520/And3

Special Instructions

Survivor
Merrimen

Adrian

ASSIGNMENT (Office)

From (Person)

Irene Juy

of

CTI

Date/Time

8/8/18 @ 5:04pm

Estimated Cost

Bill to

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 382 D

Insured:

GBE 2947E

at Workshop m/s

Sk Automobile

Tel:

81210478

of

8 Kewei Blvd Ave 4 #08-16

Policy No:

DMCVSN 3077301700

Claim No:

SNM18D0386102

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

8/8/18

CA / REV / REP. / REV 24 HRS

'up

H.O.D. Endorsement:

Date/Time:

9:37am @ 10/8/18

Person Contacted:

Xiang

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SLE 382 D - NA / AIG / 8/8/18 / 13	DOA: 8/8/2018
	GBE 2947E - NA / AIG / 8/8/18 / 13	DOA: 8/8/18
	US \$16600, 8 days (Red & 18001.27, 52%)	

(08/11/13) #ref

ASS. REC. BY:

REF: CFI

ASSIGNMENT

From: Date: 10/8/2018

Estimated Cost:

On: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLE 382D

at Workshop m/s SK Automobile
of 8 Kuala Selat Ave 4 #08-46

Insured:

Policy No.:

Claims No.:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLE 382D. Yr Regn: 2016 / July.

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Lexus NX200 C.C. 1998

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 35476 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTJBARBZ 702083420

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 225/60R18.

R: 225/60R18.

☒ BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I. 10/08/18

Survey held at S.K

Des. of Damages: Frt / ☒ Rea / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Check.

RECEIVED 20 FEB 2019

Date/Time, File Pass to?

1) 28/1 - twist

Date/Time, File Return to?

2)

☐ : Prel. Report☐ : Final Report

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 16600

MER-TP



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CT118014520/Aqd3

3 ANSON ROAD #16-00

SPRINGLEAF TOWERS SINGAPORE 079909

Date : 10-08-2018



Code : CTI

1.

Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 2947E	Veh. Inspected	SLE 382D
Policy No.	DMCVSN3077301700	Coverage (\$)	0.00
Claim No.	SNM18D03861C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	10/08/2018

2.

Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3.

Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4.

Description of Damages

5.

General Information

Accident Date	08/08/2018	Inspection Date	10/08/2018
Survey held at	SK AUTOMOBILE PTE LTD 23 KAKI BUKIT AVE 4 # 03-01 SINGAPORE 415933		

5a.

Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Aug 2018		08 Aug 2018 17:04 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:			
Main Claimant:	NG PENG HENG(HUANG BINGXING)		
Vehicle Reg. No.:	SLE382D	Date of Loss:	08/08/2018 00:00 - :59
Claim Type:	TP / SNM18D03861C02	Policy/Cover Note No.:	DMCVSN3077301700
Vehicle Reg. No. (Insured):	GBE2947E	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Sk Automobile Pte Ltd () 8 Kaki Bukit Ave 4, #08-46 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel: 8121 0478		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/08/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN ADRAIN LING AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

10/08/2018 @ 9:37am

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 2865B

Vehicle Details

Vehicle No.: SLE382D
Vehicle to be Exported: Yes
Intended De-registration Date: 08 Aug 2018
Vehicle Make: TOYOTA
Vehicle Model: LEXUS NX200T EXECUTIVE
Primary Colour: White
Manufacturing Year: 2016
Engine No.: 8ARW309622
Chassis No.: JTJBARBZ702083420
Maximum Power Output: 175.0 kW (234 bhp)
Open Market Value: \$41,966.00
Original Registration Date: 13 Jul 2016
First Registration Date: 13 Jul 2016
Transfer Count: 0
Actual ARF Paid: \$50,753.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 12 Jul 2026
PARF Rebate Amount: \$38,064.00

Intended COE Rebate Details

COE Expiry Date: 12 Jul 2026
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$56,000.00
COE Rebate Amount: \$44,393.00
Total Rebate Amount: \$82,457.00

The information contained herein is correct as at 08 Aug 2018

OK

70k

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Apr 2011 Audi A4 1.8A 8Speed@47,500 Deprec \$108



91% Down/Over Loan \$8K Fr
2.78% Fr \$1,122/Mth 100%
Loan: No Guarantee
Privilege Motors 304551



Browse by Category

Sort by Date Posted

20 results/page

8 vehicles

Lexus NX

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Lexus NX	Any	Any	2016	Any	Any	Any	Available



Lexus NX Turbo NX200t Classic

\$150,800

\$15,630 /yr

23-Sep-2016

1,998 cc

33,700 km

SUV

Available

Down Payment From \$15,280! 1 Owner Since New. Fully Serviced And Maintained By Borneo Motors. Most Reliable And Luxurious SUV With 5 Years Warranty And 3 Years/60,000km Free Servicing By Lexus Singapo...

Dynamic Motoring

Posted: 08-Aug-2018 Tags: 2016 Lexus NX, Lexus NX, Lexus, NX, Used Lexus



Lexus NX Turbo NX200t F Sport

\$175,000

\$18,070 /yr

14-Sep-2016

1,998 cc

45,000 km

SUV

Available

Luxury Graphite Black With 2 Tone Interior Leather Seats. Agent Unit. Full Agent Serviced With 5 Years Agent Warranty With Unlimited Mileage. Signature Lexus NX Turbo. 1 Of The Most Welcome Unit With ...

Euro Performance Asia Pte Ltd

Posted: 07-Aug-2018 Tags: 2016 Lexus NX, Lexus NX, Lexus, NX, Used Lexus



Lexus NX Turbo NX200t Luxury

\$153,888

\$16,170 /yr

29-Apr-2016

1,998 cc

37,000 km

SUV

Available

Nice Number, High PARF Value, New Road Tax, Price Negotiable, Please Call Owner For Discussion, Owner Upgrading.

Posted: 07-Aug-2018 Tags: 2016 Lexus NX, Lexus NX, Lexus, NX, Used Lexus



Lexus NX Turbo NX200t Executive

\$157,800

\$16,310 /yr

19-Sep-2016

1,998 cc

9,300 km

SUV

Available

Special Interest Rate Of 1.98%! No Gimmicks, Act Fast! 1 Owner, 5 Years Warranty And Servicing Package With Borneo Motors. Incredibly Low Mileage At Only 8300 Kms. This Executive Unit Comes With Navig...

Auto Zoom Enterprise Pte Ltd

Posted: 05-Aug-2018 Tags: 2016 Lexus NX, Lexus NX, Lexus, NX, Used Lexus

Car buying

Car Selling

Car Ownership

Buying a pre-owned car, but unsure of its Condition?
Get STA Car Evaluation

Car Aftermarket

On The Move

Lifestyle



Lexus NX Turbo NX200t Luxury

\$147,800

\$15,980 /yr

14-Jan-2016

1,998 cc

56,000 km

SUV

Available

Absolutely The Most Value For Money SUV In Town! Road Tax Renewed Another 6 Mths From Jul, New Premium Continental Sports Contact-5 Tyres, Steedmate TPMS, Stock Speakers Upgraded, Sound Proofing Done ...

Posted: 02-Aug-2018 Tags: 2016 Lexus NX, Lexus NX, Lexus, NX, Used Lexus



Lexus NX Turbo NX200t Luxury

\$159,800

\$16,880 /yr

09-May-2016

1,998 cc

34,500 km

SUV

Available

Hard To Find And Rare Lexus NX In This Colour Combination. Car In Mint Condition. 3M Crystalline Solar Film. Ceramic Paint Protection. Low Mileage. Service Just Done At Agent. New Battery.

Posted: 28-Jul-2018 Tags: 2016 Lexus NX, Lexus NX, Lexus, NX, Used Lexus

Lexus NX Turbo NX200t Executive

\$155,800

\$15,530 /yr

30-Dec-2016

1,998 cc

22,545 km

SUV

Available

Compare

\$2000 Republic Auto Service Credit, 5 Years Agent Warranty, 5 Years Agent Maintenance Package, Maintained At Lexus, 1 Owner, Well Maintained, Enjoy Exclusive Interest Rates At 2.78%, 60% Loan, Please ...



MNA116102642 / National Assessment Centre Services - Ubl
ENTRY DATE & TIME: 08/08/2018 15:02
SUBMITTED BY: Roslinda Binia Abdul Wahab

SINGAPORE ACCIDENT STATEMENT**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/08/2018 15:02
Date Of Accident	08/08/2018 07:35
Exact Location Of Accident	PIE SLIP RD TWDS TAMPINES AVE 5
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE382D
Insured/Policyholder	
Name Of Registered Owner	NG PENG HENG(HUANG BINGXING)
NRIC No	S7432865B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96153867
Alternative Phone No	OTHERS-96153867

Vehicle Particulars

Manufacturer	LEXUS
Model	NX200T
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100474625-02
Cover Note Number	

Driver

Name of Driver	NG PENG HENG(HUANG BINGXING)
NRIC No	S7432865B
Date Of Birth	30/09/1974
Occupation	INDOOR
Date Of Driving Pass	16/02/1994
Driving Experience	24 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96153867
Fax Number	
Contact Number	OTHERS-96153867
Email Address	NOEMAIL

Address 27 ELIAS ROAD
#01-15
Postcode 519932
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBE2947E
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver ZHUANG XUE LIANG
NRIC/Passport Number S7383086I
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name NG PENG HENG(HUANG BINGXING)

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SLIGHT

SLE382D

YES

NO


Accident Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claim and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used in compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

 08/08/18
Receiving Centre Personnel's Signature
Name:
NRIC/FIN No.:

Individual Statement

SKETCH PLAN



A: SLE 382.D

B: GBE 2947E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 8/8/18 @ 0735 hrs, I was travelling on PIE sliproad towards Tampines Ave 5.

There was a zebra-crossing in front of me. I stopped to allow a pedestrian to cross.

Suddenly vehicle B, GBE 2947E bang into my rear and caused severe damages to my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/VIN No.:

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	: CHINA TAIPING	DATE	: 8-Aug-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SLE382D
ADDRESS	:	MODEL	: TOYOTA LEXUS NX
TEL. NO.	:	CHASSIS NO	:
<u>ACCIDENT DETAILS</u>	DATE :	JTJBARBZ702083420.	
	TIME :		
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE Distorted.	1	\$ 2,215.60	\$ 2,215.60
2	TAIL GATE LOCK C/W MOTOR 2nd.	1	\$ 899.60	\$ 899.60
3	TAILGATE LOCK COVER lt	1	\$ 52.10	\$ 52.10
4	TAIL GATE WEATHERSTRIP lt	1	\$ 289.70	\$ 289.70
5	TAIL GATE LOGO 2	1	\$ 76.50	\$ 76.50
6	TAILGATE EMBLEM 'LEXUS' New	1	\$ 65.90	\$ 65.90
7	TAILGATE EMBLEM 'NX200T'	1	\$ 69.60	\$ 69.60
8	TAILGATE REFLECTOR LH cut, RH cracked	2	\$ 528.20	\$ 1,056.40
9	TAILGATE TOP OUTER GARNISH cracked.	1	\$ 785.20	\$ 785.20
10	TAILGATE CHROME lt	1	\$ 212.30	\$ 212.30
11	TAILGATE DAMPER MOTOR Not New	1	\$ 689.20	\$ 689.20
12	TAILGATE INNER TRIM cracked	1	\$ 525.90	\$ 525.90
13	TAILGATE SIDE TRIM lt	2	\$ 258.00	\$ 516.00
14	TAILGATE CENTRE TRIM cut	1	\$ 359.40	\$ 359.40
15	TAILGATE WIPER MOTOR not Reched	1	\$ 658.50	\$ 658.50
16	TAILGATE WIPER ARM Missing	1	\$ 289.00	\$ 289.00
17	TAILGATE WINDSCREEN GLASS Shattered	1	\$ 1,459.00	\$ 1,459.00

1485.50
745

20	TAILGATE WINDSCREEN GLASS MOULDING <i>Neu</i>	1	\$ 189.00	\$ 189.00	✓
18	TAILGATE SIDE GARNISH <i>3 AM</i>	2	\$ 278.10	\$ 556.20	+
19	TAILGATE CENTRE GARNISH	1	\$ 542.10	\$ 542.10	+
21	TAILGATE NUMBER PLATE LAMP <i>Neu</i>	2	\$ 169.80	\$ 339.60	+
22	TAILGATE THIRD BRAKE LIGHT <i>Neu</i>	1	\$ 398.70	\$ 398.70	+
23	TAILGATE SPEAKER <i>Not Neu</i>	1	\$ 689.00	\$ 689.00	+
24	TAILGATE REVERSE CAMERA <i>Damaged</i>	1	\$ 627.00	\$ 627.00	✓
25	TAILGATE DETECTOR <i>crushed</i>	1	\$ 321.00	\$ 321.00	✓
26	TAILGATE ALARM CONTROL BOX UNIT <i>crushed</i>	1	\$ 825.20	\$ 825.20	✓
27	TAILAMP <i>LH ut, RH crushed</i>	2	\$ 859.60	\$ 1,719.20	1377.20.
28	TAILAMP PANEL <i>Repair</i>	2	\$ 459.00	\$ 459.00	+
29	REAR FENDER INNER TRIM <i>3 pieces crushed</i>	2	\$ 1,025.00	\$ 2,050.00	1500.
30	REAR FENDER INNER COWLING <i>Neu</i>	2	\$ 289.00	\$ 578.00	+
31	REAR FENDER WHEEL ARCH GARNISH <i>Neu</i>	2	\$ 255.00	\$ 510.00	+
32	REAR BUMPER <i>Distorted</i>	1	\$ 1,586.20	\$ 1,586.20	627
33	REAR BUMPER LOWER <i>Distorted</i>	1	\$ 685.20	\$ 685.20	594.
34	REAR BUMPER REFLECTOR <i>Not Neu</i>	2	\$ 185.60	\$ 371.20	+
35	REAR BUMPER SIDE RETAINER <i>Neu</i>	2	\$ 81.90	\$ 163.80	-
36	REAR BUMPER SPONGE <i>Not Neu</i>	1	\$ 266.90	\$ 266.90	+
37	REAR BUMPER REINFORCEMENT <i>Beut</i>	1	\$ 799.60	\$ 799.60	588.
39	REVERSE SENSOR <i>2 pieces damaged</i>	4	\$ 321.00	\$ 1,284.00	560.
40	REAR END PANEL <i>Distorted</i>	1	\$ 798.60	\$ 798.60	627
41	REAR END PANEL TOP GARNISH <i>Deland</i>	1	\$ 425.20	\$ 425.20	✓
42	REAR END PANEL AIR VENT <i>crushed</i>	2	\$ 112.20	\$ 224.40	✓
43	REAR FLOOR PANEL TOP BOARD <i>Deland</i>	1	\$ 512.90	\$ 512.90	✓
44	REAR FLOOR PANEL SIDE TRAY RH <i>Deland</i>	1	\$ 411.00	\$ 411.00	✓
45	REAR FLOOR PANEL SIDE TRAY LH <i>Deland</i>	1	\$ 498.00	\$ 498.00	✓
46	REAR FLOOR PANEL SPONGE <i>Not Neu</i>	1	\$ 198.60	\$ 198.60	+
47	REAR FLOOR PANEL SIDE BOARD RH <i>Neu</i>	1	\$ 70.80	\$ 70.80	+
48	REAR EXHAUST SILENCER <i>2 pieces Beut</i>	1	\$ 2,526.00	\$ 2,526.00	1175.50
49	REAR EXHAUST MOUNTING <i>Same as Neu</i>	2	\$ 32.00	\$ 64.00	+

19909.60
17918.64

TOTAL PRICE \$ 30,910.30
LESS 10% \$ 3,091.03
SUB TOTAL PRICE \$ 27,819.27

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP <i>Neu</i>	10	\$ 6.50	\$ 65.00
2	TAIL GATE INNER BOARD CLIP <i>Neu</i>	10	\$ 6.50	\$ 65.00
3	TAIL GATE EMBLEM (BORNEO MOTOR) <i>Neu</i>	1	\$ 80.00	\$ 80.00

30

50

+

4	TAILGATE WINDSCREEN TINTED GLASS <i>Neu</i>	1	\$	500.00	\$	500.00	200
5	TAILGATE WINDSCREEN SEALANT <i>Neu</i>	1	\$	80.00	\$	80.00	30
6	TAILGATE WIPER BLADE <i>Missing</i>	1	\$	50.00	\$	50.00	28
7	TAILGATE WINDSCREEN INNER SEAL <i>Neu</i>	1	\$	60.00	\$	60.00	30
8	REAR VIDEO CAMERA <i>Missing</i>	1	\$	500.00	\$	500.00	380
9	REAR EXHAUST CHROME <i>Neu</i>	2	\$	400.00	\$	800.00	X
10	REAR FENDER INNER TRIM CLIP SET <i>Neu</i>	1	\$	130.00	\$	130.00	80
11	REAR END PANEL TOP GARNISH CLIPS <i>Neu</i>	4	\$	5.50	\$	22.00	10
12	REAR END PANEL INSULATION SEAL <i>Neu</i>	1	\$	150.00	\$	150.00	60
13	REVERSE SENSOR (4PCS) <i>Replaced</i>	1	\$	440.00	\$	440.00	X

855

TOTAL \$ 2,942.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$1,800.00	1000	
2	TO SPRAY PAINT AFFECTED AREA	\$1,400.00	800	
3	TUFF COAT	\$250.00	60	
4	WIRING CHECK	\$50.00	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$180.00	80	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$80.00	50	
7	CONDUCT WATER LEAKAGE TEST	\$80.00	X	

TOTAL \$3,840.00

2020

ESTIMATE REPORT

TOTAL PARTS COST : \$ 30,761.27
TOTAL LABOUR COST : \$ 3,840.00
TOTAL REPAIR COST : \$ 34,601.27

total: 20793.64

1/5: 16.61c ✓

08 Apr

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAY :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

LK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Aug 2018		08 Aug 2018 17:04 Edit Adj Rpt	\$S\$16,600.00 Edit Estimates	\$S\$16,600.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

- ID: -

Main Claimant:

NG PENG HENG(HUANG BINGXING)

Vehicle Reg. No.:

SLE382D

Date of Loss:

08/08/2018 00:00 - :59
[24 Months and 26 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP / SNM18D03861C02

Policy/Cover Note No.:

DMCVSN3077301700

Vehicle Reg. No. (Insured):

GBE2947E

Policy No. (Claimant):

Excess:

\$S\$0.00

Repairer:

Sk Automobile Pte Ltd () 8 Kaki Bukit Ave 4, #08-46 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel: 8121 0478

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 20/08/2018]

Adj Asg. Remarks:

NO EST, ASSIGN ADRAIN LING AS SJE.

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLE382D (SNM18D03861C02)
[GBE2947E]
TP
NG PENG HENG(HUANG BINGXING)
Aug 8 2018 12:00AM
[-]
Sk Automobile Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	28/02/19 09:39	General View						Load JPG	☒	
2	28/02/19 09:39	General View						Load JPG	☒	
3	28/02/19 09:39	General View						Load JPG	☒	
4	28/02/19 09:39	General View						Load JPG	☒	
5	28/02/19 09:39	General View						Load JPG	☒	
6	28/02/19 09:39	General View						Load JPG	☒	
7	28/02/19 09:39	General View						Load JPG	☒	
8	28/02/19 09:39	General View						Load JPG	☒	
9	28/02/19 09:39	General View						Load JPG	☒	
10	28/02/19 09:39	General View						Load JPG	☒	
11	28/02/19 09:39	General View						Load JPG	☒	
12	28/02/19 09:39	General View						Load JPG	☒	
13	28/02/19 09:39	General View						Load JPG	☒	
14	28/02/19 09:39	General View						Load JPG	☒	
15	28/02/19 09:39	General View						Load JPG	☒	
16	28/02/19 09:39	General View						Load JPG	☒	
17	28/02/19 09:39	General View						Load JPG	☒	
18	28/02/19 09:39	General View						Load JPG	☒	
19	28/02/19 09:39	General View						Load JPG	☒	
20	28/02/19 09:39	General View						Load JPG	☒	
21	28/02/19 09:39	General View						Load JPG	☒	
22	28/02/19 09:39	General View						Load JPG	☒	
23	28/02/19 09:39	General View						Load JPG	☒	
24	28/02/19 09:39	General View						Load JPG	☒	
25	28/02/19 09:39	General View						Load JPG	☒	
26	28/02/19 09:39	General View						Load JPG	☒	
27	28/02/19 09:39	General View						Load JPG	☒	
28	28/02/19 09:39	General View						Load JPG	☒	
29	28/02/19 09:39	General View						Load JPG	☒	
30	28/02/19 09:39	General View						Load JPG	☒	
31	28/02/19 09:39	General View						Load JPG	☒	
32	28/02/19 09:39	General View						Load JPG	☒	
33	28/02/19 09:39	General View						Load JPG	☒	
34	28/02/19 09:39	General View						Load JPG	☒	
35	28/02/19 09:39	General View						Load JPG	☒	
36	28/02/19 09:39	General View						Load JPG	☒	
37	28/02/19 09:39	General View						Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	28/02/19 09:39	General View	 Load JPG	☒
39	28/02/19 09:39	General View	 Load JPG	☒
40	28/02/19 09:39	General View	 Load JPG	☒
41	28/02/19 09:39	General View	 Load JPG	☒
42	28/02/19 09:39	General View	 Load JPG	☒
43	28/02/19 09:39	General View	 Load JPG	☒
44	28/02/19 09:39	General View	 Load JPG	☒
45	28/02/19 09:39	General View	 Load JPG	☒
46	28/02/19 09:39	General View	 Load JPG	☒
47	28/02/19 09:39	General View	 Load JPG	☒
48	28/02/19 09:39	General View	 Load JPG	☒
49	28/02/19 09:39	General View	 Load JPG	☒
50	28/02/19 09:39	General View	 Load JPG	☒
51	28/02/19 09:39	General View	 Load JPG	☒
52	28/02/19 09:39	General View	 Load JPG	☒
53	28/02/19 09:39	General View	 Load JPG	☒
54	28/02/19 09:39	General View	 Load JPG	☒
55	28/02/19 09:39	General View	 Load JPG	☒
56	28/02/19 09:39	General View	 Load JPG	☒
57	28/02/19 09:39	General View	 Load JPG	☒
58	28/02/19 09:39	General View	 Load JPG	☒
59	28/02/19 09:39	General View	 Load JPG	☒
60	28/02/19 09:39	General View	 Load JPG	☒
61	28/02/19 09:39	General View	 Load JPG	☒
62	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
63	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
64	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
65	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
66	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
67	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
68	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
69	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
70	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
71	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
72	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
73	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
74	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
75	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
76	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
77	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
78	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
79	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
80	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
81	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
82	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
83	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
84	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
85	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
86	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
87	28/02/19 09:39	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
89	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
90	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
91	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
92	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
93	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
94	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
95	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
96	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
97	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
98	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
99	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
100	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
101	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
102	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
103	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
104	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
105	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
106	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
107	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
108	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
109	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
110	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
111	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
112	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
113	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
114	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
115	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
116	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
117	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
118	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
119	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
120	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
121	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
122	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
123	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
124	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
125	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
126	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
127	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
128	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
129	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
130	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
131	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
132	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
133	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
134	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
135	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
136	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
137	28/02/19 09:39	Reinspection Photo	Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
139	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
140	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
141	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
142	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
143	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
144	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
145	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
146	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
147	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
148	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
149	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
150	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
151	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
152	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
153	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
154	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
155	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
156	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
157	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
158	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
159	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
160	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
161	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
162	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
163	28/02/19 09:39	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/08/18 17:04	PRS	 Load PDF	
2	08/08/18 17:04	TP GIA	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118014520/AQD3Q2

Date: 01/03/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3077301700

Claimant Vehicle
No: SLE382DInsured Vehicle
No: GBE2947E

Date of Loss: 08/08/2018

Nature of Claim: TP

Claim
No: SNM18D03861C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLE382D

Make & Model: LEXUS NX200T, 2.0 (A)

Engine No: 8ARW309622

Reg. Date: 13/07/2016 (Man. Year: 2016)

Chassis No: JTJBARBZ702083420

Colour: White

Odometer: 35476 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R18

Rear Tyre Size: 225/60 R18

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,761.27	18,773.64	11,987.63	38.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,840.00	2,020.00	1,820.00	47.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,601.27	20,793.64	13,807.63	39.90
Approved Total (Overridden) (S\$)		16,600.00		
(S\$)	34,601.27	16,600.00	18,001.27	52.02
+ GST 7.00/7.00% (S\$)	2,422.09	1,162.00	1,260.09	52.02
Nett Amount (S\$)	37,023.36	17,762.00	19,261.36	52.02

INSPECTION

Date of Assignment: 08/08/2018

Date Inspected: 10/08/2018 Inspected At:

Sk Automobile Pte Ltd
8 Kaki Bukit Ave 4, #08-46 Premier @ Kaki
Bukit
Singapore 415875

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Mar 2019)
Parts: M1-SUV	LEXUS NX200T 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLE382D)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Distorted	2,215.60 FL	*1,489.50 FL
2	1		*TAILGATE LOCK C/W MOTOR	Damaged	899.60 FL	*745.00 FL
3	1		*TAILGATE LOCK COVER	Cut	52.10 FL	*52.10 FL
4	1		*TAIL GATE WEATHERSTRIP	Cut	289.70 FL	*289.70 FL
5	1		*TAILGATE LOGO	Necessary	76.50 FL	*76.50 FL
6	1		*TAILGATE EMBLEM LEXUS	Necessary	65.90 FL	*65.90 FL
7	1		*TAILGATE EMBLEM NX200T	Necessary	69.60 FL	*69.60 FL
8	2		*TAILGATE REFLECTOR	N/S Cut / O/S Cracked	1,056.40 FL	*1,056.40 FL
9	1		*TAILGATE TOP OUTER GARNISH	Cracked	785.20 FL	*785.20 FL
10	1		*TAILGATE CHROME	Cut	212.30 FL	*212.30 FL
11	1		*TAILGATE DAMPER MOTOR	Not Necessary	689.20 FL	*- FL
12	1		*TAILGATE INNER TRIM	Cracked	525.90 FL	*525.90 FL
13	2		*TAILGATE SIDE TRIM	Cut	516.00 FL	*516.00 FL
14	1		*TAILGATE CENTRE TRIM	Cut	359.40 FL	*359.40 FL
15	1		*TAILGATE WIPER MOTOR	Damaged	658.50 FL	*658.50 FL
16	1		*TAILGATE WIPER ARM	Missing	289.00 FL	*289.00 FL
17	1		*TAILGATE WINDSCREEN GLASS	Shattered	1,459.00 FL	*1,459.00 FL
18	1		*TAILGATE WINDSCREEN GLASS MOULDING	Necessary	189.00 FL	*189.00 FL
19	2		*TAILGATE SIDE GARNISH	Not Necessary	556.20 FL	*- FL
20	1		*TAILGATE CENTRE GARNISH	Not Necessary	542.10 FL	*- FL
21	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	339.60 FL	*- FL
22	1		*TAILGATE THIRD BRAKE LIGHT	Not Necessary	398.70 FL	*- FL
23	1		*TAILGATE SPEAKER	Not Necessary	689.00 FL	*- FL
24	1		*TAILGATE REVERSE CAMERA	Damaged	627.00 FL	*627.00 FL
25	1		*TAILGATE DETECTOR	Cracked	321.00 FL	*321.00 FL
26	1		*TAILGATE ALARM CONTROL BOX UNIT	Cracked	825.20 FL	*825.20 FL
27	2		*TAILAMP	N/S Cut / O/S Cracked	1,719.20 FL	*1,377.20 FL
28	2		*TAILAMP PANEL	Repair	459.00 FL	*- FL
29	2		*REAR FENDER INNER TRIM	Cracked	2,050.00 FL	*1,500.00 FL
30	2		*REAR FENDER INNER COWLING	Not Necessary	578.00 FL	*- FL
31	2		*REAR FENDER WHEEL ARCH GARNISH	Not Necessary	510.00 FL	*- FL
32	1		*REAR BUMPER	Distorted	1,586.20 FL	*627.00 FL
33	1		*REAR BUMPER LOWER	Distorted	685.20 FL	*597.00 FL
34	2		*REAR BUMPER REFLECTOR	Not Necessary	371.20 FL	*- FL
35	2		*REAR BUMPER SIDE RETAINER	Necessary	163.80 FL	*163.80 FL
36	1		*REAR BUMPER SPONGE	Not Necessary	266.90 FL	*- FL
37	1		*REAR BUMPER REINFORCEMENT	Bent	799.60 FL	*598.00 FL
38	4		*REVERSE SENSOR	Damaged (2 PCS ONLY)	1,284.00 FL	*560.00 FL
39	1		*REAR END PANEL	Distorted	798.60 FL	*627.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR END PANEL TOP GARNISH	Deformed	425.20 FL	*425.20 FL
41	2		*REAR END PANEL AIR VENT	Cracked	224.40 FL	*224.40 FL
42	1		*REAR FLOOR PANEL TOP BOARD	Deformed	512.90 FL	*512.90 FL
43	1		*REAR FLOOR PANEL SIDE TRAY RH	Deformed	411.00 FL	*411.00 FL
44	1		*REAR FLOOR PANEL SIDE TRAY RH	Deformed	498.00 FL	*498.00 FL
45	1		*REAR FLOOR PANEL SPONGE	Not Necessary	198.60 FL	*- FL
46	1		*REAR FLOOR PANEL SIDE BOARD RH	Not Necessary	70.80 FL	*- FL
47	1		*REAR EXHAUST SILENCER	Bent	2,526.00 FL	*1,175.90 FL
48	2		*REAR EXHAUST MOUNTING	Not Necessary	64.00 FL	*- FL
49	10		*REAR BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
50	10		*TAIL GATE INNER BOARD CLIP	Necessary	65.00 FS	*30.00 FS
51	1		*TAIL GATE EMBLEM (BORNEO MOTOR)	Not Necessary	80.00 FS	*- FS
52	1		*TAILGATE WINDSCREEN TINTED GLASS	Necessary	500.00 FS	*200.00 FS
53	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS
54	1		*TAILGATE WIPER BLADE	Missing	50.00 FS	*25.00 FS
55	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
56	1		*REAR VIDEO CAMERA	Missing	500.00 FS	*380.00 FS
57	2		*REAR EXHAUST CHROME	Not Necessary	800.00 FS	*- FS
58	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	130.00 FS	*60.00 FS
59	4		*REAR END PANEL TOP GARNISH CLIPS	Necessary	22.00 FS	*10.00 FS
60	1		*REAR END PANEL INSLATION SEAL	Necessary	150.00 FS	*60.00 FS
61	4		*REVERSE SENSOR	Repeated	440.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Sub Total (S\$)	33,852.30	20,764.60
- List Item Discount on L Items 10.00/10.00% (S\$)		3,091.03	1,990.96
	Total Parts (S\$)	30,761.27	18,773.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,800.00	1,000.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	50.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AN ROOF LINING TO FACILITATE REPAIR	New	180.00	80.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
Gross Labour Cost (\$\$)			3,840.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >