

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gerald Poh

Date: 14 Aug 2018

Preliminary Advice

Vehicle No	: GBC1163S	Accident Date	: 26/07/2018
Make	: NISSAN URVAN	Policy No.	: Z18/VC00/101691
Assignment Date	: 10/08/2018	Excess	: S\$700.00
Date of Inspection	: 13/08/2018	Est. Duration of Repair	: 8 days
Inspection At	: Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58 Singapore 408717		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body, undercarriage affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,127.20
Revised Amount	:S\$	5,492.00
Check Items (Estimated)	:S\$	10,615.00
Total	:S\$	16,107.00
Lump Sum Repair		:S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	24,000.00
COE / PARF Rebate	:S\$	8,276.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,724.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER ABLE TO UNDERTAKE THE REPAIR COST LIMIT NOT EXCEEDING \$15,000/- ON LUMPSUM BASIS. PENDING CONFIRMATION FROM INSURED

OF THE 2 ITEMS AS BELOW :

- 1) ALUMINIUM CABIN (INTERIOR)
- 2) ALUMINIUM WHEEL ARCH BOX (INTERIOR)