

ASS. REC. BY:

REF

CS3/SPF18014541/Gvd3

Special Instruction:

Surveyor:

GudGing

ASSIGNMENT (Office)

From (Person):

Abdul Rahman

of

SPF

Date/Time:

8/8/18

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJM 2629L

Insured:

PA 3962J

at Workshop m/s

Sat Motor

Tel:

91269987/67481141

of

24 Defu Lane 12

Policy No:

Claim No:

AEMD 11051009/2018/094

Sum Insured:

Excess:

Make of Veh:

D.O.A.

2/8/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

cup

H.O.D. Endorsement:

Date/Time:

9:14am @ 10/8/18

Person Contacted:

Jerry

Vehicle

IN/OUT

Date/Time

Action/Instruction (X) Estimate

SJM 2629L - CS3/AG 18024893/Uybl

DOA: 9/5/18

PA 3962J - CS1/SPF 17014802/Gq be2

DOA: -

21/8/18

Submit DAR LS \$ 3800



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SINGAPORE POLICE FORCE		Ref : CS/SPF18014541/Gvd3	
?? POLICE DIVISIONSINGAPORE 		Date : 10-08-2018	
		Code : SPF1	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PA 3962J	Veh. Inspected	SJM 2629L
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/094	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	10/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	02/08/2018	Inspection Date	10/08/2018
Survey held at	SAT MOTORS 24 DEFU LANE 12 SINGAPORE 539131		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref : SJM2629L

Our Ref : AEMD/105/009/2018/094

Date : 8 August 2018

Tel: 64784840

Fax: 64784848

M/s LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Via Fax Only: 62564315

Dear Sir/Madam,

ACCIDENT ON 2 AUGUST 2018 INVOLVING GOVT VEHICLE PA3962J AND OTHER VEHICLE SJM2629L

We refer to the above matter.

- 2 Please assist to arrange for a PRI of Vehicle no. **SJM2629L** at **M/s SAT Motors of 24 Defu Lane 12, Singapore 539131.**
- 3 For appointment, please contact **Jonathan Lim** at HP: **91269987.**
- 4 Estimates were not provided by the workshop.
- 5 Thank you.

Yours faithfully,

Abdul Rahman
Accident Claims Officer
for Assistant Director

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/08/2018 16:50
Date Of Accident	02/08/2018 08:10
Exact Location Of Accident	JUNCTION OUTSIDE TANGLIN MALL (GRANGE ROAD)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJM2629L
Insured/Policyholder	
Name Of Registered Owner	SAT LEASING PTE. LTD.
Co Reg No	201631055N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-88122191

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5090941580-01
Cover Note Number	

Driver

Name of Driver	TAN KOK BENG
NRIC No	S1447170G
Date Of Birth	03/02/1960
Occupation	OUTDOOR
Date Of Driving Pass	10/12/1979
Driving Experience	38 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88122191
Fax Number	
Contact Number	
Email Address	NOEMAIL

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	TAN KOK BENG
Approximate Age	
Injuries Sustain	NECK INJURIES
Injured person in which vehicle?	SJM2629L
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan #2 Pg. 1

SKETCH PLAN

Grange Rd

A - SJM7629L

R - PA3962J

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS driving along Grange Rd at the MOST right lane
turning right towards Tanglewood when suddenly a police
vehicle on the left side of my vehicle which was also turning
right then cut into my lane and caused damage on my front left side
of my car. This incident would like to claim against the third party.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NEIC/FIN No.:

MOTOR CAR (LH)

Left Portion

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door	5	R	X
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror	682.00	BR	V
1259	995102	Frt LH Door Garnish			
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH			
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frt Bumper	495.50	CH	V
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1029	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender	723.40	CH	V
1098	995147	Frt LH Fender Lamp	65.30	BR	V
1099	995148	Frt LH Fender Protector			
		Frt Fender HYBRID body	25.00		

No of Items: 6

Assessor: T. T. W.

Vehicle No: SJM 2629 L

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door			
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door Hinge			
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber			
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock			
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1163	993851	Rear LH Taillamp			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1136	990247	Sticker			
		Labour			
1		To remove and replace damaged parts, including spray painting.			600.00
2		check electrical functions of changed items.			30.00
3		To spray paint damaged items.			600.00
4		To spray undercoating and rust proofing			60.00
5		Remove & Refit undergarage			\$200
6		wheel Alignment			1500.00
		Total repair cost			5193.90
		Repair days			7

17/8/2015

3491.20

MOTOR CAR (Frt)

(4) Hot Condition (H/C)

Front Section

Vehicle No: **SJM 2629L**

NAC	INC	Item	CON	AC	Qty
1001	991584	Frt Number Plate			
1002	991587	Frt Number Plate Base			
1003	991589	Frt Number Plate Garnish			
1004	991309	Frt Bumper			
1005	992341	Frt Bumper Clips	46.00	NBC	✓
1006	991325	Frt Bumper Bracket			
1007	991452	Frt Bumper Side Retainer	LH 112.20	NBC	✓
1008	991453	Frt Bumper Reinforcement			
1009	991316	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	991100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	991079	Frt LH Bumper Fog Lamp			
1020	991080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	991513	Frt LH Headlamp Assy	636.60	BR	✓
1030	991821	Frt RH Headlamp Assy			
1031	991088	Frt LH Side Lamp			
1032	991089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	991065	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	991294	Air Con Belt			
1052	991074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992733	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990131	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hoses			
1062	990059	Air Cleaner Regulator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991714	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991715	Front Exhaust Flange			
1067	991716	Exhaust			
1068	991717	Exhaust			
1069	991718	Exhaust			
1070	991719	Exhaust			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield	192.50	LT	✓
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim	640.00	LT	✓
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre	100.00	LT	✓
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		Frt fender shield clips			
		14.90			

No of Items: **4**

Assessor: **Tatim**

1702-70

UNDERCARRIAGE

VEHICLE NO:

SJM 2629L

LKK SUR:

Tel: 6256 3561

Fax: 6256 4315

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber			
1373	991944	Frt LH Shock Absorber Mounting			
1374	990632	Frt LH Coil Spring			
1375	995198	Frt LH Knuckle Arm	472	BT	/
1376	995199	Frt LH Knuckle Arm Bearing	84.5	AC	/
1377	995178	Frt LH Lower Arm	358	BT	/
1378	995169	Frt LH Upper Arm			
1379	995183	Frt LH Tie Rod			
1380	995143	Frt LH Drive Shaft			
1381	990661	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper			
1386	991292	Frt LH Brake Pipe			
1387	991287	Frt LH Brake Hose			
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion			
1391	994435	Steering Cross Member			
1392	994519	Frt Sub Frame			
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar			
1395	991219	Frt Anti Roll Bar Linkage			
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
1410	990534	Centre Exhaust Pipe Assy			
1411	990532	Centre Exhaust Mounting			
1404	991134	Floor Panel			
1405	993719	Rear LH Shock Absorber			
1406	993723	Rear LH Shock Absorber Mounting			
1407	993170	Rear LH Coil Spring			
1408	993550	Rear LH Knuckle Arm			
1409	993551	Rear LH Knuckle Arm Bearing			
1410	993597	Rear LH Lower Arm			
1411	993884	Rear LH Upper Arm			
1412	995161	Rear LH Drive Shaft			
1413	995216	Rear LH Control Arm			
1414	993881	Rear LH Trailing Arm			
1415	993573	Rear LH Leaf Spring			
1416	992941	Rear LH Brake Disc Rotor			
1417	992937	Rear LH Brake Caliper Assy			
1418	990434	Rear LH Brake Pipe			
1419	992946	Rear LH Brake Hose			
1420	993819	Rear Sub Frame			
1421	993820	Rear Sub Frame Mounting			
1422	992813	Rear Anti Roll Bar			
1423	990168	Rear Anti Roll Bar Linkage			
1424	990202	Axle Beam			
1425	990170	Rear Axle Panhard Rod			
1426	990810	Differential Assy			
1427	992706	Propeller Shaft			

[illegible]



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref: CS3/SPF18014541/Gvd3s2

ACCIDENT CLAIM SECTION(SINGAPORE POLICE
FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD
POLICE ACADEMYSINGAPORE 298333

Date: 24-08-2018



ATTN: ABDUL RAHMAN

Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	PA 3962J	Veh. Inspected	SJM 2629L
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/094	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	08/08/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1797
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	JTDKB20U103512592	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55R16	MICHELIN	5 mm
L/H Front Tyre	205/55R16	MICHELIN	5 mm
R/H Rear Tyre	205/55R16	MICHELIN	5 mm
L/H Rear Tyre	205/55R16	MICHELIN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/08/2018	Inspect Date / Time	10/08/2018 (03:30 PM)
Survey held at	SAT MOTORS 24 DEFU LANE 12 SINGAPORE 539131		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

OPINION ON REPAIR COST FOR VEHICLE NO. SJM 2629L

Qty	Description of Parts	Condition	Recommended (\$)
REPLACEMENT OF PARTS			
1	FRT LH DOOR (NPA)	TO REPAIR SEE LABOUR	-
1	FRT LH DOOR WING MIRROR	BROKEN	682.00
1	FRT BUMPER	CUT	495.50
1	FRT LH FENDER	BUCKLED	723.40
1	FRT LH FENDER LAMP	BROKEN	65.30
1	FRT FENDER HYBRID BADGE	NECESSARY	25.00
1	FRT BUMPER CLIPS	NECESSARY	40.00
1	FRT BUMPER SIDE RETAINER LH	NECESSARY	112.70
1	FRT LH HEADLAMP ASSY	BROKEN	636.60
1	FRT LH FENDER INNER SHIELD	TORN	198.50
1	FRT FENDER SHIELD CLIPS	NECESSARY	14.90
1	FRT LH KNUCKLE ARM	BENT	472.00
1	FRT LH KNUCKLE ARM BEARING	NECESSARY	84.50
1	FRT LH LOWER ARM	BENT	358.00
	LESS 25% DISCOUNT		-977.10
			2,931.30
SPECIAL NETT ITEMS			
1	FRT LH WHEEL RIM (SN)	CUT	250.00
1	FRT LH TYRE (50%) (SN)	PUNCTURE	50.00
			300.00
LABOUR			
	TO REMOVE AND REPLACE DAMAGED PARTS, INCLUDING SPRAY PAINTING. INCLUSIVE OF THE REPAIR OF FRT LH DOOR.		600.00
	CHECK ELETRICAL FUNCTIONS OF CHANGED ITEMS.		30.00
	TO SPRAY PAINT DAMAGED ITEMS.		600.00
	TO SPRAY UNDERCOATING AND RUST PROOFING.		60.00
	REMOVE & REFIT UNDERCARRIAGE.		200.00
	WHEEL ALIGNMENT.		60.00
			1,550.00
GRAND TOTAL			4,781.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,800.00

Report Ref No. CS3/SPF18014541/Gvd3s2



Report Ref No. CS3/SPF18014541/Gvd3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.