

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 146/IC/TCAC/CCR/2018
DATE : 07-AUG-2018

FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER
S(038986)
TEL : 6820 8888
FAX :
ATTN : CLAIM MANAGER

OWNER'S NAME : MDM LILIAN GUI LEOW PHENG
ADDRESS : 71 JALAN TUA KONG
#05-01
S(457265)
TELEPHONE NO : 91456758/97633641

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 2100410336-03
VEHICLE NO : SJB1057B
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2122773A
CHASSIS NO : SJNFEAJ11U1323307
MILEAGE : 69667 KM
DATE IN : 07/08/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 07/08/2018

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJB1057B

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	
2	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	
3	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	
4	WHI	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN/ SHORT CIRCUIT, REPAIR WHEN NECESSARY	240.00	
5	ZZ/001	REPLACE REAR BUMPER, TOW HOOK COVER, ENERGY ABSORBER REAR UPPER PANEL ETC. REPAIR PANELS	760.00	
6	ZZ/002	RESPRAY REAR BUMPER IN 2 COLORS, REAR UPPER PANEL	600.00	
7	ZZ/003	QC, RETUNE & CONSULT CHECK		
8	ZZ/004	COMPLIMENTARY WASH & VACUUM		
TOTAL LABOUR CHARGES			1875.00	

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJB1057B

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	REVERSE SENSOR(J11 & T32)	SENSOR-TE5140			360.00	
2	RIGHT BUMPER BRACKET	85220-4EA0A	35.90			
3	LEFT BUMPER BRACKET	85221-4EA0A	35.90			
4	ENERGY ABSORBER	85090-4EA0B	126.40			
5	RIGHT BUMPER RETAINER	79184-4EA0A	23.80			
6	LEFT BUMPER RETAINER	79185-4EA0A	23.80			
7	REAR BUMPER	85022-4EA0H	717.00			
8	TOW HOOK COVER	85071-4EA0A	16.80			
9	REAR UPPER PANEL	G9110-4EAMA	482.60			
SUB TOTAL			1462.20	0.00	360.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			292.44	0.00	0.00	
GRAND TOTAL			1169.76	0.00	360.00	
OVERALL TOTAL			1529.76			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJB1057B

TOTAL LABOUR CHARGES	1875.00
TOTAL SPARE PARTS CHARGES	1529.76

GRAND TOTAL	3404.76 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.