

SMRT Accident Vehicle Repair Estimates

C/S

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4382K
Ref. No : TAX/07/18/2165
Reg. Date : 20/12/2013
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : KAM KIAN MENG ANDY
Type of Accident : SIDE SWIPE
Date / Time of Accident : 28/07/2018 02:05:00 AM
Accident Reported Date / Time : 06/08/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024097427
Special Instruction to ARC, if any :
TOWED \$60 / SLH9754P
Prepared Date : 06/08/2018 05:51:47 PM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U70-5718962

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 676.00	0.00
Total Spray Painting Charges	: 1,494.00	0.00
Total Material Charges	: 3,267.72	3,267.72
Other Charges	: 1,189.00	0.00
TOTAL	: 6,626.72	0.00
Lum Sum Total	: 6,650.00	0.00
No. of Repair Days	: 5.00 3.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 07/08/2018 03:41:17 PM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 07/08/2018 03:41:17 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 8/7/2018 3:41:35 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	676.00	0.00
Total Labour	676.00 600	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR DOOR LH	378.00 200	0.00
TO RESPRAY ROCKER PANEL MOULDING	180.00 100	0.00
TO RESPRAY REAR FENDER LH	378.00 200	0.00
TO RESPRAY RIM	180.00 /	0.00
TO REPSRAY REAR BUMPER	378.00 200	0.00
Total Spray Painting & Panel Beating	1,494.00 700	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	84.00 50	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00 nn	0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00 X nn	0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00 20 X nn	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00 20	0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00 50	0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00 50	0.00
TO REPLACE SUNDRY PARTS	100.00 X nn	0.00
TO WASH AND VACUUM	60.00 X nn	0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00 50	0.00
TO REMOVE AND REFIT TYRE	120.00 20 X nn	0.00
Total Other Costs	1,189.00	0.00

NAZ LCC
7/8/18 1545
L/S
3 DAY
AFTER REPAIR PHOTO

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
67004-47080		6505487	DOOR RR/LH	1	954.50	25.00	715.87	Replace	Replace	No <i>XSVL</i>
75852-47900			MOULDING BODY, LH	1	673.60	25.00	505.20	Replace	Replace	No <i>X R</i>
61602-47091		6505476	FENDER RR/LH	1	766.80	25.00	575.10	Replace	Replace	No <i>X R</i>
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace	No <i>/nc</i>
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No <i>/nc</i>
62720-47031			QUARTER GLASS RR/LH	1	168.10	25.00	126.07	Replace	Replace	No <i>X n n</i>
	COMMO N		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace	No <i>X n n</i>
42611-47140		6505658	WHEEL, DISC	1	1,490.20	25.00	1,117.65	Replace	Replace	No <i>X n n</i>
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace	No <i>X n n</i>
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No <i>/CRK</i>
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No <i>?</i>
52592-47021			BUMPER SEAL, RR LH	1	88.90	25.00	66.67	Replace	Replace	No <i>?</i>
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace	No <i>/scr</i>
90467-07211			BUMPER CLIPS	10	2.10	25.00	15.75	Replace	Replace	No <i>/nc</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>/nc</i>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No <i>XSVL</i>
TOTAL MATERIALS								4,084.67	4,084.65	
TOTAL MATERIALS(Discounted)							3,267.72	3,267.72		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									