

INS. CASE OWNER:

MAMS

CC 6 / LER 180 14580

Awar3

LKK-IDAC:

Surveyor:

Wp

DOI:

ASSIGNMENT 2/8/18

Date / Time:

2/8/18

Registered in:

12/8/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLH 5634D

Claim No.:

Name of Insured:

LEAF PL

Policy No.:

019999

Insured Tel No.:

HP:

Make / Model:

M7. Attrage

Excess Sec II :S\$

D.O.A.:

4/8/2018

Place of Accident:

PIE charmai

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Lim M'hee 38

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SKK6059D



INSRS:

WSP: Hua Meng

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

12/18

SKK6059D. X;

STAGE

DATE / PIC

View

SLH5634D - CIV / LER 180 14580 / kmb3q2 : 2018 12/18

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

20/1/18

Email letter to OI

Documentation Check List: Handler Typist

Notification Itr (if non-pickup):

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PER:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

13/1/18

File -> type mandatar

25/1/18

- DV sent

28/1/18

File -> to mei kuan to lose.

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

2/1/19

Confirm with June

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : 27.

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

12500.00

Loss of Rental (LOR):

S\$

Loss of Use (LOU):

S\$

1000.00 (5 1W x 10 days)

Loss of Income (LOI):

S\$

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

S\$

7.45

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost:

S\$

1) Claim status: No mg/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

13507.45

Global Sum S\$:

13500.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

13200.00

Name 1:

Hua Meng Spray Painting Workshop.

Payee 2 (Strike if N.A.)

S\$

Payee 3 (Strike if N.A.)

S\$

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

WBAYE 22030D220966

RAJEEV LOCHAN
14 FRANKEL DRIVE
S 458093

TP CCR
Vision

Date :14.08.2018
Vehicle no :SKK 6059 D
Make/Model :BMW 730 LI
Accident date :04.08.2018

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear boot lid <i>Dented</i>	1	\$ 2186.7 ✓
2	Rear boot lid hinges @ \$200.90 <i>new</i>	2	\$ 401.8 ✓
3	Rear boot lid upper lock <i>new</i>	1	\$ 233 ✓
4	Rear boot lid lower lock <i>new</i>	1	\$ 57.5 ✓
5	Rear boot lid insulation <i>new</i>	1	\$ 155 ✓
6	Rear boot lid weather strip <i>new</i>	1	\$ 210.9 ✓
7	Rear boot lid centre logo <i>new</i>	1	\$ 87.5 ✓
8	Rear boot lid 730 emblem <i>new</i>	1	\$ 68.7 ✓
9	Rear boot lid LI emblem <i>new</i>	1	\$ 68.7 ✓
10	Rear boot lid handle <i>no all</i>	1	\$ 19.8 ✓
11	Rear boot lid reflector <i>wt</i>	2	\$ 990 ✓
12	Rear boot lid reverse lamp @ \$450 <i>new</i>	2	\$ 900 ✓
13	Rear number plate lamp @ \$41.80 <i>new</i>	2	\$ 83.6 ✓
14	Rear lamp @ \$793.70 <i>cracked</i>	2	\$ 1587.4 ✓
15	Rear lamp side garnish @ \$38.50 <i>wt</i>	2	\$ 77 ✓
16	Rear end panel <i>Dented</i>	1	\$ 1635.4 → 1245
17	Rear end panel inner top garnish <i>deland</i>	1	\$ 141.8 ✓
18	Rear bumper <i>deland</i>	1	202570 \$ 202570 ✓
19	Rear bumper side holder @ \$214.50 <i>new</i>	2	\$ 429 → 294
20	Rear bumper lower moulding <i>wt</i>	1	\$ 125.3 ✓
21	Rear bumper reflector @ \$38.70 <i>cracked</i>	1	\$ 38.7 ✓
22	Rear bumper towing hook cover <i>deland</i>	1	\$ 55.8 ✓
23	Rear bumper lower cover <i>deland</i>	1	38750 \$ 38750 ✓
24	Rear bumper reverse sensor @ \$260.60 <i>2 pieces damaged</i>	4	\$ 1042.4 → 52120
25	Rear bumper reverse sensor socket @ \$64.50 <i>no all</i>	4	\$ 258 ✓
26	Rear bumper reinforcement <i>best</i>	1	\$ 880.9 ✓
27	Rear bumper sponge <i>deland</i>	1	\$ 41.8 ✓
28	Rear bumper inner top garnish <i>cracked</i>	1	\$ 115.5 ✓
29	Rear bumper inner lower garnish <i>deland</i>	1	\$ 275 ✓
30	Rear bumper inner sensor <i>deland</i>	1	\$ 407 ✓
31	Rear bumper clips (1set) <i>new</i>	1	\$ 60 → 30
32	Rear end panel centre lower cover <i>torn</i>	1	\$ 54.8 ✓
33	Rear RH side lower cover <i>torn</i>	1	\$ 211.2 ✓
34	Rear fender inner side garnish @ \$295.40 <i>new</i>	2	\$ 590.8 ✓
35	Rear spare tyre top board <i>deland</i>	1	\$ 591.3 ✓
			15821.9

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

RAJEEV LOCHAN
14 FRANKEL DRIVE
S 458093

Date :14.08.2018
Vehicle no :SKK 6059 D
Make/Model :BMW 730 LI
Accident date :04.08.2018

No	Description	Qty	Amount (\$\$)
36	Rear spare tyre well <i>new</i>	1	\$ 4239.4
37	Rear spare tyre well insulation @ \$165.00 <i>new</i>	3	\$ 495.4
38	Rear exhaust pipe <i>Repair</i>	1	\$ 2350.3
39	Rear exhaust pipe mounting <i>new</i>	1	\$ 32.3
40	Rear exhaust pipe chrome @ \$122.10 <i>new</i>	2	\$ 244.2
41	Smart opener control unit <i>damaged</i>	1	\$ 515.7
42	Bootlid Outer Garnish. <i>254</i>	1	\$ 23698.4
		5	\$ 2369.84
			Less 10% Disc
			Total
			\$ 21328.56

Special Nett Items

1	Rear boot lid camera <i>new</i>		\$ 800
2	Rear number plate <i>2 plates</i>	60	\$ 50.30
3	Rear number palte holder		\$ 50.30
		Total	\$ 900

Labour Cost

1	To supply rear end panel inner sealant		\$ 200
2	Remove & reinstall exhaust pipe		\$ 300
3	Remove & reinstall reverse sensor	2740	\$ 200
4	Remove & reinstall boot lid inner garnish		\$ 200
5	Remove ,replace & repair consistent to the accident		\$ 1800
6	Respray painting		\$ 1400
7	Tuff kote		\$ 150
		Total	\$ 4250

Grand Total \$ 26478.56

total 15641.62

H/S 12.5K

08 Days

12.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5593E
Vehicle Details	
Vehicle No.:	SKK6059D
Vehicle to be Exported:	Yes
Intended De-registration Date:	10 Aug 2018
Vehicle Make:	B.M.W.
Vehicle Model:	730LI AT D/AB 4DR SR LED DSC NAV HUD
Primary Colour:	Blue
Manufacturing Year:	2012
Engine No.:	07738357N52B30AF
Chassis No.:	WBAYE22030DZ20966
Maximum Power Output:	190.0 kW (254 bhp)
Open Market Value:	\$74,191.00
Original Registration Date:	12 Aug 2013
First Registration Date:	12 Aug 2013
Transfer Count:	0
Actual ARF Paid:	\$105,544.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Aug 2023
PARF Rebate Amount:	\$79,158.00
Intended COE Rebate Details	
COE Expiry Date:	11 Aug 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$77,600.00
COE Rebate Amount:	\$38,820.00
Total Rebate Amount:	\$117,978.00

The information contained herein is correct as at 10 Aug 2018

OK

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Come Come Come. Take And Go. Call Us Now!

Come Come Come. Take And Go. Call Us Now!

Let Us Take Your StarAd

Lake View Credit Pte Ltd view our cars

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

[Browse by Category](#)
[Save Search](#)
[Print](#)

[Sort by Date Posted](#)
20 results/page

6 vehicles | **Search** [Advanced Search](#) [Search](#) [View All](#)

[Make](#)
[Model](#)
[Price](#)
[Depreciation](#)
[Reg Date](#)
[Eng Cap](#)
[Mileage](#)
[Veh Type](#)
[Status](#)

Search Selection	bmw 730	Any	Any	2013	Any	Any	Any	Available
------------------	---------	-----	-----	------	-----	-----	-----	-----------

BMW 7 Series 730Li Sunroof **\$116,500** **\$16,940 /yr** **15-Apr-2013** **2,996 cc** **98,000 km** **Luxury** **Available**

Only Owner, New Facelifted 730Li Sunroof With Adaptive LED Headlights, Fully Maintained By PML, Head Up Display, 100% Accident Free, Tip Top Conditions With No Repairs Required, Bank And High In House...

Posted: 21-Jul-2013 Tags: 2013 BMW 730Li, BMW 730Li, BMW 730Li, Used BMW

BMW 7 Series 730Li Sunroof **\$131,800** **\$16,410 /yr** **30-May-2013** **2,996 cc** **99,000 km** **Luxury** **Available**

SBT56K Number, New Facelift Model With Adaptive LED Headlights, No Gimmicks Guarantee Cheapest Price New Facelift In Market, Lowest Depreciation Only \$16k Per Year, Selling At Old Facelift Price. 1 Own...

Grande Auto Credit

Posted: 06-Jul-2013 Tags: 2013 BMW 730Li, BMW 730Li, BMW 730Li, Used BMW

BMW 7 Series 730Li Sunroof **\$133,800** **\$16,850 /yr** **31-May-2013** **2,996 cc** **96,000 km** **Luxury** **Available**

Only 1 Owner! High ARF At \$105,672! PARF \$52,836! Low Mileage Done! Guaranteed Lowest Price And Best Condition In Market! Comes With 1 Years Warranty And Free Servicing! Highest Trade In With Lowest ...

Posted: 23-Jul-2013 Tags: 2013 BMW 730Li, BMW 730Li, BMW 730Li, Used BMW

BMW 7 Series 730Li Sunroof **\$135,800** **\$17,070 /yr** **27-Jun-2013** **2,996 cc** **48,888 km** **Luxury** **Available**

Up To 100% Loan Available At Low Interest! Free In Car Camera, Grooming Package, 6 Months And 1 Servicing! Trade In Are Welcome Too! Call Us Now For Viewing Or Enquiry To Find Out More!

Posted: 21-Jul-2013 Tags: 2013 BMW 730Li, BMW 730Li, BMW 730Li, Used BMW

[Car Buying](#) [Car Selling](#) [Car Ownership](#)

[Car Aftermarket](#) [On The Move](#) [Lifestyle](#)

Bidder Carplates For Sale

BMW 7 Series 730Li Sunroof **\$158,800** **\$20,030 /yr** **30-Sep-2013** **2,996 cc** **35,000 km** **Luxury** **Available**

Original Low Mileage, Full Agent Maintained, Accident Free.

Posted: 30-Jul-2013 Tags: 2013 BMW 730Li, BMW 730Li, BMW 730Li, Used BMW

BMW 7 Series 730Li Sunroof **\$146,800** **\$17,400 /yr** **31-Oct-2013** **2,996 cc** **84,000 km** **Luxury** **Available**

Face Lifted Model! 1 Owner! Agent Unit! Extremely Low Mileage! Supreme Condition! Regularly Serviced, Accident Free. Buy With A Peace Of Mind! High Paper Value Of Over \$129,000 And ARF Of Over \$111,000...

Hui Hua Credit Pte Ltd

Posted: 30-Jul-2013 Tags: 2013 BMW 730Li, BMW 730Li, BMW 730Li, Used BMW

Save this search criteria, to get email alerts whenever a match is found. [Save Search](#)

[Make](#)
[Model](#)
[Price](#)
[Depreciation](#)
[Reg Date](#)
[Eng Cap](#)
[Mileage](#)
[Veh Type](#)
[Status](#)

For old advertisements, view [Expired ads](#) 20 results/page

[Compare](#)



華明噴漆廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883
 Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680
 Reg. No.: 254678/00M



Your Ref :

Our Ref :

Date: 27-11-2018

Attn: Motor Claims Dept

**ACCIDENT ON 04.08.2018 INVOLVING VEHICLE SKK 6059 D & SLH 5634 D ALONG
 PIE TOWARDS CHANGI (NEAR STEVEN)**

With regards to the above, we are writing on behalf of the registered owner of vehicle SKK 6059 D which was involved in the above mentioned accident.

We are informed that the above accident was caused solely by the negligence of your insured vehicle SLH 5634 D. As a result of the accident, our client's vehicle was damaged and our client had instructed us to submit his claims for loss and expenses, particulars of which are follows:


1) Repair cost	\$	12,500.00
2) Loss of use-\$200 X 10days	\$	2000.00
3) LTA search	\$	7.49
Total	\$	14,507.49

We hereby enclosed herewith the following documents for your consideration of the above claim.

- a) Final Repair Bill Of SKK 6059 D
- b) GIA report
- c) LTA SEARCH
- d) Owner / Driver NRIC & Driving License

華明噴漆廠
 HUA MENG SPRAY PAINTING WORKSHOP
 AUTOBAY@KAKI BUKIT
 1 KAKI BUKIT AVE #01-34 SINGAPORE 417883
 TEL: 6747 8064, 6746 5519 FAX: 6743 4896

Yours faithfully,
HUA MENG SPRAY PAINTING WORKSHOP



MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way #21-01 SGX Centre 2 Singapore 068807
Tel: (65) 6827 7888 Fax: (65) 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

MOTOR INSURANCE COVER NOTE

Cover Note No. 10115104

The Insured named in the Schedule below having proposed for insurance in respect of the Motor Vehicle described in the Schedule below the risk is hereby HELD COVERED in the terms of the Company's usual form of Policy applicable thereto for the period as stated below unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

SCHEDULE

Agent No. : 212165
Name of Insured : RAJEEV LOCHAN
Make and Description of Vehicle : B.M.W 730LI
Vehicle Registration No. : SKK6059D
Year of Manufacture : 2012
Engine No. : 07738357N52B30AF
Chassis No. : WBAYE22030DZ20966
Capacity : 2,996 Cubic Capacity
Cover Type : Comprehensive
Sum Insured (SGD) : Market Value
Period of Insurance : 12/08/2017 to 11/08/2018
Excess (SGD) : 750
Finance Company : UNITED OVERSEAS BANK LIMITED

I/We hereby certify that this Covering note is issued in accordance with the Provisions of the Motor Vehicles (Third Party Risks & Compensation) Act (Cap. 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

Not valid unless countersigned by the
Company's Authorised Representative



Sime Darby Insurance Brokers (Singapore) Pte. Ltd.

MSIG Insurance (Singapore) Pte. Ltd.
Authorised Insurers

Katherine Yeo
Senior Vice President, Brokers

Date of Issue : 03/08/2017

This covering note is valid for 30 days from the date of issue.



License Number: S2735593E

Name:

RAJEEV LOCHAN

Birth Date: 05 Aug 1964

Issue Date: 12 Jan 2006



001392455C

ICE/ICE

S2735593E



RAJEEV LOCHAN

Race:

INDIAN

Date of birth:

05-08-1964

Sex:

M

Country of birth:

INDIA

12735593E

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 2B Motorcycles <= 300 cc
Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg

PASS DATE

14 Mar 2001

14 Mar 2001

4844390



NRIC No: S2735593E



7b-03-2012

1A FRANKEL DRIVE
SINGAPORE 458093

NRIC No: S2735593E

Date: 12/11/2012

No: 7289542



License No: S2735593E

NP 425A

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 14 February 2019 9:46 AM
To: 'Mavis, Chew'
Cc: Vivian Lau (LKKAuto); Admin A
Subject: <Seek Mandate>AIG Ref: 76910030085G *LKK Ref: CC6/LCR18014580/Awa3
[ACCIDENT INVOLVING SLH 5634D(OI) SKK 6059D(TP) ON 04/08/2018]

AIG Ref: **76910030085G**
LKK Ref: CC6/LCR18014580/Awa3

Dear Sirs/Madam,

ACCIDENT INVOLVING SLH 5634D(OI) SKK 6059D(TP) ON 04/08/2018

We refer to the above matter.

This is a head-to-rear collision. Liability is not in our driver's favour.

We seek your approval to offer to Third Party repairer, "**HUA MENG SPRAY PAINTING WKSP**" is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair	\$ 28,544.70	\$ 12,500.00
2. Loss of Use (10days x \$200.00)	\$ 2,000.00	\$ 1,200.00 (10days x \$120.00)
3. LTA/ GIA Search Fee	\$ 7.45	\$ 7.45
Total	\$ 30,552.15	\$ 13,707.45

**08days recommendation for repair + 1Sunday + 1PH = 10days.

All the relevant documents had been uploaded in Merimen for your perusal.

For your approval in Merimen please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)


From: Mavis, Chew <Chew.Mavis@aig.com>
Sent: Thursday, 14 February 2019 2:10 PM
To: Hsiao Tong (LKKAuto)
Cc: Vivian Lau (LKKAuto); Admin A
Subject: #7691003008SG003#023# << AIG ref | *LKK Ref: CC6/LCR18014580/Awa3 [ACCIDENT INVOLVING SLH 5634D(OI) SKK 6059D(TP) ON 04/08/2018]

Dear Hsiao Tong

Mandate approved in Merimen.

Best Regards,
Ms. Mavis Chew
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way, #08-16, Singapore 079120
Tel +(65) 6419 1970
chew.mavis@aig.com | www.aig.sg



AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards. [Click here to find out more.](#)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]
Sent: Thursday, February 14, 2019 9:46 AM
To: Mavis, Chew
Cc: Vivian Lau (LKKAuto); Admin A
Subject: <Seek Mandate>AIG Ref: 7691003008SG *LKK Ref: CC6/LCR18014580/Awa3 [ACCIDENT INVOLVING SLH 5634D(OI) SKK 6059D(TP) ON 04/08/2018]

AIG Ref: **7691003008SG**
LKK Ref: CC6/LCR18014580/Awa3

Dear Sirs/Madam,

ACCIDENT INVOLVING SLH 5634D(OI) SKK 6059D(TP) ON 04/08/2018

We refer to the above matter.

This is a head-to-rear collision. Liability is not in our driver's favour.

We seek your approval to offer to Third Party repairer, "HUA MENG SPRAY PAINTING WKSP" is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair	\$ 28,544.70	\$ 12,500.00
2. Loss of Use (10days x \$200.00)	\$ 2,000.00	\$ 1,200.00 (10days x \$120.00)
3. LTA/ GIA Search Fee	\$ 7.45	\$ 7.45
Total	\$ 30,552.15	\$ 13,707.45

**08days recommendation for repair + 1Sunday + 1PH = 10days.

All the relevant documents had been uploaded in Merimen for your perusal.

For your approval in Merimen please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Print Received Message

This mail is associated with :

***SKK6059D (7691003008SG)**
[SLH5634D]

TP

RAJEEV LOCHAN

Aug 4 2018 3:00PM

[LCRF Pte Ltd]

Hua Meng Spray Painting Workshop

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 14/02/2019 14:05 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$13707.45) - SKK6059D - Claim Handler: Chew, Mavis

Approved:13707.45.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 20 February 2019 5:16 PM
To: 'Hua Meng'
Subject: RE: Your Ref: SKK 6059D,Our Ref : CC6/LCR18014580/Awa3,Accident involving SKK 6059D & SLH 5634D ON 04/08/2018

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We have our principal instruction to offer at a global sum of \$13,500.00(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hua Meng <huameng@live.com.sg>
Sent: Thursday, January 3, 2019 6:28 PM
To: Vivian Lau; NTUC Income Motor Dept
Subject: Re: Your Ref: SKK 6059D,Our Ref : CC6/LCR18014580/Awa3,Accident involving SKK 6059D & SLH 5634D ON 04/08/2018

Dear Vivian

We refer the latest email you sent dated 27.11.2018

We have yet to receive your offer.

We are sorry to inform you we have to pass the matter to lawyer as we have no receive your offer.

Thanks & Regards

June

Hua Meng Spray painting Workshop

Vivian Lau (LKKAuto)

From: Vivian Lau (LKKAuto)
Sent: Monday, 20 August, 2018 3:58 PM
To: 'eyap@lioncityrentals.com.sg'; 'insurance@lioncityrentals.com.sg'
Cc: Hsiao Tong (LKKAuto); Joy Irene (LKKAuto)
Subject: ACCIDENT INVOLVING SLH 5634D and SKK 6059D on 04/08/2018

Our Ref: CC6/LCR18014580/Awa3

20 August 2018

LION CITY RENTALS PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SLH 5634D and SKK 6059D on 04/08/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please call us if you have further queries.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

AUTHORISATION TO ACT

I/We, Rajeev Lochan ("the third party claimant") of
14 Frankel Drive, S(458093) (address),
owner of SKK6059D (vehicle no.) hereby authorise **HUA MENG SPRAY PAINTING**
WORKSHOP ("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SKK6059D that was damaged pursuant
to the accident which occurred on 04.02.2018 (date) along PIE towards Changi
(near Steven) (location) involving vehicle no/s SLH5634D ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem
fit and the workshop is further authorized to receive payment further to settlement of my claim
with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 6 (day) of Aug (month) 20 18 (year)

Rajeev Lochan

Signed by "the third party claimant"
(with company stamp if applicable)

華明噴漆廠
HUA MENG SPRAY PAINTING WORKSHOP
AUTOBAY@KAKI BUKIT
1 KAKI BUKIT AVE 6 #01-34 SINGAPORE 417882
TEL: 6747 8964, 6746 5519 FAX: 6743 4896

[Signature]
Signed by "the workshop"
(with company stamp)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **HUA MENG SPRAY PAINTING WORKSHOP** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$13,500.00** (Global Sum) for vehicle no. **SKK 6059D** that was damaged pursuant to the accident which occurred on **04/08/2018** (date) along **PIE TWDS CHANGI (NEAR STEVEN)** involving vehicle no/s **SLH 5634D**.

This is pursuant to the inspection conducted on **07/08/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **RAJEEV LOCHAN** ("the third party claimant") of vehicle no. **SKK 6059D** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SKK 6059D** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 25 (day) of Feb (month) 2019 (year)



Signed by appointed surveyor

華明噴漆廠
HUA MENG SPRAY PAINTING WORKSHO
AUTOBUKAKI BUKIT
1 KAKI BUKIT AVZ 6 #01-34 SINGAPORE 41788
TEL: 6747 3064 6740 5515 FAX: 6743 489

Signed by "the workshop" (with chop)

WITHOUT PREJUDICE
TO OUR CLIENT'S PERSONAL INJURY
CLAIM (PRESENT OR FUTURE) WHICH IS
EXPRESSLY RESERVED



華 明 噴 漆 廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883
Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680
Reg. No.: 254678/00M



Your Ref :

27/11/2018

Our Ref :

Date:.....

VEHICLE NO :SKK 6059 D
MAKE / MODEL :BMW 730LI
NAME :RAJEEV LOCHAN
ADDRESS :14 FRANKEL DRIVE
S 458093

FINAL REPAIR BILL FOR VEHICLE NO:SKK 6059 D

TO SUPPLY AND REPLACE PARTS, LABOUR CHARGES FOR
REPAIRING, KNOCKING, WELDING AND TO RESPRAY PAINTING
(LUMP SUM REPAIR)

\$ 12,500.00

SINGAPORE DOLLARS:TWELEVE THOUSAND FIVE HUNDRED ONLY

> Back to OneMotoring

Land Transport Authority

Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 06 Aug 2018 / 13:19:40

Receipt Date/Time : 06 Aug 2018 / 13:19:40

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180806-001116

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLH5634D As at 04 Aug 2018/15:30:00 Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLH5634D Enquiry Fee 20180806131848171006	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20180806131859729	Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Aug 2018 Edit Reg		07 Aug 2018 00:00 Edit Adj Rpt	\$12,500.00 Edit Estimates	\$12,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF PTE LTD , Co. Reg. No.: 201624597K, Tel: +6588888888								
Main Claimant:	RAJEEV LOCHAN , ID: S2735593E								
Vehicle Reg. No.:	SKK6059D	Date of Loss:	04/08/2018 15:00 - :59 [59 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 7691003008SG	Policy/Cover Note No.:	0999994790 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLH5634D	Policy No. (Claimant):	10115104						
		Excess:							
Repairer:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chew, Mavis] Chew.Mavis@aig.com								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/08/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (14/02/2019): Alert - Adj Mandate Approved (\$13707.45) - SKK6059D - Claim Handler: Chew, Mavi... 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKK6059D (7691003008SG)
[SLH5634D]
TP
RAJEEV LOCHAN
Aug 4 2018 3:00PM
[LCRF PTE LTD]
Hua Meng Spray Painting Workshop

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser					
Letters/Correspondences															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print						
1	(Draft)	Third Party Express Settlement - Payment Breakdown										1 Edit								
Assessment Reports															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail		Print						
1	16/08/18 17:06	Accident Statement <small>From: SC - Reg. No: SLH5634D, Claimant: LCRF PTE LTD</small>										1 Load HTM								
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print						
1	14/08/18 21:28	TP GIA REPORT										1 Load PDF								
2	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
3	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
4	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
5	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
6	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
7	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
8	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
9	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
10	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
11	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
12	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
13	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
14	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
15	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
16	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
17	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
18	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
19	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
20	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
21	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
22	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
23	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
24	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
25	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
26	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
27	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
28	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
29	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						
30	20/11/18 17:27	General View										1 Load JPG		<input checked="" type="checkbox"/>						

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	20/11/18 17:27	General View	 Load JPG	<input checked="" type="checkbox"/>
32	20/11/18 17:27	General View	 Load JPG	<input checked="" type="checkbox"/>
33	20/11/18 17:27	General View	 Load JPG	<input checked="" type="checkbox"/>
34	20/11/18 17:27	General View	 Load JPG	<input checked="" type="checkbox"/>
35	20/11/18 17:27	General View	 Load JPG	<input checked="" type="checkbox"/>
36	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	20/11/18 17:27	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	20/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	20/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	20/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
124	20/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
125	20/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
126	20/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
127	20/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
128	20/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
129	20/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
130	20/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
131	20/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
132	20/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
133	20/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
134	20/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
135	20/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
136	20/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
137	20/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
138	20/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
139	20/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
140	20/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
141	20/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
142	20/11/18 17:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/08/18 15:58	Email letter to OI ACCIDENT INVOLVING SLH 5634D and SKK 6059D on 04.08.2018	 Load PDF	
2	14/02/19 09:08	LTA SEARCH	 Load PDF	
3	14/02/19 09:34	TP ESTIMATE MARKED	 Load PDF	
4	14/02/19 09:34	LETTER TO OI	 Load PDF	
5	04/03/19 10:21	WORKSHOP INVOICE	 Load PDF	
6	04/03/19 10:21	AUTHORISATION TO ACT FORM	 Load PDF	
7	04/03/19 10:21	Release Voucher	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLH5634D (Insd veh)	Model:	BMW 730LI 3.0 D/AB 4DR SR LED DSC NAV HUD (A)
	SKK6059D (TP veh)		
Date of Accident:	04/08/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	28,544.70
Final Repair Cost	:	\$	13,500.00
Loss of Use	:	\$	10.00 days at \$120.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	13,500.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability ___100___(%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No:	
BOLA Liability: _____(%)		Assessed Liability (*): _____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Hua Meng Spray Painting Workshop	:	\$ 13,500.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

04 Mar
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18014580/APA3Q2
Date: 04/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994790
Claimant Vehicle No : SKK6059D	Insured Vehicle No :	SLH5634D
Date of Loss: 04/08/2018	Nature of Claim:	TP
		Claim No: 7691003008SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKK6059D		
Make & Model:	BMW 730LI, 3.0 D/AB 4DR SR LED DSC NAV HUD (A)	Engine No:	07738357N52B30AF
Reg. Date:	12/08/2013 (Man. Year: 2012)	Chassis No:	WBAYE22030DZ20966
Colour:	Blue	Odometer:	62648 km
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/50 R18	Rear Tyre Size:	245/50 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,294.70	12,901.62	11,393.08	46.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,250.00	2,740.00	1,510.00	35.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,544.70	15,641.62	12,903.08	45.20
Approved Total (Overridden) (S\$)		12,500.00		
Nett Amount (S\$)	28,544.70	12,500.00	16,044.70	56.21
+ Loss of Use (10.0 x S\$120.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		13,707.45		
Global Sum Settlement (S\$)		13,500.00		

INSPECTION

Date of Assignment:	07/08/2018	
Date Inspected:	07/08/2018 Inspected At:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61

Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	2,186.70 FL	*2,186.70 FL
2	2		*REAR BOOT LID HINGES	Not Necessary	401.80 FL	*- FL
3	1		*REAR BOOT LID UPPER LOCK	Dented	233.00 FL	*233.00 FL
4	1		*REAR BOOT LID LOWER LOCK	Not Necessary	57.50 FL	*- FL
5	1		*REAR BOOT LID INSULATION	Not fitted	155.00 FL	*- FL
6	1		*REAR BOOT LID WEATHERSTRIP	Necessary	210.90 FL	*210.90 FL
7	1		*REAR BOOT LID CENTRE LOGO	Necessary	87.50 FL	*87.50 FL
8	1		*REAR BOOT LID 730 EMBLEM	Necessary	68.70 FL	*68.70 FL
9	1		*REAR BOOT LID LI EMBLEM	Necessary	68.70 FL	*68.70 FL
10	1		*REAR BOOT LID HANDLE	Not Necessary	19.80 FL	*- FL
11	2		*REAR BOOT LID REFLECTOR	Cut	990.00 FL	*990.00 FL
12	2		*REAR BOOT LID REVERSE LAMP	Not Necessary	900.00 FL	*- FL
13	2		*REAR NUMBER PLATE LAMP	Not Necessary	83.60 FL	*- FL
14	2		*REAR LAMP	Cracked	1,587.40 FL	*1,587.40 FL
15	2		*REAR LAMP SIDE GARNISH	Cut	77.00 FL	*77.00 FL
16	1		*REAR END PANEL	Dented	1,635.40 FL	*1,245.00 FL
17	1		*REAR END PANEL INNER TOP GARNISH	Deformed	141.80 FL	*141.80 FL
18	1		*REAR BUMPER	Deformed	2,025.70 FL	*2,025.70 FL
19	2		*REAR BUMPER SIDE HOLDER	Necessary	429.00 FL	*294.00 FL
20	1		*REAR BUMPER LOWER MOULDING	Cut	125.30 FL	*125.30 FL
21	1		*REAR BUMPER REFLECTOR	Cracked	38.70 FL	*38.70 FL
22	1		*REAR BUMPER TOWING HOOK COVER	Deformed	55.80 FL	*55.80 FL
23	1		*REAR BUMPER LOWER COVER	Deformed	387.50 FL	*387.50 FL
24	4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	1,042.40 FL	*521.20 FL
25	4		*REAR BUMPER REVERSE SENSOR SOCKET	Not Necessary	258.00 FL	*- FL
26	1		*REAR BUMPER REINFORCEMENT	Bent	880.90 FL	*880.90 FL
27	1		*REAR BUMPER SPONGE	Not Necessary	41.80 FL	*- FL
28	1		*REAR BUMPER INNER TOP GARNISH	Cracked	115.50 FL	*115.50 FL
29	1		*REAR BUMPER INNER LOWER GARNISH	Cracked	275.00 FL	*275.00 FL
30	1		*REAR BUMPER INNER SENSOR	Not Necessary	407.00 FL	*- FL
31	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FL	*30.00 FL
32	1		*REAR END PANEL CENTRE LOWER COVER	Torn	54.80 FL	*54.80 FL
33	1		*REAR RH SIDE LOWER COVER	Torn	211.20 FL	*211.20 FL
34	2		*REAR FENDER INNER SIDE GARNISH	Not Necessary	590.80 FL	*- FL
35	1		*REAR SPARE TYRE TOP BOARD	Deformed	591.30 FL	*591.30 FL
36	1		*REAR SPARE TYRE WELL	Not Necessary	4,239.00 FL	*- FL
37	3		*REAR SPARE TYRE WELL INSULATION	Not Necessary	495.00 FL	*- FL
38	1		*REAR EXHAUST PIPE	Repair	2,350.30 FL	*- FL
39	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	32.30 FL	*- FL
40	2		*REAR EXHAUST PIPE CHROME	Bent	244.20 FL	*244.20 FL
41	1		*SMART OPENER CONTROL UNIT	Damaged	515.70 FL	*515.70 FL
42	1		*BOOTLID OUTER GARNISH	Necessary	254.00 FL	*254.00 FL
43	1		*REAR BOOT LID CAMERA	Not Necessary	800.00 FS	*- FS
44	1		*REAR NUMBER PLATE	Deformed	50.00 FS	*30.00 FS
45	1		*REAR NUMBER PLATE HOLDER	Deformed	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$) **25,526.00** **13,577.50**
 - List Item Discount on L Items 5.00/5.00% (S\$) 1,231.30 675.88

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (S\$)	24,294.70	12,901.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SUPPLY REAR END PANEL INNER SEALANT	New	200.00	60.00
2	REMOVE & REINSTALL EXHAUST PIPE	New	300.00	100.00
3	REMOVE & REINSTALL REVERSE SENSOR	New	200.00	60.00
4	REMOVE & REINSTALL BOOT LID INNER GARNISH	New	200.00	80.00
5	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,800.00	1,200.00
6	RESPRAY PAINTING	New	1,400.00	1,200.00
7	TUFF KOTE	New	150.00	40.00
Gross Labour Cost (\$\$)			4,250.00	2,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >