

PLATINUM WERKZ PTE LTD
 95 UBI AVENUE 1, #01-25, PAYA UBI INDUSTRIAL PARK, SINGAPORE 408934
 Contact: +65 6741 0610 Email: platinumwerkz@gmail.com FAX: 67410892

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Signature:
 Date:

Model: MITSUBISHI LANCER
 Acknowledged by Repairer

TP III
 Thin Thin

Vehicle:

Make &

Model:

Signature:

Date:

Particular

Qty

Amount (\$)

List Price

1 REAR BOOT LID Repair 1PC 595.00

2 REAR BOOT LOGO New 1PC 42.00

3 REAR BOOT EMBLEM 'LANCER' 1PC 35.00

4 REAR BOOT LICENCE PLATE GARNISH New 1PC 197.00

5 REAR BOOT INNER LOCK 1PC 135.00

6 REAR BOOT LOCK STRICKER 1PC 45.00

7 REAR BOOT WEATHERSTRIP 1PC 146.00

8 REAR BOOT HINGE @ \$ 98.00 1718 2PCS 196.00

9 REAR TAILALMP @ \$424.00 Cracked. 1546.20 2PCS 668 848.00

10 REAR TAILALMP PANEL @ \$165.00 Repair 2PCS 330.00

11 REAR BUMPER Deformed 1PC 743.00

12 REAR BUMPER SIDE RETAINER @ \$48.00 New 2PCS 96.00

13 REAR END PANEL Repair 1PC 485.00

14 REAR END PANEL GARNISH Deformed 1PC 169.00

15 REAR SAPER TYRE TANK New 1PC 910.00

Total 4,972.00

Less 20% (994.40)

Sub-Total cost for parts 3,977.60

Part Replacement - Special

Nett Item

1 REAR END PANEL GARNISH CLIP New 1 SET 22.50

2 REAR TAILLAMP CLIP @ \$12.50 New 2PCS 25.00

3 REAR TAILLAMP CLIP HOLDER @ \$11.50 New 2PCS 23.00

4 REAR REVERSE SENSOR Damaged 1 SET 280.00

5 REAR BUMPER LOWER SPOILER Repair 1PC 760.00

Sub-Total cost for parts 1,110.50

Labour & MISC Charges

1 TO CHECK UP REAR ELECTRICAL WIRING & TEST FOR ANY LEAKAGE 1130 80.00

2 TO REMOVE & REFIX REVERSE SENSOR 80.00

3 TO REMOVE & REFIX REAR INTERIOR TRIM TO ASSIT REPAIR 150.00

4 TO RESPRAY UNDERCOATING 180.00

5 TO RESPRAY & etc 1,200.00

6 PANEL BEATING, REMOVE & REPLACING ABOVE PARTS 1,200.00

Sub-Total Labour 2,890.00