

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0918/2018/KS
Date : 11-Aug-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no. : **SGM 4000 Y**

FWD Insurance- Singapore

6 Temasek Boulevard

#18-01 Suntec Tower Four

Singapore 038986

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Ms. Ong Suat Lin
Address : Blk 207 Bishan Street 23
#16-397
Singapore 570207
Telephone : HP +65 98463322
Type of Claim : Third party Claims
Policy No. : M0006784
Vehicle No : **SKN 2997 G**
Model Code : Audi A3 Sedan 1.4 TFSI (A)
Model / Year : May-14
Engine No : CXS 090819
Chassis No : WAUZZZ8V4E1034832
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 24-Jul-18
Place of Accident : SLIP ROAD OF BISHAN ROAD TWDS BISHAN ST 22

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKN 2997 G.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid. Check function.	S/N \$ 280.00	✓
2	To remove and transfer rear lids convenience lock system and wire harness for tail lights.	S/N \$ 280.00	X NN
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 480.00	?
4	To dismantle and renew rear bumper and rear lid. Cut out and reweld end panelling. Renew rear end panel and realign. Re-organise rear crash management components. Reinstall all parts removed.	\$ 3,600.00	1200
5	To respray rear bumper, rear lid and end panelling. To carry out joint sealer works and stone chip treatment.	\$ 2,300.00	1800
6	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 7,132.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKN 2997 G.

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	REAR BUMPER / RE	\$ 1,619.00	
2	REAR BUMPER FIXING PARTS ?	\$ 166.00	
3	REAR BUMPER GUIDE - LHS/RHS < LH X NA RH - ABC	2 \$ 28.00	@ 14
4	REAR BUMPER LOCKING MECHANISM ?	\$ 50.00	
5	REAR BUMPER LIGHT REFLECTOR - LHS/RHS < LH X NA RH - CMA	2 \$ 52.00	@ 26
6	REAR BUMPER SPOILER / GY	\$ 206.00	
7	REAR REINFORCEMENT BEAM ?	\$ 501.00	
8	REAR BUMPER BRACKET LH / RH ?	2 \$ 22.00	
9	REAR BUMPER INNER GUIDE - LHS/RHS ?	2 \$ 114.00	
10	REAR PARKING AID SENSOR - DM	\$ 421.00	
11	REAR PARKING AID SENSOR SEAL - ABC	\$ 14.00	
12	REAR BUMPER WIRING SET ?	\$ 458.00	
13	REAR LID X repair.	\$ 2,310.00	
14	REAR LID ATTACHMENT PARTS X	\$ 253.00	
15	REAR LID WEATHERSTRIP X	\$ 176.00	
16	REAR LID LOCK X	\$ 170.00	
17	REAR LID LOCK COVER X	\$ 6.00	
18	"AUDI" EMBLEM /	\$ 108.00	
19	"A3" EMBLEM /	\$ 83.00	
20	"1.4T" EMBLEM /	\$ 108.00	
SUB- TOTAL SPARE PARTS		\$ 6,865.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKN 2997 G

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
21	LED TAILLIGHT RH ?	\$	946.00
22	LED TAILLIGHT TRIM RH ?	\$	26.00
23	REAR CROSS PANEL ?	\$	317.00
24	REINFROCMENT FOR CROSS PANEL ?	\$	645.00
25	CONNECTING PIECE ?	\$	158.00
26	CONNECTING PLATE ?	\$	126.00
27	REAR NUMBER PLATE X NN	S/N \$	25.00
28	ACRYLIC SEALER X ?	S/N \$	180.00
29	CAVITY WAX X ?	S/N \$	140.00
30	STONE CHIP ?	S/N \$	180.00
31	SUNDRIES ?	\$	500.00
GRAND TOTAL SPARE PARTS		:	\$ 10,108.00
TOTAL LABOUR CHARGES		:	\$ 7,132.00
GRAND TOTAL		:	\$ 17,240.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

5 Days .
Eno Qiaf - 82880282
before paint photos.
15/8/18 .

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

L&K Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant