

AUTOWORX HOUSE

C/O176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL : 6452 8211 FAX : 6451 7420

ESTIMATE

MARINA, NEZIA

c/o 46 Lenton Plain
Singapore 786548

*Not with air
1/1/18 B?
Penny After Paint
5 days*

Date: 6/8/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: HONDA STREAM / SJY 661 Y	
1 pc	rear bumper	CM 794.70 ✓
2 pcs	rear bumper lower bracket @ 83.60	R 167.20 X
1 pc	rear bumper side retainer	DI 62.30 ✓
1 pc	rear bumper tow cover	NI 69.30 ✓
1 pc	rear end outer panel	596.40 ?
1 pc	rear end inner panel	R 326.00 X
1 pc	rear end panel garnish	320.60 ?
1 pc	rear end lower sub panel	R 176.40 X
1 pc	rear fender inner trim	SM 479.60 X
1 pc	rear windscreen glass inner seal	NI 64.10 300
1 pc	rear windscreen glass moulding	NI 172.40 —
1 pc	rear spare tyre bracket	R 478.00 X
1 pc	tail lamp assy	CM 579.00 ✓
1 pc	tailgate	R 1,070.00 ✓
1 pc	tailgate damper	SM 242.90 X
1 pc	tailgate inner garnish	SM 376.60 X
1 pc	tailgate lock assy	R 276.30 X
1 pc	tailgate lock catch	R 65.00 X
1 pc	tailgate weatherstrip	115.10 ?
	sub-total	6,431.90
	less 20%	1,286.38
	sub-total	5,145.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

	Balance brought forward.			5,145.52	
1 tube	windscreen glass sealant	s.nett	<i>40sm</i>	60.00	
1 pc	number plate	s.nett	<i>sm</i>	45.00	X
1 set	reverse sensor (4 sensor tyre)	s.nett	<i>320sm</i>	450.00	
1 set	sundries (clips, bolts, nuts etc.)	s.nett	<i>sm</i>	20.00	X
	To remove & replace parts, realign & panel beat the affected areas.			1,400.00	?
	To check wiring system.			50.00	<i>200</i>
	To spray painting on affected areas.		<i>600</i>	1,100.00	
	To apply rust proofing.			150.00	?
	To install reverse sensor.		<i>600</i>	80.00	
	To remove and refit tailgate accessories.		<i>600</i>	80.00	
	To remove and refit rear windscreen glass.		<i>1200</i>	140.00	
	To apply water proof sealant on jointed panels.			150.00	?
		Total		8,870.52	